

Report on Operating Subsidiaries on its Web site at <http://www.occ.gov>.
Dated: October 29, 2004.
Julie L. Williams,
Acting Comptroller of the Currency.
[FR Doc. 04-24735 Filed 11-4-04; 8:45 am]
BILLING CODE 4810-33-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19001; Directorate Identifier 2004-NM-98-AD; Amendment 39-13842; AD 2004-22-14]

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB SF340A and SAAB 340B Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.
ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Saab Model SAAB SF340A and SAAB 340B series airplanes. This AD requires an inspection of the elevator and aileron trim-tab fittings, and related investigative/corrective actions if necessary. This AD is prompted by reports of improperly installed rivets in the retainers that hold the elevator trim-tab bearings. We are issuing this AD to

prevent the elevator and aileron trim-tab bearings from coming loose, which could result in excessive play in the elevator and aileron trim systems, and reduced controllability of the airplane.
DATES: This AD becomes effective December 10, 2004.

The incorporation by reference of a certain publication listed in the AD is approved by the Director of the Federal Register as of December 10, 2004.

ADDRESSES: For service information identified in this AD, contact Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. You can examine this information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Docket: The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section.

FOR FURTHER INFORMATION CONTACT:

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Inspection	16	\$65	None	\$1,040	170	\$176,800

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.
For the reasons discussed above, I certify that this AD:
(1) Is not a “significant regulatory action” under Executive Order 12866;
(2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.
We prepared a regulatory evaluation of the estimated costs to comply with this AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

Technical information: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

Plain language information: Marcia Walters, marcia.walters@faa.gov.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR Part 39 with an AD for certain Saab Model SAAB SF340A and SAAB 340B series airplanes. That action, published in the **Federal Register** on September 3, 2004 (69 FR 53846), proposed to require an inspection of the elevator and aileron trim-tab fittings, and related investigative/corrective actions if necessary.

Comments

We provided the public the opportunity to participate in the development of this AD. No comments have been submitted on the proposed AD or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD.

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2004-22-14 Saab Aircraft AB: Amendment 39-13842. Docket No. FAA-2004-19001; Directorate Identifier 2004-NM-98-AD.

Effective Date

(a) This AD becomes effective December 10, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to certain Saab Model SAAB SF340A series airplanes, line numbers 004 through 159 inclusive; and SAAB 340B series airplanes, line numbers 160 through 459 inclusive; certificated in any category.

Unsafe Condition

(d) This AD was prompted by reports of improperly installed rivets in the retainers located in the elevator trim-tab fittings. The retainers hold the trim-tab bearings. We are issuing this AD to prevent the elevator and aileron trim-tab bearings from coming loose, which could result in excessive play in the elevator and aileron trim systems, and reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Related Investigative/Corrective Actions

(f) Within 800 flight hours or 6 months after the effective date of this AD, whichever is first: Do a detailed inspection of the elevator and aileron trim-tab fittings, and all applicable related investigative and corrective actions, by accomplishing all of the actions in the Accomplishment Instructions of Saab Service Bulletin 340–51–025, Revision 01, dated October 21, 2003. Any related investigative and corrective actions must be done before further flight.

Note 1: For the purposes of this AD, a detailed inspection is: “An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.”

Parts Installation

(g) As of the effective date of this AD, no person may install on any airplane an elevator or aileron trim-tab fitting unless it has been inspected, and any applicable corrective actions have been done, in accordance with paragraph (f) of this AD.

Reporting Not Required

(h) Although the service bulletin referenced in this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(i) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(j) Swedish airworthiness directive 1–194, dated October 14, 2003, also addresses the subject of this AD.

Material Incorporated by Reference

(k) You must use Saab Service Bulletin 340–51–025, Revision 01, dated October 21, 2003, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approves the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. For copies of the service information, contact Saab Aircraft AB, SAAB Aircraft Product Support, S–581.88, Linköping, Sweden. For information on the availability of this material at the National Archives and Records Administration (NARA), call (202) 741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. You may view the AD docket at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL–401, Nassif Building, Washington, DC.

Issued in Renton, Washington, on October 21, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04–24520 Filed 11–4–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF COMMERCE**Bureau of Industry and Security****15 CFR Parts 740, 748, and 774**

[Docket No. 041020285–4285–01]

RIN 0694–AD18

Computer Technology and Software Eligible for Export Under License Exception; and Establishment of “Foreign National Review” Requirement and Procedure

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Final rule.

SUMMARY: This final rule expands the availability of license exceptions for certain deemed exports of computer technology and source code under the Export Administration Regulations (EAR), partially implementing the expansion set forth in a proposed rule published on October 24, 2003. In addition, this final rule clarifies certain provisions of License Exception CTP. This rule also establishes a new “Foreign National Review (FNR)” requirement for deemed exports of technology or source code under License Exception CTP.

DATES: This rule is effective on November 5, 2004.

FOR FURTHER INFORMATION CONTACT: Sharron Cook, Senior Export Policy Analyst, Office of Exporter Services,

Regulatory Policy Division, Bureau of Industry and Security, Telephone: (202) 482–2440.

SUPPLEMENTARY INFORMATION:**Background**

On June 4, 2002, BIS published a notice of inquiry (67 FR 39675), requesting information from industry to assist BIS in evaluating the license exception eligibility level of 33,000 MTOPS for exports and reexports of computer technology and software controlled under ECCNs 4D001 and 4E001. BIS received four comments in response to the notice of inquiry, all stating that the license exception threshold should be adjusted.

On October 24, 2003, BIS published a proposed rule with request for comments from industry (68 FR 60891) to expand the availability of License Exception CTP for exports and reexports of computer technology and software on the Commerce Control List (CCL) of the Export Administration Regulations (EAR) under Export Classification Control Numbers (ECCNs) 4D001 and 4E001. These ECCNs control technology and software that can be used for the development, production, or use of computers. The proposed rule also requested comments to assist BIS in evaluating microprocessor technology controlled under ECCN 3E002. BIS received eleven comments in response to the proposed rule and the questions posed in the preamble. BIS has decided to address computer technology and software and microprocessor technology in two different final rules. This final rule implements the license exception expansion for computer technology and software. The corresponding rule on license exception eligibility for microprocessor technology is published elsewhere in this issue of the **Federal Register**.

Current Controls on Computer Technology and Software

Export controls for computer technology and software are controlled multilaterally through the Wassenaar Arrangement. The current Wassenaar Arrangement (WA) control thresholds for computer technology and software are: 28,000 MTOPS for the Basic List (BL), 75,000 MTOPS for the Sensitive List (SL); and 150,000 MTOPS for the Very Sensitive List (VSL). (**Note:** the computer hardware level within WA (under the BL) and in the United States is currently at 190,000 MTOPS. Computer hardware is not controlled on WA’s SL and VSL.)

The EAR control the export and reexport of technology and software for the development, production, or use of