

Rules and Regulations

Federal Register

Vol. 76, No. 235

Wednesday, December 7, 2011

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-1299; Directorate Identifier 2011-NE-40-AD; Amendment 39-16878; AD 2011-25-02]

RIN 2120-AA64

Airworthiness Directives; BRP-Powertrain GmbH & Co. KG Reciprocating Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for BRP-Powertrain GmbH & Co. KG Rotax 912 F2, 912 F3, 912 F4, 912 S2, 912 S3, 912 S4, 914 F2, 914 F3, and 914 F4 reciprocating engines. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During a production process review, a deviation in the manufacturing process of certain part number (P/N) 888164 crankshafts has been detected, which may have resulted in a latent defect. This condition, if not corrected, could lead to crack formation on the power takeoff side of the crankshaft journal, possibly resulting in failure of the crankshaft support bearing, in-flight engine shutdown and forced landing, damage to the aeroplane and injury to the occupants.

We are issuing this AD to prevent in-flight failure of the engine and forced landing.

DATES: This AD becomes effective December 22, 2011.

We must receive comments on this AD by January 6, 2012.

The Director of the Federal Register approved the incorporation by reference of BRP-Powertrain GmbH & Co. KG, Rotax Aircraft Engines, Mandatory Alert Service Bulletins (ASB) Nos. ASB-912-059 and ASB 914-042 (combined in one document), dated November 15, 2011, listed in the AD as of December 22, 2011.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- **Mail:** U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- **Fax:** (202) 493-2251.

For service information identified in this AD, contact BRP-Powertrain GmbH & Co. KG, Welser Strasse 32, A-4623 Gunskirchen, Austria, or go to: <http://www.rotax-aircraft-engines.com>. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (phone: (800) 647-5527) is the same as the Mail address provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Alan Strom, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; email: alan.strom@faa.gov; phone: (781) 238-7143; fax: (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2011-0222-E, dated November 15, 2011 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During a production process review, a deviation in the manufacturing process of certain part number (P/N) 888164 crankshafts has been detected, which may have resulted in a latent defect. This condition, if not corrected, could lead to crack formation on the power takeoff side of the crankshaft journal, possibly resulting in failure of the crankshaft support bearing, in-flight engine shutdown and forced landing, damage to the aeroplane and injury to the occupants.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

We reviewed BRP-Powertrain GmbH & Co. KG, Rotax Aircraft Engines, Mandatory ASB Nos. ASB-912-059 and ASB 914-042 (combined in one document), dated November 15, 2011. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of this AD

This product has been approved by the aviation authority of Austria, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between the AD and the MCAI or Service Information

None.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because of the short compliance

time of 4 operating hours, and the risk to single-engine airplanes affected. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-1299; Directorate Identifier 2011-NE-40-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of the Web site, anyone can find and read the comments in any of our dockets, including, if provided, the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2011-25-02 BRP-Powertrain GmbH & Co. KG (formerly BRP-Rotax GmbH & Co. KG, Bombardier-Rotax GmbH & Co. KG, and Bombardier-Rotax GmbH):
Amendment 39-16878; Docket No. FAA-2011-1299; Directorate Identifier 2011-NE-40-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective December 22, 2011.

(b) Affected ADs

None.

(c) Applicability

This AD applies to BRP-Powertrain GmbH & Co. KG Rotax 912 F2, 912 F3, 912 F4, 912 S2, 912 S3, 912 S4, 914 F2, 914 F3, and 914 F4 reciprocating engines, with the following part number (P/N) 888164 crankshafts installed.

TABLE 1—AFFECTED P/N 888164 CRANKSHAFT SERIAL NOS. (S/NS)

S/NS 40232 through 40267 inclusive.
S/NS 40293 through 40374 inclusive.
S/NS 40408 through 40433 inclusive.
S/NS 40435 through 40507 inclusive.

(d) Reason

This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During a production process review, a deviation in the manufacturing process of certain part number (P/N) 888164 crankshafts has been detected, which may have resulted in a latent defect. This condition, if not corrected, could lead to crack formation on the power takeoff side of the crankshaft journal, possibly resulting in failure of the crankshaft support bearing, in-flight engine shutdown and forced landing, damage to the aeroplane and injury to the occupants.

We are issuing this AD to prevent in-flight failure of the engine and forced landing.

(e) Actions and Compliance

Unless already done, do the following actions.

(1) Within 4 flight hours after the effective date of this AD, clean and fluorescent-penetrant-inspect the crankshaft for cracks, in accordance with the Accomplishment Instructions paragraphs 3.1)4., 3.1)6., and Figure 1 of BRP-Powertrain GmbH & Co. KG, Rotax Aircraft Engines, Mandatory Alert Service Bulletins (ASB) Nos. ASB-912-059 and ASB 914-042 (combined in one document), dated November 15, 2011.

(2) If any crack is found, remove the crankshaft from service.

(f) Installation Prohibition

(1) After the effective date of this AD, do not install an engine having an affected P/N 888164 crankshaft installed, listed in Table 1 of this AD, on any airplane, unless the crankshaft has passed the inspection specified in paragraph (e)(1) of this AD.

(2) After the effective date of this AD, do not install an affected P/N 888164 crankshaft listed in Table 1 of this AD, in any engine, unless the crankshaft has passed the inspection specified in paragraph (e)(1) of this AD.

(g) FAA AD Differences

None.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(i) Related Information

(1) Refer to MCAI European Aviation Safety Agency AD 2011-0222-E, dated November 15, 2011, for related information.

(2) Contact Alan Strom, Aerospace Engineer, Engine Certification Office, FAA,

Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; email: alan.strom@faa.gov; phone: (781) 238-7143; fax: (781) 238-7199, for more information about this AD.

(j) Material Incorporated by Reference

You must use BRP-Powertrain GmbH & Co. KG, Rotax Aircraft Engines, Mandatory Alert Service Bulletins Nos. ASB 912-059 and ASB 914-042 (combined in one document), dated November 15, 2011, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact BRP-Powertrain GmbH & Co. KG, Welser Strasse 32, A-4623 Gunskirchen, Austria, or go to: <http://www.rotax-aircraft-engines.com>.

(3) You may review copies of the service information at the FAA, New England Region, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call (202) 741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on November 29, 2011.

Peter A. White,

Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2011-31501 Filed 12-6-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 110

[USCG-2011-0231]

RIN 1625-AA01

Anchorage Regulations; Wells, ME

AGENCY: Coast Guard, DHS.

ACTION: Final rule.

SUMMARY: The Coast Guard is establishing three special anchorage areas in Wells Harbor, Wells, Maine. This action is necessary to facilitate safe navigation in that area and provide safe and secure anchorages for vessels not more than 20 meters in length. This action is intended to increase the safety of life and property in Wells Harbor, improve the safety of anchored vessels, and provide for the overall safe and

efficient flow of vessel traffic and commerce.

DATES: This rule is effective January 6, 2012.

ADDRESSES: Comments and material received from the public, as well as documents mentioned in this preamble as being available in the docket, are part of docket USCG-2011-0231 and are available online by going to <http://www.regulations.gov>, inserting USCG-2011-0231 in the "Keyword" box, and then clicking "Search." This material is also available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email Mr. John J. Mauro, Waterways Management Branch Chief, First Coast Guard District; telephone (617) 223-8355, email John.J.Mauro@uscg.mil. If you have questions on viewing or submitting material to the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone (202) 366-9826.

SUPPLEMENTARY INFORMATION:

Regulatory Information

On August 23, 2011, we published a notice of proposed rulemaking (NPRM) entitled "Anchorage Regulations; Wells, Maine" in the **Federal Register** (76 FR 52599). We received no comments on the proposed rule. A public meeting was not requested and none was held.

Basis and Purpose

The legal basis for this rule is 33 U.S.C. 471, 1221 through 1236, 2030, 2035, 2071; 33 CFR 1.05-1; and Department of Homeland Security Delegation No. 0170.1, which collectively authorize the Coast Guard to define anchorage grounds.

This rule is intended to reduce the risk of vessel collisions by creating three special anchorage areas in the western, central and eastern portions of Wells Harbor creating anchorage for approximately 150 vessels.

Background

This rule creates three new special anchorage areas in Wells, Maine. These three new special anchorage areas in Wells Harbor are described below. All coordinates are North American Datum 1983 (NAD 83).

Vessels not more than 20 meters in length are not required to sound signals as per Rule 35 of the Inland Navigation

Rules (33 U.S.C. 2035) nor exhibit anchor lights or shapes as per Rule 30 of the Inland Navigation Rules (33 U.S.C. 2030) when at anchor in a special anchorage area. Mariners utilizing the anchorage areas are encouraged to contact local and state authorities, such as the local harbor master, to ensure compliance with any additional applicable state and local laws. Such laws may involve, for example, compliance with direction from the local harbor master when placing or using moorings within the anchorage.

Discussion of Comments and Changes

The Coast Guard received no comments on the proposed rulemaking. We have finalized the rule as proposed, without change.

Regulatory Analyses

We developed this rule after considering numerous statutes and executive orders related to rulemaking. Below we summarize our analyses based on 13 of these statutes or executive orders.

Executive Order 12866 and Executive Order 13563

This rule is not a significant regulatory action under section 3(f) of Executive Order 12866, Regulatory Planning and Review, as supplemented by Executive Order 13563, and does not require an assessment of potential costs and benefits under section 6(a)(3) of that Order. The Office of Management and Budget has not reviewed it under that Order.

Although this regulation may have some impact on the public, the potential impact will be minimized for the following reasons: Normal surface navigation will not be affected as this area has been historically used as a mooring field by the Town of Wells and the number of vessels using the anchorage is limited due to depth (less than or equal to 18 feet).

Small Entities

Under the Regulatory Flexibility Act (5 U.S.C. 601-612), we have considered whether this rule will have a significant economic impact on a substantial number of small entities. The term "small entities" comprises small businesses, not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions with populations of less than 50,000.

The Coast Guard certifies under 5 U.S.C. 605(b) that this rule will not have a significant economic impact on a substantial number of small entities. This rule could affect the following