

Proposed Rules

Federal Register

Vol. 87, No. 158

Wednesday, August 17, 2022

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0994; Project Identifier MCAI-2022-00052-T]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft Industries, Ltd.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Gulfstream Aerospace LP Model Gulfstream G200 airplanes. This proposed AD was prompted by reports that wing flap fairing debonding and corrosion were discovered at certain areas of the lower skin on both wings. This proposed AD requires an inspection for corrosion in certain areas of the wing skin fairings, additional inspections if necessary, resealing the fairings with new fillet seal, and applicable corrective actions, as specified in the Civil Aviation Authority of Israel (CAAI) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by October 3, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to www.regulations.gov. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For CAAI service information identified in this NPRM, contact Civil Aviation Authority of Israel (CAAI), P.O. Box 1101, Golan Street, Airport City, 70100, Israel; telephone 972-3-9774665; fax 972-3-9774592; email aip@mot.gov.il. You may find this CAAI AD on the CAAI website at www.caa.gov.il. For Gulfstream service information identified in this NPRM, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Mail Station D-25, Savannah, GA 31402-2206; telephone 800-810-4853; fax 912-965-3520; email pubs@gulfstream.com; internet www.gulfstream.com/customer-support. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket at www.regulations.gov by searching for and locating Docket No. FAA-2022-0994; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206-231-3225; email dan.rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0994; Project Identifier MCAI-2022-00052-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider

all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to www.regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206-231-3225; email dan.rodina@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The CAAI, which is the aviation authority for Israel, has issued AD ISR I-57-2021-12-4, dated January 1, 2022 (CAAI AD ISR I-57-2021-12-4) (also referred to after this as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Gulfstream Aerospace LP Model Gulfstream G200 airplanes.

This proposed AD was prompted by reports that wing flap fairing debonding and corrosion were discovered at the lower skin of rib 3 and rib 11 on both wings. The FAA is proposing this AD to

address flap fairing debonding and moisture intrusion that might lead to lower wing skin corrosion and cracking on both wings, and reduced structural integrity of the wings. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

CAAI AD ISR I-57-2021-12-4, dated January 1, 2022, describes procedures for an inspection for corrosion in the area of the wing skin (or doubler if installed) under the rib 3 and rib 11 fairings, a penetration or eddy current inspection for cracks if corrosion was found, a measurement of the thickness of remaining wing skin (or doubler) if no cracks were found, resealing of rib 3 and rib 11 fairings with new fillet seal, and applicable corrective actions.

Corrective actions include cleaning and removing corrosion, crack repair, and repair of fairing installation locations with a certain thickness reduction. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because the FAA

evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD requires accomplishing the actions specified in CAAI AD ISR I-57-2021-12-4 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 168 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
29 work-hours × \$85 per hour = \$2,465	Minimal	\$2,465	\$414,120

The FAA estimates the following costs to do any necessary on-condition action that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS [¹]

Labor cost	Parts cost	Cost per product
Up to 10 work-hours × \$85 per hour = \$850	\$0	Up to \$850.

* The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this proposed AD.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft

Industries, Ltd.): Docket No. FAA–2022–0994; Project Identifier MCAI–2022–00052–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by October 3, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Gulfstream Aerospace LP Model Gulfstream G200 airplanes, certificated in any category, as identified in The Civil Aviation Authority of Israel (CAAI) AD ISR I–57–2021–12–4, dated January 1, 2022 (CAAI AD ISR I–57–2021–12–4).

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports that wing flap fairing debonding and corrosion were discovered at lower skin of rib 3 and rib 11 on both wings. The FAA is issuing this AD to address flap fairing debonding and moisture intrusion that might lead to lower wing skin corrosion and cracking on both wings, and reduced structural integrity of the wings.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, CAAI AD ISR I–57–2021–12–4.

(h) Exceptions to Service Information Specifications

(1) Where CAAI AD ISR I–57–2021–12–4 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where the Compliance paragraph of CAAI AD ISR I–57–2021–12–4 requires compliance at a certain time, replace the text “at the next suitable planned maintenance inspection within the next 24 months from the effective date of this AD” with “within 24 months after the effective date of this AD.”

(3) Where the Action paragraph of CAAI AD ISR I–57–2021–12–4 refers to certain service information, replace the text “Gulfstream Service Bulletin No. 200–57–426, dated January 01, 2022, or later approved revision,” with “Gulfstream Service Bulletin No. 200–57–426, Revision 1, dated June 16, 2022, or later approved revision.”

(4) Where the service information specified in CAAI AD ISR I–57–2021–12–4 specifies to report to Gulfstream if “cracks were discovered” and “for any fairing installation location with one or more grid squares with thickness reduction of greater than 10%,” for this AD, cracks and fairing installation locations with one or more grid squares with

thickness reduction of greater than 10% must be repaired before further flight using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or CAAI; or CAAI’s authorized Designee. If approved by the authorized Designee, the approval must include the Designee’s authorized signature.

(i) No Reporting Requirement

Although the service information referenced in CAAI AD ISR I–57–2021–12–4 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or the Civil Aviation Authority of Israel (CAAI); or the CAAI’s authorized Designee. If approved by the CAAI Designee, the approval must include the Designee’s authorized signature.

(k) Related Information

(1) For CAAI AD ISR I–57–2021–12–4, dated January 1, 2022, contact Civil Aviation Authority of Israel (CAAI), P.O. Box 1101, Golan Street, Airport City, 70100, Israel; telephone 972–3–9774665; fax 972–3–9774592; email aip@mot.gov.il. You may find this CAAI AD on the CAAI website at www.caa.gov.il. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket at www.regulations.gov by searching for and locating Docket No. FAA–2022–0994.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA–2022–0994, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206–231–3225; email dan.rodina@faa.gov.

Issued on August 4, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–17119 Filed 8–16–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2022–0970; Airspace Docket No. 22–ASW–18]

RIN 2120–AA66

Proposed Revocation of Class E Airspace; Stratford, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to remove the Class E airspace at Stratford, TX. The FAA is proposing this action due to the cancellation of the instrument procedures at the associated airport, and the airspace no longer being required.

DATES: Comments must be received on or before October 3, 2022.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590; telephone (202) 366–9826, or (800) 647–5527. You must identify FAA Docket No. FAA–2022–0970/Airspace Docket No. 22–ASW–18, at the beginning of your comments. You may also submit comments through the internet at www.regulations.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT: Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711.