

(2) If any discrepancy is detected, prior to further flight, replace, one at a time, each affected fastener with a new fastener having a washer, in accordance with the service bulletin. Repeat the inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 400 flight hours until accomplishment of the optional terminating action specified by paragraph (c) of this AD.

Note 5: Replacement of the attaching fasteners one at a time will avoid the loss of the servo tab or spring tab hinge fittings position.

Optional Terminating Action

(c) Rework (including installation of the elevator servo and spring tabs; and reidentification, static balancing, and installation of the elevator) of all elevator servo and spring tabs in accordance with Part III of the Accomplishment Instructions of S.B. 145-055-0022, Change 02, dated May 4, 2000, constitutes terminating action for the repetitive inspections required by this AD. Model EMB-135 and EMB-145 series airplanes having serial numbers 145004 through 145043, must accomplish the modifications specified by S.B. 145-27-0034, Change 01, dated August 5, 1998, prior to the rework specified by this paragraph.

Note 6: Modifications of certain airplanes specified in paragraph (c) of this AD, accomplished before the effective date of this amendment, in accordance with S.B. 145-27-0034, dated April 3, 1998, are considered acceptable for compliance with the modification requirement in paragraph (c) of this AD.

Reporting Requirement

(d) Submit a report of inspection findings for any discrepancy detected during any inspection required by paragraph (a) of this AD to Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil; at the applicable time specified in paragraph (d)(1) or (d)(2) of this AD. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(1) For airplanes on which any inspection is accomplished after the effective date of this AD: Submit the report within 10 days after performing any detailed visual inspection required by paragraph (a) of this AD.

(2) For airplanes on which any inspection has been accomplished prior to the effective date of this AD: Submit the report within 10 days after the effective date of this AD.

Alternative Methods of Compliance

(e)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance

Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 2000-04-09, amendment 39-11591, are approved as alternative methods of compliance with this AD.

Note 7: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The inspections shall be done in accordance with Embraer Service Bulletin 145-55-0024, dated May 25, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. Copies may be inspected at the FAA, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 8: The subject of this AD is addressed in Brazilian airworthiness directives 1999-09-01R2, dated May 1, 2000, and 2000-05-01, dated May 25, 2000.

Effective Date of This AD

(h) This amendment becomes effective on November 22, 2000.

Issued in Renton, Washington, on October 27, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-28087 Filed 11-6-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-121-AD; Amendment 39-11958; AD 2000-22-12]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-120 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain EMBRAER Model EMB-120 series airplanes, that requires replacement of the existing wire between certain circuit breakers with an improved wire. The actions specified by this AD are intended to prevent overheating of the wire between certain circuit breakers, which could result in smoke emissions in the cockpit. This action is intended to address the identified unsafe condition.

DATES: Effective December 12, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 12, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Carla Worthey, Program Manager, Program Management & Services Branch, ACE-118A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6062; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain EMBRAER Model EMB-120 series airplanes, was published in the **Federal Register** on

July 31, 2000 (65 FR 46671). That action proposed to require replacement of the existing wire between certain circuit breakers with an improved wire.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 240 airplanes of U.S. registry will be affected by this AD, that it will take approximately 2 work hours per airplane to accomplish the required action, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$8 per airplane. Based on these figures, the cost impact of this AD on U.S. operators is estimated to be \$30,720, or \$128 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator will accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a

substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-22-12 Empresa Brasileira de Aeronautica S.A. (EMBRAER):
Amendment 39-11958. Docket 2000-NM-121-AD.

Applicability: Model EMB-120 series airplanes, serial numbers 120003, 120004, 120006 through 120308 inclusive, 120310, 120312 through 120314 inclusive, 120316 through 120323 inclusive, and 120325 through 120330 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent overheating of the wire between certain circuit breakers, which could result in smoke emissions in the cockpit, accomplish the following:

Wire Replacement

(a) At the next scheduled maintenance inspection ("A"-check), but no later than 400 flight hours after the effective date of this AD: Replace the existing wire between circuit breakers 0304 and 0358 with a wire coded W200-1063-12, in accordance with EMBRAER Service Bulletin 120-30-0028, dated August 25, 1997.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Manager, Atlanta ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The replacement shall be done in accordance with EMBRAER Service Bulletin 120-30-0028, dated August 25, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Brazilian airworthiness directive 97-11-01, dated November 25, 1997.

Effective Date

(e) This amendment becomes effective on December 12, 2000.

Issued in Renton, Washington, on October 27, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-28088 Filed 11-6-00; 8:45 am]

BILLING CODE 4910-13-P