

this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To find and fix corroded, cracked or broken barrel nuts that attach the vertical fin to body section 48, which could result in reduced structural integrity of the vertical fin attachment joint, loss of the vertical fin, and consequent loss of controllability of the airplane; accomplish the following:

Internal/External Detailed Visual Inspections

(a) Do internal and external detailed visual inspections of the barrel nuts at the 16 locations that attach the vertical fin to body section 48 to find discrepancies (i.e., cracked or damaged sealant, signs of corrosion damage, cracked or broken barrel nuts). Do the inspections at the times specified in paragraphs (a)(1) and (a)(2) of this AD, as applicable; per Part 1 of the Accomplishment Instructions of Boeing Service Bulletin 767-53-0085, dated May 14, 1998, or Boeing Alert Service Bulletin 767-53A0085, Revision 1, dated July 1, 1999.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) For airplanes on which the inspections specified in paragraph (a) of this AD have been done within the last 3 years per Boeing 767 Maintenance Planning Document (MPD) D622T001, Items 5380-311-021 and 5380-312-021: Do the inspections at the later of the times specified in paragraphs (a)(1)(i) and (a)(1)(ii) of this AD.

(i) Within 3 years or 6,000 flight cycles after doing the most recent inspection per the MPD, whichever comes first.

(ii) Within 45 days after the effective date of this AD.

(2) For airplanes on which the inspections specified in paragraph (a) of this AD have NOT been done within the last 3 years per Boeing 767 MPD D622T001, Items 5380-311-021 and 5380-312-021: Do the inspections within 45 days after the effective date of this AD.

Follow-On Actions

(b) *If no discrepancies are found as a result of any inspection specified in paragraph (a) of this AD:* Before further flight, do a torque check of each of the 16 bolts in the barrel nuts that attach the vertical fin to body section 48 to determine if any bolt turns, per Part 2 of the Accomplishment Instructions of Boeing Service Bulletin 767-53-0085, dated May 14, 1998, or Boeing Alert Service Bulletin 767-53A0085, Revision 1, dated July 1, 1999.

(1) *If no bolt turns:* Repeat the inspections required by paragraph (a) of this AD (and applicable follow-on actions) every 3 years or

6,000 flight cycles, whichever comes first; until paragraphs (d) and (e) of this AD are done, as applicable.

(2) *If any bolt turns:* Before further flight, do the actions specified in paragraphs (b)(2)(i) and (b)(2)(ii) of this AD, as applicable. Then repeat the inspections required by paragraph (a) of this AD (and applicable follow-on actions) every 3 years or 6,000 flight cycles, whichever comes first; until paragraphs (d) and (e) of this AD are done, as applicable.

(i) *For all airplanes:* Replace the barrel nut at that bolt with a new, Inconel barrel nut per Part 3 of the Accomplishment Instructions of the service bulletin. No further action is required for that barrel nut only.

(ii) *For Group 1 airplanes:* If an H-11 steel alloy bolt is installed with the affected barrel nut, replace the bolt with a new, Inconel bolt per Figure 5 of the Accomplishment Instructions of the service bulletin. No further action is required for that bolt only.

(c) *If any discrepancy of any barrel nut is found as a result of any inspection specified in paragraph (a) of this AD:* Before further flight, do the actions specified in paragraphs (c)(1) and (c)(2) of this AD, as applicable.

(1) *For all airplanes:* Replace the affected barrel nut with a new, Inconel barrel nut per Part 3 of the Accomplishment Instructions of Boeing Service Bulletin 767-53-0085, dated May 14, 1998, or Boeing Alert Service Bulletin 767-53A0085, Revision 1, dated July 1, 1999. No further action is required for that barrel nut only.

(2) *For Group 1 airplanes:* If an H-11 steel alloy bolt is installed with the affected barrel nut, replace the bolt with a new, Inconel bolt per Figure 5 of the Accomplishment Instructions of the service bulletin. No further action is required for that bolt only.

Optional Terminating Actions

(d) *For all airplanes:* Except as provided by paragraph (e) of this AD, replacement of all 16 H-11 steel alloy barrel nuts that attach the vertical fin to body section 48, with new, Inconel barrel nuts per Part 3 of the Accomplishment Instructions of Boeing Service Bulletin 767-53-0085, dated May 14, 1998, or Boeing Alert Service Bulletin 767-53A0085, Revision 1, dated July 1, 1999; ends the repetitive inspections required by this AD.

(e) *For Group 1 airplanes:* Accomplishment of paragraph (d) of this AD and replacement of the H-11 steel alloy bolts having an Inconel barrel nut installed at the same location, with new, Inconel bolts per Figure 5 of the Accomplishment Instructions of Boeing Service Bulletin 767-53-0085, dated May 14, 1998, or Boeing Alert Service Bulletin 767-53A0085, Revision 1, dated July 1, 1999; ends the repetitive inspections required by this AD.

Spares

(f) *As of the effective date of this AD:* No person shall install, on any airplane, an Inconel vertical fin attach bolt, unless an Inconel barrel nut is installed at the same location; nor shall any person install an H-11 steel alloy attachment nut or bolt on the vertical fin on any airplane.

Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(i) The actions shall be done in accordance with Boeing Service Bulletin 767-53-0085, dated May 14, 1998; or Boeing Alert Service Bulletin 767-53A0085, Revision 1, dated July 1, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(j) This amendment becomes effective on October 9, 2001.

Issued in Renton, Washington, on September 14, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 01-23418 Filed 9-20-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 01-ASO-11]

Amendment of Class D Airspace; Titusville, FL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action makes a technical amendment to the Class D airspace description at Titusville, FL, by changing the name of the Titusville, Space Center Executive Airport to the

Titusville, Space Coast Regional Airport.

EFFECTIVE DATE: 0901 UTC, December 27, 2001.

FOR FURTHER INFORMATION CONTACT: Walter R. Cochran, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5627.

SUPPLEMENTARY INFORMATION:

History

The Titusville, Space Center Executive Airport, FL, was renamed the Titusville, Space Coast Regional Airport on September 5, 1996. As a result, the Class D airspace legal description must be amended. This rule will become effective on the date specified in the **DATES** section. Since this action has no impact on users of the airspace in the vicinity of the Titusville, Space Coast Regional Airport, Titusville, FL, notice and public procedure under 5 U.S.C. 553(b) are unnecessary. Class D airspace designations for airspace areas extending upward from the surface of the earth are published in paragraph 5000 of FAA Order 7400.9H, dated September 1, 2000, and effective September 16, 2000, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designations listed in this document will be published subsequently in the Order.

The Rule

This amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) amends Class D airspace at Titusville, FL.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; EO 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389; 14 CFR 11.69.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9H, Airspace Designations and Reporting Points, dated September 1, 2000, and effective September 16, 2000, is amended as follows:

Paragraph 5000 Class D Airspace
* * * * *

ASO FL D Titusville, FL [REVISED]

Titusville, Space Coast Airport, FL
(Lat. 28°30'50"N, long. 80°47'58" W)

That airspace extending upward from the surface to and including 2,500 feet MSL within a 4-mile radius of Space Coast Regional Airport; excluding the portion within Restricted Area R-2934 when it is effective. This Class D airspace area is effective during the specific days and times established in advance by a Notice to Airmen. The effective days and times will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in College Park, Georgia, on September 7, 2001.

Wade T. Carpenter,

*Acting Manager, Air Traffic Division,
Southern Region.*

[FR Doc. 01-23565 Filed 9-20-01; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30268; Amdt. No. 2069]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard

Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference—approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

*For Purchase—*Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

*By Subscription—*Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form