(c) Within 100 hours TIS and thereafter at intervals not to exceed 100 hours TIS, visually inspect the outer surface of the flange for a crack using a light and a 10x or higher magnifying glass. If a crack is detected, replace the unairworthy hub assembly with an airworthy hub assembly before further flight.

(d) At intervals not to exceed 300 hours TIS, remove the drive plate and visually inspect the flange for a crack using a light and a 10x or higher magnifying glass. If a crack is detected, replace the unairworthy hub assembly with an airworthy hub assembly before

further flight.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (LAACO), FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, LAACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the LAACO.

(f) If any nut torque is below minimum torque and no hub assembly crack is found before disassembly inspection, after re-torque in accordance with the applicable maintenance manual, a special flight permit for one flight below 100 knots indicated airspeed may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can

be accomplished.

(g) The inspections and replacement, if necessary, shall be done in accordance with the Accomplishment Instructions, Part I, paragraph 2.A., steps (1) through (7); and Part II, paragraph 2.B., steps (1) through (6), (8), and (9), of MD Helicopter Inc. Service Bulletin SB900-072, dated December 10, 1999. The incorporation by reference of that document was previously approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of May 1, 2001 (66 FR 19383, April 16, 2001). Copies may be obtained from MD Helicopters Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9734, telephone 1-800-388-3378, fax (480) 891-6782, or on the web at www.mdhelicopters.com. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office

of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective on June 19, 2002.

Issued in Fort Worth, Texas, on May 2, 2002.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 02–12051 Filed 5–14–02; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF THE INTERIOR

Bureau of Indian Affairs

25 CFR Part 900 RIN 1076-AE30

Contracts Under the Indian Self-Determination and Education Assistance Act; Change of Address for the Office of Hearings and Appeals

AGENCY: Bureau of Indian Affairs, Interior.

ACTION: Final rule; change of address.

SUMMARY: The Bureau of Indian Affairs is revising its regulations governing contracts under the Indian Self-Determination and Education Assistance Act to reflect a change of address for the Department of Interior's Office of Hearing and Appeals (OHA).

DATES: This rule is effective May 15, 2002.

FOR FURTHER INFORMATION CONTACT:

Mitchell Chouteau, Program Analyst, Office of Administration, Bureau of Indian Affairs, Department of the Interior, 1849 C Street, NW, MS 4656 MIB, Washington, DC 20240, telephone 202–208–2675.

SUPPLEMENTARY INFORMATION:

I. Background

Regulations promulgated by the Department of the Interior to govern the administration of contracts under the Indian Self-Determination and Education Assistance Act reference an address for the Office of Hearings and Appeals (OHA). Since February 2002, this Office has moved to a new address within the same city of Arlington, Virginia. This action references the new street address.

II. Procedural Requirements

A. Determination To Issue Final Rule Effective in Less than 30 Days

BIA has determined that the public notice and comment provisions of the Administrative Procedure Act, 5 U.S.C. 553(b), do not apply to this rulemaking. The changes being made relate solely to matters of agency organization, procedure and practice. They therefore satisfy the exemption from notice and comment in 5 U.S.C. 553(b)(A).

B. Review Under Procedural Statutes and Executive Orders

BIA has reviewed this rule under the following statutes and Executive Orders governing rulemaking procedures: the Unfunded Mandates Reform Act of 1995, 2 U.S.C. 1501 et sea.: the Regulatory Flexibility Act. 5 U.S.C. 601 et seq.; the Small Business Regulatory Enforcement Fairness Act of 1996, 5 U.S.C. 801 et seq.; the Paperwork Reduction Act, 44 U.S.C. 3501 et seq.; Executive Order 12630 (Takings); Executive Order 12866 (Regulatory Planning and Review); Executive Order 12988 (Civil Justice Reform); Executive Order 13132 (Federalism); Executive Order 13175 (Tribal Consultation); and Executive Order 13211 (Energy Impacts). BIA has determined that this rule does not trigger any of the procedural requirements of those statutes and Executive Orders, since this rule merely changes the street address for OHA.

List of Subjects in 25 CFR Part 900

Administrative practice and procedure, Buildings and facilities, Claims, Government contracts, Government property management, Grant programs—Indians, Health care, Indians, Indians—business and finance.

For the reasons stated in the preamble, BIA amends its regulations in 25 CFR part 900 as follows:

PART 900—[AMENDED]

1. The authority citation for part 900 continues to read as follows:

Authority: 25 U.S.C. 450f et seq.

2. In part 900 revise "4015 Wilson Boulevard" to read "801 North Quincy Street" everywhere it appears.

Dated: May 3, 2002.

Neal A. McCaleb,

Assistant Secretary—Indian Affairs.
[FR Doc. 02–12080 Filed 5–14–02; 8:45 am]
BILLING CODE 4310–RK–P