

**Corrective Action**

(h) If any damage is detected during any inspection required by this AD, prior to further flight, replace the damaged fuel pump or fuel pump canister with a new or serviceable part in accordance with Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999; or Airbus Service Bulletin A300-28-6061, Revision 04, dated August 1, 2002.

**Modification**

(i) Within 18 months after December 20, 2004 (the effective date of AD 2004-23-08): Modify the canisters of the center tank fuel pumps (including an operational test) by doing all the actions in accordance with paragraphs 3.A., 3.B., 3.C., and 3.D. of the Accomplishment Instructions of Airbus Service Bulletin A300-28-6069, dated September 4, 2001; Revision 01, dated May 28, 2002; or Revision 02, dated October 17, 2003. After the effective date of this AD, Revision 02 of the service bulletin must be used for accomplishing the modification. Accomplishing this modification ends the repetitive inspections required by paragraph (g) of this AD.

**New Requirements of This AD****One-Time Inspection/Replacement if Necessary**

(j) For airplanes on which Airbus Service Bulletin A300-28-6069, dated September 4, 2001; or Revision 01, dated May 28, 2002, has been accomplished before the effective date of this AD: Within 18 months after the effective date of this AD, perform a one-time detailed inspection of the attachment bolts of the outlet flange of the canisters of the center tank fuel pumps for bolts that are too short and do not protrude through the nut, and

replace the bolts as applicable, by doing all the actions in accordance with paragraphs 3.A., 3.B., 3.C., 3.D., and 3.E. of the Accomplishment Instructions of Airbus Service Bulletin A300-28-6087, dated April 8, 2005. Do any applicable bolt replacement before further flight.

**Note 2:** Airplanes modified in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-28-6069, Revision 02, dated October 17, 2003, are not subject to the requirements of paragraph (j) of this AD.

**Alternative Methods of Compliance (AMOCs)**

(k)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) AMOCs approved previously in accordance with AD 2004-23-08 are approved as AMOCs for the corresponding provisions of this AD.

**Related Information**

(l) French airworthiness directive F-2005-147, dated August 17, 2005, also addresses the subject of this AD.

**Material Incorporated by Reference**

(m) You must use the service bulletins specified in Table 1 of this AD, as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Airbus Service Bulletin A300-28-6069, dated September 4, 2001; Airbus Service Bulletin A300-28-6069, Revision 02, dated October 17, 2003; and Airbus Service Bulletin A300-28-6087, dated April 8, 2005, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On December 20, 2004 (69 FR 65528, November 15, 2004), the Director of the Federal Register approved the incorporation by reference of Airbus Service Bulletin A300-28-6069, Revision 01, dated May 28, 2002; and Airbus Service Bulletin A300-28-6061, Revision 04, dated August 1, 2002.

(3) On February 8, 2000 (65 FR 213, January 4, 2000), the Director of the Federal Register approved the incorporation by reference of Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999.

(4) On December 28, 1998 (63 FR 70639, December 22, 1998), the Director of the Federal Register approved the incorporation by reference of Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998.

(5) Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

TABLE 1.—MATERIAL INCORPORATED BY REFERENCE

| Airbus service information                       | Revision level | Date               |
|--|----------------|--------------------|
| Airbus Alert Service Bulletin A300-28A6061 ..... | Original ..... | February 19, 1999. |
| Airbus All Operators Telex 28-09 .....           | Original ..... | November 28, 1998. |
| Airbus Service Bulletin A300-28-6061 .....       | 04 .....       | August 1, 2002.    |
| Airbus Service Bulletin A300-28-6069 .....       | Original ..... | September 4, 2001. |
| Airbus Service Bulletin A300-28-6069 .....       | 01 .....       | May 28, 2002.      |
| Airbus Service Bulletin A300-28-6069 .....       | 02 .....       | October 17, 2003.  |
| Airbus Service Bulletin A300-28-6087 .....       | Original ..... | April 8, 2005.     |

Issued in Renton, Washington, on May 11, 2006.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate,  
Aircraft Certification Service.*

[FR Doc. 06-4675 Filed 5-22-06; 8:45 am]

BILLING CODE 4910-13-P

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2005-22146; Directorate Identifier 2002-NM-184-AD; Amendment 39-14606; AD 2006-11-02]**

**RIN 2120-AA64**

**Airworthiness Directives; Viking Air Limited Model DHC-7 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Viking Air Limited Model DHC-7 airplanes. This AD requires implementing a corrosion prevention and control program (CPCP) either by accomplishing specific tasks or by revising the maintenance inspection program to include a CPCP. This AD results from a determination that, as airplanes age, they are more likely to exhibit indications of corrosion. We are issuing this AD to prevent structural failure of the airplane due to corrosion.

**DATES:** This AD becomes effective June 27, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of June 27, 2006.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Viking Air Limited, 9574 Hampden Road, Sidney, British Columbia V8L 5V5, Canada, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Jon Hjelm, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7323; fax (516) 794-5531.

#### **SUPPLEMENTARY INFORMATION:**

#### **Examining the Docket**

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

#### **Discussion**

The FAA issued a supplemental notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all Bombardier Model DHC-7 airplanes. That supplemental NPRM was published in the **Federal Register** on March 27, 2006 (71 FR 15063). That supplemental NPRM proposed to require implementing a corrosion prevention and control program (CPCP) either by accomplishing specific tasks or by revising the maintenance inspection program to include a CPCP.

#### **Comments**

We provided the public the opportunity to participate in the development of this AD. No comments have been received on the supplemental NPRM or on the determination of the cost to the public.

#### **Explanation of Changes to the Supplemental NPRM**

We have revised the applicability of the supplemental NPRM to identify model designations as published in the most recent type certificate data sheet for the affected models.

We have also revised the contact name/address for the service

information to that of the current type certificate holder.

#### **Conclusion**

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

#### **Costs of Compliance**

This AD will affect about 26 airplanes of U.S. registry. The 148 specific inspections specified in the de Havilland Dash 7, Corrosion Prevention and Control Manual, Product Support Manual (PSM) 1-7-5, dated May 13, 1997, will take about 48 work hours per airplane, per inspection cycle, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the AD for U.S. operators is \$81,120, or \$3,120 per airplane, per inspection cycle.

#### **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### **Regulatory Findings**

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866;

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

#### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### **Adoption of the Amendment**

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### **PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2006-11-02 Viking Air Limited (Formerly Bombardier, Inc.):** Amendment 39-14606. Docket No. FAA-2005-22146; Directorate Identifier 2002-NM-184-AD.

#### **Effective Date**

(a) This AD becomes effective June 27, 2006.

#### **Affected ADs**

(b) None.

#### **Applicability**

(c) This AD applies to all Viking Air Limited Model DHC-7-1, DHC-7-100, DHC-7-101, DHC-7-102, and DHC-7-103 airplanes, certificated in any category.

#### **Unsafe Condition**

(d) This AD results from a determination that, as airplanes age, they are more likely to exhibit indications of corrosion. We are issuing this AD to prevent structural failure of the airplane due to corrosion.

#### **Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### **Manual References**

(f) The term "the Manual," as used in this AD, means the de Havilland Dash 7, Corrosion Prevention and Control Manual,

Product Support Manual (PSM) 1–7–5, dated May 13, 1997.

#### Approval of Information Collection Requirements

(g) Information collection requirements in paragraphs (l) and (m) of this AD are approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and are assigned OMB Control Number 2120–0056.

#### Initial Inspections

(h) Within 12 months after the effective date of this AD, perform each of the Corrosion Tasks, including re-protection actions, as applicable, specified in Part 3 of the Manual by accomplishing the basic tasks defined in Parts 2 and 3 of the Manual, in accordance with the procedures of the Manual.

#### Repetitive Inspections

(i) Except as provided by paragraph (j) of this AD, repeat each of the Corrosion Tasks, and re-protection actions, as applicable, specified in Part 3 of the Manual at intervals not to exceed 3 or 6 years, as specified in Part 3 of the Manual.

(j) After accomplishment of each initial Corrosion Task required by paragraph (h) of this AD, the FAA may approve the incorporation into the operator's approved maintenance/inspection program of the Corrosion Prevention and Control Program (CPCP) specified in the Manual and this AD; or an equivalent program that is approved by the FAA. In all cases, the initial Corrosion Task for each airplane area must be completed at the compliance time specified in paragraph (h) of this AD.

(1) Any operator complying with paragraph (j) of this AD may use an alternative recordkeeping method to that otherwise required by section 91.417 ("Maintenance records") or section 121.380 ("Maintenance recording requirements") of the Federal Aviation Regulations (14 CFR 91.417 or 14 CFR 121.380, respectively) for the actions required by this AD, provided that the recordkeeping method is approved by the FAA and is included in a revision to the FAA-approved maintenance/inspection program. For the purposes of this paragraph, the FAA is defined as the cognizant Flight Standards District Office.

(2) After the initial accomplishment of the Corrosion Tasks required by paragraph (h) of this AD, any extension of the repetitive intervals specified in the Manual must be approved by the FAA. For the purposes of this paragraph, the FAA is defined as the Manager, New York Aircraft Certification Office (ACO), FAA.

#### Corrective Actions

(k) If any corrosion is found during accomplishment of any action required by paragraph (h) or (i) of this AD: Within 30 days after the finding; rework, repair, or replace, as applicable, any subject part, in accordance with Section 4.0 of Part 3 of the Manual.

#### Reporting Requirements and Repetitive Actions for Remainder of Affected Fleet

(l) If any Level 3 corrosion, as defined in the Introduction of the Manual, is found during accomplishment of any action required by this AD: Do paragraphs (l)(1), (l)(2), and (l)(3) of this AD.

(1) Within 10 days after the finding of Level 3 corrosion, submit a report of the findings to the Manager, New York Aircraft Certification Office (ACO), FAA, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; fax (516) 794–5531. The report must follow the format specified in Section 5.0 of Part 3 of the Manual, or be submitted using a Service Difficulty Report, as applicable.

(2) Within 10 days after the finding of Level 3 corrosion, submit a plan to the FAA to identify a schedule for accomplishing the applicable Corrosion Task on the remainder of the airplanes in the operator's fleet that are subject to this AD, or data substantiating that the Level 3 corrosion that was found is an isolated case. The FAA may impose a schedule other than proposed in the plan upon finding that a change to the schedule is needed to ensure that any other Level 3 corrosion is detected in a timely manner. For the purposes of this paragraph, the FAA is defined as the cognizant Principal Maintenance Inspector (PMI) for operators that are assigned a PMI (e.g., part 121, 125, and 135 operators), and the cognizant Flight Standards District Office for other operators (e.g., part 91 operators).

(3) Within the time schedule approved in accordance with paragraph (l)(2) of this AD, accomplish the applicable Corrosion Task on the remainder of the airplanes in the operator's fleet that are subject to this AD.

(m) If any Level 2 or 3 corrosion, as defined in the Introduction of the Manual, is found during accomplishment of any action required by this AD: At the applicable time specified in Section 5.0 of Part 3 of the Manual, report these findings to the manufacturer according to Section 5.0 of Part 3 of the Manual.

#### Limiting Future Corrosion Findings

(n) If corrosion findings that exceed Level 1 are found in any area during any repeat of any Corrosion Task after the initial accomplishment required by paragraph (h) of this AD: Within 60 days after such finding, implement a means approved by the FAA to reduce future findings of corrosion in that area to Level 1 or better. For the purposes of this paragraph, the FAA is defined as the cognizant Principal Maintenance Inspector (PMI) for operators that are assigned a PMI (e.g., part 121, 125, and 135 operators), and the cognizant Flight Standards District Office for other operators (e.g., part 91 operators).

#### Scheduling Corrosion Tasks for Transferred Airplanes

(o) Before any airplane subject to this AD is transferred and placed into service by an operator: Establish a schedule for accomplishing the Corrosion Tasks required by this AD in accordance with paragraph (o)(1) or (o)(2) of this AD, as applicable.

(1) For airplanes on which the Corrosion Tasks required by this AD have been

accomplished previously at the schedule established by this AD: Perform the first Corrosion Task in each area in accordance with the previous operator's schedule, or in accordance with the new operator's schedule, whichever results in an earlier accomplishment of that Corrosion Task. After the initial accomplishment of each Corrosion Task in each area as required by this paragraph, repeat each Corrosion Task in accordance with the new operator's schedule.

(2) For airplanes on which the Corrosion Tasks required by this AD have not been accomplished previously, or have not been accomplished at the schedule established by this AD: The new operator must perform the initial accomplishment of each Corrosion Task in each area before further flight or in accordance with a schedule approved by the FAA. For the purposes of this paragraph, the FAA is defined as the cognizant PMI for operators that are assigned a PMI (e.g., part 121, 125, and 135 operators), and the cognizant Flight Standards District Office for other operators (e.g., part 91 operators).

#### Alternative Methods of Compliance (AMOCs)

(p)(1) The Manager, New York ACO, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

#### Related Information

(q) Canadian airworthiness directive CF–98–03, dated February 27, 1998, also addresses the subject of this AD.

#### Material Incorporated by Reference

(r) You must use de Havilland Dash 7, Corrosion Prevention and Control Manual, Product Support Manual 1–7–5, dated May 13, 1997, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. (Page number 64 containing Figure 21 is actually the 66th page of the document; the page number is incorrect.) Contact Viking Air Limited, 9574 Hampden Road, Sidney, British Columbia V8L 5V5, Canada, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL–401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741–6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on May 15, 2006.

**Kevin M. Mullin,**

*Acting Manager, Transport Airplane  
Directorate, Aircraft Certification Service.*

[FR Doc. 06-4677 Filed 5-22-06; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2003-NE-12-AD; Amendment  
39-14609; AD 2006-11-05]

**RIN 2120-AA64**

#### **Airworthiness Directives; Rolls-Royce plc RB211 Series Turbofan Engines**

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding an existing airworthiness directive (AD) for Rolls-Royce plc (RR) RB211-22B series, RB211-524B, -524C2, -524D4, -524G2, -524G3, and -524H series, and RB211-535C and -535E series turbofan engines with high pressure compressor (HPC) stage 3 disc assemblies, part numbers (P/Ns) LK46210, LK58278, LK67634, LK76036, UL11706, UL15358, UL22577, UL22578, and UL24738 installed. This AD requires removing from service certain disc assemblies before they reach their full published life if not modified with anticorrosion protection. This AD results from the manufacturer's reassessment of the corrosion risk on HPC stage 3 disc assemblies that have not yet been modified with sufficient application of anticorrosion protection. We are issuing this AD to prevent corrosion-induced uncontained disc failure, resulting in damage to the airplane.

**DATES:** This AD becomes effective June 27, 2006. The Director of the Federal Register previously approved the incorporation by reference of certain publications listed in the regulations as of February 24, 2004 (69 FR 2661, January 20, 2004).

**ADDRESSES:** You can get the service information identified in this AD from Rolls-Royce plc, P.O. Box 31, Derby, England, DE248BJ; telephone: 011-44-1332-242424; fax: 011-44-1332-245-418.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, at the FAA, New England Region, Office of

the Regional Counsel, 12 New England Executive Park, Burlington, MA.

**FOR FURTHER INFORMATION CONTACT:** Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park; Burlington, MA 01803; telephone (781) 238-7178; fax (781) 238-7199.

**SUPPLEMENTARY INFORMATION:** We proposed to amend 14 CFR Part 39 with a proposed AD. The proposed AD applies to RR RB211-22B series, RB211-524B, -524C2, -524D4, -524G2, -524G3, and -524H series, and RB211-535C and -535E series turbofan engines with HPC stage 3 disc assemblies, P/Ns LK46210, LK58278, LK67634, LK76036, UL11706, UL15358, UL22577, UL22578, and UL24738 installed. We published the proposed AD in the **Federal Register** on July 28, 2005 (70 FR 43659). That action proposed to require removing from service certain disc assemblies before they reach their full published life if not modified with anticorrosion protection.

#### **Examining the AD Docket**

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

#### **Comments**

We provided the public the opportunity to participate in the development of this AD. We received no comments on the proposal or on the determination of the cost to the public.

#### **Conclusion**

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

#### **Costs of Compliance**

We estimate that this AD will affect 1,000 engines installed on airplanes of U.S. registry. We also estimate that it will take about 31 workhours per engine to perform the actions, and that the average labor rate is \$65 per workhour. Required parts will cost about \$38,000 per engine. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$40,015,000.

#### **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### **Regulatory Findings**

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-12-AD" in your request.

#### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### **Adoption of the Amendment**

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

#### **PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by removing Amendment 39-13434 (69 FR