

Proposed Rules

Federal Register

Vol. 69, No. 19

Thursday, January 29, 2004

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF ENERGY

10 CFR Part 300

RIN 1901-AB11

General Guidelines for Voluntary Greenhouse Gas Reporting

AGENCY: Office of Policy and International Affairs, Department of Energy.

ACTION: Proposed rule; extension of comment period.

SUMMARY: On December 5, 2003, the Department of Energy published a Notice of Proposed Rulemaking (68 FR 68204) to revise the General Guidelines governing the Voluntary Reporting of Greenhouse Gases Program established by Section 1605(b) of the Energy Policy Act of 1992. The notice announced that the closing date for receiving public comments would be February 3, 2004. Several organizations requested that the comment period be extended to allow additional time for understanding and preparing written comments on the proposed revisions to the General Guidelines. The Department has agreed to extend the comment period to February 17, 2004. In addition, the Department intends, subsequently, to publish for comment a supplemental notice of proposed revised General Guidelines, simultaneously with the publication for public comment of planned Technical Guidelines.

DATES: Comments must be received on or before February 17, 2004.

ADDRESSES: Please submit written comments to: *1605bgeneralguidelines.comments@hq.doe.gov*. Alternatively, written comments may be sent to: Mark Friedrichs, PI-40; Office of Policy and International Affairs; U.S. Department of Energy; Room 1E190, 1000 Independence Ave., SW., Washington, DC 20585. You may review comments received by DOE, the record of the public workshop held on January 12, 2004, and other related material at the following Web site: <http://www.pi.energy.gov/enhancing>

GHGregistry/proposed guidelines/generalguidelines.html. If you lack access to the internet, you may access this website by visiting the DOE Freedom of Information Reading Room, 1000 Independence Avenue, SW., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mark Friedrichs, PI-40, Office of Policy and International Affairs, U.S. Department of Energy, 1000 Independence Ave., SW., Washington, DC 20585, or e-mail: *1605bgeneralguidelines.comments@hq.doe.gov* [Please indicate if your e-mail is a request for information, rather than a public comment.]

Issued in Washington, DC, on January 23, 2004.

Robert G. Card,

Under Secretary for Energy, Science and Environment.

[FR Doc. 04-1922 Filed 1-28-04; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NM-63-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A319, A320, and A321 series airplanes. This proposal would require replacement of a certain transformer rectifier unit (TRU) with a certain new TRU. This action is necessary to prevent ignition of the input filter capacitors of the TRU in position 2 of the avionics compartment, which could potentially result in smoke in the cockpit. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by March 1, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation

Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-63-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2003-NM-63-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2003-NM-63-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-63-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A319, A320, and A321 series airplanes. The DGAC advises that it has received reports of smoke and/or smoke smells in the cockpit. Investigation revealed that ignition of the input filter capacitors of the transformer rectifier unit (TRU) in position 2 of the avionics compartment was the origin of the smoke generation. This condition, if not corrected, could potentially result in smoke in the cockpit.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A320-24-1099, Revision 02, dated February 11, 2003, which describes procedures for replacement of a certain TRU with a certain new TRU. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 2002-554(B), dated November 13, 2002, to ensure the continued airworthiness of these airplanes in France.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 553 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed actions, and that the average labor rate is \$65 per work hour. Required parts would be supplied by the airplane manufacturer at no cost to the operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$35,945, or \$65 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal

would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus: Docket 2003-NM-63-AD.

Applicability: Model A319, A320, and A321 series airplanes, certificated in any category; except those airplanes on which Airbus Modification 30737 has been accomplished in production (reference Airbus Service Bulletin A320-24-1099, Revision 02, dated February 11, 2003, in service);

Compliance: Required as indicated, unless accomplished previously.

To prevent ignition of the input filter capacitors of the transformer rectifier unit (TRU) in position 2 of the avionics compartment, which could potentially result in smoke in the cockpit, accomplish the following:

Replacement

(a) Prior to the accumulation of 15,000 total flight hours, or within 16 months after the effective date of this AD, whichever occurs later, replace the TRU, part number Y005-2, with a new TRU, part number Y005-3, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-24-1099, Revision 02, dated February 11, 2003.

(b) Replacements accomplished before the effective date of this AD per Airbus Service Bulletin A320-24-1099, dated March 5, 2002; or Revision 1, dated July 26, 2002; are considered acceptable for compliance with the corresponding action specified in this AD.

Parts Installation

(c) As of the effective date of this AD no person shall install a TRU, part number Y005-2, within position 2 of the avionics compartment on any airplane.

Alternative Methods of Compliance

(d) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Note 1: The subject of this AD is addressed in French airworthiness directive 2002-544(B), dated November 13, 2002.

Issued in Renton, Washington, on January 21, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04-1908 Filed 1-28-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NM-153-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-7-100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to revise an existing airworthiness directive (AD), applicable to all Bombardier Model DHC-7-100 series airplanes, that currently requires repetitive high frequency eddy current inspections to detect cracks on the locking pin fittings of the baggage door and locking pin housings of the fuselage; repetitive detailed inspections to detect cracks of the inner door structure on all four door locking attachment fittings; and corrective actions, if necessary. In lieu of accomplishing the corrective actions, that amendment also provides a temporary option, for certain cases, for revising the Airplane Flight Manual (AFM), and installing a placard. That AD was prompted by issuance of mandatory continuing airworthiness information by a foreign civil

airworthiness authority. The actions specified by that AD are intended to detect and correct fatigue cracking of the baggage door fittings and the support structure, which could result in structural failure, and consequent rapid decompression of the airplane during flight. This action would extend the compliance time of the repetitive inspections based on test evidence and is intended to address the identified unsafe condition.

DATES: Comments must be received by March 1, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-153-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2003-NM-153-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Westbury, New York.

FOR FURTHER INFORMATION CONTACT: David Lawson, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Westbury, New York 11590; telephone (516) 228-7327; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date

for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2003-NM-153-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-153-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On January 20, 2000, the FAA issued AD 2000-02-07, amendment 39-11526 (65 FR 4354, January 27, 2000), applicable to all Bombardier Model DHC-7-100 series airplanes, to require repetitive high frequency eddy current inspections to detect cracks on the locking pin fittings of the baggage door and locking pin housings of the fuselage; repetitive detailed inspections to detect cracks of the inner door structure on all four door locking attachment fittings; and corrective actions, if necessary. In lieu of accomplishing the corrective actions, that amendment also provides a temporary option, for certain cases, for revising the Airplane Flight Manual (AFM), and installing a placard. That action was prompted by issuance of mandatory continuing airworthiness