

No Report Required

(k) Although the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2451, including Appendix A, dated October 5, 2000; and Boeing Alert Service Bulletin 747-53A2451, Revision 1, dated November 10, 2005; describe procedures for reporting certain information to the manufacturer, this AD does not require that report.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

(4) AMOCs approved previously in accordance with AD 2001-14-22, are approved as AMOCs for the corresponding provisions of paragraphs (f) and (j) of this AD.

(5) AMOCs approved previously in accordance with AD 2006-12-12, are approved as alternative methods of compliance with this AD.

Issued in Renton, Washington, on April 19, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-7978 Filed 4-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-28017; Directorate Identifier 2007-NM-005-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A310-203, A310-204, A310-222, A310-304, A310-322, and A310-324 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the

products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

* * * some structural areas have been identified for which existing recommended SB (service bulletin) needs to be rendered mandatory.

As a consequence, and because it has been shown that the torque applied to the tension bolts connecting the beam (stringer 49) to the forward and aft beam extension at FR11 and FR17 may be insufficient, this AD renders mandatory the replacement of those tension bolts, in order to limit the risks of damage or corrosion of the specified areas.

Damage or corrosion of the specified areas could result in reduced structural integrity of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by May 29, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- *Fax:* (202) 493-2251.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.
- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington

98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Streamlined Issuance of AD**

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-28017; Directorate Identifier 2007-NM-005-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2006-0367, dated December 5, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During the A310 life extension exercise performed by Airbus, the Airlines Representatives and the Airworthiness Authorities, some structural areas have been identified for which existing recommended SB (service bulletin) needs to be rendered mandatory.

As a consequence, and because it has been shown that the torque applied to the tension bolts connecting the beam (stringer 49) to the forward and aft beam extension at FR11 and FR17 may be insufficient, this AD renders mandatory the replacement of those tension bolts, in order to limit the risks of damage or corrosion of the specified areas.

Damage or corrosion of the specified areas could result in reduced structural integrity of the airplane. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Airbus has issued Service Bulletin A310–53–2045, Revision 05, dated July 20, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 29 products of U.S. registry. We also estimate that it would take about 9 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$886 per

product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$46,574, or \$1,606 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

AIRBUS: Docket No. FAA–2007–28017; Directorate Identifier 2007–NM–005–AD.

Comments Due Date

- (a) We must receive comments by May 29, 2007.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Airbus Model A310–203, A310–204, A310–222, A310–304, A310–322, and A310–324 airplanes, certificated in any category, manufacturing serial numbers 283 through 434 inclusive. Airplanes which have received application of Airbus Service Bulletin A310–53–2045 at original issue up to Revision 05 are not affected by this AD.

Subject

- (d) Fuselage.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

During the A310 life extension exercise performed by Airbus, the Airlines Representatives and the Airworthiness Authorities, some structural areas have been identified for which existing recommended SB (service bulletin) needs to be rendered mandatory.

As a consequence, and because it has been shown that the torque applied to the tension bolts connecting the beam (stringer 49) to the forward and aft beam extension at FR11 and FR17 may be insufficient, this AD renders mandatory the replacement of those tension bolts, in order to limit the risks of damage or corrosion of the specified areas.

Damage or corrosion of the specified areas could result in reduced structural integrity of the airplane.

Actions and Compliance

- (f) Unless already done, do the following actions at the applicable time specified in paragraph (f)(1) or (f)(2) of this AD: Rework the structure between frame 11 and frame 17 of the nose landing gear well of the fuselage in accordance with the instructions of Airbus Service Bulletin A310–53–2045, Revision 05, dated July 20, 2006.

(1) For Model A310–300 airplanes: Prior to accumulation of 35,000 total flight cycles from first flight of the airplane, or within 30 days after the effective date of this AD, whichever occurs later.

(2) For Model A310-200 airplanes: Prior to the accumulation of 40,000 total flight cycles from the first flight of the airplane, or within 30 days after the effective date of this AD, whichever occurs later.

(3) Actions done before the effective date of this AD in accordance with Airbus Service Bulletin A310-53-2045, dated March 11, 1988; Revision 1, dated June 16, 1988; Revision 2, dated September 7, 1988; Revision 3, dated October 4, 1989; or Revision 4, dated April 20, 1990; is acceptable for compliance with the requirements of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *ATTN:* Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149. Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2006-0367, dated December 5, 2006; and Airbus Service Bulletin A310-53-2045, Revision 05, dated July 20, 2006; for related information.

Issued in Renton, Washington, on April 19, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-7998 Filed 4-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2007-27850; Airspace Docket No. 07-ASO-5]

RIN 2120-AA66

Proposed Amendment to Restricted Areas R-3702A and R-3702B Fort Campbell, KY

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend the designated altitudes of restricted areas R-3702A and R-3702B, Fort Campbell, KY, to better accommodate training requirements and provide greater access to the airspace for nonparticipating aircraft flying through the area above 10,000 feet MSL.

DATES: Comments must be received on or before June 11, 2007.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify FAA Docket No. FAA-2007-27850 and Airspace Docket No. 07-ASO-05, at the beginning of your comments. You may also submit comments through the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace and Rules Group, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2007-27850 and Airspace Docket No. 07-ASO-05) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for

address and phone number). You may also submit comments through the Internet at <http://dms.dot.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2007-27850 and Airspace Docket No. 07-ASO-05." The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the **Federal Register's** Web page at <http://www.gpoaccess.gov/fr/index.html>.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 1601 Lind Avenue, #14, SW., Renton, WA 98055.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

Background

R-3702A and R-3702B were established to contain a variety of hazardous activities involving both ground-based and aircraft weapons systems. Currently, R-3702A extends from ground level up to and including 6,000 feet MSL. R-3702B overlies R-3702A and extends from 6,000 feet MSL to Flight Level (FL) 220. A third subdivision, restricted area R-3702C,