

# Rules and Regulations

Federal Register

Vol. 68, No. 233

Thursday, December 4, 2003

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## FEDERAL HOUSING FINANCE BOARD

### 12 CFR Part 905

[No. 2003-09]

RIN 3069-AB25

#### Amendments to the Description of Organization and Functions Regulation; Correction

**AGENCY:** Federal Housing Finance Board.

**ACTION:** Final rule; correction.

**SUMMARY:** The Federal Housing Finance Board (Finance Board) is correcting a final rule that appeared in the **Federal Register** of June 27, 2003. That document revised the Finance Board's Description of Organization and Functions regulation to reflect agency reorganizations that already have taken effect. The document was published with an inadvertent error, which referenced § 905.15 as being revised rather than removed. This document corrects that error.

**DATES:** The rule was effective June 27, 2003.

**FOR FURTHER INFORMATION CONTACT:** Mary H. Gottlieb, Paralegal Specialist, Office of General Counsel, by telephone at 202/408-2826, by electronic mail at [gottlieb@fhfb.gov](mailto:gottlieb@fhfb.gov), or by regular mail at the Federal Housing Finance Board, 1777 F Street, NW., Washington, DC 20006.

**SUPPLEMENTARY INFORMATION:** In FR Doc. 03-16317, appearing in the **Federal Register** of Friday, June 27, 2003 (68 FR 38169), the following correction is made:

■ On page 38170, in the first column, amendatory instruction No. 6 is corrected to read as follows:

#### Subpart B—[Corrected]

■ 6. Amend Subpart B of part 905 by revising §§ 905.10 through 905.14, and

removing §§ 905.15 through 905.19 to read as follows:

Dated: November 17, 2003.

By the Federal Housing Finance Board.

**Arnold Intrater,**  
General Counsel.

[FR Doc. 03-30180 Filed 12-3-03; 8:45 am]

**BILLING CODE 6725-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2003-CE-28-AD; Amendment 39-13382; AD 2003-24-13]

RIN 2120-AA64

#### Airworthiness Directives; Cessna Aircraft Company Models 172R, 172S, 182S, 182T, T182T, 206H, and T206H Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA adopts a new airworthiness directive (AD) for certain Cessna Aircraft Company (Cessna) Models 172R, 172S, 182S, 182T, T182T, 206H, and T206H airplanes that are equipped with a Honeywell KAP 140 autopilot computer system installed on the center instrument control panel near the throttle. This AD requires you to install an update to the operating software of the KAP 140 autopilot computer system, change the unit's part number, and change the software modification identification tag. This AD is the result of reports of inadvertent and undetected engagement of the autopilot system. We are issuing this AD to prevent unintentionally engaging the KAP 140 autopilot computer system, which could cause the pilot to take inappropriate actions.

**DATES:** This AD becomes effective on January 20, 2004.

As of January 20, 2004, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

**ADDRESSES:** You may get the service information identified in this AD from Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277; telephone: (316) 517-5800; facsimile: (316) 942-9006 and

Honeywell, Business, Regional, and General Aviation, 23500 W. 105th Street, Olathe, Kansas 66061.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-28-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays. **FOR FURTHER INFORMATION CONTACT:** Dan Withers, Aerospace Engineer, Wichita Aircraft Certification Office (ACO), FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4196; facsimile: (316) 946-4407.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

*What events have caused this AD? We have received reports of an unsafe condition on certain Cessna Models 172R, 172S, 182S, 182T, T182T, 206H, and T206H airplanes that are equipped with a Honeywell KAP 140 autopilot computer system.*

The KAP 140 autopilot computer system is located on the lower portion of the center instrument control panel near the throttle on these Cessna airplanes. Because of this location on the instrument control panel of the affected Cessna airplanes, the Autopilot Engage (AP) button could unintentionally be depressed when the pilot pushes the throttle knob forward. The pilot could also unintentionally engage the autopilot system by inadvertently bumping the Heading (HDG) button, Altitude (ALT) mode-select button, or Autopilot Engage (AP) button on the KAP 140 computer. Unless intentionally engaged, the pilot does not know that the autopilot system is engaged.

The Honeywell KAP 140 autopilot computer system is also installed in the New Piper, Inc. Model PA-28-181 airplanes. This AD does not affect these airplanes because of the location of the equipment. The equipment is installed on the center instrument panel near the throttle on the affected airplanes, but is installed in the upper half of the instrument control panel on the Piper airplanes. The unsafe condition only exists on the Cessna airplanes.

Honeywell has updated the operating software for the KAP 140 autopilot computer system, which will now only allow the AP button on the instrument