

Proposed Rules

Federal Register

Vol. 68, No. 88

Wednesday, May 7, 2003

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NE-08-AD]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc RB211 Trent 800 Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for Rolls-Royce plc (RR) RB211 Trent 875-17, Trent 877-17, Trent 884-17, Trent 892-17, Trent 892B-17, and Trent 895-17 turbofan engines with intermediate pressure (IP) turbine discs, part numbers (P/Ns) FK21117 and FK33083 installed. This proposed AD would require removal from service of these IP turbine discs in accordance with newly established reduced turbine disc life limits. This proposed AD is prompted by reports of two IP turbine blade release incidents as a result of dust caps separating from the blades, and subsequent improved modeling analysis. The actions specified in this proposed AD are intended to prevent uncontained IP turbine disc failure and damage to the airplane.

DATES: We must receive any comments on this proposed AD by July 7, 2003.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD:

- Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-NE-08-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

- By fax: (781) 238-7055.

- By e-mail: 9-ane-adcomment@faa.gov.

You may examine the AD docket, by appointment, at the FAA, New England

Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT:

James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299, telephone (781) 238-7176; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-08-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. If a person contacts us through a nonwritten communication, and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You may get more information about plain language at <http://www.plainlanguage.gov>.

Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

Discussion

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom (U.K.), recently notified the FAA that an unsafe condition may exist on RR RB211 Trent

875-17, Trent 877-17, Trent 884-17, Trent 892-17, Trent 892B-17, and Trent 895-17 turbofan engines. The CAA advises that reports were received of two IP turbine blade release incidents as a result of dust caps separating from the blades. Subsequently, the manufacturer applied improved modeling techniques for analysis, which revealed higher than predicted operating temperatures at the IP turbine disc rim and surrounding area due to inflow of annulus exhaust gases. As a result of this analysis, the manufacturer has assigned new lower life limits of 8,600 cycles-since-new (CSN) for IP turbine disc P/N FK21117, and 3,000 CSN for IP turbine disc P/N FK33083.

FAA's Determination and Requirements of the Proposed AD

These RR RB211 Trent 875-17, Trent 877-17, Trent 884-17, Trent 892-17, Trent 892B-17, and Trent 895-17 turbofan engines, manufactured in the U.K., are type-certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept us informed of the situation described above. We have examined the CAA's findings, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States. Therefore, we are proposing this AD, which would require replacing IP turbine discs, P/Ns FK21117 and FK33083, at or before reaching the new reduced life cycle limits of 8,600 CSN and 3,000 CSN respectively.

Changes to 14 CFR Part 39—Effect on the Proposed AD

On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

There are approximately 350 RR RB211 Trent 875-17, Trent 877-17,

Trent 884-17, Trent 892-17, Trent 892B-17, and Trent 895-17 turbofan engines of the affected design in the worldwide fleet. We estimate that 114 engines installed on airplanes of U.S. registry would be affected by this proposed AD. We also estimate that the prorated cost of the life reduction per engine would be approximately \$246,000. Based on these figures, the total cost of the proposed AD is estimated to be \$28,044,000.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposal and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-08-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Rolls-Royce plc: Docket No. 2003-NE-08-AD.

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this airworthiness directive (AD) action by July 7, 2003.

Affected ADs

- (b) None.

Applicability

(c) This AD is applicable to Rolls-Royce plc (RR) RB211 Trent 875-17, Trent 877-17, Trent 884-17, Trent 892-17, Trent 892B-17, and Trent 895-17 turbofan engines with intermediate pressure (IP) turbine discs P/Ns FK21117 and FK33083 installed. These engines are installed on, but not limited to Boeing 777 airplanes.

Unsafe Condition

(d) This AD was prompted by reports of two IP turbine blade release incidents as a result of dust caps separating from the blades. Subsequently, the manufacturer applied improved modeling techniques for analysis, which revealed higher than predicted operating temperatures at the IP turbine disc rim and surrounding area due to inflow of annulus exhaust gases. The actions specified in this AD are intended to prevent uncontained IP turbine disc failure and damage to the airplane.

Compliance

(e) Compliance with this AD is required as indicated, unless already done.

(f) To prevent uncontained IP turbine disc failure and damage to the airplane, do the following:

- (1) Remove IP turbine disc P/N FK21117 from service at or before accumulating 8,600 cycles-since-new (CSN), and remove IP turbine disc P/N FK33083 from service at or before accumulating 3,000 CSN.
- (2) After the effective date of this AD, do not install any IP turbine disc P/N FK21117, that exceeds 8,600 CSN, or any IP turbine disc P/N FK33083, that exceeds 3,000 CSN.

Alternative Methods of Compliance

(g) Alternative methods of compliance must be requested in accordance with 14 CFR part 39.19, and must be approved by the Manager, Engine Certification Office, Engine and Propeller Directorate, FAA.

Material Incorporated by Reference

- (h) None.

Related Information

(i) The subject of this AD is addressed in CAA airworthiness directive 002-01-2003, dated January 14, 2003.

Issued in Burlington, Massachusetts, on April 30, 2003.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. 03-11267 Filed 5-6-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

23 CFR Part 630

[FHWA Docket No. FHWA-2001-11130]

RIN 2125-AE29

Work Zone Safety and Mobility

AGENCY: Federal Highway Administration (FHWA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); request for comments.

SUMMARY: The FHWA proposes to amend its regulation that governs traffic safety in highway and street work zones. The FHWA recognizes that increasing road construction activity on our highways can lead to an increase in congestion and crashes, as well as loss in productivity and public frustration with work zones. These proposed changes are intended to facilitate consideration of the broader safety and mobility impacts of work zones in a more coordinated and comprehensive manner across project development stages.

DATES: Comments must be received on or before September 4, 2003.

ADDRESSES: Mail or hand deliver comments to the U.S. Department of Transportation, Dockets Management Facility, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590, or submit electronically at <http://dmses.dot.gov/submit>. All comments should include the docket number that appears in the heading of this document. All comments received will be available for examination and copying at the above address from 9 a.m. to 5 p.m., e.t., Monday through Friday, except Federal holidays. Those desiring notification of receipt of comments must include a self-addressed, stamped postcard or you may print the acknowledgment page that appears after submitting comments electronically. Anyone is able to search the electronic form of all comments received into any of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (Volume 65, Number 70, Pages 19477-78) or you may visit <http://dms.dot.gov>

FOR FURTHER INFORMATION CONTACT: Mr. Scott Battles, Office of Transportation Operations, HOTO-1, (202) 366-4372; or Mr. Raymond Cuprill, Office of the