

○ Evaluation of fuel tank system component qualification as a result of elevated fuel tank system temperatures. [§§ 23.1301, and 23.1309]

○ Evaluation of service/maintenance instructions, activities, and personnel due to elevated fuel tank system temperatures. [§ 23.1529].

Type Certification Basis

Under the provisions of § 21.101, Cessna Aircraft Company must show that the model 525C meets the applicable provisions of the regulations incorporated by reference in Type Certificate Number A1WI or the applicable regulations in effect on the date of application for the change to the model 525C. The regulations incorporated by reference in the type certificate are commonly referred to as the "original type certification basis." In addition, the certification basis includes exemptions, if any; equivalent level of safety findings, if any; and the special condition adopted by this rulemaking action.

If the Administrator finds that the applicable airworthiness regulations in 14 CFR part 23 do not contain adequate or appropriate safety standards for the model 525C because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

In addition to the applicable airworthiness regulations and special conditions, the model 525C must comply with the fuel vent and exhaust emission requirements of 14 CFR part 34 and the noise certification requirements of 14 CFR part 36.

Special conditions, as appropriate, as defined in § 11.19, are issued in accordance with § 11.38, and become part of the type certification basis in accordance with § 21.101(b)(2).

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same novel or unusual design feature, or should any other model already included on the same type certificate be modified to incorporate the same novel or unusual design feature, the special conditions would also apply to the other model under the provisions of § 21.101(a)(1).

Novel or Unusual Design Features

The model 525C will incorporate the following novel or unusual design features:

High Fuel Temperatures.

Discussion of Comments

A notice of proposed special conditions No. 23–09–03–SC for the Cessna Aircraft Company, model 525C airplanes was published on September 1, 2009, 74 FR 45133. No comments were received, and the special conditions are adopted as proposed.

Applicability

As discussed above, these special conditions are applicable to the model 525C. Should Cessna Aircraft Company apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, the special conditions would apply to that model as well under the provisions of § 21.101(a)(1).

Under standard practice, the effective date of final special conditions would be 30 days after the date of publication in the **Federal Register**; however, as the certification date for the Cessna Aircraft Company, model 525C is imminent, the FAA finds that good cause exists to make these special conditions effective upon issuance.

Conclusion

This action affects only certain novel or unusual design features on one model of airplanes. It is not a rule of general applicability, and it affects only the applicant who applied to the FAA for approval of these features on the airplane.

List of Subjects in 14 CFR Part 23

Aircraft, Aviation safety, Signs and symbols.

Citation

■ The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113 and 44701; 14 CFR 21.16 and 21.17; and 14 CFR 11.38 and 11.19.

The Special Conditions

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Cessna Aircraft Company, model 525C airplanes.

1. *SC § 23.961:*

Instead of compliance with § 23.961, the following apply:

Each fuel system must be free from vapor lock when using fuel at its critical temperature, with respect to vapor formation, when operating the airplane in all critical operating and environmental conditions for which approval is requested. For turbine fuel, the initial temperature must be 110 °F,

– 0°, +5 °F or the maximum outside air temperature for which approval is requested or the fuel tank system temperature that is determined to be more critical.

Issued in Kansas City, Missouri on December 16, 2009.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9–30436 Filed 12–22–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2009–1196; Directorate Identifier 2009–NM–170–AD; Amendment 39–16146; AD 2008–09–12 R1]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Model CL–600–2B19 (Regional Jet Series 100 & 440) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above that would revise an existing AD. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Bombardier Aerospace has completed a system safety review of the aircraft fuel system against fuel tank safety standards introduced in Chapter 525 of the Airworthiness Manual through Notice of Proposed Amendment (NPA) 2002–043. The identified non-compliances were then assessed using Transport Canada Policy Letter No. 525–001, to determine if mandatory corrective action is required.

The assessment showed that it is necessary to introduce Critical Design Configuration Control Limitations (CDCCL), in order to preserve critical fuel tank system ignition source prevention features during configuration changes such as modifications and repairs, or during maintenance actions. Failure to preserve critical fuel tank system ignition source prevention features could result in a fuel tank explosion. * * *

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective January 7, 2010.

On June 6, 2008 (73 FR 24147, May 2, 2008), the Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD.

We must receive comments on this AD by February 8, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: James Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7321; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

On April 18, 2008, we issued AD 2008-09-12, Amendment 39-15493 (73 FR 24147, May 2, 2008). That AD applied to all Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. That AD required revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness to include the critical design configuration control limitations (CDCCL) data.

CDCCLs are limitation requirements to preserve a critical ignition source prevention feature of the fuel tank system design that is necessary to prevent the occurrence of an unsafe condition. The purpose of a CDCCL is to provide instruction to retain the critical ignition source prevention feature during configuration change that may be caused by alterations, repairs, or maintenance actions. A CDCCL is not a periodic inspection.

Since we issued that AD, we have determined that it is necessary to clarify the AD's intended effect on spare and on-airplane fuel tank system components, regarding the use of maintenance manuals and instructions for continued airworthiness.

Section 91.403(c) of the Federal Aviation Regulations (14 CFR 91.403(c)) specifies the following:

No person may operate an aircraft for which a manufacturer's maintenance manual or instructions for continued airworthiness has been issued that contains an airworthiness limitation section unless the mandatory * * * procedures * * * have been complied with.

Some operators have questioned whether existing components affected by the new CDCCLs must be reworked. We did not intend for the AD to retroactively require rework of components that had been maintained using acceptable methods before the effective date of the AD. Owners and operators of the affected airplanes therefore are not required to rework affected components identified as airworthy or installed on the affected airplanes before the required revisions of the ALS. But once the CDCCLs are incorporated into the ALS, future maintenance actions on components must be done in accordance with those CDCCLs.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. This new AD retains the requirements of the existing AD, and adds a new note to clarify the intended effect of the AD on spare and on-airplane fuel tank system components. We have renumbered subsequent notes accordingly.

Explanation of Changes Made to This AD

We have revised this AD to identify the correct legal name of the manufacturer as published in the most recent type certificate data sheet for the affected airplane models.

Explanation of Additional Change to AD

AD 2008-09-12 allowed the use of alternative CDCCLs that are a part of "a later revision" of Appendix D, "Fuel System Limitations," of Part 2, "Airworthiness Requirements," Revision 7, dated May 10, 2007, of the Bombardier CL-600-2B19 Maintenance Requirements Manual CSP A-053. That provision has been removed from this AD. Allowing the use of "a later revision" of specific service documents violates Office of the Federal Register regulations for approving materials that are incorporated by reference. Affected operators, however, may request approval to use a later revision of the referenced service documents as an alternative method of compliance, under the provisions of paragraph (g) of this AD.

Differences Between the AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a Note within the AD.

Costs of Compliance

This revision imposes no additional economic burden. The current costs for this AD are repeated for the convenience of affected operators, as follows:

We estimate that this AD will affect about 700 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$56,000, or \$80 per product.

FAA's Justification and Determination of the Effective Date

This revision merely clarifies the intended effect on spare and on-airplane fuel tank system components, and makes no substantive change to the AD's requirements. For this reason, it is found that notice and opportunity for prior public comment for this action are unnecessary, and good cause exists for

making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-1196; Directorate Identifier 2009-NM-170-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 39-15493 (73 FR 24147, May 2, 2008) and adding the following new AD:

2008-09-12 R1 Bombardier, Inc. (Type Certificate previously held by Canadair): Amendment 39-16146. Docket No. FAA-2009-1196; Directorate Identifier 2009-NM-170-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective January 7, 2010.

Affected ADs

(b) This AD revises AD 2008-09-12, Amendment 39-15493.

Applicability

(c) This AD applies to all Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Bombardier Aerospace has completed a system safety review of the aircraft fuel system against fuel tank safety standards introduced in Chapter 525 of the Airworthiness Manual through Notice of Proposed Amendment (NPA) 2002-043. The identified non-compliances were then assessed using Transport Canada Policy Letter No. 525-001, to determine if mandatory corrective action is required.

The assessment showed that it is necessary to introduce Critical Design Configuration Control Limitations (CDCCL), in order to preserve critical fuel tank system ignition source prevention features during configuration changes such as modifications and repairs, or during maintenance actions. Failure to preserve critical fuel tank system ignition source prevention features could result in a fuel tank explosion. Revision has been made to Canadair Regional Jet Model CL-600-2B19 Maintenance Requirements Manual, CSP A-053, Part 2, Appendix D, "Fuel System Limitations" to introduce the required CDCCL.

The corrective action is revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness to include the CDCCL data.

Restatement of Requirements of AD 2008-09-12, With Revised Compliance Method Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 60 days after June 6, 2008 (the effective date AD 2008-09-12), revise the ALS of the Instructions for Continued Airworthiness to include the CDCCLs specified in Canadair Temporary Revision (TR) 2D-2, dated March 31, 2006, to Appendix D, "Fuel System Limitations," of Part 2, "Airworthiness Requirements," of the Bombardier CL-600-2B19 Maintenance Requirements Manual CSP A-053.

Note 1: The revision required by paragraph (f)(1) of this AD may be done by inserting a copy of the TR into the maintenance requirements manual. When the TR has been included in the general revision of the maintenance program, the general revision may be inserted into the maintenance requirements manual, provided the relevant information in the general revision is identical to that in the TR, and the temporary revision may be removed.

(2) After accomplishing the action specified in paragraph (f)(1) of this AD, no alternative CDCCLs may be used unless the CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (g)(1) of this AD.

New Information: Explanation of CDCCL Requirements

Note 2: Notwithstanding any other maintenance or operational requirements, components that have been identified as airworthy or installed on the affected airplanes before the revision of the ALS, as required by paragraph (f) of this AD, do not need to be reworked in accordance with the CDCCLs. However, once the ALS has been revised, future maintenance actions on these components must be done in accordance with the CDCCLs.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows:
No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, 1600 Stewart Avenue, Suite 41, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to ensure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Canadian Airworthiness Directive CF-2007-35, dated December 21, 2007, Canadair Temporary Revision (TR) 2D-2, dated March 31, 2006, and TR 2D-2, dated May 10, 2007, for related information.

Material Incorporated by Reference

(i) You must use Canadair Temporary Revision 2D-2, dated March 31, 2006, to Appendix D, "Fuel System Limitations," of Part 2, "Airworthiness Requirements," of the Bombardier CL-600-2B19 Maintenance Requirements Manual CSP A-053, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register previously approved the incorporation by reference of Canadair Temporary Revision 2D-2, dated March 31, 2006, to Appendix D, "Fuel System Limitations," of Part 2, "Airworthiness Requirements," of the Bombardier CL-600-2B19 Maintenance Requirements Manual CSP A-053 on June 6, 2008 (73 FR 24147, May 2, 2008).

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.cri@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by

reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on December 11, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-30417 Filed 12-22-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0521; Directorate Identifier 2008-NM-187-AD; Amendment 39-16034; AD 2009-20-11]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-300, -400, and -500 Series Airplanes Equipped With a Digital Transient Suppression Device (DTSD) Installed in Accordance With Supplemental Type Certificate (STC) ST00127BO

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting information in an existing airworthiness directive (AD) that was published in the **Federal Register** on October 1, 2009. The error resulted in use of an outdated division name and e-mail address in the vendor contact information. This AD applies to certain Boeing Model 737-300, -400, and -500 series airplanes. This AD requires revising the maintenance program to include new fuel system limitations for airplanes modified in accordance with STC ST00127BO. This AD also requires inspections and checks of the DTSDs and corrective actions, if necessary.

DATES: Effective November 5, 2009.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West

Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Marc Ronell, Aerospace Engineer, ANE-150, FAA, Boston Aircraft Certification Office, 12 New England Executive Park, Burlington, Massachusetts 01803; telephone (781) 238-7776; fax (781) 238-7170.

SUPPLEMENTARY INFORMATION: On September 18, 2009, the FAA issued AD 2009-20-11, Amendment 39-16034 (74 FR 50683, October 1, 2009), for certain Boeing Model 737-300, -400, and -500 series airplanes. The AD requires revising the maintenance program to include new fuel system limitations for airplanes modified in accordance with Supplemental Type Certificate ST00127BO. This AD also requires inspections and checks of the digital transient suppression device and corrective actions, if necessary.

As published, the vendor contact information specified in the Addresses section of the preamble and paragraph (n)(2) of the regulatory text of AD 2009-20-11 contained an outdated division name and e-mail address. Since that AD was published, the vendor has provided us with the recently updated contact information.

No other part of the regulatory information has been changed; therefore, the final rule is not republished in the **Federal Register**.

The effective date of this AD remains November 5, 2009.

■ Correction of non-regulatory text:

In the **Federal Register** of October 1, 2009, on page 50683, in the second column, the **ADDRESSES** section of AD 2009-20-11 is corrected to read as follows:

"ADDRESSES: For service information identified in this AD, contact Goodrich Corporation, Sensors and Integrated Systems (Formerly Fuel and Utility Systems), 100 Pantan Road, Vergennes, Vermont 05491-1008; telephone 802-877-4476; e-mail SIS.TechPubs-VT@Goodrich.com; Internet <http://www.goodrich.com/TechPubs>."

■ Correction of regulatory text:

§ 39.13 [Corrected]

■ In the **Federal Register** of October 1, 2009, on page 50685, in the second column, paragraph (n)(2) of AD 2009-20-11 is corrected to read as follows:

* * * * *

(2) For service information identified in this AD, contact Goodrich Corporation, Sensors and Integrated Systems (Formerly Fuel and Utility Systems), 100 Pantan Road, Vergennes, Vermont 05491-1008; telephone 802-