

DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016–0116, dated June 16, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9504.

(2) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201–440–6700; Internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on December 6, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–30029 Filed 12–20–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–9507; Directorate Identifier 2016–NM–127–AD]

RIN 2120–AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (Embraer)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Embraer S.A. Model EMB–120, –120ER, –120FC, –120QC, and –120RT airplanes. This proposed AD was prompted by changes to the airworthiness limitations, which add life-limited landing gear parts not previously identified. This proposed AD would require revising the maintenance or inspection program to incorporate new airworthiness limitations that add life limits for previously unidentified landing gear parts. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by February 6, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Empresa Brasileira de Aeronautica S.A. (Embraer), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227–901 São Jose dos Campos—SP—Brasil; telephone +55 12 3927–5852 or +55 12 3309–0732; fax +55 12 3927–7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9507; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–1175; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2016–9507; Directorate Identifier 2016–NM–127–AD” at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Agência Nacional de Aviação Civil (ANAC), which is the aviation authority for Brazil, has issued Brazilian Airworthiness Directive 2016–07–02, dated July 27, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Embraer S.A. Model EMB–120, –120ER, –120FC, –120QC, and –120RT airplanes. The MCAI states:

This [Brazilian] AD was prompted by changes to the Airworthiness Limitation Section of the Maintenance Review Board Report MRB 120–HI–200, which add life-limited landing gear parts not previously identified. We are issuing this [Brazilian] AD to prevent life-limited landing gear parts from being used beyond their safe-life limits, which could lead to collapse of the landing gear.

This proposed AD would require revising the maintenance or inspection program to incorporate new airworthiness limitations that add life limits for previously unidentified landing gear parts. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9507.

Related Service Information Under 1 CFR Part 51

We reviewed the following Embraer S.A. service information:

- Temporary Revision (TR) 28–1 to MRB Report 120–HI–200, dated May 17, 2016. This service information adds life-limited landing gear parts not previously identified to the airworthiness limitations section.

- Alert Service Bulletin 120–32–A543, dated July 11, 2016. This service information provides procedures for replacement of affected parts.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of

Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or

develop on other products of these same type designs.

Costs of Compliance

We estimate that this proposed AD affects 70 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Maintenance program revision	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$5,950

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Empresa Brasileira de Aeronautica S.A.

(Embraer): Docket No. FAA-2016-9507; Directorate Identifier 2016-NM-127-AD.

(a) Comments Due Date

We must receive comments by February 6, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Embraer S.A. Model EMB-120, EMB-120RT, EMB-120ER, EMB-120FC, and EMB-120QC airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Reason

This AD was prompted by changes to the Airworthiness Limitation Section of the Maintenance Review Board (MRB) Report 120-HI-200, which adds life-limited landing gear parts not previously identified. We are issuing this AD to prevent life-limited landing gear parts from being used beyond their safe-life limits, which could lead to collapse of the landing gear.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of Maintenance or Inspection Program

Within 90 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, by incorporating the life-limited landing gear parts and the applicable safe-life limits identified in table 1 to paragraph (g) of this AD, as specified in Embraer S.A. Temporary Revision (TR) 28-1 to MRB Report 120-HI-200, dated May 17, 2016.

TABLE 1 TO PARAGRAPH (g) OF THIS AD—LIFE-LIMITED LANDING GEAR PARTS

Part number	Description	Safe-life limits (landings)
19699-001-00	Pin drag strut, lower	104,054
19429-000-00	Piston tube (pre-modification service bulletin 120-032-0514)	30,000
19429-000-00	Piston tube (post-modification service bulletin 120-032-0514)	90,000
19946-001-00	Pin leg hinge	90,000
20030-001-00	Pin torque link	90,000
19437-000-00	Drag strut, upper half	104,054
20031-001-00	Pin drag strut hinge	104,054
19414-000-00	Piston tube	90,000

TABLE 1 TO PARAGRAPH (g) OF THIS AD—LIFE-LIMITED LANDING GEAR PARTS—Continued

Part number	Description	Safe-life limits (landings)
19919-000-00	Pin leg hinge	90,000

(h) Replace Affected Parts

The initial compliance for the replacement of affected parts is specified in paragraphs (h)(1) and (h)(2) of this AD. Replace affected parts with serviceable parts, in accordance with the Accomplishment Instructions of Embraer S.A. Alert Service Bulletin 120-32-A543, dated July 11, 2016.

(1) Before the applicable safe-life limit identified in table 1 to paragraph (g) of this AD, or within 90 days after the effective date of this AD, whichever occurs later.

(2) Within 90 days after the effective date of this AD for parts on which the current status is unknown.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install on any airplane a main landing gear part or nose landing gear part having a part number identified in table 1 to paragraph (g) of this AD, if it has reached or exceeded its safe-life limit, or if its current status is unknown.

(j) No Alternative Actions and Intervals

After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance in accordance with the procedures specified in paragraph (k)(1) of this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch ACO, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Agência Nacional de Aviação Civil

(ANAC); or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) ANAC AD No.: 2016-07-02, dated July 27, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9507.

(2) For service information identified in this NPRM, contact Empresa Brasileira de Aeronautica S.A. (Embraer), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227-901 São Jose dos Campos—SP—BRASIL; telephone +55 12 3927-5852 or +55 12 3309-0732; fax +55 12 3927-7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on December 6, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-30030 Filed 12-20-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF VETERANS AFFAIRS

38 CFR Part 3

RIN 2900-AP23

Special Monthly Compensation for Veterans With Traumatic Brain Injury

AGENCY: Department of Veterans Affairs.

ACTION: Proposed rule.

SUMMARY: The Department of Veterans Affairs (VA) seeks to amend its adjudication regulations to add an additional benefit for veterans with residuals of traumatic brain injury (TBI). This benefit was enacted by the Veterans' Benefits Act of 2010 and provides special monthly compensation for veterans with TBI who are in need of aid and attendance and, in the absence of such aid and attendance, would require hospitalization, nursing home care, or other residential institutional care. Prior to the law's enactment, veterans with TBI were not

eligible for this benefit unless they had a separate service-related disability that qualified under the law.

DATES: Comments must be received on or before February 21, 2017.

ADDRESSES: Written comments may be submitted through

www.Regulations.gov; by mail or hand-delivery to Director, Regulation Policy and Management (00REG), Department of Veterans Affairs, 810 Vermont Avenue NW., Room 1068, Washington, DC 20420; or by fax to (202) 273-9026. Comments should indicate that they are submitted in response to "RIN 2900-AP23—Special Monthly Compensation for Veterans with Traumatic Brain Injury." Copies of comments received will be available for public inspection in the Office of Regulation Policy and Management, Room 1068, between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday (except holidays). Please call (202) 461-4902 for an appointment. (This is not a toll-free number.) In addition, during the comment period, comments may be viewed online through the Federal Docket Management System (FDMS) at www.Regulations.gov.

FOR FURTHER INFORMATION CONTACT: Eric G. Mandle, Policy Analyst, Regulations Staff (211D), Compensation Service, Department of Veterans Affairs, 810 Vermont Avenue NW., Washington, DC 20420, (202) 461-9700. (This is not a toll-free telephone number.)

SUPPLEMENTARY INFORMATION: On October 13, 2010, the Veterans' Benefits Act of 2010, Public Law 111-275 (the Act) was signed into law. Section 601 of the Act amends 38 U.S.C. 1114, adding subsection (t) to include special monthly compensation (SMC) for veterans who as the result of service-connected disability, are in need of regular aid and attendance for the residuals of traumatic brain injury (TBI), and in the absence of such regular aid and attendance would require hospitalization, nursing home care, or other residential institutional care. The law grants an additional monetary allowance for veterans with residuals of TBI who require this higher level of care but would not otherwise qualify for the benefit under 38 U.S.C. 1114(r)(2). The amendment became effective October 1, 2011.

VA administers SMC benefits under 38 CFR 3.350. Additionally, 38 CFR