

TABLE 1.—INCORPORATION BY REFERENCE—Continued

GE Service Bulletin No.	Page	Revision	Date
CF34–8E–AL S/B 73–0015, Total Pages: 11	ALL	3	November 1, 2007.
CF34–10E S/B 72–0067, Total Pages: 10	ALL	2	August 28, 2007.

Issued in Burlington, Massachusetts, on February 15, 2008.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E8–3462 Filed 2–27–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–0226; Directorate Identifier 2007–NM–187–AD; Amendment 39–15393; AD 2008–04–21]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 737–300, –400, and –500 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Boeing Model 737–300, –400, and –500 series airplanes. This AD requires repetitive inspections for cracking of the body buttock line (BBL) 0.07 floor beam between body station (BS) 651 and BS 676 and between BS 698 and BS 717, and related investigative and corrective actions if necessary. This AD also provides an optional terminating action for the repetitive inspections. This AD results from reports of cracking in the BBL 0.07 floor beam. We are issuing this AD to prevent failure of the main deck floor beams at certain body stations due to fatigue cracking, which could result in rapid decompression of the airplane.

DATES: This AD is effective April 3, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 3, 2008.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the

Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800–647–5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 917–6440; fax (425) 917–6590.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to certain Boeing Model 737–300, –400, and –500 series airplanes. That NPRM was published in the **Federal Register** on November 26, 2007 (72 FR 65901). That NPRM proposed to require repetitive inspections for cracking of the body buttock line 0.07 floor beam between body station (BS) 651 and BS 676 and between BS 698 and BS 717, and related investigative and corrective actions if necessary.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comment received. Boeing supports the NPRM.

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

There are 1,961 airplanes of the affected design in the worldwide fleet. This AD affects 599 airplanes of U.S. registry. The required inspections take about 4 work hours per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the required AD for U.S.

operators is \$191,680, or \$320 per airplane, per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008-04-21 Boeing: Amendment 39-15393. Docket No. FAA-2007-0226; Directorate Identifier 2007-NM-187-AD.

Effective Date

(a) This airworthiness directive (AD) is effective April 3, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 737-300, -400, and -500 series airplanes, certificated in any category; as identified in Boeing Service Bulletin 737-57-1210, Revision 2, dated June 13, 2007.

Unsafe Condition

(d) This AD results from reports of cracking in the body buttock line (BBL) 0.07 floor beam. We are issuing this AD to prevent failure of the main deck floor beams at certain body stations due to fatigue cracking, which could result in rapid decompression of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections and Related Investigative/Corrective Actions

(f) Before the accumulation of 20,000 total flight hours, or within 7,000 flight cycles after the effective date of this AD, whichever occurs later: Do the detailed inspections for cracking of the BBL 0.07 floor beam between body station (BS) 651 and BS 676 and between BS 698 and BS 717, and do all the applicable related investigative and corrective actions before further flight, by accomplishing all of the applicable actions specified in paragraphs B.2. and B.4. of the Accomplishment Instructions of Boeing Service Bulletin 737-57-1210, excluding Appendix A, Revision 2, dated June 13, 2007, except as provided by paragraph (g) of this AD. Repeat the inspections thereafter at intervals not to exceed 7,000 flight cycles. Installing a repair in accordance with paragraphs B.2. and B.4. of the Accomplishment Instructions of the service bulletin, or doing the modification in accordance with paragraph (h) of this AD, terminates the repetitive inspections for the applicable area only.

Exception to Corrective Action

(g) If any cracking is found during any inspection required by this AD, and Boeing Service Bulletin 737-57-1210, excluding Appendix A, Revision 2, dated June 13, 2007, specifies to contact Boeing for appropriate action: Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

Optional Terminating Action

(h) If no cracking is found during the detailed inspection and related investigative action required by paragraph (f) of this AD: Accomplishing the modification of the BBL 0.07 floor beam between BS 651 and BS 676 and between BS 698 and BS 717, as applicable, in accordance with paragraphs B.2. and B.4., as applicable, of the Accomplishment Instructions of Boeing Service Bulletin 737-57-1210, excluding Appendix A, Revision 2, dated June 13, 2007, terminates the repetitive inspections for the applicable area only.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(j) You must use Boeing Service Bulletin 737-57-1210, Revision 2, dated June 13, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/

code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 15, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-3461 Filed 2-27-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0300; Directorate Identifier 2007-NM-191-AD; Amendment 39-15394; AD 2008-04-22]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Mark 0070 and 0100 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Reports have been received from Fokker 100 (F28 Mark 0100) operators where the crew experienced difficulties with roll control. Analysis suggests that these phenomena are due to frozen water on the aileron pulleys that are installed on the Center Wing Spar and located in the Main Landing Gear (MLG) wheel bays. Investigation has confirmed that improper closure of the aerodynamic seals of the wing-to-fuselage fairings above the MLG wheel bays can cause rainwater, wash-water or de-icing fluid to leak onto the affected aileron pulleys. This condition, if not corrected, can lead to further incidents of frozen water on aileron pulleys during operation of the aircraft, resulting in restricted roll control and/or higher control forces. * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective April 3, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 3, 2008.

ADDRESSES: You may examine the AD docket on the Internet at http://www.faa.gov/aircraft/air_cert/design_approvals/air_notices/ad_2008_04_22/