

adequate veterinary care. They serve as a basis for reviewing the medical history and planning veterinary care and provide a mechanism of communication for matters of animal health, behavior, and well-being. Medical records document the animal's illness, veterinary care, and treatment and serve as a basis for review, study, and evaluation of veterinary care rendered by the facility. Medical records must be legible and include at least the following information:

(i) The identity of the individual animal; *Provided, however*, That routine husbandry, such as vaccinations, preventive medical procedures, or treatments, performed on all animals in a group (or herd), may be kept on a single record;

(ii) The date, description of the problem, pertinent history, observations, examination findings, test results, and plan for treatment and care with a tentative diagnosis and a prognosis, when appropriate;

(iii) The type and chronology of treatment procedures performed, the context of the problem to which the treatment procedures pertain, and the identification of the medication used, the date given, dosage, route of administration, frequency, and duration of treatment;

(iv) The names of all vaccines administered and the dates of vaccination; and

(v) The dates and results of all screening, routine, or other required or recommended tests.

5. In § 2.75, a new paragraph (b)(4) would be added to read as follows:

§ 2.75 Records: Dealers and exhibitors.

* * * * *

(b) * * *

(4) One copy of the medical records containing the information required by § 2.40(b)(6) shall be provided to the subsequent owner of the animal or to any person to whom the animal is consigned.

Done in Washington, DC, this 7th day of April 2003.

Peter Fernandez,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 03-8928 Filed 4-10-03; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-401-AD]

RIN 2120-AA64

Airworthiness Directives; Aerospatiale Model ATR72 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Aerospatiale Model ATR72 series airplanes. This proposal would require installing brackets and ramps under floor panels between frames 23C and 23D, and installing wire bundles on the ramps. This action is necessary to prevent chafing damage to the electrical wire cables, which could lead to an electrical short circuit and potential for a fire under the floor panels. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by May 12, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-401-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-401-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601

Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-401-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-401-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Aerospatiale Model ATR72 series

airplanes. The DGAC advises of an incident in which loss of a blue hydraulic circuit occurred during landing. The circuit failure was found to be the result of an electrical short circuit between the electrical power supply cables for the blue hydraulic pump and the steering hydraulic pipe, located under certain floor panels. There was evidence of a fire in the vicinity due to the electrical short circuit. The apparent cause of these failures was a specific quality problem during cable installation on the production line. Improper routing of electrical cables in the subject area, if not corrected, could result in chafing damage to the electrical wire cables, which could lead to an electrical short circuit and potential for a fire under the floor panels.

Explanation of Relevant Service Information

Aerospatiale has issued Avions de Transport Regional Service Bulletin ATR72-92-1006, dated September 28, 2001, which describes procedures for installing, under floor panels between frames 23C and 23D, brackets and ramps that correctly route the wire bundles, which have the power supply cables for the blue hydraulic pump, and installing wire bundles on the ramps so that the cables pass the steering hydraulic pipe without chafing. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 2001-505-059(B), dated October 17, 2001, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United

States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 65 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 6 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$1,844 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$143,260, or \$2,204 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Aerospatiale: Docket 2001-NM-401-AD.

Applicability: Model ATR72 series airplanes, certificated in any category; except those airplanes on which modification 5297 has been accomplished in production, or on which Avions de Transport Regional (ATR) Service Bulletin ATR72-92-1006, dated September 28, 2001, has been accomplished in service.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent chafing damage to the electrical wire cables, which could lead to an electrical short circuit and consequent fire under the floor panels, accomplish the following:

Installation

(a) Within 12 months after the effective date of this AD, perform the actions specified in paragraphs (a)(1) and (a)(2) of this AD per the Accomplishment Instructions of ATR Service Bulletin ATR72-92-1006, dated September 28, 2001.

(1) Install brackets and ramps under floor panels between frames 23C and 23D.

(2) Install wire bundles on the ramps.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directive 2001-505-059(B), dated October 17, 2001.

Issued in Renton, Washington, on April 7, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 03-8891 Filed 4-10-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-16-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A319, A320, and A321 series airplanes equipped with certain cockpit lateral fixed windows manufactured by PPG Aerospace. This proposal would require a detailed inspection of the cockpit lateral fixed windows to detect moisture ingress and delamination, and follow-on/corrective actions as applicable. This proposed AD also provides for an optional terminating action for the repetitive inspections. This action is necessary to prevent moisture ingress and delamination of the cockpit lateral fixed windows, which could result in the loss of the outer glass ply, and consequent damage to the airplane and injury to people or damage to property on the ground. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by May 12, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation

Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-16-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-16-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments

submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-16-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-16-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Generale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A319, A320, and A321 series airplanes equipped with certain cockpit lateral fixed windows manufactured by PPG Aerospace. The DGAC advises that an operator reported partial separation of the outer glass ply of the right-hand cockpit lateral fixed window. This window had been previously identified as having delamination in the lower forward corner. Investigation revealed that a process used in the manufacturing of these windows was deficient, resulting in moisture ingress and delamination of the outer glass ply. This condition, if not corrected, could result in loss of the outer glass ply, and consequent damage to the airplane and injury to people or damage to property on the ground.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A320-56-1009, Revision 01, including Appendix 01 and Reporting Sheet, dated July 4, 2002. This service bulletin describes procedures for a detailed inspection of cockpit lateral fixed windows manufactured by PPG Aerospace having part number (P/N) NP-165313-1 or NP-165313-2, and having a serial number (S/N) below 95001H0001 (PPG Aerospace manufacturing date before January 1, 1995), to detect moisture ingress evidenced by urethane degradation or delamination. For windows having no