

Rules and Regulations

Federal Register

Vol. 77, No. 5

Monday, January 9, 2012

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0710; Directorate Identifier 2010-NE-26-AD; Amendment 39-16892; AD 2010-19-06R1]

RIN 2120-AA64

Airworthiness Directives; Turbomeca Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that was published in the **Federal Register**. That AD applies to Turbomeca Arriel 1 series turboshaft engines. The AD number is incorrect in the preamble and in the Regulatory text. This document corrects those errors. In all other respects, the original document remains the same.

DATES: This final rule revision is effective January 17, 2012.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: (800) 647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, 12 New England Executive Park, Burlington, MA; phone: (781) 238-7779;

fax: (781) 238-7199; email: frederick.zink@faa.gov.

SUPPLEMENTARY INFORMATION:

Airworthiness Directive 2011-26-02, Amendment 39-16892 (76 FR 77378, December 13, 2011), currently requires removing from service certain gas generator second stage turbine discs, part number (P/N) 0 292 25 040 0, that are not marked with "CFR" before the discs exceed 4,000 cycles-in-service (CIS) since new. That AD also requires removing from service certain gas generator second stage turbine discs, P/N 0 292 25 040 0, that are marked with "CFR" before the discs exceed 6,500 CIS since new.

As published, the AD number 2011-26-02 in the preamble of the AD and under § 39.13 [Amended], is incorrect.

No other part of the preamble or regulatory information has been changed; therefore, only the changed portion of the final rule is being published in the **Federal Register**.

The effective date of this AD revision remains January 17, 2012.

Correction of Non-Regulatory Text

In the **Federal Register** of December 13, 2011, AD 2011-26-02; Amendment 39-16892 is corrected as follows:

On page 77378, in the second column, on line 3 under 14 CFR Part 39, change AD 2011-26-02 to AD 2010-19-06R1.

Correction of Regulatory Text

§ 39.13 [Corrected]

■ In the **Federal Register** of December 13, 2011, on page 77379, in the second column, lines 6 and 7 under § 39.13 [Amended] of AD 2011-26-02, are corrected to read as follows:

* * * * *

AD 2010-19-06R1 Turbomeca:
Amendment 39-16892; Docket No.
FAA-2010-0710;

* * * * *

Issued in Burlington, Massachusetts, on December 29, 2011.

Peter A. White,

*Manager, Engine & Propeller Directorate,
Airframe Certification Service.*

[FR Doc. 2012-79 Filed 1-6-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0162; Directorate Identifier 2004-NE-19-AD; Amendment 39-16803; AD 2011-18-21]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc (RR) RB211-524 Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are superseding an existing airworthiness directive (AD) for the products listed above. That AD currently requires initial and repetitive borescope inspections of the head section and meterpanel assembly of the combustion liner, and replacement if necessary. This new AD requires those same inspections, and replacement. This AD also expands the applicability to include part numbers (P/N) of additional combustion liners. This AD was prompted by an inquiry submitted by an operator, which resulted in RR performing a complete review of the affected front combustion liner part numbers. We are issuing this AD to prevent deterioration of the engine combustion liner, which can result in combustion liner breakup, case burn-through, engine fire, and damage to the airplane.

DATES: This AD is effective February 13, 2012.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of February 9, 2005 (70 FR 680, January 5, 2005).

ADDRESSES: For service information identified in this AD, contact Rolls-Royce plc, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: 011-44-1332-242424; fax: 011-44-1332-249936, for the service information identified in this proposed AD. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: (800) 647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Alan Strom, Aerospace Engineer, Engine Certification Office, FAA, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7143; fax: (781) 238-7199; email: alan.strom@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 to supersede airworthiness directive (AD) 2004-26-05, amendment 39-13917 (70 FR 680, January 5, 2005). That AD applies to the specified products. The SNPRM published in the **Federal Register** on October 18, 2010 (75 FR 63727). The SNPRM proposed to require:

- Initial and repetitive borescope inspections of the combustion liner head section and meterpanel assembly of the combustion liner and, if necessary, replacement.
- Reduction of the inspection intervals of certain RB211-524 engine models that have not been repaired to RR Field Repair Scheme FRS5367/B, and
- A mandatory terminating action to the repetitive inspections to be completed no later than December 31, 2012.

Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comment received. The Boeing Company supports the SNPRM published in the **Federal Register** on October 18, 2010 (75 FR 63727).

We simplified wording for clarity in the regulatory section. We did not change the requirements of this AD.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that this AD will affect 18 engines installed on airplanes of U.S. registry. We also estimate that it will take about 32 work-hours per engine to perform the required actions, and that the average labor rate is \$85 per work-hour. Required parts will cost about \$231,000. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$4,206,960.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2004-26-05, Amendment 39-13917 (70 FR 680, January 5, 2005), and adding the following new AD:

2011-18-21 Rolls-Royce plc: Amendment 39-16803; Docket No. FAA-2009-0162; Directorate Identifier 2004-NE-19-AD.

(a) Effective Date

This airworthiness directive (AD) is effective February 13, 2012.

(b) Affected ADs

This AD supersedes AD 2004-26-05, Amendment 39-13917 (70 FR 680, January 5, 2005).

(c) Applicability

This AD applies to Rolls-Royce plc (RR) engine models RB211-524B-02, -524B3-02 engines and RB211-524B2, -524B4, -524C2, and -524D4 series engines with a front combustion liner assembly that incorporates RR Service Bulletin (SB) No. RB.211-72-7221 or RR SB No. RB.211-72-7998, but doesn't incorporate RR SB No. RB.211-72-9670 or RR SB No. RB.211-72-9764, and engine models RB211-524G and -524H series engines with a front combustion liner assembly that doesn't incorporate RR SB No. RB.211-72-9764.

(d) Unsafe Condition

This AD results from an inquiry submitted by an operator which resulted in RR performing a complete review of the affected front combustion liner part numbers. We are issuing this AD to prevent deterioration of the engine combustion liner, which can result in combustion liner breakup, case burn-through, engine fire, and damage to the airplane.

(e) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

(f) Credit for Previous Inspections

Engine inspections previously done using RR SB No. RB.211-72-B482, Revision 8, meet the requirements of this AD for the initial and repetitive inspections specified in paragraph (g) and Table 1 of this AD; and paragraph (h) and Table 2 of this AD.

(g) Inspections of Combustion Liner Head Sections—Not Previously Repaired

Borescope-inspect combustion liner head sections that have not been previously

repaired. Use paragraphs 3.A.(1) through 3.A.(5) of the Accomplishment Instructions of RR Alert Service Bulletin (ASB) No. RB.211-72-AB482, Revision 9, dated July 28,

2003, and the compliance thresholds in Table 1 of this AD to do the inspections.

TABLE 1—COMBUSTION LINER HEAD SECTION—NOT PREVIOUSLY REPAIRED

Engine series	Initial inspection	Repetitive inspection	Parts exceeding initial inspection cycles
RB211-524C2, -524D4, -524G, and -524H.	Within 1,400 to 1,600 cycles-since-new (CSN).	Within 200 cycles-since-last inspection (CSLI).	Within 100 cycles-in-service (CIS) after the effective date of this AD.
RB211-524B-02, -524B2, -524B3-02, and -524B4.	Within 3,000 to 3,200 CSN	Within 200 CSLI	Within 200 CIS after the effective date of this AD.

(h) Inspections of Combustion Liner Head Sections—Previously Repaired Using RR Field Repair Scheme FRS5367/B

Borescope-inspect combustion liner head sections previously repaired using RR Field

Repair Scheme FRS5367/B. Use paragraphs 3.A.(1) through 3.A.(5) of the Accomplishment Instructions of RR ASB No. RB.211-72-AB482, Revision 9, dated July 28,

2003, and the compliance thresholds in Table 2 of this AD to do the inspections.

TABLE 2—COMBUSTION LINER HEAD SECTION—PREVIOUSLY REPAIRED USING RR FIELD REPAIR SCHEME FRS5367/B

Engine series	Initial inspection	Repetitive inspection	Parts exceeding initial inspection cycles
RB211-524C2, -524D4, -524G, and -524H.	Within 1,800 to 2,200 cycles-since-last repair (CSLR).	Within 400 CSLI	Within 200 CIS after the effective date of this AD.
RB211-524B-02, -524B2, -524B3-02, and -524B4.	Within 3,000 to 3,200 CSLR	Within 400 CSLI	Within 200 CIS after the effective date of this AD.

(i) Inspections of Combustion Liner Head Sections That Have Been Repaired But Did Not Use RR Field Repair Scheme FRS5367/B

Borescope-inspect combustion liner head sections that have been repaired using a

method other than RR Field Repair Scheme FRS5367/B. Use paragraphs 3.A.(1) through 3.A.(5) of the Accomplishment Instructions of RR ASB No. RB.211-72-AB482, Revision 9, dated July 28, 2003, and the compliance

thresholds in Table 3 of this AD to do the inspections.

TABLE 3—COMBUSTION LINER HEAD SECTION—REPAIRED, BUT DID NOT USE RR FIELD REPAIR SCHEME FRS5367/B

Engine series	Initial inspection	Repetitive inspection	Parts exceeding initial inspection cycles
RB211-524C2, -524D4, -524G, and -524H.	Within 500 to 700 CSLR	Within 200 CSLI	Within 100 CIS after the effective date of this AD.
RB211-524B-02, -524B2, -524B3-02, and -524B4.	Within 2,000 to 2,200 CSLR	Within 200 CSLI	Within 200 CIS after the effective date of this AD.

(1) For an installed front combustion liner that is subject to RR ASB No. RB.211-72-AB482, Revision 9, dated July 28, 2003, if the microbrazed repair RR Field Repair Scheme FRS5367 has been applied to all 18 struts, then that repair is equivalent to compliance with RR Field Repair Scheme FRS5367/B.

(2) Head sections repaired by replacement of all 18 struts using RR Field Repair Scheme

FRS6548 are considered as equivalent to fitting a new head section for inspection purposes.

(j) Inspections of Meterpanel Assemblies—Not Repaired

Borescope-inspect meterpanel assemblies that incorporate SB No. RB.211-72-7998, that have not been previously repaired. Use

paragraphs 3.B.(1) through 3.B.(7) of the Accomplishment Instructions of RR ASB No. RB.211-72-AB482, Revision 9, dated July 28, 2003, and the compliance thresholds in Table 4 of this AD to do the inspections.

TABLE 4—METERPANEL ASSEMBLY—NOT REPAIRED

Engine series	Initial inspection	Repetitive inspection	Parts exceeding initial inspection cycles
RB211-524D4, -524G, and -524H	Within 1,000 to 1,200 CSN	Within 400 CSLI	Within 50 CIS after the effective date of this AD.
RB211-524D4, -524G, and -524H that have not used RB211-524H ratings at any time.	Within 1,800 to 2,000 CSN	Within 400 CSLI	Within 50 CIS after the effective date of this AD.

(k) Inspections of Meterpanel Assemblies—Repaired

Borescope-inspect meterpanel assemblies that incorporate SB No. RB.211-72-7998,

that have been previously repaired. Use paragraphs 3.B.(1) through 3.B.(7) of the Accomplishment Instructions of RR ASB No. RB.211-72-AB482, Revision 9, dated July 28,

2003, and the compliance thresholds in Table 5 of this AD to do the inspections.

TABLE 5—METERPANEL ASSEMBLY—REPAIRED

Engine series	Initial inspection	Repetitive inspection	Parts exceeding initial inspection cycles
RB211-524D4, -524G, and -524H..	Within 500 to 700 CSLR	Within 400 CSLI	Within 50 CIS after the effective date of this AD.

(l) Reject Parts

Remove from service, parts that exceed the acceptance criteria.

(m) Mandatory Terminating Action

Replace any front combustion liner assembly that has a P/N listed in paragraph (c) of this AD at the next shop visit.

(1) For RB211-524B-02, -524B3-02, -524B4, -524C2 and -524B2, -524B4, -524C2, and -524D4 series engines, replacing the front combustion liner assembly with a front combustion liner assembly that incorporates the modifications in RR SB No. RB.211-72-9670, Original Issue, dated August 27, 1993; or RR SB No. RB.211-72-9764, Revision 3, dated January 16, 1998, constitutes terminating action to the repetitive inspections in paragraphs (g), (h), (i), (j), and (k) of this AD.

(2) For RB211-524G and -524H engines, replacing the front combustion liner assembly with a front combustion liner assembly that incorporates the modifications in RR SB No. RB.211-72-9764, Revision 3, dated January 16, 1998, constitutes terminating action to the repetitive inspections in paragraphs (f), (g), (h), (i), and (j) of this AD.

(n) Definition of Shop Visit

For the purpose of this AD, a shop visit is any time that the 04 module is removed for refurbishment or overhaul.

(o) Related Information

Contact Alan Strom, Aerospace Engineer, Engine Certification Office, FAA, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7143; fax: (781) 238-7199; email: alan.strom@faa.gov, for more information about this AD.

(p) Material Incorporated by Reference

You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51 on the date specified:

(1) Rolls-Royce plc Alert Service Bulletin No. RB.211-72-AB482, Revision 9, July 28, 2003, approved for IBR February 9, 2005 (70 FR 680, January 5, 2005).

(2) Rolls-Royce plc Service Bulletin No. RB.211-72-9670, Original Issue, August 27, 1993, approved for IBR February 9, 2005 (70 FR 680, January 5, 2005).

(3) Rolls-Royce plc Service Bulletin No. RB.211-72-9764, Revision 3, January 16,

1998, approved for IBR February 9, 2005 (70 FR 680, January 5, 2005).

(4) For service information identified in this AD, contact Rolls-Royce plc, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: 011-44-1332-242424; fax: 011-44-1332-249936.

(5) You may review copies of the service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

(6) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Burlington, Massachusetts, on December 28, 2011.

Peter A. White,

Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2012-134 Filed 1-6-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2011-0540; Airspace Docket No. 11-ASO-20]

Establishment of Class E Airspace; Inverness, FL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E Airspace at Inverness, FL, to accommodate the new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedures serving Inverness Airport. This action enhances the safety and airspace management of Instrument Flight Rules (IFR) operations within the National Airspace System. This action also makes a minor adjustment to the geographic coordinates of the airport.

DATES: Effective 0901 UTC, April 5, 2012. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:**History**

On October 28, 2011, the FAA published in the **Federal Register** a notice of proposed rulemaking to establish Class E airspace at Inverness, FL (76 FR 66871) Docket No. FAA-2011-0540. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Subsequent to publication, the FAA found that the geographic coordinates for Inverness Airport needed to be adjusted. This action makes that adjustment. Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9V dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 establishes the Class E airspace extending upward from 700 feet above the surface at Inverness, FL to provide the controlled airspace required to accommodate the new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedures developed for Inverness Airport. This action is necessary for the safety and management of IFR operations at the airport. This action also adjusts the geographic coordinates