

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2007-0059, dated March 5, 2007; and Service Bulletin No. DO228-119780-0104 Revision 2, dated December 21, 2006, for related information.

Issued in Kansas City, Missouri, on April 20, 2007.

Charles L. Smalley,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-7993 Filed 4-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-28015; Directorate Identifier 2006-NM-210-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to all Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series airplanes. The existing AD currently requires repetitive inspections for cracking of the station 800 frame assembly, and repair if necessary. This proposed AD would revise certain applicabilities and compliance times in the existing AD. This proposed AD results from several reports of cracks of the station 800 frame assembly on airplanes that had accumulated fewer total flight cycles than the initial inspection threshold in the original AD. We are proposing this AD to detect and correct fatigue cracks that could extend and fully sever the frame, which could result in development of skin cracks that could lead to rapid depressurization of the airplane.

DATES: We must receive comments on this proposed AD by June 11, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your

comments to an address listed in the **ADDRESSES** section. Include the docket number "Docket No. FAA-2007-28015; Directorate Identifier 2006-NM-210-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or may can visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m. Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

On May 31, 2006, we issued AD 2006-12-12, amendment 39-14638 (71 FR 33595, June 12, 2006), for all Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series airplanes. That AD requires repetitive inspections for cracking of the station 800 frame assembly, and repair if necessary. That AD resulted from several reports of cracks of the station 800 frame assembly on airplanes that had accumulated fewer total flight cycles than the initial inspection threshold in an existing AD that AD 2006-12-12 superseded. We issued AD 2006-12-12 to detect and correct fatigue cracks that could extend and fully sever the frame, which could result in development of skin cracks that could

lead to rapid depressurization of the airplane.

Actions Since Existing AD Was Issued

Since we issued AD 2006–12–12, errors have been found in the applicability of paragraphs (f) and (g), and the compliance times in Tables 1 and 2 of that AD. Therefore, we have made the following changes:

- We have removed the Model 747–200F from paragraphs (f) and (g) of this NPRM. The Model 747–200F was not included in the applicability of AD 2006–12–12 because the Model 747–200F is not subject to the unsafe condition.
- We have added the Model 747SR to paragraphs (f) and (g) of this NPRM and added a new Table 2 to accommodate it. These airplanes were identified in the main applicability in paragraph (c) of AD 2006–12–12.
- We have removed the Model 747–100B SUD from paragraphs (f) and (g) of this NPRM because they are not subject to the requirements of AD 2001–14–22 (the AD that was superseded by AD 2006–12–12).
- We have revised the thresholds in paragraphs (f)(2), (f)(3), (h)(2), and (h)(3) of this NPRM to correct an inadvertent error in the compliance times.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to develop on other airplanes of the same type design. For this reason, we are proposing this AD, which would supersede AD 2006–12–12 and would retain the requirements of the existing AD. This proposed AD would also revise certain applicabilities and compliance times in the existing AD.

Costs of Compliance

There are about 900 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 156 airplanes of U.S. registry.

The repetitive inspections would take between 12 and 14 work hours per airplane, depending on the airplane configuration. The average labor rate is \$80 per work hour. Based on these figures, the estimated cost of the currently required actions is between \$149,760 and \$174,720, or between \$960 and \$1,120 per airplane, per inspection cycle.

The repetitive inspections of the expanded area would take between 18 and 20 work hours per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the new actions specified in this

proposed AD for U.S. operators is between \$224,640 and \$249,600, or between \$1,440 and \$1,600 per airplane, per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39–14638 (71 FR 33595, June 12, 2006) and adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA–2007–28015; Directorate Identifier 2006–NM–210–AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by June 11, 2007.

Affected ADs

(b) This AD supersedes AD 2006–12–12.

Applicability

(c) This AD applies to all Boeing Model 747–100, 747–100B, 747–100B SUD, 747–200B, 747–200C, 747–300, 747–400, 747–400D, and 747SR series airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from several reports of cracks of the station 800 frame assembly on airplanes that had accumulated fewer total flight cycles than the initial inspection threshold in the existing AD. We are issuing this AD to detect and correct fatigue cracks that could extend and fully sever the frame, which could result in development of skin cracks that could lead to rapid depressurization of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Requirements of AD 2006–12–12 With Revised Applicabilities and Thresholds

Repetitive Inspections

(f) For Boeing Model 747–100, 747–100B, 747–200B, 747–200C, and 747SR series airplanes, as identified in Boeing Alert Service Bulletin 747–53A2451, including Appendix A, dated October 5, 2000: Do detailed, surface high-frequency eddy current (HFEC), and open-hole HFEC inspections, as applicable, for cracking of the station 800 frame assembly (including the inner chord strap, angles, and exposed web) between stringers 14 and 18, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747–53A2451, including Appendix A, dated October 5, 2000; or Boeing Alert Service Bulletin 747–53A2451, Revision 1, dated November 10, 2005; after the effective date of this AD, only Revision 1 of the service bulletin may be used. Except as provided by paragraph (g) of this AD, do the inspection at the applicable time specified in Table 1 or Table 2 of this AD, as applicable, and repeat the inspections thereafter at intervals not to exceed 3,000

flight cycles until the initial inspections required by paragraph (h) of this AD are accomplished.

TABLE 1.—COMPLIANCE TIMES FOR BOEING MODEL 747–100, 747–100B, 747–200B, AND 747–200C SERIES AIRPLANES

Total flight cycles as of August 30, 2001 (the effective date of AD 2001–14–22, amendment 39–12333, which was superseded by AD 2006–12–12)	Do the inspection in paragraph (f) of this AD at this time
(1) Fewer than 19,000	Before the accumulation of 19,000 total flight cycles, or within 1,500 flight cycles after August 30, 2001, whichever comes later.
(2) 19,000 or more, but 24,250 or fewer	Within 1,500 flight cycles or 12 months after August 30, 2001, whichever comes first.
(3) 24,251 or more	Within 750 flight cycles or 12 months after August 30, 2001, whichever comes first.

TABLE 2.—COMPLIANCE TIMES FOR BOEING MODEL 747SR SERIES AIRPLANES

Total flight cycles as of the effective date of this AD	Do the inspection in paragraph (f) of this AD at this time
(4) Fewer than 19,000	Before the accumulation of 19,000 total flight cycles, or within 1,500 flight cycles after the effective date of this AD, whichever comes later.
(5) 19,000 or more, but 24,250 or fewer	Within 1,500 flight cycles or 12 months after the effective date of this AD, whichever comes first.
(6) 24,251 or more	Within 750 flight cycles or 12 months after the effective date of this AD, whichever comes first.

Adjustments to Compliance Time: Cabin Differential Pressure

(g) For Boeing Model 747–100, 747–100B, 747–200B, and 747–200C series airplanes, as identified in Boeing Alert Service Bulletin 747–53A2451, including Appendix A, dated October 5, 2000, that were inspected before July 17, 2006 (the effective date of AD 2006–12–12); and for Boeing Model 747SR airplanes, as identified in Boeing Alert Service Bulletin 747–53A2451, that were inspected before the effective date of this AD: Except as provided by paragraph (i) of this AD, for the purposes of calculating the compliance threshold and repetitive interval for the actions required by paragraph (f) of this AD, the number of flight cycles in which cabin differential pressure is at 2.0 pounds

per square inch (psi) or less need not be counted when determining the number of flight cycles that have occurred on the airplane, provided that the flight cycles with momentary spikes in cabin differential pressure above 2.0 psi are included as full pressure cycles. For this provision to apply, all cabin pressure records must be maintained for each airplane: No fleet-averaging of cabin pressure is allowed.

Repetitive Inspections of Expanded Area at a New Reduced Threshold

(h) For all airplanes, at the applicable time specified in Table 3 of this AD, except as provided by paragraph (i) of this AD, do the following inspections of the station 800 frame assembly in accordance with the

Accomplishment Instructions of Boeing Alert Service Bulletin 747–53A2451, Revision 1, dated November 10, 2005: A detailed inspection for cracking of the inner chord strap, angles, and exposed web adjacent to the inner chords on the station 800 frame between stringer 14 and stringer 18; and surface HFEC and open-hole HFEC inspections for cracking of the inner chord strap and angles. Do the initial inspections at the applicable time specified in Table 3 of this AD, and repeat the inspections thereafter at intervals not to exceed 3,000 flight cycles. Accomplishing the initial inspections required by this paragraph terminates the inspection requirements of paragraph (f) of this AD.

TABLE 3.—REVISED COMPLIANCE TIMES

Total flight cycles as of July 17, 2006—	Do the inspections in paragraph (h) of this AD at this time—
(1) Fewer than 16,000	Before the accumulation of 16,000 total flight cycles, or within 1,500 flight cycles after July 17, 2006, whichever comes later.
(2) 16,000 or more, but 21,250 or fewer	Within 1,500 flight cycles after July 17, 2006, or within 1,000 flight cycles after the effective date of this AD, whichever comes later.
(3) 21,251 or more	Within 750 flight cycles after the July 17, 2006 or within 500 flight cycles after the effective date of this AD, whichever comes later.

Adjustments to Compliance Time: Cabin Differential Pressure

(i) For the purposes of calculating the compliance threshold and repetitive interval for actions required by paragraphs (f) and (h) of this AD, for Boeing Model 747–100, 747–100B, 747–200B, and 747–200C series airplanes, on or after July 17, 2006; and for Boeing Model 747SR series airplanes, on or after the effective date of this AD: All flight cycles, including the number of flight cycles in which cabin differential pressure is at 2.0

psi or less, must be counted when determining the number of flight cycles that have occurred on the airplane. However, for airplanes on which the repetitive interval for the actions required by paragraph (f) of this AD have been calculated in accordance with paragraph (g) of this AD by excluding the number of flight cycles in which cabin differential pressure is at 2.0 pounds psi or less: Continue to adjust the repetitive inspection interval in accordance with paragraph (g) of this AD until the initial

inspections required by paragraph (h) of this AD are accomplished. Thereafter, no adjustment to compliance times based on paragraph (g) of this AD is allowed.

Repair

(j) If any cracking is detected during any inspection required by paragraph (f) or (h) of this AD, and the service bulletin specifies to contact Boeing for appropriate action: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

No Report Required

(k) Although the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2451, including Appendix A, dated October 5, 2000; and Boeing Alert Service Bulletin 747-53A2451, Revision 1, dated November 10, 2005; describe procedures for reporting certain information to the manufacturer, this AD does not require that report.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

(4) AMOCs approved previously in accordance with AD 2001-14-22, are approved as AMOCs for the corresponding provisions of paragraphs (f) and (j) of this AD.

(5) AMOCs approved previously in accordance with AD 2006-12-12, are approved as alternative methods of compliance with this AD.

Issued in Renton, Washington, on April 19, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-7978 Filed 4-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-28017; Directorate Identifier 2007-NM-005-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A310-203, A310-204, A310-222, A310-304, A310-322, and A310-324 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the

products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

* * * some structural areas have been identified for which existing recommended SB (service bulletin) needs to be rendered mandatory.

As a consequence, and because it has been shown that the torque applied to the tension bolts connecting the beam (stringer 49) to the forward and aft beam extension at FR11 and FR17 may be insufficient, this AD renders mandatory the replacement of those tension bolts, in order to limit the risks of damage or corrosion of the specified areas.

Damage or corrosion of the specified areas could result in reduced structural integrity of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by May 29, 2007.

ADDRESSES: You may send comments by any of the following methods:

- **DOT Docket Web Site:** Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- **Fax:** (202) 493-2251.

- **Mail:** Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- **Hand Delivery:** Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- **Federal eRulemaking Portal:** <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington

98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Streamlined Issuance of AD**

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-28017; Directorate Identifier 2007-NM-005-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2006-0367, dated December 5, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During the A310 life extension exercise performed by Airbus, the Airlines Representatives and the Airworthiness Authorities, some structural areas have been identified for which existing recommended SB (service bulletin) needs to be rendered mandatory.