

concurrence before applying for a loan. NCUA will obtain the concurrence directly from the state supervisory authority rather than through the qualifying state-chartered credit union. Additionally, before NCUA will provide a loan to a qualifying state-chartered credit union the credit union must make copies of its state examination reports available to NCUA and agree to examination by NCUA.

* * * * *

(f) *Notice of Award.* NCUA will determine whether an application meets NCUA's standards established by this part and the related Notice of Funding Opportunity. NCUA will provide written notice to a Qualifying Credit Union as to whether or not it has qualified for a loan or technical assistance grant under this part. A Qualifying Credit Union whose application has been denied for failure of a qualification may appeal that decision in accordance with § 705.10 of this part.

(g) *Disbursement—(1) Loans.* Before NCUA will disburse a loan, the Participating Credit Union must sign the loan agreement, promissory note, and any other loan related documents. NCUA may, in its discretion, choose not to disburse the entire amount of the loan at once.

(2) *Technical Assistance Grants.* NCUA will disburse technical assistance grants in such amounts, and in accordance with such terms and conditions, as NCUA may establish. In general, technical assistance grants are provided on a reimbursement basis, to cover expenditures approved in advance by NCUA and supported by receipts evidencing payment by the Participating Credit Union.

■ 9. Revise § 705.9(b) to read as follows:

§ 705.9 Reporting and monitoring.

* * * * *

(b) *Reporting—(1) Reporting to NCUA.* A Participating Credit Union must complete and submit to NCUA all required reports, at such times and in such formats as NCUA will direct. Such reports must describe how the Participating Credit Union has used the loan or technical assistance grant proceeds and the results it has obtained, in relation to the programs, policies, or initiatives identified by the Participating Credit Union in its application. NCUA may request additional information as it determines appropriate.

(2) *Reporting to Members—(i) Loans.* A Participating Credit Union that receives a loan under this part must report on the progress of providing needed community services to the

Participating Credit Union's members once a year, either at the annual meeting or in a written report sent to all members. The Participating Credit Union must also submit to NCUA the written report or a summary of the report provided to members.

(ii) *Technical Assistance Grants.* A Participating Credit Union that receives a technical assistance grant under this part should report on the progress of providing needed community services to the Participating Credit Union's members once a year, either at the annual meeting or in a written report sent to all members.

* * * * *

■ 10. Revise § 705.10 to read as follows:

§ 705.10 Appeals.

(a) *Appeals of non-qualification.* A Qualifying Credit Union whose application for a loan or technical assistance grant has been denied, under § 705.7(f), for failure of a qualification may appeal that decision to the NCUA Board in accordance with the following:

(1) Within thirty days of its receipt of a notice of non-qualification, a credit union may appeal the decision to the NCUA Board. The scope of the NCUA Board's review is limited to the threshold question of qualification and not the issue of whether, among qualified applicants, a particular loan or technical assistance grant is funded.

(2) The foregoing procedure shall apply only with respect to Applications received by NCUA during an open period in which funds are available and NCUA has called for Applications. Any Application submitted by an applicant during a period in which NCUA has not called for Applications will be rejected, except for those Applications submitted under § 705.8. Any such rejection shall not be subject to appeal or review by the NCUA Board.

(b) *Appeals of technical assistance grant reimbursement denials.* Pursuant to NCUA Interpretative Ruling and Policy Statement 11-1, any Participating Credit Union may appeal a denial of a technical assistance grant reimbursement to NCUA's Supervisory Review Committee. All appeals of technical assistance grant reimbursements must be submitted to the Supervisory Review Committee within 30 days from the date of the denial. The decisions of the Supervisory Review Committee are final and may not be appealed to the NCUA Board.

[FR Doc. 2016-28229 Filed 11-23-16; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-5597; Directorate Identifier 2016-NM-009-AD; Amendment 39-18715; AD 2016-23-08]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 737-400 series airplanes. This AD was prompted by reports of cracks in the upper chord of the overwing stub beams at body station (STA) 578 emanating from the rivet location common to the crease beam inner chord and the overwing stub beam upper chord. This AD requires repetitive inspections for cracking, and related investigative and corrective actions if necessary. We are issuing this AD to prevent the unsafe condition on these products.

DATES: This AD is effective December 30, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 30, 2016.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5597.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5597; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday,

except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Galib Abumeri, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model 737-400 series airplanes. The NPRM published in the **Federal Register** on April 28, 2016 (81 FR 25360) (“the NPRM”). The NPRM was prompted by reports of cracks in the upper chord of the overwing stub beams at STA 578 emanating from the rivet location common to the crease beam inner chord and the overwing stub beam upper chord. The NPRM proposed to require repetitive inspections for cracking, and related investigative and corrective actions if necessary. Replacement of the overwing stub beam terminates the repetitive inspections for cracking at the replacement location only, and post-replacement inspections are required if the replacement is done. We are issuing this AD to detect and correct cracking in the upper chord of the overwing stub beam caused by high flight-cycle fatigue stresses from both pressurization and maneuver loads. Cracking of the overwing stub beam could adversely

affect the fuselage structural integrity and result in possible decompression of the airplane.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Request To Clarify Unsafe Condition Statement in the “Discussion” Section

Boeing requested that, in the “Discussion” section of the NPRM, that we clarify the cause of cracking in the overwing stub beams is from high flight-cycle fatigue stresses. Boeing submitted suggested wording.

We agree to clarify the unsafe condition. The unsafe condition statement in the **SUMMARY** section of the NPRM and paragraph (e) of the proposed AD already specified that the cracking in the upper chord of the overwing stub beam is caused by high flight-cycle fatigue stresses from both pressurization and maneuver loads. However, the “Discussion” section of the NPRM is not restated in this final rule. Therefore, we have not revised this final rule in this regard.

Request To Revise Paragraph (i) of the NPRM

Boeing requested that we revise paragraph (i) of the proposed AD to specify that the actions in that paragraph are required on airplanes that have had an overwing stub beam replaced at STA 578 as specified in Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1347, Original Issue, dated December 9, 2015 (“ASB 737-53A1347 Original Issue”), and not replaced with any other method. Boeing stated that the post-replacement inspection requirements specified in table 2 of paragraph 1.E., “Compliance,” of ASB

737-53A1347 Original Issue are applicable only to a STA 578 stub beam replacement accomplished as specified in Part 4 of the Accomplishment Instructions of ASB 737-53A1347 Original Issue.

We agree with Boeing’s request. We have revised paragraph (i) of this AD accordingly.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM or correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Related Service Information Under 1 CFR Part 51

We reviewed ASB 737-53A1347 Original Issue. The service information describes procedures for doing a surface high frequency eddy current inspection for cracking in the overwing stub beam upper chord at STA 559, STA 578, and STA 601, and repairs and replacement. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 93 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	24 work-hours × \$85 per hour = \$2,040 per inspection cycle.	\$0	\$2,040 per inspection cycle.	\$189,720 per inspection cycle.

We estimate the following costs to do any necessary inspections/replacements that would be required based on the

results of the inspection. We have no way of determining the number of

aircraft that might need these inspections/replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Related investigative inspection	9 work-hours × \$85 per hour = \$765 per side	\$0	\$765 per side.

ON-CONDITION COSTS—Continued

Action	Labor cost	Parts cost	Cost per product
STA 578 Replacement	41 work-hours × \$85 per hour = \$3,485 per side.	\$41,500 per side	\$44,985 per side.
STA 578 Post-replacement inspection	1 work-hour × \$85 per hour = \$85 per side	\$0	\$85 per side.

We have received no definitive data that would enable us to provide cost estimates for the remaining on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2016–23–08 The Boeing Company:
Amendment 39–18715; Docket No. FAA–2016–5597; Directorate Identifier 2016–NM–009–AD.

(a) Effective Date

This AD is effective December 30, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all the Boeing Company Model 737–400 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks in the upper chord of the overwing stub beams at body station (STA) 578 emanating from the rivet location common to the crease beam inner chord and the overwing stub beam upper chord. We are issuing this AD to detect and correct cracking in the upper chord of the overwing stub beam caused by high flight-cycle fatigue stresses from both pressurization and maneuver loads. Cracking of the overwing stub beam could adversely affect the fuselage structural integrity and result in possible decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections, Related Investigative Actions, and Corrective Actions

At the applicable time specified in table 1 in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737–53A1347, Original Issue, dated December 9, 2015 ("ASB 737–53A1347 Original Issue"), except as required

by paragraphs (j)(1) and (j)(2) of this AD: Do a surface high frequency eddy current (HFEC) inspection for any cracking in the overwing stub beam upper chord at STA 559, STA 578, and STA 601; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of ASB 737–53A1347 Original Issue, except as specified in paragraph (j)(3) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the HFEC inspection thereafter at the applicable intervals specified in ASB 737–53A1347 Original Issue.

Note 1 to paragraph (g) of this AD: Deviation from the actions specified in ASB 737–53A1347 Original Issue may affect compliance with the fuel tank ignition prevention requirements specified in Critical Design Configuration Control Limitation 28–AWL–11 of Document D6–38278–CMR.

(h) Terminating Action

Replacement of the overwing stub beam, in accordance with Part 4 of the Accomplishment Instructions of ASB 737–53A1347 Original Issue, terminates the repetitive inspections required by paragraph (g) of this AD at the STA 578 replacement location only. The post-replacement inspections required by paragraph (i) of this AD are still required at the STA 578 replacement location.

(i) Post-Replacement Inspections and Corrective Action

For airplanes on which an overwing stub beam has been replaced at STA 578, in accordance with Part 4 of the Accomplishment Instructions of ASB 737–53A1347 Original Issue: At the applicable time specified in table 2 in paragraph 1.E., "Compliance," of ASB 737–53A1347 Original Issue, do a surface HFEC inspection for any cracking in the overwing stub beam upper chord at STA 578, in accordance with the Accomplishment Instructions of ASB 737–53A1347 Original Issue. Repeat the HFEC inspection thereafter at the applicable intervals specified in ASB 737–53A1347 Original Issue. If any cracking is found during any inspection required by this paragraph, before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (j)(3) of this AD.

(j) Exceptions to Service Information

(1) Where ASB 737–53A1347 Original Issue, specifies a compliance time after the "original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) The Condition column of paragraph 1.E., "Compliance," of ASB 737–53A1347

Original Issue, refers to airplanes with specified total flight-cycles "at the original issue date of this service bulletin." This AD, however, applies to the airplanes with the specified total flight-cycles as of the effective date of this AD.

(3) If any cracking is found during any inspection required by this AD, and ASB 737-53A1347 Original Issue specifies to contact Boeing for appropriate action: Before further flight, repair the cracking or replace the stub beam, using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

(k) No Economic Inspection Required

This AD does not require the "Recommended Economic Inspection" specified in paragraph 3.B.3. of the Accomplishment Instructions of ASB 737-53A1347 Original Issue.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m) of this AD. Information may be emailed to: 9-ANM-LAACO-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (j)(3) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (l)(4)(i) and (l)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(m) Related Information

For more information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1347, Original Issue, dated December 9, 2015.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 8, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-27640 Filed 11-23-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-5044; Directorate Identifier 2014-NM-166-AD; Amendment 39-18718; AD 2016-24-01]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain

Bombardier, Inc. Model DHC-8-102, -103, and -106 airplanes; and Model DHC-8-200 and -300 series airplanes. This AD was prompted by a report of heat damage found on a nacelle firewall after an unsuccessful engine ground start and several events of heat damage found on direct current starter/generator terminal block assemblies. This AD requires an inspection to detect damage on the nacelle firewalls and the terminal block assemblies and to make sure the insulating sleeves are installed and have no damage, and corrective action if necessary. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 30, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 30, 2016.

ADDRESSES: For service information identified in this final rule, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5044.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5044; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Assata Dessaline, Aerospace Engineer, Avionics and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY