

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2002-23-07 Cameron Balloons Ltd. (Sky Balloons): Amendment 39-12951; Docket No. 2000-CE-50-AD.

(a) *What aircraft are affected by this AD?* This AD affects any aircraft (specifically balloons), certificated in any category, that

incorporate at least one of the following burners:

Model	Serial Nos.
Mk1 (BR1)	001 through 098, 100, and 101.
Mk2 (Mistral) ..	001 through 098, 100, and 101.

(b) *Who must comply with this AD?*
Anyone who wishes to operate any aircraft

(specifically balloons) with the equipment identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?*
The actions specified by this AD are intended to correct the mechanical failure of the valve stem/seat pinned joint, which could result in a propane vapor leak. Such failure could lead to a propane explosion and fire.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) On the main blast, liquid fire, and pilot light valves of the Mk1 (BR1) and Mk2 (Mistral) burners, replace: (i) Valve stem part number (P/N) A4/BR1/2000/012 with a new improved-design valve, P/N CB6425; (ii) Valve stem P/N A4/BR2/2000/006 with a new improved-design valve, P/N CB6426; and (iii) Rubber sealing ring with O-ring P/N BS1806-008. (2) Only install: (i) Valves that are P/N CB6425 and P/N CB6426, or FAA-approved equivalent P/Ns; and (ii) O-ring P/N BS1806-008, or FAA-approved equivalent P/N.	Within 20 hours time-in-service after January 7, 2003 (the effective date of this AD), unless already accomplished. As of January 7, 2003 (the effective date of this AD).	In accordance with Cameron Balloons LTD (Sky Balloons) Service Bulletin No. SB10, Issue A, dated May 12, 2000. Not Applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Standards Office Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Standards Office Manager.

Note 1: This AD applies to each aircraft (specifically balloons) with a Cameron Balloons Ltd. (Sky Balloons) Mk1 or Mk2 burner identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For aircraft (specifically balloons) that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Roger Chudy, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4140; facsimile: (816) 329-4090.

(g) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Cameron Balloons LTD (Sky Balloons)

Service Bulletin No. SB10, Issue A, dated May 12, 2000. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from Cameron Balloons Ltd. (Sky Balloons), St. Johns Street, Bedminster, Bristol; BS3 4NH; telephone: +44 (0)117 9637216; facsimile: +44 (0)177 966168; or Cameron Balloons, PO Box 3672, Ann Arbor, Michigan 46106; telephone: (734) 426-5525; facsimile: (734) 426-5026. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

Note 2: The subject of this AD is addressed in British AD 003-05-2000, dated May 31, 2000.

(h) *When does this amendment become effective?* This amendment becomes effective on January 7, 2003.

Issued in Kansas City, Missouri, on November 8, 2002.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-29131 Filed 11-19-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-SW-26-AD; Amendment 39-12947; AD 2002-23-03]

RIN 2120-AA64

Airworthiness Directives; MD Helicopters, Inc. Model MD900 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for MD Helicopters, Inc. (MDHI) Model MD900 helicopters that requires inspecting and, if necessary, repairing the longitudinal drive link (drive link) and modifying certain nonrotating swashplate (swashplate) assemblies. This AD also requires recording compliance with the AD on a component history card or equivalent record. This amendment is prompted by reports of damage to the drive link assembly caused by the sharp inner edge of the bushing in the swashplate assembly. The actions specified by this AD are intended to prevent damage to the drive link, loss of control of the main rotor system, and subsequent loss of control of the helicopter.

DATES: Effective December 26, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 26, 2002.

ADDRESSES: The service information referenced in this AD may be obtained from MD Helicopters, Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9734, telephone 1-800-388-3378, fax 480-891-6782, or on the web at www.mdhelicopters.com. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Jon Mowery, Aviation Safety Engineer, FAA, Los Angeles Aircraft Certification Office, Airframe Branch, 3960 Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5322, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend 14 CFR part 39 to include an AD for certain MDHI Model MD900 helicopters was published in the **Federal Register** on May 29, 2002 (67 FR 37356). That action proposed to require modifying each swashplate assembly, part number (P/N) 900C2010192-105, -107, and -109. That action also proposed dye-penetrant inspecting for gouging and cracking and, if necessary, repairing the drive link assembly, P/N 900C2010212-101. Recording compliance with the AD on the component history card or equivalent record was also proposed.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed with minor changes in paragraph (b) and Note 2 to further clarify that the dye-penetrant inspection required after modifying the nonrotating swashplate is required before further flight. The dye-penetrant inspection is required whether the drive-link assembly has been dye-penetrant inspected previously. These changes will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that this AD will affect 28 helicopters of U.S. registry, that it will take approximately 2 work hours per helicopter to accomplish the

required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$1164 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$35,952.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2002-23-03 MD Helicopters, Inc.:

Amendment 39-12947. Docket No. 2001-SW-26-AD.

Applicability: Model MD900 helicopters, serial numbers 0008 through 0068, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in

the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated.

To prevent damage to the longitudinal drive link (drive link), loss of control of the main rotor system, and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 100 hours time-in-service (TIS) or 3 months, whichever occurs first, unless previously accomplished, modify the nonrotating swashplate assembly, part number (P/N) 900C2010192-105, -107, or -109, in accordance with the Accomplishment Instructions, paragraphs 2.A.(1). and 2.A.(2)., of MD Helicopters Service Bulletin SB900-078, dated April 23, 2001 (SB).

(b) After modifying the nonrotating swashplate assembly, P/N 900C2010192-105, -107 or -109, in accordance with paragraph (a) of this AD, before further flight, dye-penetrant inspect the drive link assembly, P/N 900C2010212-101, for gouging or cracking in accordance with the Accomplishment Instructions, paragraph 2.B.(1). and 2.B.(2). of the SB, except that returning cracked parts to MDHI is not required by this AD.

(1) If a crack is found, before further flight, replace the drive link assembly, P/N 900C2010212-101, with an airworthy drive link assembly.

(2) If gouging is found without a crack, before further flight, rework the drive link assembly, P/N 900C2010212-101, in accordance with the Accomplishment Instructions, paragraph 2.B.(3). of the SB.

Note 2: Even if you have previously dye-penetrant inspected the drive link assembly, you must accomplish the inspection required by paragraph (b) of this AD after modifying the swashplate assembly in accordance with paragraph (a) of this AD.

(c) Record compliance with this AD on the component history card or equivalent record for the nonrotating swashplate assembly.

(d) Accomplishing the actions required by paragraphs (a) and (b) of this AD is terminating action for the requirements of this AD.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Los Angeles Aircraft Certification Office.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles Aircraft Certification Office.

(f) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

(g) The inspection and modification shall be done in accordance with the Accomplishment Instructions, paragraphs 2.A.(1), 2.A.(2), 2.B.(1), 2.B.(2), and 2.B.(3) of MD Helicopters Service Bulletin SB900-078, dated April 23, 2001 (SB). This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from MD Helicopters, Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9734, telephone 1-800-388-3378, fax 480-891-6782, or on the web at www.mdhelicopters.com. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

(h) This amendment becomes effective on December 26, 2002.

Issued in Fort Worth, Texas, on November 6, 2002.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 02-29156 Filed 11-19-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-218-AD; Amendment 39-12949; AD 2002-23-05]

RIN 2120-AA64

Airworthiness Directives; Cessna Model 750 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Cessna Model 750 airplanes, that requires replacement of reset circuit breakers for the auxiliary hydraulic pump system and the King KHF 950 high frequency communication system(s) with new circuit breakers. This amendment is prompted by a report from the airplane manufacturer indicating that the trip levels for the reset circuit breakers installed in the auxiliary hydraulic pump system and the King KHF 950 high frequency system(s) are too high, which can prevent corresponding high current remote control circuit breakers

from tripping when excessive electrical loads are present. The actions specified by this AD are intended to prevent overloading of the affected airplane electrical wiring and circuits, which could result in a fire.

DATES: Effective December 26, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 26, 2002.

ADDRESSES: The service information referenced in this AD may be obtained from Cessna Aircraft Co., PO Box 7706, Wichita, Kansas 67277. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Jose Flores, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4133; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Cessna Model 750 airplanes was published in the **Federal Register** on November 4, 1999 (64 FR 60136). That action proposed to require replacement of reset circuit breakers for the auxiliary hydraulic pump system and the King KHF 950 high frequency communication system(s) with new circuit breakers.

Comment

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comment received.

Request To Withdraw Proposed AD

One commenter, the airplane manufacturer, states that it has verified that 100 percent of the affected Cessna Model 750 airplanes have done the replacement required by the proposed AD per Cessna Service Bulletin SB750-24-15, dated May 7, 1999 (which is referenced as an acceptable means of compliance in the proposed AD). The commenter adds that "production

aircraft units; 750-0073 through 750-0100 received replacement circuit breakers by disposition," and that this change was serialized on airplanes having serial number 750-0101 in production, with the incorporation of the split bus.

From this comment, the FAA infers that the commenter is requesting that the proposed AD be withdrawn. We do not agree. The airplane manufacturer provided no data that all affected airplanes, worldwide, have had the required replacement incorporated; therefore, this AD is necessary to address the identified unsafe condition on the affected airplanes.

Because the language in Note 2 of the proposed AD is regulatory in nature, that note has been redesignated as paragraph (b) of this final rule.

Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the change previously described. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

There are approximately 82 airplanes of the affected design in the worldwide fleet. The FAA estimates that 80 airplanes of U.S. registry will be affected by this AD, that it will take approximately 3 work hours per airplane to accomplish the required replacement, and that the average labor rate is \$60 per work hour. The airplane manufacturer has committed previously to its customers that it will bear the cost of replacement parts. As a result, the costs of those parts are not attributable to this AD. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$14,400, or \$180 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD, and that no operator would accomplish those actions in the future if this AD were not adopted. However, the FAA has been advised that manufacturer warranty remedies are available for parts and labor costs associated with accomplishing the actions required by this AD. Therefore, the future economic cost impact of this rule on U.S. operators may be less than the cost impact figure indicated above.