

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. FAA amends § 39.13 by adding a new AD to read as follows:

2004–15–19 The New Piper Aircraft, Inc.:
Amendment 39–13753; Docket No. 2003–CE–52–AD.

When Does This AD Become Effective?

(a) This AD becomes effective on September 13, 2004.

What Other ADs Are Affected by This Action?

(b) None.

What Airplanes Are Affected by This AD?

(c) This AD affects Model PA–46–500TP airplanes, serial numbers 4697001 through 4697163, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of reports of a protective cover installed over the percussion cap or a silicon tube installed over the end of the trigger mechanism pin, on the oxygen

generator, rendering the emergency oxygen system inoperative. The actions specified in this AD are intended to detect and remove any protective cover over the percussion cap or any silicon tube over the end of the trigger mechanism pin, which could result in failure of the emergency oxygen system. This failure could lead to the crew or passengers not being able to get oxygen in an emergency situation.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Inspect: (i) the percussion cap of any oxygen generator (part number (P/N) 471–025) for the presence of any protective cover; and (ii) the end of the trigger mechanism of any oxygen generator (P/N 471–025) for the presence of any silicon tube.	Within the next 50 hours time-in-service after September 13, 2004 (the effective date of this AD) or within the next 30 calendar days after September 13, 2004 (the effective date of this AD), whichever occurs first, unless already done.	Follow the <i>INSTRUCTIONS</i> paragraph in The New Piper Aircraft, Inc. Service Bulletin No. 1140, dated September 16, 2003, and the applicable airplane maintenance manual.
(2) If during the inspections required by paragraphs (e)(1)(i) and (e)(1)(ii) of this AD, you find any protective cover over the percussion cap or any silicon tube over the end of the trigger mechanism, remove any protective cover or silicon tube.	Before further flight after the inspection required in paragraph (e)(1) of this AD, unless already done.	Follow the <i>INSTRUCTIONS</i> paragraph in The New Piper Aircraft, Inc. Service Bulletin No. 1140, dated September 16, 2003, and the applicable airplane maintenance manual.
(3) Do not operate the airplane after installation of any oxygen generator (P/N 471–025) referenced in this AD unless any protective cover of the percussion cap or any silicon tube over the end of the trigger mechanism has been removed.	As of September 13, 2004 (the effective date of this AD).	Not applicable.

Note 1: Standard procedure is to remove the protective cover after installation. Refer to the applicable airplane maintenance manual for specific procedures for removing any protective cover of the percussion cap or any silicon tube over the end of the trigger mechanism.

Note 2: The affected models in the service bulletin referenced in this AD include the Models PA–46–310P and PA–46–350P airplanes. However, these models are certificated at a lower service ceiling than the Model PA–46–500TP airplane. Since Piper has demonstrated an emergency descent to a lower altitude with no oxygen to the pilot, neither Model PA–46–310P nor PA–46–350P airplanes are affected by the identified condition.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Atlanta Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Hector Hernandez, Aerospace Engineer, FAA, Atlanta ACO, One Crown Center, 1895 Phoenix Boulevard, Suite 450,

Atlanta, Georgia 30349; telephone: (770) 703–6069; facsimile: (770) 703–6097.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following the instructions in The New Piper Aircraft, Inc. Service Bulletin No. 1140, dated September 16, 2003. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (772) 567–4361; facsimile: (772) 978–6584. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on July 22, 2004.

Dorenda D. Baker,
Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04–17218 Filed 7–29–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–SW–40–AD; Amendment 39–13745; AD 2004–15–11]

RIN 2120–AA64

Airworthiness Directives; Eurocopter France Model EC155B and B1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for the specified Eurocopter France (ECF) model helicopters that requires cleaning the auxiliary system unit (ASU) board

and modifying the wiring and wiring harness. If a temporary modification is done, the AD requires inserting a placard regarding on-ground operation of the emergency landing gear pump (pump). Also, this AD revises the Limitations section of the Rotorcraft Flight Manual (RFM) to limit the operation of the pump. Permanently modifying the wiring and wiring harness and removing the placard and limitations from the RFM is terminating action for the requirements of this AD. This amendment is prompted by the report of an emergency landing with the landing gear retracted. The landing gear failed to extend in normal and emergency extension modes following failure of the ASU board 10 Alpha 2. The actions specified by this AD are intended to prevent an electrical short circuit, failure of landing gear to extend, and a landing gear-up emergency landing.

DATES: Effective September 3, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 3, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FOR FURTHER INFORMATION CONTACT:

Jorge Castillo, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5127, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend 14 CFR part 39 to include an AD for the specified model helicopters was published in the **Federal Register** on March 26, 2004 (69 FR 15744). That action proposed to require cleaning the ASU board and modifying the wiring and wiring harness. If a temporary modification is done, the action proposed to require inserting a placard regarding on-ground operation of the pump. Also, the action proposed to revise the Limitations

section of the RFM to limit the operation of the pump. Also proposed was permanently modifying the wiring and wiring harness and then removing the placard and limitations from the RFM, which would be terminating action for the requirements of the AD.

The Direction Generale De L'Aviation Civile (DGAC), the airworthiness authority for France, notified the FAA that an unsafe condition may exist on Model EC 155B and B1 helicopters equipped with ASU board 10 Alpha 2, part number (P/N) SE07451. The DGAC advises that a landing gear did not extend in "NORMAL" and "EMERGENCY" extension modes due to a short-circuit between two components of the ASU board 10 Alpha 2.

ECF has issued Alert Telex No. 31A005R1, dated September 19, 2002, and Alert Service Bulletin (ASB) Nos. 31A005 and 31A008, both dated August 20, 2003. The Alert Telex and ASB No. 31A005 describe procedures for modifying the electrical circuit to preclude the risk of the landing gear not extending in the normal and emergency extension modes following failure of the ASU board 10 Alpha 2. ASB No. 31A008 describes procedures to enhance the reliability of the normal and emergency landing gear extension functions by separating their power supplies. The DGAC classified these service bulletins as mandatory and issued AD Nos. 2002-515(A) R1 and 2003-323(A), both dated September 3, 2003, to ensure the continued airworthiness of these helicopters in France.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that this AD will affect 5 helicopters of U.S. registry, and modifying the electrical system will take about 11 work hours per helicopter at an average labor rate of \$65 per work hour. Required parts will cost approximately \$400 per helicopter. Based on these figures, we estimate the total cost impact of the AD on U.S. operators to be \$5,575.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not

have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2004-15-11 Eurocopter France:

Amendment 39-13745. Docket No. 2003-SW-40-AD.

Applicability: Model EC155B and B1 helicopters with auxiliary system unit (ASU) board 10 Alpha 2, part number (P/N) SE07451, installed, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent an electrical short circuit, failure of landing gear to extend, and an emergency landing, accomplish the following:

(a) Within 15 hours time-in-service (TIS), clean the auxiliary system unit (ASU) board 10 Alpha 2. Clean the ASU board by following the Accomplishment Instructions, paragraphs 2.B.1, and 2.B.2.a., of Eurocopter EC155 Alert Service Bulletin (ASB) No. 31A005, dated August 20, 2003 (ASB No. 31A005).

(b) Within 30 days, modify the wiring and wiring harness permanently by complying with paragraph (c) of this AD or temporarily by following the Accomplishment Instructions, paragraphs 2.B.1. and 2.B.2.a. through 2.B.2.d. of ASB No. 31A005. If temporarily modified:

(1) Install a self-adhesive placard of the size and in the location depicted in Figure 4 of ASB No. 31A005 with the following text in white letters on a red background: "CAUTION: ON GROUND OPERATION OF EMERGENCY LANDING GEAR PUMP IS TIME LIMITED—SEE OPERATING LIMITATIONS" and

(2) Revise the Operating Limitations by inserting the following text into the Rotorcraft Flight Manual (RFM):

"(i) Limit the emergency landing gear pump (pump) to 10 minutes of continuous operation.

(ii) When the pump is continuously operated from 1 to 5 minutes, allow it to cool for 15 minutes before further use.

(iii) When the pump is continuously operated from 5 to 10 minutes, allow it to cool for 30 minutes before further use."

Note 1: Modifying the electric wiring covered by Alert Telex No. 31A005R1, dated September 19, 2002, led to inhibiting the protective thermal switch of the electric pump. This resulted in the need for a limitation placard. The purpose of the limitation placard is to remind operators about the on-ground operating limitations that apply to the electric pump.

(c) Within 10 months, modify the wiring and wiring harness by following the Accomplishment Instructions, paragraphs 2.A. and 2.B., of Eurocopter EC155 ASB No. 31A008, dated August 20, 2003 (ASB No. 31A008). If you made the temporary modifications described in paragraph (b) of this AD, remove the placard from the helicopter and the limitations inserted in the RFM as a result of paragraphs (b)(1) and (b)(2) of this AD.

(d) Permanently modifying the wiring and wiring harness following ASB No. 31A008 is terminating action for the requirements of this AD.

(e) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

(f) Special flight permits will not be issued.

(g) Cleaning the auxiliary system unit and modifying the wiring and wiring harness shall be done by following Eurocopter EC155 Alert Service Bulletin No. 31A005 and Alert Service Bulletin No. 31A008, both dated August 20, 2003, as applicable. The Director of the Federal Register approved this incorporation by reference in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

(h) This amendment becomes effective on September 3, 2004.

Note 2: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD Nos. 2002-515(A) R1 and 2003-323(A), both dated September 3, 2003.

Issued in Fort Worth, Texas, on July 16, 2004.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 04-17219 Filed 7-29-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-302-AD; Amendment 39-13751; AD 2004-15-17]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes, that requires a one-time inspection to determine the part number of the engine mounting frames, brace struts, and attachment fittings; and related corrective action. This action is necessary to ensure the structural integrity of the engine-to-wing load path and prevent possible separation of the engine from the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective September 3, 2004.

The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of September 3, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1503; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes was published in the **Federal Register** on June 2, 2004 (69 FR 31053). That action proposed to require a one-time inspection to determine the part number of the engine mounting frames, brace struts, and attachment fittings; and related corrective action.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 41 airplanes of U.S. registry will be affected by this AD, that it will take approximately 4 work hours per airplane to accomplish the required actions, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$10,660, or \$260 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various