

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus SAS Airplanes: Docket No. FAA–2022–1407; Project Identifier MCAI–2022–01043–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 19, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel System.

(e) Unsafe Condition

This AD was prompted by reports of potential foreign object debris (FOD) contamination of the thermal relief valve (TRV). The FAA is issuing this AD to address potential FOD contamination, which could lead to a fuel leak. The unsafe condition, if not addressed, could result in an auxiliary power unit (APU) or engine fire and contribute to an uncontrolled fire, possibly resulting in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0157, dated August 4, 2022 (EASA AD 2022–0157).

(h) Exceptions to EASA AD 2022–0157

(1) Where EASA AD 2022–0157 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (3) of EASA AD 2022–0157 specifies “any discrepancy” this AD defines discrepancy as leaks of the APU, the engine low pressure (LP) shut-off valve (SOV), and the APU isolation shut-off valve (ISOV).

(3) The “Remarks” section of EASA AD 2022–0157 does not apply to this AD.

(4) Where the service information referenced in EASA AD 2022–0157 specifies

to scrap certain parts, send those parts to the manufacturer, or check spares, this AD does not include that requirement.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2022–0157 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (j)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Additional Information

For more information about this AD, contact Hassan Ibrahim, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3653; email Hassan.M.Ibrahim@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0157, dated August 4, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0157, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on October 27, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–23808 Filed 11–3–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–1401; Project Identifier AD–2022–01017–E]

RIN 2120–AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain General Electric Company (GE) CF6–80E1A2, CF6–80E1A3, CF6–80E1A4, and CF6–80E1A4/B model turbofan engines. This proposed AD was prompted by a manufacturer investigation that revealed that certain compressor discharge pressure seals (CDP seals) and forward outer seals were manufactured from powder metal material suspected to contain iron inclusion. This proposed AD would require the replacement of the affected CDP seals and forward outer seals. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by December 19, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to *regulations.gov*. Follow the instructions for submitting comments.
- *Fax*: (202) 493–2251.
- *Mail*: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* by searching for and locating Docket No. FAA–2022–1401; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:
Alexei Marqueen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7178; email: *Alexei.T.Marqueen@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2022–1401; Project Identifier AD–2022–01017–E” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other

information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Alexei Marqueen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA was notified by the manufacturer of the detection of iron inclusion in a turbine disk manufactured from the same powder metal material used to manufacture certain CDP seals and forward outer seals for GE CF6–80E1A2, CF6–80E1A3, CF6–80E1A4, and CF6–80E1A4/B model turbofan engines. Further investigation by the manufacturer determined that the iron inclusion is attributed to deficiencies in the manufacturing process. The investigation by the manufacturer also

determined that certain CF6–80E1A2, CF6–80E1A3, CF6–80E1A4, and CF6–80E1A4/B CDP seals and forward outer seals made from billets manufactured using the same process may have reduced material properties and a lower fatigue life capability due to iron inclusion, which may cause premature fracture and uncontained failure. As a result of its investigation, the manufacturer published service information that specifies procedures for the removal and replacement of certain CDP seals and forward outer seals installed on CF6–80E1A2, CF6–80E1A3, CF6–80E1A4, and CF6–80E1A4/B model turbofan engines. This condition, if not addressed, could result in uncontained debris release, damage to the engine, and damage to the aircraft.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information

The FAA reviewed GE CF6–80E1 Service Bulletin (SB) 72–0597 R00, dated August 5, 2022. This service information specifies procedures for removing the CDP seal and forward outer seal from service.

Proposed AD Requirements in This NPRM

This proposed AD would require the removal of certain CDP seals and forward outer seals from service and replacement with parts eligible for installation.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 0 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace CDP seal	8 work-hours × \$85 per hour = \$680.	\$154,768 (prorated)	\$155,448	\$0
Replace forward outer seal	8 work-hours × \$85 per hour = \$680.	1,289,792 (prorated)	1,290,472	0

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

General Electric Company: Docket No. FAA–2022–1401; Project Identifier AD–2022–01017–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 19, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company CF6–80E1A2, CF6–80E1A3, CF6–80E1A4, CF6–80E1A4/B model turbofan engines with an installed:

- (1) Compressor discharge pressure seal (CDP seal) with part number (P/N) 1669M73P02 and serial number (S/N) TMT1C0E1 or TMT1C0E2; or
- (2) Forward outer seal with P/N 1778M70P03 and S/N NCU65340.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section; 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by a manufacturer investigation that revealed that certain CDP seals and forward outer seals were manufactured from powder metal material suspected to contain iron inclusion. The FAA is issuing this AD to prevent fracture and uncontained failure of certain CDP seals and forward outer seals. The unsafe condition, if not addressed, could result in uncontained debris release, damage to the engine, and damage to the aircraft.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

- (1) At the next piece-part exposure after the effective date of this AD or before the affected CDP seal exceeds 6,400 cycles since new (CSN), whichever occurs first, remove the affected CDP seal from service and replace with a part eligible for installation.
- (2) At the next piece-part exposure after the effective date of this AD or before the affected forward outer seal exceeds 5,400 CSN, whichever occurs first, remove the affected forward outer seal from service and replace with a part eligible for installation.

(h) Definitions

- (1) For the purpose of this AD, a “part eligible for installation” is a CDP seal that does not have P/N 1669M73P02 and S/N TMT1C0E1 or S/N TMT1C0E2, and a forward outer seal that does not have P/N 1778M70P03 and S/N NCU65340.
- (2) For the purpose of this AD, “piece-part exposure” is when the affected part is removed from the engine.

(i) Installation Prohibition

After the effective date of this AD, do not install a CDP seal with P/N 1669M73P02 and S/N TMT1C0E1 or S/N TMT1C0E2, or a forward outer seal with P/N 1778M70P03 and S/N NCU65340, onto any engine.

(j) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office,

send it to the attention of the person identified in paragraph (k) of this AD and email to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Alexei Marqueen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7178; email: Alexei.T.Marqueen@faa.gov.

(l) Material Incorporated by Reference

None.

Issued on October 24, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–23460 Filed 11–3–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2022–1225; Airspace Docket No. 22–AGL–31]

RIN 2120–AA66

Proposed Amendment of Class E Airspace; Plymouth and Winamac, IN

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend the Class E airspace at Plymouth and Winamac, IN. The FAA is proposing this action due to an airspace review conducted as part of the decommissioning of the Knox very high frequency (VHF) omnidirectional range (VOR) as part of the VOR Minimal Operational Network (MON) Program. The geographic coordinates of Plymouth Municipal Airport would also be updated to coincide with the FAA’s aeronautical database.

DATES: Comments must be received on or before December 19, 2022.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590; telephone (202) 366–9826, or (800) 647–5527. You must identify FAA Docket No. FAA–2022–1225/Airspace Docket No. 22–AGL–31 at the beginning of your comments. You may also submit comments through the