

Proposed Rules

Federal Register

Vol. 73, No. 24

Tuesday, February 5, 2008

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0116; Directorate Identifier 2007-NM-257-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 2000 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Wing anti ice telescopic tubes (P/N [part number] 5035-400 and 5035-500) ball joints were originally designed with high temperature polymer (Kynel™) sealing rings. Temperature induced cracking of these rings associated with long term wear has been encountered in a small number of cases. This degradation may lead to binding of the ball joint and high swiveling forces which may result in improper operation of the leading edge slats and also in failure of the ball joint mounting bracket with possible friction on the aileron control rod, which could lead, if combined with a failure of the aileron emergency actuator, to an aileron jamming.

The unsafe condition is a jammed aileron, which results in reduced controllability of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by March 6, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0116; Directorate Identifier 2007-NM-257-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2006-0276, dated September 6, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Wing anti ice telescopic tubes (P/N [part number] 5035-400 and 5035-500) ball joints were originally designed with high temperature polymer (Kynel™) sealing rings. Temperature induced cracking of these rings associated with long term wear has been encountered in a small number of cases. This degradation may lead to binding of the ball joint and high swiveling forces which may result in improper operation of the leading edge slats and also in failure of the ball joint mounting bracket with possible friction on the aileron control rod, which could lead, if combined with a failure of the aileron emergency actuator, to an aileron jamming.

A replacement carbon based material has been defined by the telescopic tube manufacturer Zodiac and can be applied per Zodiac Service bulletins (SB) 5035-30-001 and 5035-30-002, resulting in P/N redesignations 5035-600 Amdt.A and 5035-700 Amdt.A, respectively.

The purpose of this Airworthiness Directive (AD), by requiring modification of the wing anti-ice telescopic tubes in accordance with the Zodiac service bulletins, is to ensure that no old definition sealing rings remain in operation beyond a life limit of 2,400 flight hours (FH) or 2,000 flight cycles (FC).

The unsafe condition is a jammed aileron, which results in reduced controllability of the airplane. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Zodiac has issued Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information

referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 159 products of U.S. registry. We also estimate that it would take about 4 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$1,423 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$277,137, or \$1,743 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Dassault Aviation: Docket No. FAA-2008-0116; Directorate Identifier 2007-NM-257-AD.

Comments Due Date

(a) We must receive comments by March 6, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Dassault Model Falcon 2000 airplanes, certificated in any category; all serial numbers; equipped with wing anti-ice telescopic tubes having part number (P/N) 5035-400 or 5035-500.

Subject

(d) Air Transport Association (ATA) of America Code 30: Ice and rain protection.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: Wing anti ice telescopic tubes (P/N [part number] 5035-400 and 5035-500) ball joints were originally designed with high temperature polymer (Kynel™) sealing rings. Temperature induced cracking of these rings associated with long term wear has been encountered in a small number of cases. This degradation may lead to binding of the ball joint and high swiveling forces which may result in improper operation of the leading edge slats and also in failure of the ball joint mounting bracket with possible friction on the aileron control rod, which could lead, if combined with a failure of the aileron emergency actuator, to an aileron jamming.

A replacement carbon based material has been defined by the telescopic tube manufacturer Zodiac and can be applied per Zodiac Service bulletins (SB) 5035-30-001 and 5035-30-002, resulting in P/N redesignations 5035-600 Amdt.A and 5035-700 Amdt.A, respectively.

The purpose of this Airworthiness Directive (AD), by requiring modification of the wing anti-ice telescopic tubes in accordance with the Zodiac service bulletins, is to ensure that no old definition sealing rings remain in operation beyond a life limit of 2,400 flight hours (FH) or 2,000 flight cycles (FC).

The unsafe condition is a jammed aileron, which results in reduced controllability of the airplane.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) At the later of the compliance times specified in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD, remove and modify the affected tubes in accordance with instructions contained in Zodiac Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002.

(i) Before the telescopic tubes, P/N 5035-400 and 5035-500, exceed the limit of 2,400 flight hours, or 2,000 flight cycles, time-in-service since new, whichever occurs first.

(ii) At the earlier of the times specified in paragraphs (f)(1)(ii)(A) and (f)(1)(ii)(B) of this AD.

(A) Within 330 flight hours after the effective date of this AD.

(B) Within 7 months after the effective date of this AD.

(2) As of 7 months after the effective date of this AD, no person may install an affected telescopic tube P/N 5035-400 or 5035-500 in any aircraft as a replacement part, unless it has been modified in accordance with instructions contained in Zodiac Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2006-0276, dated September 6, 2006; and Zodiac Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002; for related information.

Issued in Renton, Washington, on January 24, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-1984 Filed 2-4-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0118; Directorate Identifier 2007-NM-289-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 50 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the

products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

This Airworthiness Directive (AD) is issued following the discovery of a risk of chafing between an electrical feeder bundle and a bus bar under the circuit breaker panel. Most of the time, this possible chafing would be dormant and would lead to an uneventful loss of segregation within the different electrical system components. However, missing segregation combined with additional electrical failures may impair flight safety.

* * * * *

Chafing between an electrical feeder bundle and a bus bar under the circuit breaker panel could lead to electrical arcing, which could result in smoke and fire in the cockpit. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by March 6, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601

Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0118; Directorate Identifier 2007-NM-289-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued Airworthiness Directive 2007-0175, dated June 28, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

This Airworthiness Directive (AD) is issued following the discovery of a risk of chafing between an electrical feeder bundle and a bus bar under the circuit breaker panel. Most of the time, this possible chafing would be dormant and would lead to an uneventful loss of segregation within the different electrical system components. However, missing segregation combined with additional electrical failures may impair flight safety.

This AD mandates inspection of the electrical feeder bundle, and modification of its routing under the circuit breaker panel through implementation of modification M3093.

Chafing between an electrical feeder bundle and a bus bar under the circuit breaker panel could lead to electrical arcing, which could result in smoke and fire in the cockpit.

The corrective action includes repairing or replacing damaged wiring; re-routing the feeder cables above the wiring of the "Avionic Master" and "Aux Bat" relays; installing a protective sheath on the feeder cables; adding spacers to separate the bus bar wiring assemblies from the feeder cables; and adding Teflon protection on the feeder cables and securing the feeder cables