

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary at the address listed under ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2008-19-12 Honeywell International Inc. (formerly AlliedSignal Inc., formerly Garret Turbine Engine Company): Amendment 39-15679. Docket No. FAA-2008-0264; Directorate Identifier 2008-NE-07-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective October 27, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Honeywell International Inc. TFE731-4, -4R, -5, -5AR, -5BR, and -5R series turboprop engines, with interstage turbine transition (ITT) duct, part number (P/N) 3075292-1; 3075292-3; 3074766-1; 3077063-1; 3075655-1; 3075655-2; 3075699-1; or 3075699-3, installed. These engines are installed on, but not limited to, Avions Marcel Dassault Mystere-Falcon 50 series, Dassault-Aviation 20, 50, 900, MF900 series, Cessna Model 650, Cessna Citation VII, and Raytheon Corporate Jets (formerly British Aerospace) Hawker 800 and 850XP series airplanes.

Unsafe Condition

(d) This AD results from reports of 49 low-pressure turbine (LPT) blade separation events. Six of those events resulted in circumferential failure of the LPT2 or LPT3 nozzle assembly, leading to deformation of the ITT duct and uncontainment of the turbine blades and fragments of the LPT nozzle assembly. We are issuing this AD to prevent uncontainment of turbine blades and fragments of the LPT nozzle assembly, which could result in damage to the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed at the next Major Periodic Inspection of the engine or at next access of the ITT duct, whichever occurs first, but not to exceed 2,600 hours time-in-service after the effective date of this AD, unless the actions have already been done.

Replacement of the ITT Duct

(f) Replace the affected ITT ducts listed by part number in paragraph (c) of this AD, with a serviceable and redesigned ITT duct.

Definitions

(g) For the purpose of this AD, a serviceable and redesigned ITT duct is one not having a part number listed in this AD.

(h) For the purpose of this AD, next access of the ITT duct is when the ITT duct is removed from the engine.

Prohibition of Affected ITT Ducts

(i) After the effective date of this AD, do not install any ITT duct listed by P/N in paragraph (c) of this AD, onto any engine.

Alternative Methods of Compliance

(j) The Manager, Los Angeles Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(k) Honeywell International Inc. Service Bulletin (SB) No. TFE731-72-3727, dated September 12, 2007, and SB No. TFE731-72-3728, dated September 12, 2007, pertain to the subject of this AD.

(l) Contact Joseph Costa, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712-4137; e-mail: joseph.costa@faa.gov; telephone: (562) 627-5246; fax: (562) 627-5210, for more information about this AD.

Issued in Burlington, Massachusetts, on September 12, 2008.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E8-21835 Filed 9-19-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0674; Directorate Identifier 2008-NM-086-AD; Amendment 39-15675; AD 2008-19-08]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 10 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to all Avions Marcel Dassault-Breguet Model Falcon 10 airplanes. That AD currently requires either revising the airplane flight manual and installing a placard in the flight deck to prohibit flight into known or forecasted icing conditions, or repetitively inspecting for delamination of the flexible hoses in the wing (slat) anti-icing system and performing corrective actions if necessary. The existing AD also requires replacement of the flexible hoses installed in the slat anti-icing systems, which ends the repetitive inspections. This new AD continues to require replacement of the flexible hoses installed in the slat anti-icing systems with new hoses, but at intervals defined in flight hours instead of flight cycles. This AD results from information we received from operators and the airplane manufacturer indicating that the repetitive interval for the required replacement deviated from the referenced service information. We are issuing this AD to prevent collapse of the flexible hoses in the slat anti-icing system, which could lead to insufficient anti-icing capability and, if icing is encountered in this situation, could result in reduced controllability of the airplane.

DATES: This AD becomes effective October 27, 2008.

On October 11, 2007 (72 FR 51161, September 6, 2007), the Director of the Federal Register approved the incorporation by reference of Dassault Service Bulletin F10-313, Revision 1, dated May 10, 2006.

ADDRESSES: For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://>

www.regulations.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2007-18-08, amendment 39-15188 (72 FR 51161, September 6, 2007). The existing AD applies to all Avions Marcel Dassault-Breguet Model Falcon 10 airplanes. That NPRM was published in the **Federal Register** on June 27, 2008 (73 FR 36473). That NPRM proposed to continue to require either revising the airplane flight manual and installing a placard in the flight deck to prohibit flight into known or forecasted icing conditions, or repetitively inspecting for delamination of the flexible hoses in the wing (slat) anti-icing system and performing corrective actions if necessary. That NPRM also proposed to require replacement of the flexible hoses

installed in the slat anti-icing systems with new hoses, but at intervals defined in flight hours instead of flight cycles.

Comments

We provided the public the opportunity to participate in the development of this AD. No comments have been received on the NPRM or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD. The average labor rate is \$80 per work hour.

ESTIMATED COSTS

Action	Work hours	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Hose replacement	8	\$880	\$1,520, per replacement cycle ..	Up to 146.	Up to \$221,920, per replacement cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-15188 (72 FR 51161, September 6, 2007) and by adding the following new airworthiness directive (AD):

2008-19-08 Dassault Aviation (Formerly Avions Marcel Dassault-Breguet Aviation (AMD/BA)): Amendment 39-15675. Docket No. FAA-2008-0674; Directorate Identifier 2008-NM-086-AD.

Effective Date

- (a) This AD becomes effective October 27, 2008.

Affected ADs

- (b) This AD supersedes AD 2007-18-08.

Applicability

- (c) This AD applies to all Dassault Model Falcon 10 airplanes, certificated in any category.

Unsafe Condition

- (d) This AD results from information we received from operators and the airplane manufacturer indicating that the repetitive interval for the required replacement deviated from the referenced service information. We are issuing this AD to prevent collapse of the flexible hoses in the slat anti-icing system, which could lead to insufficient anti-icing capability and, if icing is encountered in this situation, could result in reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Certain Requirements of AD 2007–18–08**Hose Replacement**

(f) Within 330 flight hours or 7 months after October 11, 2007 (the effective date of AD 2007–18–08), whichever occurs first: Replace the flexible hoses installed in the slat anti-icing system with new hoses having part number (P/N) FAL1007, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F10–313, Revision 1, dated May 10, 2006. Repeat the hose replacement thereafter at intervals not to exceed 700 flight cycles, except as provided by paragraph (h) of this AD.

(g) Replacement of a hose before October 11, 2007, in accordance with Dassault Service Bulletin F10–313, dated August 10, 2005, is acceptable for compliance with the requirements of paragraph (f) of this AD.

New Requirements of This AD:**New Repetitive Interval**

(h) As of the effective date of this AD, repeat the hose replacement required by paragraph (f) of this AD within 700 flight hours since the last replacement, or within 100 flight hours after the effective date of this AD, whichever occurs later, and thereafter at intervals not to exceed 700 flight hours.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, International Branch, ANM–116, FAA, ATTN: Tom Rodriguez, Aerospace Engineer, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1137; fax (425) 227–1149; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(j) European Aviation Safety Agency airworthiness directive 2006–0114, dated May 10, 2006, also addresses the subject of this AD.

Material Incorporated by Reference

(k) You must use Dassault Service Bulletin F10–313, Revision 1, dated May 10, 2006, to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) On October 11, 2007 (72 FR 51161, September 6, 2007), the Director of the Federal Register approved the incorporation by reference of Dassault Service Bulletin F10–313, Revision 1, dated May 10, 2006.

(2) Contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606, for a copy of this service information.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 12, 2008.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8–22033 Filed 9–19–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. 29334; Amendment No. 71–40]

Airspace Designations; Incorporation by Reference

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 relating to airspace designations to reflect the approval by the Director of the Federal Register of the incorporation by reference (IBR) of FAA Order 7400.9R, Airspace Designations and Reporting Points. This action also explains the procedures the FAA will use to amend the listings of Class A, B, C, D, and E airspace areas; air traffic service routes; and reporting points incorporated by reference.

DATES: *Effective Date:* These regulations are effective September 16, 2008 until October 31, 2008. The incorporation by reference of FAA Order 7400.9R is approved by the Director of the Federal Register as of September 16, 2008 until October 31, 2008.

FOR FURTHER INFORMATION CONTACT: Tameka Bentley, Airspace and Rules Group, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267–9239.

SUPPLEMENTARY INFORMATION:**History**

FAA Order 7400.9R, Airspace Designations and Reporting Points, effective September 15, 2007, listed Class A, B, C, D and E airspace areas; air traffic service routes; and reporting points. Due to the length of these descriptions, the FAA requested

approval from the Office of the **Federal Register** to incorporate the material by reference in the Federal Aviation Regulations section 71.1. During the incorporation by reference period, from September 15, 2007 through September 15, 2008, the FAA processed all proposed changes of the airspace listings in FAA Order 7400.9R in full text as proposed rule documents in the **Federal Register**. Likewise, all amendments of these listings were published in full text as final rules in the **Federal Register**. This rule reflects the continued incorporation of 7400.9R, pending a revised edition of the Order. The Director of the Federal Register has extended the IBR approval of FAA Order 7400.9R in section 71.1, as of September 16, 2008 until October 31, 2008. This rule also explains the procedures the FAA will use to amend the airspace designations incorporated by reference in part 71. Sections 71.5, 71.15, 71.31, 71.33, 71.41, 71.51, 71.61, 71.71, and 71.901 are amended to reflect the incorporation by reference of FAA Order 7400.9R.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 to reflect the approval by the Director of the Federal Register of the incorporation by reference of FAA Order 7400.9R, effective September 16, 2008. This rule reflects the continued incorporation of 7400.9R, pending a revised edition of the Order. During the incorporation by reference, the FAA will continue to process all proposed changes of the airspace listings in the Order. Likewise, all amendments of these listings will be published in full text as final rules in the **Federal Register**. The FAA will periodically integrate all final rule amendments into a revised edition of the Order, and submit the revised edition to the Director of the Federal Register for approval for incorporation by reference in section 71.1.

The FAA has determined that this action: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation, as the anticipated impact is so minimal. This action neither places any new restrictions or requirements on the public, nor changes the dimensions or operation requirements of the airspace listings incorporated by reference in part 71. Consequently, notice and public procedure under 5 U.S.C. 553(b) are unnecessary. Because this action will continue to update the changes to the