

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2013–0978; Directorate Identifier 2013–NM–120–AD.

(a) Comments Due Date

We must receive comments by January 21, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 767–400ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 767–29–0113, dated May 29, 2013.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 29, Hydraulic Power.

(e) Unsafe Condition

This AD was prompted by reports of turbine wheel bursts in the air driven pump (ADP) turbine gearbox assembly (TGA), which resulted in the release of high energy fragments. We are issuing this AD to prevent fragments from an uncontained turbine wheel burst penetrating the fuselage and striking passengers, or penetrating the wing-to-body fairing and striking ground handling or maintenance personnel, causing serious injury.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement of Turbine Gearbox Assembly

Except as required by paragraph (i) of this AD: At the time specified in paragraph 1.E., “Compliance,” of Boeing Special Attention Service Bulletin 767–29–0113, dated May 29, 2013, replace the existing ADP TGA having part number N012000000 or N012000000–1 with an improved ADP TGA having part number N012000000–2 or N012000000–3, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767–29–0113, dated May 29, 2013.

Note 1 to paragraph (g) of this AD:

Guidance on modifying an existing ADP TGA so it can be re-identified as part number N012000000–2 or N012000000–3 can be found in Fairchild Controls Service Bulletin N012000000–29–03, Revision 2, dated January 29, 2013.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install an ADP TGA having part number N012000000 or N012000000–1 on any airplane.

(i) Exception to Service Information Specifications

Where Boeing Special Attention Service Bulletin 767–29–0113, dated May 29, 2013, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

(k) Related Information

(1) For more information about this AD, contact Kenneth Frey, Aerospace Engineer, Systems and Equipment Branch, ANM–130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6468; fax: 425–917–6190; email: kenneth.frey@faa.gov.

(2) For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on November 26, 2013.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013–29136 Filed 12–5–13; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2013–1024; Directorate Identifier 2013–NM–140–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model DHC–8–102, –103, –106, –201, –202, –301, –311, and –315 airplanes. This proposed AD was prompted by reports of a fractured wing-to-fuselage strut attachment joint bolt. This proposed AD would require doing a torque check of all wing-to-fuselage strut attachment joint bolts, and repairing or replacing if necessary. For certain airplanes this proposed AD would require a detailed inspection for corrosion, damage, and wear of each wing-to-fuselage strut attachment joint bolt and associated hardware, and replacing if necessary; and a borescope inspection for corrosion and damage of the bore hole and barrel nut threads, and repairing or replacing if necessary. We are proposing this AD to detect and correct fractured bolts, which could result in reduced structural integrity of the wing-to-fuselage strut attachment joint and subsequent loss of the wing.

DATES: We must receive comments on this proposed AD by January 21, 2014.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416–375–4000; fax 416–375–4539; email

thd.qseries@aero.bombardier.com;
Internet <http://www.bombardier.com>.
You may view this referenced service
information at the FAA, Transport
Airplane Directorate, 1601 Lind Avenue
SW., Renton, WA. For information on
the availability of this material at the
FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on
the Internet at <http://www.regulations.gov>; or in person at the
Docket Management Facility between 9
a.m. and 5 p.m., Monday through
Friday, except Federal holidays. The AD
docket contains this proposed AD, the
regulatory evaluation, any comments
received, and other information. The
street address for the Docket Office
(telephone (800) 647-5527) is in the
ADDRESSES section. Comments will be
available in the AD docket shortly after
receipt.

FOR FURTHER INFORMATION CONTACT:

Jeffrey Zimmer, Aerospace Engineer,
Airframe and Propulsion Branch, ANE-
171, FAA, New York Aircraft
Certification Office, 1600 Stewart
Avenue, Suite 410, Westbury, New York
11590; telephone (516) 228-7306; fax
(516) 794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written
relevant data, views, or arguments about
this proposed AD. Send your comments
to an address listed under the
ADDRESSES section. Include “Docket No.
FAA-2013-1024; Directorate Identifier
2013-NM-140-AD” at the beginning of
your comments. We specifically invite
comments on the overall regulatory,
economic, environmental, and energy
aspects of this proposed AD. We will
consider all comments received by the
closing date and may amend this
proposed AD based on those comments.

We will post all comments we
receive, without change, to <http://www.regulations.gov>, including any
personal information you provide. We
will also post a report summarizing each
substantive verbal contact we receive
about this proposed AD.

Discussion

Transport Canada Civil Aviation
(TCCA), which is the aviation authority
for Canada, has issued Canadian
Airworthiness Directive CF-2013-17R1,
dated June 27, 2013 (referred to after
this as the Mandatory Continuing
Airworthiness Information, or “the
MCAI”), to correct an unsafe condition
for the specified products. The MCAI
states:

There have been two in-service reports of
a wing-to-fuselage strut attachment joint bolt
found fractured during routine maintenance.
Laboratory examination of one fractured bolt
revealed that the fracture was attributed to
stress corrosion cracking.

Failure of the bolts could compromise the
structural integrity of the wing-to-fuselage
strut attachment joint and could lead to a
subsequent loss of the wing.

This [Canadian] AD mandates the
inspection and rectification, as required, of
the wing-to-fuselage strut attachment joint
bolts and associated hardware.

* * * * *

Required actions include doing a torque
check of wing-to-fuselage strut
attachment joint bolts, and repairing or
replacing if necessary. For certain
airplanes, required actions include a
detailed inspection for corrosion,
damage (including but not limited to
scratching, cracking, pitting, cross
threads, etc.), and wear of each wing-to-
fuselage strut attachment joint bolt and
associated hardware, and replacement if
necessary; and a borescope inspection
for corrosion and damage of the bore
hole and barrel nut threads, and repair
or replacement if necessary. You may
examine the MCAI in the AD docket on
the Internet at <http://www.regulations.gov> by searching for
and locating it in Docket No. FAA-
2013-1024.

Relevant Service Information

Bombardier has issued Service
Bulletin 8-57-47, Revision A, dated
May 29, 2013. The actions described in
this service information are intended to
correct the unsafe condition identified
in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by
the aviation authority of another
country, and is approved for operation
in the United States. Pursuant to our
bilateral agreement with the State of
Design Authority, we have been notified
of the unsafe condition described in the
MCAI and service information
referenced above. We are proposing this
AD because we evaluated all pertinent
information and determined an unsafe
condition exists and is likely to exist or
develop on other products of the same
type design.

Differences Between This Proposed AD and the MCAI or Service Information

In many FAA transport ADs, when
the service information specifies to
contact the manufacturer for further
instructions if certain discrepancies are
found, we typically include in the AD
a requirement to accomplish the action
using a method approved by either the

FAA or the State of Design Authority (or
its delegated agent).

We have recently been notified that
certain laws in other countries do not
allow such delegation of authority, but
some countries do recognize design
approval organizations. In addition, we
have become aware that some U.S.
operators have used repair instructions
that were previously approved by a
State of Design Authority or a Design
Approval Holder (DAH) as a method of
compliance with this provision in FAA
ADs. Frequently, in these cases, the
previously approved repair instructions
come from the airplane structural repair
manual or the DAH repair approval
statements that were not specifically
developed to address the unsafe
condition corrected by the AD. Using
repair instructions that were not
specifically approved for a particular
AD creates the potential for doing
repairs that were not developed to
address the unsafe condition identified
by the MCAI AD, the FAA AD, or the
applicable service information, which
could result in the unsafe condition not
being fully corrected.

To prevent the use of repairs that
were not specifically developed to
correct the unsafe condition, this
proposed AD would require that the
repair approval specifically refer to the
FAA AD. This change is intended to
clarify the method of compliance and to
provide operators with better visibility
of repairs that are specifically developed
and approved to correct the unsafe
condition. In addition, we use the
phrase “its delegated agent, or by the
DAH with State of Design Authority
design organization approval, as
applicable” in this proposed AD to refer
to a DAH authorized to approve
required repairs for this proposed AD.

Costs of Compliance

We estimate that this proposed AD
affects 94 airplanes of U.S. registry. We
estimate the following costs to comply
with this proposed AD.

We also estimate that it would take
about 107 work-hours per product to
comply with the basic requirements of
this proposed AD. The average labor
rate is \$85 per work-hour. Required
parts would cost about \$5,476 per
product. Based on these figures, we
estimate the cost of this proposed AD on
U.S. operators to be \$1,369,674, or
\$14,571 per product.

We have received no definitive data
that would enable us to provide a cost
estimate for the repairs or replacements
specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This proposed regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

Bombardier, Inc.: Docket No. FAA-2013-1024; Directorate Identifier 2013-NM-140-AD.

(a) Comments Due Date

We must receive comments by January 21, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes; certificated in any category; serial numbers 003 through 672 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by reports of a fractured wing-to-fuselage strut attachment joint bolt. We are issuing this AD to detect and correct fractured bolts, which could result in reduced structural integrity of the wing-to-fuselage strut attachment joint and subsequent loss of the wing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Torque Check

At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD: Do a torque check of the wing-to-fuselage strut attachment joint bolts, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-47, Revision A, dated May 29, 2013.

(1) For airplanes that have accumulated fewer than 40,000 total flight cycles, and have less than 15 years in service since new, as of the effective date of this AD: Do the torque check before the accumulation of 42,000 total flight cycles, or within 16 years in service since new, whichever occurs first.

(2) For airplanes that have accumulated 40,000 total flight cycles or more, or have 15 years or more in service since new, as of the effective date of this AD: Do the torque check within 2,000 flight cycles or 12 months after the effective date of this AD, whichever occurs first.

(h) Inspection and Corrective Actions

(1) If only one bolt fails the torque check, before further flight, replace the bolt, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-47, Revision A, dated May 29, 2013; and before further flight do the actions specified in paragraphs (h)(3)(i) and (h)(3)(ii) of this AD.

(2) If more than one bolt fails the torque check, before further flight, repair, using a method approved by the Manager, New York Aircraft Certification Office (ACO), FAA; or Transport Canada Civil Aviation (TCCA) (or

its delegated agent or by the Design Approval Holder with the TCCA design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD.

(3) If all bolts pass the torque check, before further flight, do the actions specified in paragraphs (h)(3)(i) and (h)(3)(ii) of this AD, as applicable.

(i) Do a detailed inspection for corrosion, damage (including but not limited to scratching, cracking, pitting, and cross threads, etc.), and wear, of each wing-to-fuselage strut attachment joint bolt and associated hardware, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-47, Revision A, dated May 29, 2013. If any bolt or hardware has corrosion, damage, or wear, before further flight, replace the affected part, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-47, Revision A, dated May 29, 2013.

(ii) Do a borescope inspection for corrosion and damage (including but not limited to scratching, cracking, pitting, and cross threads, etc.) of the bore hole and barrel nut threads, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-47, Revision A, dated May 29, 2013, except as provided by paragraph (i) of this AD.

(A) If any corrosion or damage is found in the barrel nut threads, before further flight, replace the barrel nut, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-47, Revision A, dated May 29, 2013, except as provided by paragraph (i) of this AD.

(B) If any corrosion or damage is found in the bore of the hole, before further flight, repair, using a method approved by the Manager, New York ACO, FAA; or Transport Canada Civil Aviation (TCCA) (or its delegated agent or by the Design Approval Holder with the TCCA design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD.

(i) Exception to Service Information

Where Bombardier Service Bulletin 8-57-47, Revision A, dated May 29, 2013, specifies to contact the manufacturer for repair information, this AD requires repairing before further flight using a method approved by the Manager, New York ACO, FAA; or TCCA (or its delegated agent, or by the Design Approval Holder with TCCA design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 8-57-47, dated March 16, 2012.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO, ANE-170, FAA, has the authority to approve

AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they were approved by the State of Design Authority (or its delegated agent, or by the Design Approval Holder with a State of Design Authority's design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD. You are required to ensure the product is airworthy before it is returned to service.

(l) Special Flight Permits

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2013-17R1, dated June 27, 2013, for related information, which can be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-1024.

(2) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on November 29, 2013.

John P. Piccola,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-29134 Filed 12-5-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2013-0683; Airspace Docket No. 13-ANE-1]

Proposed Amendment of Class E Airspace; Morrisville, VT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E Airspace at Morrisville, VT, as the Morrisville-Stowe Non-Directional Beacon (NDB) has been decommissioned, requiring airspace redesign at Morrisville-Stowe State Airport. This action would enhance the safety and airspace management of Instrument Flight Rules (IFR) operations at the airport. This action also would update the geographic coordinates of the airport.

DATES: Comments must be received on or before January 21, 2014.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey, SE., Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2013-0683; Airspace Docket No. 13-ANE-1, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to comment on this rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2013-0683; Airspace Docket No. 13-

ANE-1) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2013-0683; Airspace Docket No. 13-ANE-1." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports-airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal Holidays at the office of the Eastern Service Center, Federal Aviation Administration, Room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory circular No. 11-2A, Notice of Proposed Rulemaking distribution System, which describes the application procedure.

The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class E airspace extending upward from 700 feet above the surface at Morrisville-Stowe State Airport, Morrisville, VT.