

for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2005–20–28 Airbus:** Amendment 39–14325. Docket No. FAA–2005–20687; Directorate Identifier 2004–NM–171–AD.

#### Effective Date

(a) This AD becomes effective November 16, 2005.

#### Affected ADs

(b) None.

### Applicability

(c) This AD applies to Airbus Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes; Model A320–111, –211, –212, –214, –231, –232, and –233 airplanes; and Model A321–111, –112, –131, –211 and –231 airplanes; certificated in any category; in which the floor proximity emergency escape path marking system (FPEPMS) is equipped with BRUCE emergency power supply units (EPSUs) having BRUCE part number (P/N) 100865.

### Unsafe Condition

(d) This AD was prompted by information that the existing system design for interconnection of the EPSUs of the FPEPMS does not provide adequate floor path lighting and marking for safe evacuation of the airplane in the event of an emergency. We are issuing this AD to prevent inadequate lighting and marking of the escape path, which could delay or impede the flightcrew and passengers when exiting the airplane during an emergency landing.

### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Modification

(f) Within 24 months after the effective date of this AD: Modify the FPEPMS by doing all the actions specified in the Accomplishment Instructions of Airbus Service Bulletin A320–33–1041, dated December 11, 2003.

### Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### Related Information

(h) French airworthiness directive F–2004–121 R1, dated October 13, 2004, also addresses the subject of this AD.

### Material Incorporated by Reference

(i) You must use Airbus Service Bulletin A320–33–1041, dated December 11, 2003, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the **Federal Register** approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL–401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on

the availability of this material at the NARA, call (202) 741–6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on September 28, 2005.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05–20074 Filed 10–11–05; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2005–20441; Directorate Identifier 2003–CE–35–AD; Amendment 39–14322; AD 2003–19–14 R2]

**RIN 2120–AA64**

**Airworthiness Directives; BURKHART GROB LUFT—UND RAUMFAHRT GmbH & CO KG Models G103 TWIN ASTIR, G103A TWIN II ACRO, and G103C TWIN III ACRO Sailplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is revising Airworthiness Directive (AD) 2003–19–14 R1, which applies to certain BURKHART GROB LUFT—UND RAUMFAHRT GmbH & CO KG (GROB) Models G103 TWIN ASTIR, G103A TWIN II ACRO, and G103C TWIN III ACRO sailplanes. AD 2003–19–14 R1 requires you to modify the airspeed indicators, install flight speed reduction and aerobatic maneuver restrictions placards (as applicable), and revise the flight and maintenance manuals. AD 2003–19–14 R1 approves simple aerobatic maneuvers for Model G103A TWIN II ACRO sailplanes and provides an option for modifying the rear fuselage for Models G103A TWIN II ACRO and G103C TWIN III ACRO sailplanes to terminate the flight limitation restrictions for aerobatic maneuvers. This AD retains all the actions from AD 2003–19–14 R1 for Models G103A TWIN II ACRO and G103C TWIN III ACRO and reinstates certain operating limits for Model G103 TWIN ASTIR sailplanes. We are issuing this AD to prevent damage to the fuselage during limit load flight, which could result in reduced structural integrity. This condition could lead to loss of control of the sailplane.

**DATES:** This AD becomes effective on November 30, 2005.

On August 12, 2004 (69 FR 34258, June 21, 2004) the Director of the

Federal Register approved the incorporation by reference GROB Service Bulletin No. MSB315-65, dated September 15, 2003; GROB Service Bulletin No. OSB 315-66, dated October 16, 2003; and GROB Work Instruction for OSB 315-66, dated October 16, 2003.

As of November 30, 2005, the Director of the Federal Register approved the incorporation by reference of GROB Service Bulletin No. MSB315-64/3, dated September 14, 2004.

**ADDRESSES:** To get the service information identified in this AD, contact GROB Luft-und Raumfahrt, Lettenbachstrasse 9, D-86874 Tussenhausen-Mattsies, Germany; telephone: 011 49 8268 998139; facsimile: 011 49 8268 998200; e-mail: [productsupport@grob-aerospace.de](mailto:productsupport@grob-aerospace.de).

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2005-20441; Directorate Identifier 2003-CE-35-AD.

#### FOR FURTHER INFORMATION CONTACT:

Gregory A. Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

*Has FAA taken any action to this point?* Reports from the Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, that the safety margins established into the design of the fuselage may not be sufficient to sustain limit loads during certain maneuvers and during flight at certain speeds for Model G103 TWIN ASTIR, G103 TWIN II, G103A TWIN II ACRO, and G103C TWIN III ACRO sailplanes. This caused us to issue AD 2003-19-14, Amendment 39-13317 (68 FR 56152, September 30, 2003). AD 2003-19-14 required the following:

- Modifying the airspeed indicators;
- Installing placards restricting flight speeds, prohibiting aerobatic maneuvers, and restricting load limits; and
- Incorporating revisions to the flight and maintenance manuals.

AD 2003-19-14 was issued as an interim action until the manufacturer completed further investigations into the effects of certain flight conditions on the fuselage structure and the development of corrective procedures.

The manufacturer conducted further investigations and static strength tests to verify the safety margins of the fuselage on the affected sailplanes. This information prompted us to issue AD 2003-19-14 R1, Amendment 39-13676 (69 FR 34258, June 21, 2004). AD 2003-19-14 R1 requires the following:

For Model G103 TWIN ASTIR sailplanes:

- Retain all flight limitation restrictions in AD 2003-19-14.

For Model G103 TWIN II sailplanes:

- Reinstate the original flight speed limitations and maneuver operations and remove from the applicability section of AD 2003-19-14;

For Model G103A TWIN II ACRO (utility category) sailplanes:

- Reinstate the original flight speed limitations and maneuver operations; and

- Allow only basic aerobatic maneuvers (spins, lazy eights, chandelles, stall turns, steep turns, and positive loops).

For Model G103A TWIN II ACRO (aerobatic category) sailplanes:

- Reinstate the original flight speed limitations except for rough air ( $V_B$ ) and maneuvering speeds ( $V_A$ ); and
- Allow only basic aerobatic maneuvers (spins, lazy eights, chandelles, stall turns, steep turns, and positive loops).

For Model G103C TWIN III ACRO sailplanes:

- Increase airspeed limits specified in AD 2003-19-14 but maintain a reduction from the original limitations; and
- Retain restrictions in AD 2003-19-14 on all aerobatic flights, including simple maneuvers, and cloud flying.

The manufacturer also developed a modification for Models G103A TWIN II ACRO (aerobatic category) and G103C TWIN III ACRO sailplanes (aerobatic category). When this modification is incorporated, full aerobatic status is restored to these sailplanes.

*What has happened since AD 2003-19-14 R1 to initiate this proposed action?* The LBA recently notified FAA of the need to change AD 2003-19-14 R1. Based on analysis, the LBA reports that certain limits of operation for Model G103 TWIN ASTIR sailplanes may be reinstated.

Specifically, the maximum airspeed in calm air ( $V_{NE}$ ) could be reinstated to 135 knots (155 mph/250kmh) for Model G103 TWIN ASTIR sailplanes. Aerobatic flight is still prohibited; however, simple aerobatic flight (looping, steep turns, lazy eights, and chandelles) may be performed following the flight manual.

*What is the potential impact if FAA took no action?* If not prevented,

damage to the fuselage during limit load flight could result in reduced structural integrity. This condition could lead to loss of control of the sailplane.

*Has FAA taken any action to this point?* We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain GROB Models G103 TWIN ASTIR, G103A TWIN II ACRO, and G103C TWIN III ACRO sailplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on March 23, 2005 (70 FR 14580). The NPRM proposed to revise AD 2003-19-14 R1 with a new AD that would:

- (1) retain all actions required in AD 2003-19-14 R1 for Models G103A TWIN II ACRO and G103C TWIN III ACRO sailplanes; and

- (2) reinstate certain operating limits for Model G103 TWIN ASTIR sailplanes.

#### Comments

*Was the public invited to comment?* We provided the public the opportunity to participate in developing this AD. We received no comments on the proposal or on the determination of the cost to the public.

#### Conclusion

*What is FAA's final determination on this issue?* We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

#### Changes to 14 CFR Part 39—Effect on the AD

*How does the revision to 14 CFR part 39 affect this AD?* On July 10, 2002, the FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

**Costs of Compliance**

*How many sailplanes does this AD impact? We estimate that this AD affects 94 sailplanes in the U.S. registry.*

*What is the cost impact of this AD on owners/operators of the affected sailplanes? We estimate the following costs to do the modifications to the*

airspeed indicators, flight limitations placards, and revising the flight and maintenance manuals:

Labor cost	Parts cost	Total cost per sailplane	Total cost on U.S. operators
1 work hour × \$65 = \$65 .....	Not applicable .....	\$65	\$65 × 94 = \$6,110.

For G103A TWIN II ACRO (aerobatic category) sailplanes and G103C TWIN III ACRO (aerobatic category) sailplanes,

we estimate the following costs to do the fuselage modification:

Labor cost	Parts cost	Total cost per sailplane
30 work hours × \$65 = \$1,950 .....	\$5,307	\$7,257.

*What is the difference between the cost impact of this AD and the cost impact of AD 2003–19–14 R1? There is no cost difference between this AD and AD 2003–19–14 R1. This AD is only revising certain operating limits for certain Model G103 TWIN ASTIR. This AD does not require any additional actions than are currently required in AD 2003–19–14 R1.*

**Authority for This Rulemaking**

*What authority does FAA have for issuing this rulemaking action? Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.*

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

**Regulatory Findings**

*Will this AD impact various entities? We have determined that this AD will*

not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*Will this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this AD:*

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD (and other information as included in the Regulatory Evaluation) and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "Docket No. FAA–2005–20441; Directorate Identifier 2003–CE–35–AD" in your request.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2003–19–14 R1, Amendment 39–13676 (69 FR 34258, June 21, 2004), and by adding a new AD to read as follows:

**2003–19–14 R2 BURKHART GROB LUFT—UND RAUMFAHRT GmbH & CO KG:**  
Amendment 39–14322; Docket No. FAA–2005–20441; Directorate Identifier 2003–CE–35–AD; Revises AD 2003–19–14 R1, Amendment 39–13676.

**When Does This AD Become Effective?**

(a) This AD becomes effective on November 30, 2005.

**What Other ADs Are Affected By This Action?**

(b) This AD revises AD 2003–19–14 R1, Amendment 39–13676.

**What Sailplanes Are Affected by This AD?**

(c) This AD affects the following sailplane models and serial numbers that are certificated in any category:

Model	Serial numbers
G103 TWIN ASTIR .....	All serial numbers.
G103A TWIN II ACRO (aerobatic category) .....	All serial numbers with suffix "K".
G103C TWIN III ACRO (aerobatic category) .....	All serial numbers.

**What Is the Unsafe Condition Presented in This AD?**

(d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for

Germany. The actions specified in this AD are intended to prevent damage to the fuselage during limit load flight, which could result in reduced structural integrity. This condition could lead to loss of control of the sailplane.

**What Must I Do To Address This Problem?**

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) For G103 TWIN ASTIR sailplanes: (i) Re-set the airspeed indicator to the new placard limitations; (ii) Install the following placard:	Within the next 25 hours time-in-service (TIS) after November 30, 2005 (the effective date of this AD), unless already done.	Following GROB Service Bulletin No. MSB315-64/3, dated September 14, 2004.

<b>Maximum flying weight</b>				
<b>Without Waterballast: 650 kg / 1435lbs</b>				
<b>With Waterballast: 650 kg / 1435 lbs</b>				
Maximum airspeeds:		km/h	kts	mph
In calm air:	V <sub>NE</sub>	250	135	155
In rough air:	V <sub>B</sub>	170	92	106
Aerotow:	V <sub>T</sub>	170	92	106
Winch or auto launch:	V <sub>W</sub>	120	65	75
Airbrakes open:	V <sub>DF</sub>	250	135	155
Maneuvering speed:	V <sub>A</sub>	170	92	106

- (iii) You may perform simple aerobatic flight (looping, steep turns, lazy eights, and chandelles) following the flight manual; and  
(iv) Revise the flight and maintenance manuals.

(2) For G103A TWIN II ACRO (acrobatic category) and G103C TWIN III ACRO (acrobatic category) sailplanes:

- (i) Re-set the airspeed indicator to the new placard limitations; and  
(ii) Install the following placards on Model G103A TWIN II ACRO (acrobatic category) sailplanes:

Within the next 25 hours time-in-service (TIS) after August 12, 2004 (the effective date AD 2003-19-14 R1), unless already done.

Follow Grob Service Bulletin No. MSB315-65, dated September 15, 2003.

“Simple Aerobatic” maneuvers (spins, lazy eights, chandelles, stall turns, steep turns, and positive loops) are permitted.

<b>Maximum flying weight</b>				
<b>580 kg / 1280 lbs</b>				
Maximum airspeeds:		km/h	kts	mph
In calm air:	V <sub>NE</sub>	250	135	155
In rough air:	V <sub>B</sub>	170	92	106
Aerotow:	V <sub>T</sub>	170	92	106
Winch or auto tow:	V <sub>W</sub>	120	65	75
Airbrakes extended:	V <sub>FE</sub>	250	135	155
Maneuvering speed:	V <sub>A</sub>	170	92	106

- (iii) Install the following placards on Model G103C TWIN III ACRO (acrobatic category) sailplanes:

All aerobatic maneuvers and cloud flying are prohibited

Maximum flying weight		580 kg / 1280 lbs		
Maximum airspeeds:		km/h	kts	mph
In calm air:	V <sub>NE</sub>	250	135	155
In rough air:	V <sub>RA</sub>	170	92	106
Aerotow:	V <sub>T</sub>	170	92	106
Winch or auto tow:	V <sub>W</sub>	120	65	75
Airbrakes extended:	V <sub>FE</sub>	250	135	155
Maneuvering speed:	V <sub>A</sub>	170	92	106

(3) For G103A TWIN II ACRO (acrobatic category) and G103C TWIN III ACRO (acrobatic category) sailplanes: as an alternative to the flight restrictions in paragraph (e)(2) of this AD, you may install additional stringers in the rear fuselage section. Installing additional stringers terminates the flight restrictions in paragraph (e)(2) of this AD.

(4) For G103A TWIN II ACRO (acrobatic category) and G103C TWIN III ACRO (acrobatic category) sailplanes: only if you installed the additional stringers specified in paragraph (e)(3) of this AD, do the following:

- (i) Remove the placard prohibiting all aerobatic maneuvers;
- (ii) Install the following flight limitation placard on Model G103A TWIN II ACRO (aerobatic category) sailplanes:

Maximum flying weight		580 kg / 1280 lbs		
Maximum airspeeds:		km/h	kts	mph
In calm air:	V <sub>NE</sub>	250	135	155
In rough air:	V <sub>RA</sub>	180	97	112
Aerotow:	V <sub>T</sub>	170	92	106
Winch or auto tow:	V <sub>W</sub>	120	65	75
Airbrakes extended:	V <sub>FE</sub>	250	135	155
Maneuvering speed:	V <sub>A</sub>	180	97	112

- (iii) Install the following flight limitation placard on Model G103C TWIN III ACRO (aerobatic category) sailplanes:

Maximum flying weight		600 kg / 1323 lbs		
Maximum airspeeds:		km/h	kts	mph
In calm air:	V <sub>NE</sub>	280	151	174
In rough air:	V <sub>B</sub>	200	108	124
Aerotow:	V <sub>T</sub>	185	100	115
Winch or auto tow:	V <sub>W</sub>	140	76	87
Airbrakes extended:	V <sub>FE</sub>	280	151	174
Maneuvering speed:	V <sub>A</sub>	185	100	115

At any time after August 12, 2004 (the effective date AD 2003-19-14 R1).

Prior to further flight after doing the actions in paragraph (e)(3) of this AD.

Follow Grob Service Bulletin No. OSB 315-66, dated October 16, 2003, and Work Instruction for OSB 315-66, dated October 16, 2003. Follow Grob Service Bulletin No. OSB 315-66, dated October 16, 2003.

**Note:** The placard information in this AD is different from the information in the applicable service bulletins. This AD takes precedence over the service bulletins. You should update your placards to reflect the information presented in this AD.

#### May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Gregory A. Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

#### Is There Other Information That Relates to This Subject?

(g) German AD D-2003-231R3, dated November 9, 2004, also addresses the subject of this AD.

#### Does This AD Incorporate Any Material by Reference?

(h) You must do the actions required by this AD following the instructions in GROB Service Bulletin No. MSB315-64/3, dated September 14, 2004; Grob Service Bulletin No. MSB315-65, dated September 15, 2003; Grob Service Bulletin No. OSB 315-66, dated October 16, 2003; and Work Instruction for OSB 315-66, dated October 16, 2003.

(1) On August 12, 2004 (69 FR 34258, June 21, 2004), and in accordance with 5 U.S.C. 552(a) and 1 CFR part 51, the Director of the Federal Register approved the incorporation by reference of Grob Service Bulletin No. MSB315-65, dated September 15, 2003; Grob Service Bulletin No. OSB 315-66, dated October 16, 2003; and Work Instruction for OSB 315-66, dated October 16, 2003.

(2) As of November 30, 2005, and in accordance with 5 U.S.C. 552(a) and 1 CFR part 51, the Director of the Federal Register approved the incorporation by reference of GROB Service Bulletin No. MSB315-64/3, dated September 14, 2004.

(3) To get a copy of this service information, contact GROB Luft-und Raumfahrt, Lettenbachstrasse 9, D-86874 Tussenhausen-Mattsies, Germany; telephone: 011 49 8268 998139; facsimile: 011 49 8268 998200; e-mail: [productsupport@grob-aerospace.de](mailto:productsupport@grob-aerospace.de). To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html) or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-

2005-20441; Directorate Identifier 2003-CE-35-AD.

Issued in Kansas City, Missouri, on September 28, 2005.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-19929 Filed 10-11-05; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2005-20221; Directorate Identifier 2004-NM-173-AD; Amendment 39-14329; AD 2005-20-32]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Airbus Model A330-200 and -300 and A340-200 and -300 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Airbus Model A330-200 and -300 and A340-200 and -300 series airplanes. This AD requires inspecting to determine the part number and serial number of the left- and right-hand elevator assemblies, performing related investigative and corrective actions if necessary, and re-protecting the elevator assembly. This AD results from reports that areas on the top skin panel of the right-hand elevator have disbonded due to moisture penetration. We are issuing this AD to prevent disbonding of the elevator assembly, which could reduce the structural integrity of the elevator and result in reduced controllability of the airplane.

**DATES:** This AD becomes effective November 16, 2005.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of November 16, 2005.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Tim Backman, Aerospace Engineer,

International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2797; fax (425) 227-1149.

#### **SUPPLEMENTARY INFORMATION:**

##### **Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

##### **Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all Airbus Model A330, A340-200, and A340-300 series airplanes. That NPRM was published in the **Federal Register** on February 1, 2005 (70 FR 5073). That NPRM proposed to require inspecting to determine the part number and serial number of the left- and right-hand elevator assemblies, performing related investigative and corrective actions if necessary, and re-protecting the elevator assembly.

##### **Comments**

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

##### **Request To Allow Records Check as a Method of Compliance**

One commenter believes that it is unnecessary to inspect its fleet to determine that none of the airplanes in its fleet are subject to the proposed AD. The commenter states that its airplanes were delivered new from Airbus in July 2003, after Airbus had changed its production processes to prevent moisture penetration of the elevator. The delivery records for these airplanes show the part number and serial number of the left- and right-hand elevator assemblies. The commenter notes that it has not replaced the elevator assemblies on any airplane in its fleet. Further, the Illustrated Parts Catalog shows that the elevator assemblies that would be affected by the proposed AD cannot legally be installed on the airplanes in its fleet. The commenter asserts that its airplanes are in compliance with the intent of the proposed AD, and that it will be able to ensure continuing compliance by inspecting all incoming spare elevator