

addition, FSIS offers an electronic mail subscription service which provides automatic and customized access to selected food safety news and information. This service is available at <http://www.fsis.usda.gov/wps/portal/fsis/programs-and-services/email-subscription-service>. Options range from recalls to export information to regulations, directives, and notices. Customers can add or delete subscriptions themselves, and have the option to password protect their accounts.

Done at Washington, DC, on November 26, 2013.

**Alfred V. Almanza,**  
Administrator.

[FR Doc. 2013-28840 Filed 12-2-13; 8:45 am]

BILLING CODE 3410-DM-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2013-1012; Directorate Identifier 2013-CE-037-AD]

RIN 2120-AA64

#### Airworthiness Directives; British Aerospace Regional Aircraft Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for British Aerospace Regional Aircraft Jetstream Series 3101 and Jetstream Model 3201 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as stress corrosion cracking of the main landing gear yoke pintle housing on a Jetstream series 3100 airplane. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by January 17, 2014.

**ADDRESSES:** You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

• **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact BAE Systems (Operations) Ltd, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; phone: +44 1292 675207, fax: +44 1292 675704; email: [RApublications@baesystems.com](mailto:RApublications@baesystems.com); Internet: <http://www.jetstreamcentral.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: [taylor.martin@faa.gov](mailto:taylor.martin@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2013-1012; Directorate Identifier 2013-CE-037-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

*regulations.gov*, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No.: 2013-0206, dated September 9, 2013 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

An occurrence of Jetstream 3100 main landing gear (MLG) failure after landing was reported. The subsequent investigation revealed stress corrosion cracking of the MLG yoke pintle housing as a root cause of the MLG failure. Degradation of the surface protection by abrasion can occur when the forward face of the yoke pintle rotates against the pintle bearing, which introduces corrosion pits and, consequently, stress corrosion cracking.

This condition, if not corrected, could lead to structural failure of the MLG possibly resulting in loss of control of the aeroplane during take-off or landing runs.

To address this potential unsafe condition, BAE Systems (Operations) Ltd issued Service Bulletin (SB) 32-JM7862 to provide instruction for installation of a protective washer fitted at the forward spigot on both, left hand (LH) and right hand (RH), MLG.

For the reasons described above, this AD requires installation of a washer to protect the MLG at the forward face of the yoke pintle.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-1012.

#### Relevant Service Information

British Aerospace Regional Aircraft has issued British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JM7862, Revision 1, dated May 7, 2013. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

## Costs of Compliance

We estimate that this proposed AD will affect 66 products of U.S. registry. We also estimate that it would take about 15 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$84,150, or \$1,275 per product.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

**British Aerospace Regional Aircraft:** Docket No. FAA-2013-1012; Directorate Identifier 2013-CE-037-AD.

#### (a) Comments Due Date

We must receive comments by January 17, 2014.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to British Aerospace Regional Aircraft Jetstream Series 3101 and Jetstream Model 3201 airplanes, all serial numbers, certificated in any category.

#### (d) Subject

Air Transport Association of America (ATA) Code 32: Landing Gear.

#### (e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as stress corrosion cracking of the main landing gear yoke pintle housing on a Jetstream series 3101 airplane. We are issuing this proposed AD to add protective measure to prevent abrasion and subsequent corrosion from building on the main landing gear (MLG) yoke pintle housing. This condition if not corrected could cause structural failure of the MLG resulting in loss of control during take-off or landing.

#### (f) Actions and Compliance

Unless already done, do the following actions as applicable in paragraphs (f)(1) through (f)(3) of this AD:

- (1) At the next scheduled MLG removal after the effective date of this AD, modify the LH and RH MLG installation at the forward spigot following the accomplishment instructions of British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JM7862, Revision 1, dated May 7, 2013.

- (2) As of the effective date of this AD, do not install any LH or RH MLG on Jetstream Series 3101 airplanes and Jetstream Model 3201 airplanes unless it is found to be in compliance with the requirements of paragraph (f)(1) of this AD.

## (g) Credit for Actions Done in Accordance With Previous Service Information

This AD allows credit for modification of an MLG to comply with the requirements of paragraph (f)(1) of this AD if already done before the effective date of this AD, following BAE Systems (Operations) Ltd SB 32-JM7862, original issue, dated April 8, 2013.

## (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: [taylor.martin@faa.gov](mailto:taylor.martin@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

## (i) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2013-0206, dated September 9, 2013 for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-1012. For service information related to this AD, contact BAE Systems (Operations) Ltd, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; phone: +44 1292 675207, fax: +44 1292 675704; email: [RApublications@baesystems.com](mailto:RApublications@baesystems.com); Internet: <http://www.jetstreamcentral.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on November 25, 2013.

**Earl Lawrence,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2013-28872 Filed 12-2-13; 8:45 am]

**BILLING CODE 4910-13-P**