

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2022-0512; Project Identifier AD-2022-00367-E; Amendment 39-22042; AD 2022-10-04]

RIN 2120-AA64

Airworthiness Directives; Engine Alliance Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Engine Alliance (EA) GP7270, GP7272, and GP7277 model turbofan engines. This AD was prompted by a manufacturer investigation that revealed certain stages 7–9 compressor rotor spools were manufactured from a billet of material suspected of having foreign material embedded. This AD requires the replacement of the affected stages 7–9 compressor rotor spool. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 23, 2022.

The FAA must receive comments on this AD by June 21, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Engine Alliance, 411 Silver Lane, East Hartford, CT 06118; phone: (800) 565-0140; email: help24@pw.utc.com; website: www.engineallianceportal.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0512; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for the Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Stephen Elwin, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7236; email: Stephen.L.Elwin@faa.gov.

SUPPLEMENTARY INFORMATION:**Background**

The FAA was notified by the manufacturer of a powder metal material contamination discovered in a part manufactured from the same billet material used to manufacture the EA GP7270, GP7272, and GP7277 high-pressure compressor (HPC) stage 8 rotor disk. Subsequent investigation by the manufacturer determined that the HPC stage 8 rotor disk, which is welded into the stages 7–9 compressor rotor spool, was manufactured from billets suspected of having foreign material embedded. The presence of foreign material in the billet may lead to crack formations and premature failure of the HPC stage 8 rotor disk. This condition, if not addressed, could result in failure of the HPC stage 8 rotor disk, uncontained release of the HPC stage 8 rotor disk, damage to the engine, and damage to the airplane. The FAA is issuing this AD to address the unsafe condition on these products.

FAA's Determination

The FAA is issuing this AD because the agency has determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Related Service Information

The FAA reviewed Engine Alliance Service Bulletin (SB) EAGP7-72-449, Original Issue, dated December 9, 2021. The SB describes procedures for removing and replacing the affected stages 7–9 compressor rotor spool.

AD Requirements

This AD requires the replacement of the affected stages 7–9 compressor rotor spool.

Interim Action

The FAA considers this AD to be an interim action. This issue is still under

investigation by the manufacturer and, depending on the results of that investigation, the FAA may consider further rulemaking action.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

The FAA justifies waiving notice and comment prior to adoption of this rule because no domestic operators use this product. It is unlikely that the FAA will receive any adverse comments or useful information about this AD from any U.S. operator. Accordingly, notice and opportunity for prior public comment are unnecessary, pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the foregoing reason(s), the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days.

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2022-0512 and Project Identifier AD-2022-00367-E” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and

actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as

confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Stephen Elwin, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when

an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 0 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace stages 7–9 compressor rotor spool ..	8 work-hours × \$85 per hour = \$680	\$853,400	\$854,080	\$0

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022–10–04 Engine Alliance: Amendment 39–22042; Docket No. FAA–2022–0512; Project Identifier AD–2022–00367–E.

(a) Effective Date

This airworthiness directive (AD) is effective May 23, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Engine Alliance (EA) GP7270, GP7272, and GP7277 model turbofan engines with an installed:

(1) Stages 7–9 compressor rotor spool, part number (P/N) 2031M90G05, having serial number (S/N) GWN0R7R3; or

(2) Stages 7–9 compressor rotor spool, P/N 2031M90G07, having S/N GWN0R9R3, GWN0R9TC, GWN0R9TM, GWN0RCT5, or GWN0RCT6.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by a manufacturer investigation that revealed certain stages 7–9 compressor rotor spools were manufactured from a billet of material suspected of having foreign material embedded. The FAA is issuing this AD to prevent failure of the high-pressure compressor (HPC) stage 8 rotor disk. The unsafe condition, if not addressed, could result in uncontained release of the HPC stage 8 rotor disk, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 500 flight cycles (FCs) after the effective date of this AD, remove the affected stages 7–9 compressor rotor spool from service and replace with a part eligible for installation.

(h) Definition

For the purpose of this AD, a "part eligible for installation" is any stages 7–9 compressor rotor spool with an S/N that is not identified in paragraph (c)(1) or (2) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD and email to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Stephen Elwin, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7236; email: Stephen.L.Elwin@faa.gov.

(k) Material Incorporated by Reference

None.

Issued on April 30, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-09631 Filed 5-5-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2022-0506; Project Identifier MCAI-2022-00507-G; Amendment 39-22037; AD 2022-09-17]

RIN 2120-AA64

Airworthiness Directives; Scheibe-Aircraft-GmbH Gliders

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Scheibe-Aircraft-GmbH Model SF 25 C gliders. This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as severe corrosion on the inner surface of the control stick tube. This AD requires inspecting the left-hand (LH) and right-hand (RH) control sticks for corrosion and, if corrosion is found, replacing the affected control stick. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 23, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 23, 2022.

The FAA must receive comments on this AD by June 21, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Scheibe Aircraft GmbH, Am Flugplatz 5, Heubach, D-73540, Germany; phone: +49 07173 184286; email: info@scheibe-aircraft.de; website: <https://scheibe-aircraft.de/>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0506.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0506; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The street address for the Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:**Background**

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Emergency AD 2022-0066-E, dated April 11, 2022 (referred to after this as “the MCAI”), to address an unsafe condition on Scheibe-Aircraft-GmbH (formerly Sportavia-Pützer GmbH & Co. KG and Scheibe Flugzeugbau GmbH) Model SF 25-series sailplanes (gliders). The MCAI states:

An occurrence was reported of finding fracture in a RH control stick of a powered sailplane, located above the weld seam at the transfer joint. Subsequent investigation determined that the fracture was a result of severe corrosion phenomena affecting the inner surface of the control stick tube due to water ingress.

This condition, if not detected and corrected, could lead to a rupture of an affected part, possibly resulting in reduced control, or loss of control, of the powered sailplane.

To address this unsafe condition, Scheibe issued the original issue of [service bulletin] TM/SB 653-96 to provide inspection and replacement instructions.

Consequently, EASA issued Emergency AD 2022-0043-E (later revised) to require repetitive inspections of each affected part to detect corrosion and replacement of each affected part with a serviceable part.

Since EASA AD 2022-0043R1 was issued, it was identified that powered sailplanes on which Scheibe modification] 653C-41-S10.1 is embodied are also affected by this unsafe condition.

For the reason described above, this [EASA] AD retains the requirements of EASA AD 2022-0043R1, which is superseded, and expands the Applicability.

You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0506.

FAA's Determination

The FAA is issuing this AD because the agency has determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Scheibe Aircraft GmbH Service Bulletin 653-96/1, dated April 4, 2022. This service information specifies procedures for repetitive inspections for corrosion on the LH and RH control sticks and replacement instructions for when corrosion is found. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Other Related Service Information

The FAA also reviewed Scheibe Aircraft GmbH Service Bulletin 653-96, dated March 2, 2022. This service information specifies procedures for repetitive inspections for corrosion on the LH and RH control sticks and replacement instructions for when corrosion is found.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service