

TABLE 2 TO PARAGRAPH (b)(3)—IM-
PORT ASSESSMENT TABLE—Contin-
ued

[Raw cotton fiber]

HTS No.	Conv. factor.	Cents/kg.
6302213020	1.1073	1.6267
6302213030	1.1073	1.6267
6302213040	1.1073	1.6267
6302213050	1.1073	1.6267
6302215010	0.7751	1.1387
6302215020	0.7751	1.1387
6302215030	0.7751	1.1387
6302215040	0.7751	1.1387
6302215050	0.7751	1.1387
6302217010	1.1073	1.6267
6302217020	1.1073	1.6267
6302217030	1.1073	1.6267
6302217040	1.1073	1.6267
6302217050	1.1073	1.6267
6302219010	0.7751	1.1387
6302219020	0.7751	1.1387
6302219030	0.7751	1.1387
6302219040	0.7751	1.1387
6302219050	0.7751	1.1387
6302221010	0.5537	0.8134
6302221020	0.3876	0.5694
6302221030	0.5537	0.8134
6302221040	0.3876	0.5694
6302221050	0.3876	0.5694
6302221060	0.3876	0.5694
6302222010	0.3876	0.5694
6302222020	0.3876	0.5694
6302222030	0.3876	0.5694
6302290020	0.2215	0.3254
6302313010	1.1073	1.6267
6302313020	1.1073	1.6267
6302313030	1.1073	1.6267
6302313040	1.1073	1.6267
6302313050	1.1073	1.6267
6302315010	0.7751	1.1387
6302315020	0.7751	1.1387
6302315030	0.7751	1.1387
6302315040	0.7751	1.1387
6302315050	0.7751	1.1387
6302317010	1.1073	1.6267
6302317020	1.1073	1.6267
6302317030	1.1073	1.6267
6302317040	1.1073	1.6267
6302317050	1.1073	1.6267
6302319010	0.7751	1.1387
6302319020	0.7751	1.1387
6302319030	0.7751	1.1387
6302319040	0.7751	1.1387
6302319050	0.7751	1.1387
6302321010	0.5537	0.8134
6302321020	0.3876	0.5694
6302321030	0.5537	0.8134
6302321040	0.3876	0.5694
6302321050	0.3876	0.5694
6302321060	0.3876	0.5694
6302322010	0.5537	0.8134
6302322020	0.3876	0.5694
6302322030	0.5537	0.8134
6302322040	0.3876	0.5694
6302322050	0.3876	0.5694
6302322060	0.3876	0.5694
6302390030	0.2215	0.3254
6302402010	0.9412	1.3827
6302511000	0.5537	0.8134
6302512000	0.8305	1.2201
6302513000	0.5537	0.8134
6302514000	0.7751	1.1387
6302593020	0.5537	0.8134

TABLE 2 TO PARAGRAPH (b)(3)—IM-
PORT ASSESSMENT TABLE—Contin-
ued

[Raw cotton fiber]

HTS No.	Conv. factor.	Cents/kg.
6302600010	1.1073	1.6267
6302600020	0.9966	1.4641
6302600030	0.9966	1.4641
6302910005	0.9966	1.4641
6302910015	1.1073	1.6267
6302910025	0.9966	1.4641
6302910035	0.9966	1.4641
6302910045	0.9966	1.4641
6302910050	0.9966	1.4641
6302910060	0.9966	1.4641
6302931000	0.4429	0.6507
6302932000	0.4429	0.6507
6302992000	0.2215	0.3254
6303191100	0.8859	1.3015
6303910010	0.609	0.8947
6303910020	0.609	0.8947
6303921000	0.2768	0.4066
6303922010	0.2768	0.4066
6303922030	0.2768	0.4066
6303922050	0.2768	0.4066
6303990010	0.2768	0.4066
6304111000	0.9966	1.4641
6304113000	0.1107	0.1626
6304190500	0.9966	1.4641
6304191000	1.1073	1.6267
6304191500	0.3876	0.5694
6304192000	0.3876	0.5694
6304193060	0.2215	0.3254
6304200020	0.8859	1.3015
6304200070	0.2215	0.3254
6304910120	0.8859	1.3015
6304910170	0.2215	0.3254
6304920000	0.8859	1.3015
6304996040	0.2215	0.3254
6505001515	1.1189	1.6438
6505001525	0.5594	0.8218
6505001540	1.1189	1.6438
6505002030	0.9412	1.3827
6505002060	0.9412	1.3827
6505002545	0.5537	0.8134
6507000000	0.3986	0.5856
9404401000	0.9966	1.4641
9404409005	0.6644	0.9761
9404409036	0.0997	0.1465
9404901030	0.2104	0.3091
9404901060	0.2104	0.3091
9404901090	0.2104	0.3091
9404908100	0.9966	1.4641
9404909605	0.6644	0.9761
9404909636	0.0997	0.1465
9619002100	0.8681	1.2753
9619002500	0.1085	0.1594
9619003100	0.9535	1.4008
9619003300	1.1545	1.6961
9619004100	0.2384	0.3502
9619004300	0.2384	0.3502
9619006100	0.8528	1.2528
9619006400	0.2437	0.3580
9619006800	0.3655	0.5370
9619007100	1.1099	1.6306
9619007400	0.2466	0.3623
9619007800	0.2466	0.3623
9619007900	0.2466	0.3623

* * * * *

Authority: 7 U.S.C. 2101–2118.

Melissa Bailey,
Associate Administrator, Agricultural
Marketing Service.

[FR Doc. 2023–17220 Filed 8–14–23; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. FAA–2023–1467; Special
Conditions No. 25–840–SC]**Special Conditions: The Boeing
Company Model 737–10 Airplane;
Dynamic Test Requirements for Single
Occupant Oblique Seats With or
Without Airbags and/or 3-Point
Restraints****AGENCY:** Federal Aviation
Administration (FAA), DOT.**ACTION:** Final special conditions; request
for comments.

SUMMARY: These special conditions are issued for The Boeing Company (Boeing) Model 737–10 series airplane. This airplane will have a novel or unusual design feature when compared to the state of technology envisioned in the airworthiness standards for transport-category airplanes. This design feature is oblique (side-facing) single-occupant seats equipped with airbag devices or 3-point restraints. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for this design feature. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

DATES: This action is effective on Boeing on August 15, 2023. Send comments on or before September 29, 2023.

ADDRESSES: Send comments identified by Docket No. FAA–2023–1467 using any of the following methods:

- *Federal eRegulations Portal:* Go to <https://www.regulations.gov/> and follow the online instructions for sending your comments electronically.

- *Mail:* Send comments to Docket Operations, M–30, U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE, Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey

Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- **Fax:** Fax comments to Docket Operations at 202–493–2251.

- **Docket:** Background documents or comments received may be read at <https://www.regulations.gov/> at any time. Follow the online instructions for accessing the docket or go to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: John Shelden, Cabin Safety Section, AIR–624, Technical Policy Branch, Policy and Standards Division, Aircraft Certification Service, Federal Aviation Administration, 2200 South 216th Street, Des Moines, Washington 98198; telephone and fax 206–231–3214; email John.Shelden@faa.gov.

SUPPLEMENTARY INFORMATION:

The substance of these special conditions has been published in the **Federal Register** for public comment in several prior instances with no substantive comments received. Therefore, the FAA finds, pursuant to 14 CFR 11.38(b), that new comments are unlikely, and notice and comment prior to this publication are unnecessary.

Privacy

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in title 14, Code of Federal Regulations (14 CFR) 11.35, the FAA will post all comments received without change to <https://www.regulations.gov/>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about these special conditions.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to these special conditions contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to these special conditions, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as

confidential under the FOIA, and the indicated comments will not be placed in the public docket of these special conditions. Send submissions containing CBI to John Shelden, Cabin Safety Section, AIR–624, Technical Policy Branch, Policy and Standards Division, Aircraft Certification Service, Federal Aviation Administration, 2200 South 216th Street, Des Moines, Washington 98198; telephone and fax 206–231–3214; email John.Shelden@faa.gov. Comments the FAA receives, which are not specifically designated as CBI, will be placed in the public docket for these special conditions.

Comments Invited

The FAA invites interested people to take part in this rulemaking by sending written comments, data, or views. The most helpful comments reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data.

The FAA will consider all comments received by the closing date for comments and will consider comments filed late if it is possible to do so without incurring delay. The FAA may change these special conditions based on the comments received.

Background

On October 28, 2022, Boeing applied for a change to Type Certificate No. A16WE for the installation of oblique (side-facing) passenger seats with or without airbag devices or 3-point restraints in the Boeing Model 737–10 series airplanes. The Boeing Model 737–10 series airplanes are twin-engine, transport category airplanes with a maximum certified passenger capacity of up to 230, and a maximum takeoff weight of approximately 197,900 lbs.

Type Certification Basis

Under the provisions of title 14, Code of Federal Regulations (14 CFR) 21.101, Boeing must show that the Model 737–10 series airplanes, as changed, continue to meet the applicable provisions of the regulations listed in Type Certificate No. A16WE or the applicable regulations in effect on the date of application for the change, except for earlier amendments as agreed upon by the FAA.

If the Administrator finds that the applicable airworthiness regulations (e.g., 14 CFR part 25) do not contain adequate or appropriate safety standards for the Boeing Model 737–10 series airplane because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same novel or unusual design feature, or should any other model already included on the same type certificate be modified to incorporate the same novel or unusual design feature, the special conditions would also apply to the other model under § 21.101.

In addition to the applicable airworthiness regulations and special conditions, the Boeing Model 737–10 series airplane must comply with the exhaust-emission requirements of 14 CFR part 34, and the noise-certification requirements of 14 CFR part 36.

The FAA issues special conditions, as defined in 14 CFR 11.19, in accordance with § 11.38, and they become part of the type certification basis under § 21.101.

Novel or Unusual Design Features

The Boeing Model 737–10 series airplane will incorporate a seating configuration that is novel or unusual due to the installation of oblique (side-facing) passenger seats and surrounding furniture that introduces occupant alignment and loading concerns. These oblique seats may be installed at an angle of 18 to 45 degrees to the aircraft centerline and may include a 3-point restraint system and/or airbags, for occupant restraint and injury protection.

Discussion

Title 14, Code of Federal Regulations (14 CFR) 25.785(d) requires that each occupant of a seat that makes more than an 18 degree angle with the vertical plane containing the airplane centerline must be protected from head injury by a safety belt and an energy absorbing rest that will support the arms, shoulders, head, and spine, or by a safety belt and shoulder harness that will prevent the head from contacting any injurious object.

The proposed Boeing Model 737–10 airplane seat installation is novel in that the current requirements do not adequately address protection of the occupant's neck and spine for seating configurations that are positioned at angles greater than 18 degrees up to and including 45 degrees from the airplane centerline. The installation of passenger seats at angles of 18 to 45 degrees to the airplane centerline is unique due to the seat/occupant interface with the surrounding furniture that introduces occupant alignment/loading concerns with or without the installation of a 3-point or airbag restraint system, or both.

In order to provide a level of safety that is equivalent to that afforded to occupants of forward and aft facing seating, additional airworthiness standards, in the form of new special conditions, are necessary.

The FAA has been conducting and sponsoring research on appropriate injury criteria for oblique (side-facing) seat installations. To reflect current research findings, the FAA issued policy statement PS-AIR-25-27. FAA-sponsored research has found that an unrestrained flailing of the upper torso, even when the pelvis and torso are nearly aligned, can produce serious spinal and torso injuries. At lower impact severities, even with significant misalignment between the torso and pelvis, these injuries did not occur. Tests with an FAA H-III anthropomorphic test dummy (ATD) have identified a level of lumbar spinal tension corresponding to the no-injury impact severity. This level of tension is included as a limit in the special conditions. The spine tension limit selected is conservative with respect to other aviation injury criteria since it corresponds to a no-injury loading condition.

As noted in the special conditions for each airbag restraint system, because an airbag restraint system is essentially a single use device, there is the potential that it could deploy under crash conditions that are not sufficiently severe as to require head injury protection from the airbag restraint system. Since an actual crash is frequently composed of a series of impacts before the airplane comes to rest, this could render the airbag restraint system useless if a larger impact follows the initial impact. This situation does not exist with energy absorbing pads or upper torso restraints, which tend to provide protection according to the severity of the impact. Therefore, the installation of the airbag restraint system should be such that the airbag restraint system will provide protection when it is required, and will not expend its protection when it is not needed.

Because these airbag restraint systems may or may not activate during various crash conditions, the injury criteria listed in these special conditions and in § 25.562 must be met in an event that is slightly below the activation level of the airbag restraint system. If an airbag restraint system is included with the oblique seats, the system must meet the requirements in one of the airbag (inflatable restraint) special conditions applicable to the Boeing Model 737 series airplanes. These special conditions supplement part 25 and,

more specifically, supplement §§ 25.562 and 25.785.

These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

Applicability

As discussed above, these special conditions are applicable to the Boeing Model 737-10 series airplane. Should Boeing apply at a later date for a change to the type certificate to include another model that incorporates the same novel or unusual design feature, or should any other model already included on the same type certificate be modified to incorporate the same novel or unusual design feature, these special conditions would apply to that model as well.

Conclusion

This action affects only a certain novel or unusual design feature on one model series of airplanes. It is not a rule of general applicability.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

Authority Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40113, 44701, 44702, and 44704.

The Special Conditions

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for The Boeing Company Model 737-10 series airplanes.

In addition to the requirements of § 25.562, passenger seats installed at an angle between 18 degrees and 45 degrees from the aircraft centerline must meet the following:

1. Head Injury Criteria (HIC)

Compliance with § 25.562(c)(5) is required, except that, if the anthropomorphic test dummy (ATD) has no apparent contact with the seat/structure but has contact with an airbag, a HIC unlimited score in excess of 1000 is acceptable, provided the HIC15 score (calculated in accordance with 49 CFR 571.208) for that contact is less than 700.

2. Body-to-Wall/Furnishing Contact

If a seat is installed aft of structure (e.g., interior wall or furnishings) that does not provide a homogenous contact surface for the expected range of

occupants and yaw angles, then additional analysis and tests may be required to demonstrate that the injury criteria are met for the area that an occupant could contact. For example, if different yaw angles could result in different airbag device performance, then additional analysis or separate tests may be necessary to evaluate performance.

3. Neck Injury Criteria

The seating system must protect the occupant from experiencing serious neck injury. The assessment of neck injury must be conducted with the airbag device activated, unless there is reason to also consider that the neck-injury potential would be higher for impacts below the airbag-device deployment threshold.

a. The N_{ij} (calculated in accordance with 49 CFR 571.208) must be below 1.0, where $N_{ij} = F_z/F_{zc} + M_y/M_{yc}$, and N_{ij} critical values are:

- i. $F_{zc} = 1530$ lbs. for tension
- ii. $F_{zc} = 1385$ lbs. for compression
- iii. $M_{yc} = 229$ lb-ft in flexion
- iv. $M_{yc} = 100$ lb-ft in extension

b. In addition, peak F_z must be below 937 lbs. in tension and 899 lbs. in compression.

c. Rotation of the head about its vertical axis relative to the torso is limited to 105 degrees in either direction from forward facing.

d. The neck must not impact any surface that would produce concentrated loading on the neck.

4. Spine and Torso Injury Criteria

a. The lumbar spine tension (F_z) cannot exceed 1200 lbs.

b. Significant concentrated loading on the occupant's spine, in the area between the pelvis and shoulders during impact, including rebound, is not acceptable. During this type of contact, the interval for any rearward (X direction) acceleration exceeding 20g must be less than 3 milliseconds as measured by the thoracic instrumentation specified in 49 CFR part 572, subpart E filtered in accordance with SAE International (SAE) recommended practice J211/1, "Instrumentation for Impact Test—Part 1—Electronic Instrumentation."

c. The occupant must not interact with the armrest or other seat components in any manner significantly different than would be expected for a forward-facing seat installation.

5. Pelvis Criteria

Any part of the load-bearing portion of the bottom of the ATD pelvis must not translate beyond the edges of the

seat bottom seat-cushion supporting structure.

6. Femur Criteria

Axial rotation of the upper leg (about the z-axis of the femur per SAE Recommended Practice J211/1) must be limited to 35 degrees from the nominal seated position. Evaluation during rebound does not need to be considered.

7. ATD and Test Conditions

Longitudinal tests conducted to measure the injury criteria above must be performed with the FAA Hybrid III ATD, as described in SAE 1999-01-1609, "A Lumbar Spine Modification to the Hybrid III ATD for Aircraft Seat Tests." The tests must be conducted with an undeformed floor, at the most-critical yaw cases for injury, and with all lateral structural supports (e.g., armrests or walls) installed.

Note: Boeing must demonstrate that the installation of seats via plinths or pallets meets all applicable requirements. Compliance with the guidance contained in policy memorandum PS-ANM-100-2000-00123, "Guidance for Demonstrating Compliance with Seat Dynamic Testing for Plinths and Pallets," dated February 2, 2000, is acceptable to the FAA.

8. Inflatable Airbag Restraint Systems Special Conditions

If inflatable airbag restraint systems are installed, the airbag systems must meet the requirements in special conditions 25-386-SC, or other airbag system special conditions which are applicable to the Boeing Model 737 series airplanes.

Issued in Des Moines, WA, on August 9, 2023.

Paul R. Siegmund,

Acting Manager, Technical Policy Branch, Policy and Standards Division, Aircraft Certification Service.

[FR Doc. 2023-17403 Filed 8-14-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1712; Project Identifier MCAI-2023-00821-A; Amendment 39-22523; AD 2023-16-04]

RIN 2120-AA64

Airworthiness Directives; Piaggio Aviation S.p.A. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Piaggio Aviation S.p.A. (Piaggio) Model P-180 airplanes. This AD was prompted by a report of corrosion-induced cracking on the horizontal tail trim actuator (HTTA) fitting assembly. This AD requires repetitively inspecting the HTTA fitting assembly for corrosion and cracking until the HTTA fitting assembly is replaced with a new part. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective August 30, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 30, 2023.

The FAA must receive comments on this AD by September 29, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1712; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this final rule, contact Piaggio Aero Industries S.p.A., P180 Customer Support, via Pionieri e Aviatori d'Italia, snc-16154 Genoa, Italy; phone: +39 331 679 74 93; email: technicalsupport@piaggioaerospace.it.

• You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1712.

FOR FURTHER INFORMATION CONTACT:

Mike Kiesov, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329-4144; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-1712; Project Identifier MCAI-2023-00821-A" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Mike Kiesov, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2023-0122R1, dated July 5, 2023