

eliminate unnecessary regulations to the extent that such action is appropriate. Finally, section 2222 requires the Council, of which the Agencies are members, to submit a report to Congress that summarizes any significant issues raised in the public comments and the relative merits of such issues. The report also must include an analysis of whether the Agencies are able to address the regulatory burdens associated with such issues by regulation or whether these burdens must be addressed by legislative action.

For purposes of this review, the Agencies have grouped our regulations into 12 categories: Applications and Reporting; Banking Operations; Capital; Community Reinvestment Act; Consumer Protection; Directors, Officers and Employees; International Operations; Money Laundering; Powers and Activities; Rules of Procedure; Safety and Soundness; and Securities. On June 4, 2014, we published a **Federal Register** notice announcing the start of the EGRPRA review process and also asking for public comment on three of these categories—Applications and Reporting; Powers and Activities; and International Operations regulations.³ In that notice we published a chart, listing the Agencies' regulations in the 12 categories included in the EGRPRA review. On February 13, 2015, we published a **Federal Register** notice asking for public comment on three additional categories—Banking Operations; Capital; and the Community Reinvestment Act.⁴ The comment period for the current **Federal Register** notice closes on May 14, 2015.

Recently, the Agencies have decided to expand the scope of the EGRPRA review in order to be as inclusive as possible. Accordingly, the Agencies will take comment on all of our regulations issued in final form up to the date that we publish our last EGRPRA notice for public comment and report back to the Congress on all such regulations.

Dated: April 8, 2015.

Thomas J. Curry,
Comptroller of the Currency.

By order of the Board of Governors of the Federal Reserve System, April 7, 2015.

Robert deV. Frierson,
Secretary of the Board.

Dated: April 6, 2015.

Federal Deposit Insurance Corporation by
Robert E. Feldman,
Executive Secretary.

[FR Doc. 2015-08619 Filed 4-14-15; 8:45 am]

BILLING CODE 6210-01P; 6714-01-P; 4810-33-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0826; Directorate Identifier 2014-NM-221-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A318, A319, and A320 series airplanes modified by a particular supplemental type certificate (STC). This proposed AD was prompted by reports of cracks found during inspections of the in-flight entertainment system radome assembly. This proposed AD would require repetitive detailed inspections for cracks in the radome assembly, and replacement of the radome if necessary. We are proposing this AD to detect and correct cracks in the radome assembly, which could result in the radome (or pieces) separating from the airplane and striking the tail, consequently reducing the controllability of the airplane.

DATES: We must receive comments on this proposed AD by June 1, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Live TV, 7415 Emerald Dunes Drive, Orlando, FL 32822; telephone 407-812-2643; email: CertificationEngineering@livetv.net; Internet: <http://www.LiveTV.net>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0826; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Barry Culler, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office (ACO), 1701 Columbia Avenue, College Park, GA 30337; phone: 404-474-5546; fax: 404-474-5605; email: william.culler@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-0826; Directorate Identifier 2014-NM-221-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received reports of cracks in the in-flight entertainment system radomes of certain Airbus airplanes. The cracks were found during inspections of the radome assembly on various Airbus Model A318, A319, and A320 series airplanes that had in-flight entertainment systems installed using a certain STC issued to Live TV (STC number ST00788SE, [http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/6df40775b10ef09a86257ae200613cfe/\\$FILE/ST00788SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/6df40775b10ef09a86257ae200613cfe/$FILE/ST00788SE.pdf)). Investigation of the cause of the cracks revealed that radome manufacturing variation, due to a lack of dimensional

³ 79 FR 32172.

⁴ 80 FR 7980.

controls on the radome manufacturing drawings, can result in the introduction of preload stress on the radome during its assembly with the skirt fairing. Preload stress combined with flight or handling stress, such as maintenance personnel stepping on the radome fairing assembly, might initiate a crack. The radome manufacturing drawings were revised on September 13, 2010, to add a control dimension, which was incorporated into production at radome serial number 498. Cracks in the radome, if not corrected, could result in the radome (or pieces) separating from the airplane and striking the tail, consequently reducing the controllability of the airplane.

Related Service Information Under 1 CFR Part 51

We reviewed Live TV Service Bulletin A320–53–006, Rev 01, dated September 10, 2014. The service information describes procedures for repetitive detailed inspections for cracks in the outer ply of the radome, and replacement of the radome with a new or serviceable radome, if any crack is found. This service information is reasonably available; see ADDRESSES for ways to access this service information.

FAA’s Determination
We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

Proposed AD Requirements
This proposed AD would require accomplishing the actions specified in the service information described previously. In addition, if any crack is found in a radome during an inspection, this proposed AD would require sending the inspection results to Live TV.

Explanation of “RC” Steps in Service Information
The FAA worked in conjunction with industry, under the Airworthiness Directive Implementation Aviation Rulemaking Committee (ARC), to enhance the AD system. One enhancement was a new process for annotating which steps in the service information are required for compliance with an AD. Differentiating these steps from other tasks in the service information is expected to improve an owner’s/operator’s understanding of

crucial AD requirements and help provide consistent judgment in AD compliance. The steps identified as RC (required for compliance) in any service information identified previously have a direct effect on detecting, preventing, resolving, or eliminating an identified unsafe condition.
Steps that are identified as RC in any service information must be done to comply with the proposed AD. However, steps that are not identified as RC are recommended. Those steps that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an alternative method of compliance (AMOC), provided the steps identified as RC can be done and the airplane can be put back in a serviceable condition. Any substitutions or changes to steps identified as RC will require approval of an AMOC.
Costs of Compliance
We estimate that this proposed AD affects 120 airplanes of U.S. registry.
We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS				
Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspections	1 work-hour × \$85 per hour = \$85, per inspection cycle.	N/A	\$85, per inspection cycle	\$10,200, per inspection cycle.

We estimate the following costs to do any necessary replacements that would

be required based on the results of the proposed inspections. We have no way

of determining the number of aircraft that might need this replacement:

ON-CONDITION COSTS			
Action	Labor cost	Parts cost	Cost per product
Replacement	8 work-hours × \$85 per hour = \$680	\$0	\$680

Paperwork Reduction Act
A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120–0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and

reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.
Authority for This Rulemaking
Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency’s authority.
We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA–2015–0826; Directorate Identifier 2014–NM–221–AD.

(a) Comments Due Date

We must receive comments by June 1, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplane models identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category, with Live TV radomes having part number (P/N) 5063–100–XX (XX designates the color option) and a serial number in the range of 001 through 497 inclusive, and modified by supplemental type certificate (STC) STC ST00788SE, [http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/6df40775b10ef09a86257ae200613cfe/\\$FILE/ST00788SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/6df40775b10ef09a86257ae200613cfe/$FILE/ST00788SE.pdf).

(1) Airbus Model A318–111 and –112 airplanes.

(2) Airbus Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes.

(3) Airbus Model A320–111, 211, –212, –214, –231, –232, and –233 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks found during inspections of the radome assembly. We are issuing this AD to detect and correct cracks in the in-flight entertainment system radome assembly, which could result in the radome (or pieces) separating from the airplane and striking the tail, consequently reducing the controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections and Corrective Actions

Within 3,900 flight hours after the effective date of this AD: Perform a detailed inspection for cracks of the radome assembly, in accordance with the Accomplishment Instructions of Live TV Service Bulletin A320–53–006, Rev 01, dated September 10, 2014. Repeat the inspection thereafter at intervals not to exceed 3,900 flight hours. If any crack is found during any inspection required by this paragraph, before further flight, replace the radome with a new or serviceable radome, in accordance with the Accomplishment Instructions of Live TV Service Bulletin A320–53–006, Rev 01, dated September 10, 2014.

(h) Reporting Requirement

If any crack is found during any inspection required by paragraph (g) of this AD, submit a report of the findings to Live TV, Attn: Oscar Hernandez, email: CertificationEngineering@livetv.net; at the applicable time specified in paragraph (h)(1) or (h)(2) of this AD. The report must include the information specified in the service bulletin reporting form provided in Live TV Service Bulletin A320–53–006, Rev 01, dated September 10, 2014.

(1) If the inspection was accomplished on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was accomplished before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(i) Special Flight Permit

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

(j) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to

a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) If any service information contains steps that are identified as RC (Required for Compliance), those steps must be done to comply with this AD; any steps that are not identified as RC are recommended. Those steps that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the steps identified as RC can be done and the airplane can be put back in a serviceable condition. Any substitutions or changes to steps identified as RC require approval of an AMOC.

(l) Related Information

(1) For more information about this AD, contact Barry Culler, Aerospace Engineer, Airframe Branch, ACE–117A, FAA, Atlanta Aircraft Certification Office (ACO), 1701 Columbia Avenue, College Park, GA 30337; phone: 404–474–5546; fax: 404–474–5605; email: william.culler@faa.gov.

(2) For service information identified in this AD, contact Live TV, 7415 Emerald Dunes Drive, Orlando, FL 32822; telephone 407–812–2643; email: CertificationEngineering@livetv.net; Internet: <http://www.LiveTV.net>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on April 6, 2015.

John P. Piccola, Jr.,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-08465 Filed 4-14-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0828; Directorate Identifier 2014-NM-146-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) 2013-23-03, which applies to certain The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series airplanes. AD 2013-23-03 currently requires doing a detailed inspection of certain attach fittings for a cylindrical defect and replacing if necessary. Since we issued AD 2013-23-03, we received a report that a machining defect was also found on some of the actuator assemblies inspected during manufacture. This defect could lead to fatigue cracking and subsequent fracture. For certain airplanes, this proposed AD would mandate new inspections of the inboard actuator attach fittings for machining defects, and overhaul or replacement, if necessary. This proposed AD would also limit the compliance time for doing the replacement for certain other airplanes. We are proposing this AD to detect and correct defective inboard actuator attach fittings which, combined with loss of the outboard actuator load path, could result in uncontrolled retraction of the outboard flap, damage to flight control systems, and consequent reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by June 1, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0828.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0828; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: nathan.p.weigand@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-0828; Directorate Identifier 2014-NM-146-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will

consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On October 31, 2013, we issued AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013), for certain The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series airplanes. AD 2013-23-03 requires inspecting to determine the part number of the inboard actuator attach fittings of the outboard flap. For affected attach fittings, AD 2013-23-03 requires doing a detailed inspection of the attach fittings for a cylindrical defect and replacing if necessary. As an option to the detailed inspection, AD 2013-23-03 allows replacement of affected attach fittings. AD 2013-23-03 resulted from a report of the fracture of an inboard actuator attach fitting of the outboard flap. An inspection of the attach fitting revealed that it was incorrectly machined with a cylindrical profile instead of a conical profile, resulting in reduced wall thickness. We issued AD 2013-23-03 to detect and correct defective inboard actuator attach fittings which, combined with loss of the outboard actuator load path, could result in uncontrolled retraction of the outboard flap, damage to flight control systems, and consequent reduced controllability of the airplane.

Actions Since AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013) Was Issued

The preamble to AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013), specified that we considered the requirements "interim action." AD 2013-23-03 explained that we might consider further rulemaking to require a minimum thickness inspection of inboard actuator attach fittings that are conically machined. Since we issued AD 2013-23-03, we received a report that a machining defect was also found on some of the actuator assemblies inspected during manufacture at the point where the tapered machining transitioned to the hemispherical machining at the top of the inner surface. Revised service information has been issued and, for certain airplanes, this proposed AD would mandate new