

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Inspect the flight control system operating levers for damaged ball bearings and replace any lever with a damaged ball bearing.	Inspect within the next 50 hours time-in-service (TIS) after the effective date of this AD. Replace prior to further flight after the inspection.	In accordance with GROB Service Bulletin No. MSB1121-033, dated May 8, 2003.
(2) Accomplish the modifications to: (a) elevator rod 1, part number (P/N) 120A-4400.08 or part number 120A-4217 (which supersedes P/N 120A-4400.08); and (b) the flight control system operating levers	Within the next 50 hours TIS after the effective date of this AD.	In accordance with GROB Service Letter No. SL1121-009, dated May 23, 2003, and GROB Service Bulletin No. MSB1121-034, dated May 19, 2003.
(3) Only install flight control system operating levers that have been modified in accordance with paragraph (d)(2)(a) and (d)(2)(b) of this AD.	As of the effective date of this AD	

(e) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, follow the procedures in 14 CFR 39.19. Send these requests to the Manager, Standards Office, Small Airplane Directorate. For information on any already approved alternative methods of compliance, contact Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

(f) *How do I get copies of the documents referenced in this AD?* You may get copies of the documents referenced in this AD from GROB Luft-und Raumfahrt, Lettenbachstrasse 9, D-86874 Tussenhausen-Mattsies, Germany; telephone: 011 49 8268 998139; facsimile: 011 49 8268 998200; email: productssupport@grob-aerospace.de. You may view these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Note: The subject of this AD is addressed in German AD 2003-164/2, dated May 22, 2003.

Issued in Kansas City, Missouri, on July 9, 2003.

Dorenda D. Baker,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-17818 Filed 7-14-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-319-AD]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-300 Series Airplanes Equipped With Certain Pratt & Whitney PW306B Engine Nacelles

AGENCY: Federal Aviation Administration, DOT.

ACTION: Supplemental notice of proposed rulemaking; reopening of comment period.

SUMMARY: This document revises an earlier proposed airworthiness directive (AD), applicable to certain Dornier Model 328-300 series airplanes, that would have required performing a check of the airplane maintenance records; inspecting the engine nacelle anti-ice tube for leaks, if necessary; and modifying the joint, if necessary. This new action revises the proposed rule by removing the requirement to perform a records check, which was intended to allow operators to determine whether the inspection would be required. The actions specified by this new proposed AD are intended to prevent an uncommanded engine shutdown in a critical phase of flight due to leakage of air from a loose clamp on the anti-ice tubing joint. This action is intended to address the identified unsafe condition. **DATES:** Comments must be received by August 11, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-

319-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-319-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from FAIRCHILD Dornier GmbH, P.O. Box 1103, D-82230 Wessling, Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained

in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue.

For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-319-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-319-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add an airworthiness directive (AD), applicable to certain Dornier Model 328-300 series airplanes, was published as a notice of proposed rulemaking (NPRM) in the **Federal Register** on March 12, 2003 (68 FR 11762). That NPRM (the "original NPRM") would have required performing a check of the airplane maintenance records; inspecting the engine nacelle anti-ice tube for leaks, if the records check indicated that an engine change had been accomplished or maintenance work had been carried out on the nacelle anti-ice system; and modifying the joint, if necessary. The original NPRM was prompted by a report of an in-flight engine shutdown during an airplane rollback due to a P3 air leak from a loose clamp on the anti-ice tubing joint. Such leakage of air, if not corrected, could result in an

uncommanded engine shutdown in a critical phase of flight.

Actions Since Issuance of Original NPRM

Since the issuance of the original NPRM, the FAA has determined that the proposed records check may be inadequate to identify airplanes subject to the identified unsafe condition.

While it may be possible to determine some of the maintenance history from the maintenance records, a records check cannot definitively determine that certain maintenance work has not been carried out on a particular airplane. Therefore, the FAA has determined that paragraph (a) of the original NPRM must be revised to remove the proposed records check to determine whether certain maintenance had been done. In this supplemental NPRM, paragraph (a) has been removed, paragraph (b) has been revised accordingly, and subsequent paragraphs have been reidentified.

Conclusion

Since this change expands the scope of the originally proposed rule, the FAA has determined that it is necessary to reopen the comment period to provide additional opportunity for public comment.

Changes to 14 CFR Part 39/Effect on This Supplemental NPRM

On July 10, 2002, the FAA issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. In this supplemental NPRM, the office authorized to approve AMOCs is identified in paragraph (c), and Note 1 and paragraph (e) of the original NPRM have been removed.

Cost Impact

The FAA estimates that 48 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to do the inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$2,880, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD

rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Fairchild Dornier GMBH (Formerly Dornier Luftfahrt GmbH): Docket 2001-NM-319-AD.

Applicability: Model 328-300 series airplanes equipped with Pratt & Whitney PW306B engine nacelles, from engine nacelle serial number DR0001 up to and including

serial number DR0051, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent an uncommanded engine shutdown in a critical phase of flight due to leakage of air from a loose clamp on the anti-ice tubing joint, accomplish the following:

Inspection

(a) Within 45 days after the effective date of this AD, perform a detailed inspection of the anti-ice tubing in the engine nacelle at the joint between the anti-ice tubing adapter and duct, and also between the joint of the anti-ice shutoff valve and the same duct, to detect any air leakage at the joints, as specified in the Accomplishment Instructions of Dornier Service Bulletin SB-328J-71-107, Revision 1, dated July 4, 2001. If no leakage is detected, no further action is required by this AD.

Note 1: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Modification

(b) If air leakage is found during the detailed inspection required by paragraph (a) of this AD, before further flight, modify the joint by doing the applicable actions specified in the Accomplishment Instructions of Dornier Service Bulletin SB-328J-71-107, Revision 1, dated July 4, 2001.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, FAA, is authorized to approve alternative methods of compliance for this AD.

Note 2: The subject of this AD is addressed in German airworthiness directive 2001-296, dated October 18, 2001.

Issued in Renton, Washington, on July 9, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane
Directorate, Aircraft Certification Service.
[FR Doc. 03-17817 Filed 7-14-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[CGD13-03-018]

RIN 1625-AA00

Security and Safety Zone; Protection of Large Passenger Vessels, Puget Sound, WA

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish regulations for the security and safety of large passenger vessels in the navigable waters of Puget Sound and adjacent waters, Washington. This proposed security and safety zone, when enforced by the Captain of the Port Puget Sound, would provide for the regulation of vessel traffic in the vicinity of large passenger vessels in the navigable waters of the United States.

DATES: Comments and related material must reach the Coast Guard on or before August 14, 2003.

ADDRESSES: You may mail comments and related material to Commanding Officer, Marine Safety Office Puget Sound, 1519 Alaskan Way South, Seattle, Washington 98134. Marine Safety Office Puget Sound maintains the public docket [CGD13-03-018] for this rulemaking. Comments and material received from the public, as well as documents indicated in this preamble as being available in the docket, will become part of this docket and will be available for inspection or copying at Marine Safety Office Puget Sound between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: LT J. Morgan, c/o Captain of the Port Puget Sound, 1519 Alaskan Way South, Seattle, WA 98134, (206) 217-6232. For specific information concerning enforcement of this rule, call Marine Safety Office Puget Sound at (206) 217-6200 or (800) 688-6664.

SUPPLEMENTARY INFORMATION:

Request for Comments

We encourage you to participate in this rulemaking by submitting comments and related material. If you do so, please include your name and address, identify the docket number for this rulemaking (CGD13-03-018), indicate the specific section of this document to which each comment applies, and give the reason for each comment. Please submit all comments and related material in an unbound

format, no larger than 8½ by 11 inches, suitable for copying. If you would like to know that your submission reached us, please enclose a stamped, self-addressed postcard or envelope. We will consider all comments and material received during the comment period. We may change this proposed rule in view of them.

Public Meeting

We do not now plan to hold a public meeting. But you may submit a request for a meeting by writing to Marine Safety Office Puget Sound at the address under **ADDRESSES** explaining why one would be beneficial. If we determine that one would aid this rulemaking, we will hold one at a time and place announced by a separate notice in the **Federal Register**.

Background and Purpose

Hostile entities continue to operate with the intent to harm U.S. National Security. The President has continued the national emergencies he declared following the September 11, 2001 terrorist attacks (67 FR 58317, Sept. 13, 2002) (continuing national emergency with respect to terrorist attacks)), and (67 FR 59447, Sept. 20, 2002) (continuing national emergency with respect to persons who commit, threaten to commit or support terrorism). The President also has found pursuant to law, including the Act of June 15, 1917, as amended August 9, 1950, by the Magnuson Act (50 U.S.C. 191 *et seq.*), that the security of the United States is and continues to be endangered following the attacks (E.O. 13,273, 67 FR 56215, Sept. 3, 2002) (security endangered by disturbances in international relations of U.S. and such disturbances continue to endanger such relations).

The ongoing hostilities in Afghanistan and Iraq have made it prudent for U.S. ports and waterways to be on a higher state of alert because the al Qaeda organization and other similar organizations have declared an ongoing intention to conduct armed attacks on U.S. interests worldwide. On February 8, 2003, the Captain of the Port Puget Sound issued a temporary final rule (TFR) (68 FR 15375, March 31, 2003; CGD13-03-003, 33 CFR 165.T13-002) establishing a large passenger vessel security and safety zone, which expires on August 8, 2003. The Coast Guard, through this action, intends to continue to assist large passenger vessels by establishing a permanent security and safety zone that when enforced by the Captain of the Port would exclude persons and vessels from the immediate vicinity of all large passenger vessels.