

planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Bombardier, Inc. (Formerly de Havilland, Inc.): Docket 2002-NM-338-AD.

Applicability: Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes, serial numbers 003 through 586 inclusive; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent contact between the lockwire pigtail of the fitting and the stiffener located on the inside surface of the fuel access covers of the wings, which could serve as a potential ignition source within the fuel tank if a cover is struck by lightning and result in possible

fuel tank explosion, accomplish the following:

Inspection of Fitting Assemblies and Lockwire

(a) Within 12 months after the effective date of this AD, do a general visual inspection to verify proper installation of the fitting assemblies and the lockwire located on the vent and scavenge lines routed immediately below the fuel tank access covers on both wings by accomplishing all the actions specified in Part A of the Accomplishment Instructions of Bombardier Alert Service Bulletin A8-28-33, Revision "A," dated October 10, 2002. Do the actions per the service bulletin.

Note 1: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Corrective Actions for Any Improperly Installed Fitting Assembly or Lockwire

(b) If any fitting assembly is found to be improperly installed during the general visual inspection required by paragraph (a) of this AD, before further flight, do the actions specified in paragraphs (b)(1) and (b)(2) of this AD per Part A of the Accomplishment Instructions of Bombardier Alert Service Bulletin A8-28-33, Revision "A," dated October 10, 2002.

(1) Change the orientation of the fitting assembly.

(2) Perform a general visual inspection of the O-ring for damage, and replace any damaged O-ring with a new O-ring.

(c) If any lockwire is found to be improperly installed during the general visual inspection required by paragraph (a) of this AD, before further flight, replace the lockwire with a new lockwire, per Part A of the Accomplishment Instructions of Bombardier Alert Service Bulletin A8-28-33, Revision "A," dated October 10, 2002.

Inspection of the Stiffeners

(d) Within 12 months after the effective date of this AD, do a general visual inspection of the stiffeners on the underside of fuel tank access covers on both wings for signs of chafing damage caused by incorrect orientation of the lockwire tail, per Part B of the Accomplishment Instructions of Bombardier Alert Service Bulletin A8-28-33, Revision "A," dated October 10, 2002.

Corrective Action for Chafing Damage

(e) If any chafing damage is found during the general visual inspection required by paragraph (d) of this AD, before further flight, remove the damage per Part B of the Accomplishment Instructions of Bombardier

Alert Service Bulletin A8-28-33, Revision "A," dated October 10, 2002, except where the service bulletin recommends contacting Bombardier for damage in excess of the given limits, before further flight, repair per a method approved by either the Manager, New York Aircraft Certification Office (ACO), FAA; or the Transport Canada Civil Aviation (TCCA) (or its delegated agent).

Exception to Service Bulletin Reporting

(f) Although the service bulletin referenced in this AD specifies to report inspection findings to the airplane manufacturer, this AD does not include such a requirement.

Alternative Methods of Compliance

(g) In accordance with 14 CFR 39.19, the Manager, New York Aircraft Certification Office (ACO), FAA, is authorized to approve alternative methods of compliance for this AD.

Note 2: The subject of this AD is addressed in Canadian airworthiness directive CF-2002-44, dated October 22, 2002.

Issued in Renton, Washington, on December 19, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-32133 Filed 12-30-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2003-16437; Airspace Docket No. 03-AWP-02]

RIN 2120-AA66

Proposed Revision of VOR Federal Airway 137

AGENCY: Federal Aviation Administration (FAA) DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to revise VOR Federal Airway 137 (V-137) between the Thermal, CA, Very High Frequency Omnidirectional Radio Range and Tactical Air Navigation Aids (VORTAC) intersection and the Imperial, CA, VORTAC. The current route segment between the Thermal, CA, VORTAC, and the Imperial, CA, VORTAC is aligned to avoid a restricted area that no longer exists. The FAA is proposing this action to realign V-137 to form a direct route between the Thermal, CA, VORTAC, and the Imperial, CA, VORTAC. This action would improve the management of air traffic operations and reduce the route mileage between the Thermal, CA, VORTAC and the Imperial, CA, VORTAC.

DATES: Comments must be received on or before February 17, 2004.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify FAA Docket No. FAA-2003-16437 and Airspace Docket No. 03-AWP-02, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Ken McElroy, Airspace and Rules Division, ATA-400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2003-16437 and Airspace Docket No. 03-AWP-02) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://dms.dot.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2003-16437 and Airspace Docket No. 03-AWP-02." The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned

with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the **Federal Register's** web page at <http://www.gpoaccess.gov/fr/index.html>.

You may review the public docket containing the proposal; any comments received; and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 15000 Aviation Boulevard, Hawthorne, CA 90261.

Persons interested in being placed on a mailing list for future NPRM's should call the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is proposing an amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 (part 71) to revise V-137 between the Thermal, CA, VORTAC, and the Imperial, CA, VORTAC. The current route segment between the Thermal, CA, VORTAC, and the Imperial, CA, VORTAC, is aligned to avoid a restricted area that no longer exists. The FAA is proposing this action to realign V-137 to form a direct route between the Thermal, CA, VORTAC, and the Imperial, CA, VORTAC. This action would improve the management of air traffic operations and reduce the route mileage between the Thermal, CA, VORTAC, and the Imperial, CA, VORTAC.

Domestic VOR Federal airways are published in paragraph 6010(a), of FAA Order 7400.9L dated September 2, 2003, and effective September 16, 2003, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airway listed in this document would be published subsequently in the order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation: (1) Is not a "significant regulatory action"

under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9L, Airspace Designations and Reporting Points, dated September 2, 2003, and effective September 16, 2003, is amended as follows:

Paragraph 6010(a) Domestic VOR Federal Airways

* * * * *

V-137 [Revised]

From Imperial, CA, INT Imperial 336°M/350°T and Thermal, CA, 131°M/144°T radials; Thermal; Palm Springs, CA; Palmdale, CA; Gorman, CA; Avenal, CA; Priest, CA; Salinas, CA.

* * * * *

Issued in Washington, DC, December 22, 2003.

Reginald C. Matthews,

Manager, Airspace and Rules Division.

[FR Doc. 03-32083 Filed 12-30-03; 8:45 am]

BILLING CODE 4910-13-P