

Pembroke Pines, FL 33023; *telephone*: (954) 893-1400; *fax*: (954) 964-4141.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 1, 2007.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-3990 Filed 3-7-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25000; Directorate Identifier 2006-NM-096-AD; Amendment 39-14955; AD 2005-24-03 R1]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, and -800 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is revising an existing airworthiness directive (AD) that applies to certain Boeing Model 737-600, -700, -700C, and -800 series airplanes. That AD currently requires inspecting/measuring the length of the attachment fasteners between the nacelle support fittings and the lower wing skin panels, and related investigative/corrective actions if necessary. That AD resulted from a report from the manufacturer that in production, during the installation of certain attachment fasteners for the nacelle support fittings, only one washer was installed instead of two. This new AD corrects errors found in the existing AD. We are issuing this AD to prevent inadequate fastener clamp-up, which could result in cracking of the fastener holes, cracking along the lower wing skin panels, fuel leaking from the wing fuel tanks onto the engines, and possible fire.

DATES: The effective date of this AD is April 12, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of April 12, 2007.

On December 28, 2005 (70 FR 70713, November 23, 2005), the Director of the Federal Register approved the incorporation by reference of Boeing Service Bulletin 737-57-1275, Revision 1, dated August 18, 2005.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6440; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA proposed to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) with an airworthiness directive (AD) to revise AD 2005-24-03, amendment 39-14383 (70 FR 70713, November 23, 2005). The existing AD applies to certain Boeing Model 737-600, -700, -700C, and -800 series airplanes. The proposed AD was published in the **Federal Register** on June 13, 2006 (71 FR 34026). That action proposed to continue to require inspecting/measuring the length of the attachment fasteners between the nacelle support fittings and the lower wing skin panels, and related investigative/corrective actions if necessary. That action also proposed to correct errors found in the existing AD.

Comment

We provided the public the opportunity to participate in the development of this AD. We have considered the comment received.

Request To Cite Revised Service Information

Boeing states that, subsequent to the drafting of the subject AD, Boeing

Service Bulletin 737-57-1275, Revision 2, dated July 12, 2006, was issued. Boeing notes that Revision 2 will aid operators in completing the required tasks by more effectively and efficiently performing the inspections, while reducing the likelihood of introducing damage reported during completion of the previous revisions. Boeing recommends that Boeing Service Bulletin 737-57-1275, Revision 3, dated October 17, 2006, be incorporated into the NPRM, which further improves ease in completing the required tasks. (Revision 3 was not yet issued when the comment was submitted, but has since been issued.)

We agree with this request. We have reviewed Revision 3 of the referenced service bulletin which specifies that no more work is necessary on airplanes changed as shown in the original issue, dated September 4, 2003; Revision 1, dated August 18, 2005; and Revision 2, dated July 12, 2006. (We referred to Revision 1 in the NPRM as the appropriate source of service information for accomplishing the required actions.) We have determined that Revision 3 shows changes of operators in the effectivity and clarifies the oversize limits for replacement fasteners, but does not add any further actions or increase the economic burden on operators. Therefore, we have changed the AD to add Boeing Service Bulletin 737-57-1275, Revision 3, dated October 17, 2006, as the appropriate source of service information for accomplishing the requirements in paragraph (f) of this AD after the effective date of this AD.

Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD with the change described previously. We have determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

There are about 751 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs for U.S. operators to comply with this AD. The requirements that were previously required by AD 2005-24-03 are retained in this AD; this AD adds no additional economic burden on U.S. operators. The current costs are repeated for the convenience of affected operators, as follows:

Estimated Costs

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Inspection/Measurement	12	\$65	Nominal	\$780	302	\$235,560

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-14383 (70 FR 70713, November 23, 2005) and adding the following new airworthiness directive (AD):

2005-24-03 R1 Boeing: Amendment 39-14955. Docket No. FAA-2006-25000; Directorate Identifier 2006-NM-096-AD.

Effective Date

- (a) The effective date of this AD is April 12, 2007.

Affected ADs

- (b) This AD revises AD 2005-24-03.

Applicability

- (c) This AD applies to Boeing Model 737-600, -700, -700C, and -800 series airplanes; line numbers 1 through 761 inclusive, except for line numbers 596, 683, 742, 749, 750, 751, 754, 755, 759, and 760; certificated in any category.

Unsafe Condition

- (d) This AD results from a determination that errors were inadvertently included in the existing AD. We are issuing this AD to prevent inadequate fastener clamp-up, which could result in cracking of the fastener holes, cracking along the lower wing skin panels, fuel leaking from the wing fuel tanks onto the engines, and possible fire.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection/Measurement and Related Investigative and Corrective Actions

- (f) At the applicable time specified in paragraph (f)(1) or (f)(2) of this AD: Inspect/measure the length of certain attachment fasteners between the lower wing skin panels and the nacelle support fittings. Do the inspection/measurement, and all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 737-57-1275, Revision 1, dated August 18, 2005. After the effective date of this AD only Boeing Service Bulletin 737-57-1275,

Revision 3, dated October 17, 2006; shall be used.

(1) For Model 737-700 series airplanes modified by Supplemental Type Certificate (STC) ST00830SE as of December 28, 2005 (the effective date of AD 2005-24-03): Accomplish the actions at the later of the times specified in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD.

(i) Prior to the accumulation of 25,000 total flight hours or 25,000 total flight cycles, whichever is first.

(ii) Within 12 months after December 28, 2005.

(2) For all other airplanes: Accomplish the actions at the later of the times specified in paragraphs (f)(2)(i) and (f)(2)(ii) of this AD.

(i) Prior to the accumulation of 30,000 total flight hours or 30,000 total flight cycles, whichever is first.

(ii) Within 12 months after December 28, 2005.

(g) If accomplishing a corrective action as required by paragraph (f) of this AD, and the service bulletin specifies to contact Boeing for repair information: Before further flight, do the repair using a method approved in accordance with paragraph (i) of this AD.

Actions Accomplished According to Previous Issue of Service Bulletin

(h) Actions accomplished before December 28, 2005, in accordance with Boeing Service Bulletin 737-57-1275, dated September 4, 2003; are considered acceptable for compliance with the corresponding actions specified in this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) AMOCs approved previously in accordance with AD 2005-24-03, are approved as AMOCs for the corresponding provisions of this AD.

(3) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(4) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(j) You must use the service information identified in Table 1 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

TABLE 1.—ALL MATERIAL INCORPORATED BY REFERENCE

Boeing Service Bulletin	Revision level	Date
737-57-1275 ..	1	August 18, 2005.
737-57-1275 ..	3	October 17, 2006.

(1) The Director of the Federal Register approved the incorporation by reference of Boeing Service Bulletin 737-57-1275, Revision 3, dated October 17, 2006; in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On December 28, 2005 (70 FR 70713, November 23, 2005), the Director of the Federal Register approved the incorporation by reference of Boeing Service Bulletin 737-57-1275, Revision 1, dated August 18, 2005.

(3) Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 12, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-3006 Filed 3-7-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-24709; Directorate Identifier 2006-CE-28-AD; Amendment 39-14980; AD 2007-05-19]

RIN 2120-AA64

Airworthiness Directives; Glasflugel Models H 301 “Libelle,” H 301B “Libelle,” Standard “Libelle,” and Standard Libelle-201B Sailplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA adopts a new airworthiness directive (AD) for all Glasflugel Models H 301 “Libelle,” H 301B “Libelle,” Standard “Libelle,” and

Standard Libelle-201B sailplanes. This AD requires you to replace the rudder actuator arm (manufactured according to drawing No. 301-45-10) with an improved design rudder actuator arm (manufactured following drawing No. 301-45-13). This AD results from mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. We are issuing this AD to detect and correct damage to the rudder actuator arm, which could result in failure of the rudder actuator arm. This failure could result in reduced or loss of rudder control.

DATES: This AD becomes effective on April 12, 2007.

As of April 12, 2007, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

ADDRESSES: To get the service information identified in this AD, contact Glasflugel, Glasfaser-Flugzeug-Service GmbH, Hansjory Steifeneder, Hofener Weg, 72582 Grabenstetten, Federal Republic of Germany; telephone: 011 49 7382 1032.

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2006-24709; Directorate Identifier 2006-CE-28-AD.

FOR FURTHER INFORMATION CONTACT:

Gregory Davison, Glider Project Officer, ACE-112, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:**Discussion**

On August 4, 2006, we issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Glasflugel Models H 301 “Libelle,” H 301B “Libelle,” Standard “Libelle,” and Standard Libelle-201B sailplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on August 11, 2006 (71 FR 46128). The NPRM proposed to require you to replace the rudder actuator arm (manufactured according to drawing No. 301-45-10) with an improved design rudder actuator arm (manufactured following drawing No. 301-45-13).

Comments

We provided the public the opportunity to participate in developing

this AD. The following presents the comment received on the proposal and FAA’s response to the comment:

Comment Issue: Service Documents and Parts Manufacturer Approval

Jack Buster of the Modification and Replacement Parts Association (MARPA) requests the following be incorporated into the regulatory action:

1. Service documents deemed essential to the accomplishment of this proposed action be incorporated by reference and published in the Docket Management System (DMS); and

2. The issue of parts manufacturer approval (PMA) be addressed in the proposed action and that all Directorates within the FAA treat the issue the same per Section 1, paragraph (b)(10) of Executive Order 12866.

We agree that the service documents are essential and should be incorporated by reference. However, we do not incorporate by reference any document in a proposed AD action; instead we incorporate by reference the document in the final rule. Since we are issuing the proposal as a final rule AD action, the service information referenced in this action will be incorporated by reference.

We are currently reviewing issues surrounding the posting of service bulletins in the Department of Transportation’s DMS as part of the AD docket. Once we have thoroughly examined all aspects of this issue and have made a final determination, we will consider whether our current practice needs to be revised.

On the PMA issue, Mr. Buster’s comments are timely in that the FAA is currently reviewing this issue as it applies to all products: Transport airplanes, commuter airplanes, general aviation airplanes, engines and propellers, rotorcraft, and appliances. The FAA acknowledges that there are different ways of addressing this issue to ensure that unsafe PMA parts are identified and addressed. Once we have thoroughly examined all aspects of this issue including input from industry and have made a final determination, we will consider developing a standardized approach and standardized language on how to address PMA parts in airworthiness directives.

We have determined that to delay this AD action would be inappropriate since an unsafe condition exists and that replacement of certain parts must be done to ensure continued safety. Therefore, we have made no change to the AD in this regard.

Conclusion

We have carefully reviewed the available data and determined that air