

Reduction Act of 1995 (44 U.S.C. 3501 *et seq.*).

List of Subjects in 9 CFR Part 77

Animal diseases, Bison, Cattle, Reporting and recordkeeping requirements, Transportation, Tuberculosis.

■ Accordingly, we are amending 9 CFR part 77 as follows:

PART 77—TUBERCULOSIS

■ 1. The authority citation for part 77 continues to read as follows:

Authority: 7 U.S.C. 8301–8317; 7 CFR 2.22, 2.80, and 371.4.

§ 77.7 [Amended]

■ 2. In § 77.7, paragraph (a) is amended by removing the word “California,”.

§ 77.9 [Amended]

■ 3. In § 77.9, paragraph (a) is amended by adding the words “California and” before the words “New Mexico”.

Done in Washington, DC, this 12th day of September 2008.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. E8–21814 Filed 9–17–08; 8:45 am]

BILLING CODE 3410–34–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2008–0748 Directorate Identifier 2008–CE–041–AD; Amendment 39–15677; AD 2008–19–10]

RIN 2120–AA64

Airworthiness Directives; EADS SOCATA Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been discovered that a risk of mechanical interference exists in the movement of the emergency landing gear by-pass selector, due to an insufficient functional gap between a floor panel

attachment lug and the landing gear control button.

This condition, if not corrected, causes mechanical interference which could result in a situation where, during emergency procedures, the landing gear cannot be extended.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective October 23, 2008.

On October 23, 2008, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4119; fax: (816) 329–4090.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on July 8, 2008 (73 FR 38935). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It has been discovered that a risk of mechanical interference exists in the movement of the emergency landing gear by-pass selector, due to an insufficient functional gap between a floor panel attachment lug and the landing gear control button.

This condition, if not corrected, causes mechanical interference which could result in a situation where, during emergency procedures, the landing gear cannot be extended.

For the reasons described above, this EASA Emergency Airworthiness Directive (AD) requires a check of the gap between the landing gear control button and the floor panel and, if the gap is found to be insufficient, modification of the floor panel.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect 72 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with basic requirements of this AD. The average labor rate is \$80 per work-hour (no labor cost; work-hour warranty given by manufacturer until May 31, 2009).

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$5,760 or \$80 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between

the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008-19-10 EADS SOCATA: Amendment 39-15677; Docket No. FAA-2008-0748; Directorate Identifier 2008-CE-041-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective October 23, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to TBM 700 airplanes, serial numbers 364, 367, and 370 through 439, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

"It has been discovered that a risk of mechanical interference exists in the movement of the emergency landing gear bypass selector, due to an insufficient functional gap between a floor panel attachment lug and the landing gear control button.

This condition, if not corrected, causes mechanical interference which could result in a situation where, during emergency procedures, the landing gear cannot be extended.

For the reasons described above, this EASA Emergency Airworthiness Directive (AD) requires a check of the gap between the landing gear control button and the floor panel and, if the gap is found to be insufficient, modification of the floor panel."

Actions and Compliance

(f) For airplanes that have had the floor panel removed for maintenance or if it cannot be positively determined that the floor panel has not been removed at any time, do the following actions, unless already done:

(1) Before further flight after October 23, 2008 (the effective date of this AD), inspect the gap between the landing gear control button and the floor panel. Do the inspection following paragraph A of the Accomplishment Instructions in EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008.

(2) If the gap is below the limits specified in paragraph A of EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008, before further flight after the inspection required in paragraph (f)(1) of this AD, modify the floor panel following paragraph C of the Accomplishment Instructions in EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008.

(3) If the gap is at or above the limits specified in paragraph A of EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008, before further flight after the inspection required in paragraph (f)(1) of this AD, recondition the airplane following paragraph D of the Accomplishment Instructions in EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008.

(g) For airplanes in which it can be positively determined that the floor panel has not been removed at any time, within the next 30 days after October 23, 2008 (the effective date of this AD), do the following actions, unless already done:

(1) Inspect the gap between the landing gear control button and the floor panel. Do the inspection following paragraph A of the Accomplishment Instructions in EADS

SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008.

(2) If the gap is below the limits specified in paragraph A of EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008, before further flight after the inspection required in paragraph (g)(1) of this AD, modify the floor panel following paragraph C of the Accomplishment Instructions in EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008.

(3) If the gap is at or above the limits specified in paragraph A of EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008, before further flight after the inspection required in paragraph (g)(1) of this AD, recondition the airplane following paragraph D of the Accomplishment Instructions in EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-154, dated April 2008.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Special Flight Permit

(i) A single ferry flight of the airplane with landing gear extended is allowed in order to reach the nearest maintenance facility where the inspection and modification is to be done.

Related Information

(j) Refer to MCAI European Aviation Safety Agency (EASA) Emergency AD No. 2008-0081-E, dated April 25, 2008; and EADS SOCATA Mandatory TBM Aircraft Service

Bulletin SB 70–154, dated April 2008 for related information.

Material Incorporated by Reference

(k) You must use EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70–154, dated April 2008 to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact EADS SOCATA, Direction des Services, 6921 Tarbes Cedex 9, France; or SOCATA AIRCRAFT, INC., North Perry Airport, 7501 South Airport Road, Pembroke Pine, Florida 33023.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on September 8, 2008.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8–21359 Filed 9–17–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2008–0974; Directorate Identifier 2008–CE–048–AD; Amendment 39–15673; AD 2008–19–06]

RIN 2120–AA64

Airworthiness Directives; EADS SOCATA Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Following the rupture of an alternator and vapour cycle cooling system pulley drive assembly, the AD 2008–0067–E had been published to require the replacement of the pulley drive assembly by a new one of an improved design.

Recent cases of rupture of the alternator and vapour cycle cooling system compressor drive shaft and of cracks on the standby-alternator and compressor support have reportedly been found.

Such failures could lead to the loss of the alternator and of the vapour cycle cooling systems, and could also cause mechanical damage inside the powerplant compartment.

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective October 8, 2008.

On October 8, 2008, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

You must receive comments on this AD by October 20, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493–2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4119; fax: (816) 329–4090.

SUPPLEMENTARY INFORMATION:

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Emergency AD No.: 2008–0129R1–E, dated July 31, 2008 (referred to after this as “the MCAI”), to correct an unsafe

condition for the specified products. The MCAI states:

Following the rupture of an alternator and vapour cycle cooling system pulley drive assembly, the AD 2008–0067–E had been published to require the replacement of the pulley drive assembly by a new one of an improved design.

Recent cases of rupture of the alternator and vapour cycle cooling system compressor drive shaft and of cracks on the standby-alternator and compressor support have reportedly been found.

Such failures could lead to the loss of the alternator and of the vapour cycle cooling systems, and could also cause mechanical damage inside the powerplant compartment.

To address this condition, this AD supersedes AD 2008–0067–E and mandates the removal, as a temporary measure, of the compressor drive belt and of the torque limiter, the conditional replacement of the pulley drive shear shaft, and repetitive inspections for cracks of the pulley drive assembly and of the alternator/compressor support.

Revision 1 of this AD introduces an alternative temporary solution with the aim to restore the capability to make use of the air conditioning system. This solution consists in replacing the original pulley drive assembly by a time-limited assembly of a new design, corresponding to the EADS SOCATA modification MOD 70–0240–21.

A definitive solution is still under consideration to correct this condition. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

EADS SOCATA has issued EADS SOCATA Mandatory TBM Aircraft Alert Service Bulletin SB No. 70–161, Amendment 2, and EADS SOCATA Mandatory TBM Aircraft Alert Service Bulletin SB No. 70–161, Amendment 3, both dated July 2008. The actions described in the service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.