

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024–26–07 Embraer S.A. (Type Certificate Previously Held by Yaborã Indústria Aeronáutica S.A.; Embraer S.A.; Empresa Brasileira de Aeronáutica S.A. (EMBRAER)): Amendment 39–22922; Docket No. FAA–2024–2133; Project Identifier MCAI–2024–00243–T.

(a) Effective Date

This airworthiness directive (AD) is effective March 11, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Embraer S.A. (Type Certificate previously held by Yaborã Indústria Aeronáutica S.A.; Embraer S.A.; Empresa Brasileira de Aeronáutica S.A. (EMBRAER)) airplanes specified in paragraphs (c)(1) and (2) of this AD, certificated in any category.

(1) Model EMB–135ER, –135KE, –135KL, and –135LR airplanes.

(2) Model EMB–145, –145EP, –145ER, –145LR, –145MP, –145MR, and –145XR airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a structural assessment that indicated certain central fuselage longitudinal splices are subjected to fatigue damage on multiple sites due to loose fasteners, which may reduce the structural residual strength below the required levels. The FAA is issuing this AD to address undetected fatigue damage on certain central fuselage longitudinal splices. The unsafe condition, if not addressed, could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Agência Nacional de Aviação Civil (ANAC) AD 2024–04–03R01, effective May 31, 2024 (ANAC AD 2024–04–03R01).

(h) Exceptions to ANAC AD 2024–04–03R01

(1) Where ANAC AD 2024–04–03R01 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraphs (b)(1) and (2) of ANAC AD 2024–04–03R01 specify the initial compliance time for the external detailed inspection, for this AD, the initial compliance time for doing the external detailed inspection is prior to the accumulation of 44,000 total flight cycles, or within 500 flight cycles after the effective date of this AD, whichever occurs later.

(3) Where paragraph (b)(3) of ANAC AD 2024–04–03R01 specifies “If any discrepancies are found, contact Embraer,” this AD requires replacing that text with “If any discrepancy (including cracking) is detected during an inspection required by paragraph (g) of this AD, repair the discrepancy (including cracking) before further flight using a method approved by the Manager, International Validation Branch, FAA; or ANAC; or Embraer’s ANAC Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.”

(4) Paragraph (d) of ANAC AD 2024–04–03R01 specifies to report inspection results to ANAC and Embraer within a certain compliance time. For this AD, report inspection results after each inspection required by paragraph (g) of this AD at the applicable times specified in paragraph (h)(4)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(5) This AD does not adopt paragraph (e) of ANAC AD 2024–04–03R01.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j) of this AD. Information may be emailed to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or ANAC; or ANAC’s authorized Designee. If approved by the ANAC Designee, the approval must include the Designee’s authorized signature.

(j) Additional Information

For more information about this AD, contact Hassan Ibrahim, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206–231–3653; email: Hassan.M.Ibrahim@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Agência Nacional de Aviação Civil (ANAC) AD 2024–04–03R01, effective May 31, 2024.

(ii) [Reserved]

(3) For ANAC material identified in this AD, contact ANAC, Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, Brazil; telephone 55 (12) 3203–6600; email pac@anac.gov.br; website anac.gov.br/en/. You may find this ANAC AD on the ANAC website at sistemas.anac.gov.br/certificacao/DA/DAE.asp.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 6, 2025.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–02144 Filed 2–3–25; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2024–1299; Project Identifier MCAI–2023–00237–A; Amendment 39–22925; AD 2025–01–01]

RIN 2120–AA64

Airworthiness Directives; Britten-Norman Aerospace Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Britten-Norman Aerospace Ltd. Model BN–2, BN–2A, BN–2A–2, BN–2A–3, BN–2A–6, BN–2A–8, BN–2A–9, BN–2A–20, BN–2A–21, BN–2A–26, BN–2A–27, BN–2B–20, BN–2B–21, BN–2B–26, BN–2B–27, BN–2T, BN2T–4R, and BN2T–4S airplanes; and certain Model BN2A MK. III, BN2A MK. III–2, and BN2A MK. III–3 airplanes. This AD was prompted by the determination that, in order to ensure the continued structural integrity of certain landing gear and associated components, it is necessary to require removal of these components from service prior to exceeding established fatigue lives. This AD

requires determining the number of landings on affected main landing gears (MLGs), nose landing gears (NLGs), and associated components; removing from service any part that has reached or exceeded the established fatigue life and installing a replacement part; and prohibiting the installation of any affected part unless the number of landings for that part is below the established fatigue life. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 11, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 11, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2024–1299; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Britten-Norman material identified in this AD, contact Britten-Norman Aerospace Ltd., Bembridge Airport, Bembridge, Isle of Wight, UK, PO35 5PR; phone: +44 20 3371 4000; email: *customer.support@britten-norman.com*; website: *britten-norman.com/approvals-technical-publications*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available at *regulations.gov* under Docket No. FAA–2024–1299.

FOR FURTHER INFORMATION CONTACT:

Beenal Desai, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (609) 485–9930; email: *beenal.desai@faa.gov*.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Britten-Norman Aerospace Ltd. Model BN–2, BN–2A, BN–2A–2, BN–2A–3, BN–2A–6, BN–2A–8, BN–2A–9, BN–2A–20, BN–2A–21, BN–2A–26, BN–

2A–27, BN–2B–20, BN–2B–21, BN–2B–26, BN–2B–27, BN–2T, BN2T–4R, and BN2T–4S (Islander) airplanes; and Model BN2A MK. III, BN2A MK. III–2, and BN2A MK. III–3 (Trislander) airplanes, fitted with landing gear and associated components manufactured by Fairey Hydraulics Ltd (FHL) and Britten-Norman Aircraft (BNA). The NPRM published in the **Federal Register** on May 17, 2024 (89 FR 43342). The NPRM was prompted by AD G–2023–0001, dated February 8, 2023, issued by Civil Aviation Authority (CAA), which is the aviation authority for the United Kingdom (UK) (UK CAA AD G–2023–0001) (also referred to as the MCAI). The MCAI states that to ensure the continued safe operation of certain Islander’s and Trislander’s NLG, MLG, and associated components, the manufacturer and the UK CAA determined that affected parts exceeding the established fatigue lives must be removed from service and that installation of parts that have reached their established fatigue lives must be prohibited.

In the NPRM, the FAA proposed to require determining the number of landings on affected MLGs, NLGs, and associated components; removing from service any part that has reached or exceeded the established fatigue life and installing a replacement part; and prohibiting the installation of any affected part unless the number of landings for that part is below the established fatigue life. The FAA is issuing this AD to address the unsafe condition on these products. Exceeding the established fatigue life, if not addressed, could result in failure of the structural integrity of the landing gear and associated components, which could result in damage to the airplane and injury to occupants.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2024–1299.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from one individual commenter. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Request To Include a Method for Calculating Landings Per Flight Hour

The commenter stated that in the United States landings are not required to be tracked on general aviation or commercial use non turbo prop airplanes. The commenter also mentioned that AD 2002–25–03,

Amendment 39–12978 (67 FR 76106, December 11, 2002) provides a calculation of 3 landings per flight hour to calculate the number of landings, but this calculation is not realistic for all airplane operations and should be re-evaluated. The commenter explained it is difficult to take off and land three times in an hour with taxi, loading, and unloading of passengers and cargo. The commenter stated that if a routine flight was 30 minutes to an hour, then 1 or 2 landings for 1 flight hour should be considered by the FAA. The FAA infers that the commenter is requesting that the NPRM be revised to include a method for calculating landings per flight hour.

The FAA partially agrees with the commenter’s request. The FAA acknowledges that landings are not required to be tracked on domestic general aviation airplanes. The compliance time for this AD is based on the number of landings because the affected MLGs, NLGs, and associated components that are showing fatigue are used during landing operations.

The FAA revised paragraph (h)(1) of this AD to specify how to calculate for an unknown number of landings and requires using 3 landings per 1 hour time-in-service (TIS). The FAA disagrees with using the calculation of 1 or 2 landings per 1 hour TIS because the 3 landings per 1 hour TIS calculation is a conservative estimate and has been used in previous ADs. The FAA received information from Britten-Norman that supported using a calculation of 3 landings per 1 hour TIS. In addition, Britten-Norman does not have any data to substantiate decreasing the number of landings to 1 or 2 landings per 1 hour TIS. The FAA disagrees with referring to “flight hours” and is referring to TIS because “flight hours” are not defined in FAA regulations but TIS is defined in FAA regulations and is used with respect to maintenance records.

Request for Extension of Fatigue Life Landings by 30 Percent

The commenter requested that the FAA allow a 30-percent increase of the fatigue life values specified in Tables 1, 2, and 3 of Section 6 in Britten-Norman Service Bulletin SB 298, Issue 3, dated July 7, 2023 (Britten-Norman SB 298, Issue 3). The commenter stated that other countries allow the affected airplanes to operate with heavier gross weights than the United States allows, which reduces the fatigue lives of the affected components by shortening them. The commenter suggested a periodic eddy current inspection to determine the fatigue life value.

The FAA disagrees with both the commenter’s request for a 30-percent fatigue life value increase and the commenter’s suggestion to use a periodic eddy current inspection to determine the fatigue life value. The commenter did not provide substantiating data to support the requested changes. Britten-Norman provided the fatigue lives for the affected MLGs, NLGs, and associated components for the worldwide fleet based on its analysis of the unsafe condition and does not have data to substantiate increasing the fatigue life by 30-percent. The FAA agrees with this determination for airplanes on the U.S. registry. Operators may submit a proposal, with substantiating data, for revised requirements that affect the fatigue life value by requesting an alternative method of compliance (AMOC) using the procedures specified in paragraph (j) of this AD.

The FAA has not changed this AD regarding this comment.

Request for Compliance Time Based on Operating Environments and Conditions

The commenter stated that operating environments and conditions should also be considered when establishing compliance times. The commenter explained that these are excellent cargo and passenger airplanes and are flown all over the world in remote places with short, unimproved runways of dirt and gravel. The commenter stated that these are extreme operating conditions that most airplanes do not encounter and the comparison between airplanes operated in the United States and airplanes operated in other countries are not equal.

The FAA disagrees with the commenter’s request to change the compliance time based on airplane operating environments and conditions. There is no current requirement to track the hours spent flying in different conditions. Additionally, operators may not know an airplane’s entire flight or maintenance history. Without this detailed knowledge of each airplane, it would be impossible for the FAA to

develop a special set of inspections based on airplane operating environments and conditions. However, operators may submit a proposal, with substantiating data, for revised requirements by requesting an AMOC using the procedures specified in paragraph (j) of this AD.

The FAA has not changed this AD regarding this comment.

Request To Allow Continued Use of Parts That Exceed Fatigue Life Until Replacement Parts Are Available

The commenter requested that the MLG, NLG, and associated components that exceed the fatigue lives specified in in Tables 1, 2, and 3 of Section 6 in Britten-Norman SB 298, Issue 3, be allowed to continue to be used in service until replacement parts are available. The commenter referred to paragraph 2, “Corrective Action,” of UK CAA AD G–2023–0001, which states “Any main or nose landing gear or component which exceed the fatigue life stated in Tables 1, 2 or 3 must be withdrawn from service immediately.” The commenter stated that if replacement parts are not available then the proposed AD would not only ground the fleet but close businesses that rely on these airplanes.

The FAA disagrees with allowing parts that exceed the fatigue life to be allowed in-service until replacement parts are available. While the FAA acknowledges the commenter’s concern regarding immediately removing parts that exceed the specified fatigue lives from service, this AD does not require immediately removing from service affected parts that exceed the specified fatigue lives. Paragraph (h)(2) of this AD provides a grace period of 30 days after the effective date of this AD for replacing affected parts that exceed the specified fatigue lives. Britten-Norman has confirmed that the landing gear is still in production and spares are available. To the extent replacement parts may not be available, the FAA cannot base its AD action on whether replacement parts are available or can be produced. While every effort is made to avoid grounding airplanes, the FAA

must address the unsafe condition. Operators may submit a proposal for revised requirements, with substantiating data, by requesting an AMOC using the procedures specified in paragraph (j) of this AD.

The FAA has not changed this AD regarding this comment.

Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes and any changes described previously, this AD is adopted as proposed in the NPRM. None of the changes increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Britten-Norman SB 298, Issue 3. This material provides procedures for identifying the affected MLGs, NLGs, and associated components that need to have the number of landings tracked and provides the associated fatigue life. This material also specifies to remove from service any affected part that exceeds the specified fatigue life.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 87 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Determine the number of landings accumulated on affected MLGs, NLGs, and associated components.	1 work-hour × \$85 per hour = \$85.	\$0	\$85	\$7,395.
Replace MLG	16 work-hours × \$85 per hour = \$1,360.	30,000	31,360	2,728,320.
Replace NLG	16 work-hours × \$85 per hour = \$1,360.	35,000	36,360	3,163,320.

ESTIMATED COSTS—Continued

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace associated components	Up to 4 work-hours × \$85 per hour = \$340.	4,000	Up to 4,340	Up to 377,580.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–01–01 Britten-Norman Aerospace

Ltd.: Amendment 39–22925; Docket No. FAA–2024–1299; Project Identifier MCAI–2023–00237–A.

(a) Effective Date

This airworthiness directive (AD) is effective March 11, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Britten-Norman Aerospace Ltd. airplanes, certificated in any category, fitted with Fairey Hydraulics Ltd or Britten-Norman Aircraft landing gear and associated landing gear components, identified in paragraphs (c)(1) and (2) of this AD.

(1) Model BN–2, BN–2A, BN–2A–2, BN–2A–3, BN–2A–6, BN–2A–8, BN–2A–9, BN–2A–20, BN–2A–21, BN–2A–26, BN–2A–27, BN–2B–20, BN–2B–21, BN–2B–26, BN–2B–27, BN–2T, BN2T–4R, and BN2T–4S airplanes.

(2) Model BN2A MK. III, BN2A MK. III–2, and BN2A MK. III–3 airplanes.

(d) Subject

Joint Aircraft System Component (JASC) Code 3200, Landing Gear System.

(e) Unsafe Condition

This AD was prompted by the determination that in order to ensure the continued structural integrity of certain landing gear and associated components, it is necessary to require removal of these components from service prior to exceeding established fatigue lives. Exceeding the established fatigue life, if not addressed, could result in failure of the structural integrity of the landing gear and associated components, which could result in damage to the airplane and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purpose of this AD:

(1) An "affected part" is a main landing gear (MLG), nose landing gear (NLG), or component identified in Table 1, 2, or 3 of Section 6 in Britten-Norman SB 298, Issue 3, dated July 7, 2023 (Britten-Norman SB 298, Issue 3).

(2) A "part eligible for installation" is an MLG, NLG, or component with a part that has been established to be below the associated fatigue life identified in Table 1, 2, or 3 of Section 6 in Britten-Norman SB 298, Issue 3.

(h) Required Actions

(1) Within 30 days after the effective date of this AD, determine the number of landings accumulated on the affected parts. For an unknown number of landings, calculate the number based on 3 landings per 1 hour time-in-service.

(2) Before accumulating the number of landings (fatigue life) associated with the applicable affected part as identified in Table 1, 2, or 3 of Section 6 in Britten-Norman SB 298, Issue 3, or within the next 30 days after the effective date of this AD, whichever occurs later, replace any affected part with a part eligible for installation.

(3) Thereafter, replace any affected part with a part eligible for installation before accumulating the fatigue life, as identified in Table 1, 2, or 3 of Section 6 in Britten-Norman SB 298, Issue 3.

(i) Parts Installation Limitation

As of the effective date of this AD, do not install a MLG, NLG, or associated component unless it is a part eligible for installation.

(j) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD or email to: AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Beenal Desai, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (609) 485–9930; email: beenal.desai@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Britten-Norman Service Bulletin SB 298, Issue 3, dated July 7, 2023.

(ii) [Reserved]

(3) For Britten-Norman material identified in this AD, contact Britten-Norman Aerospace Ltd., Bembridge Airport, Bembridge, Isle of Wight, UK, PO35 5PR; phone: +44 20 3371 4000; email: customer.support@britten-norman.com; website: britten-norman.com/approvals-technical-publications.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 2, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025-02187 Filed 2-3-25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2025-0017; Project Identifier MCAI-2024-00706-R; Amendment 39-22951; AD 2025-03-03]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Leonardo S.p.a. Model A109E, A109K2, A109S, AB412, AB412 EP, AB139, and AW139 helicopters. This AD was prompted by a report that certain rescue hoist cable assemblies may be equipped with a defective ball end. This AD requires inspecting certain rescue hoist cable assemblies and, depending on the results, replacing the rescue hoist cable assembly. This AD also allows installing certain rescue hoist cable assemblies and certain rescue hoists provided its

requirements are met. These actions are specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 19, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 19, 2025.

The FAA must receive comments on this AD by March 21, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to regulations.gov. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-0017; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2025-0017.

FOR FURTHER INFORMATION CONTACT: Eric Rivera, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (847) 294-7166; email: eric.rivera01@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2025-0017; Project Identifier MCAI-2024-00706-R" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Eric Rivera, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (847) 294-7166; email: eric.rivera01@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0228, dated November 29, 2024 (EASA AD 2024-0228) (also referred to as the MCAI), to correct an unsafe condition on Leonardo S.p.A. Model AB412, AB412EP, A109E, A109K2, A109S, AB139, and AW139 helicopters. The