

47997, July 22, 2002), which governs the FAA's AD system. The regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. Because we have now included this material in part 39, we no longer need to include it in each individual AD.

The FAA estimates that this proposed AD would affect 18 helicopters of U.S. registry. It would take approximately 3 work hours to disable the windshield wipers and modify the electrical system of the windshield wipers and 4 work hours per helicopter if the timed relays must be replaced by modifying the electrical system of the windshield wipers. The average labor rate is \$65 per work hour. Required parts would cost approximately \$367 per helicopter. Based on these figures, we estimate that the total cost impact of the proposed AD on U.S. operators would be \$14,796, assuming the relays are replaced on the entire fleet. However, the manufacturer states in its ABT that it will reimburse owners for 3 or 4 work hours at a fixed rate of \$40 per work hour and will provide the parts for free. Assuming a warranty credit of 4 work hours (\$2,880) and free parts (\$6,606), the estimated total cost impact of this proposed AD would be \$5,310.

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the

Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Agusta S.p.A: Docket No. 2003-SW-32-AD.

Applicability: Model A109E helicopters, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent the incompatibility of certain relays with the windshield wiper electrical system, overheating of the resistor due to system overload, and an electrical fire, accomplish the following:

(a) For helicopters, serial number (S/N) 11502 through 11504, and 11122 through 11130, except 11123, 11127, and 11129:

(1) Within 5 hours time-in-service, do the following:

(i) Disable the windshield wipers by following the Compliance Instructions, Part I, paragraphs 2.1 through 2.5, of Agusta Alert Bollettino Tecnico No. 109EP-27, Revision A, dated February 7, 2003 (ABT).

(ii) Install a placard stating that the windshield wipers are inoperative by following the Compliance Instructions, Part I, paragraph 2.6, of the ABT.

(2) Within 6 months, modify the electrical system of the windshield wipers using the Compliance Instructions, Part II, paragraphs 1. through 15., of the ABT, and remove the placard that was installed as required by paragraph (a)(1)(ii) of this AD.

(b) For helicopters, S/Ns 11151, 11501, and 11001 through 11133, except 11122, 11124 through 11128, and 11130, with timed relay, part number (P/N) T412-DJ1001-C installed, on or before [insert date 1 year after date of publication of final rule in the **Federal Register**] or when you replace a timed relay, P/N T412-DJ1001-C, with either relay, P/N TDH-8070-1001P or P/N T412-2006, whichever occurs first:

(1) If windshield wiper kit, P/N 109-0811-44-105 or -106 is installed, modify the windshield wiper electrical system and replace the timed relay, P/N T412-DJ1001-C, with a timed relay, P/N TDH-8070-1001P or P/N T412-2006, by following the Compliance Instructions, Part III, paragraphs 1. through 1.16, of the ABT.

(2) If windshield wiper kit, P/N 109-0811-44-101 or -102 is installed, modify the windshield wiper electrical system and replace the timed relay, P/N T412-DJ1001-C, with a timed relay, P/N TDH-8070-1001P or P/N T412-2006, by following the Compliance Instructions, Part III, paragraphs 2. through 2.19, of the ABT.

(c) To request a different method of compliance or a different compliance time

for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, FAA, for information about previously approved alternative methods of compliance.

Note: The subject of this AD is addressed in Ente Nazionale per l'Aviazione Civile (Italy), AD No. 2003-032, dated February 10, 2003.

Issued in Fort Worth, Texas, on December 31, 2003.

Kim Smith,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 04-369 Filed 1-7-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-SW-29-AD]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model EC 130 B4 and AS 350 B3 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes adopting a new airworthiness directive (AD) for the specified Eurocopter France (Eurocopter) model helicopters. This proposal would require inspecting the fuel transfer line and air exhaust duct for chafing, inspecting the air exhaust duct for a hole, and if necessary, repositioning the air exhaust duct to achieve the minimum clearances. This proposal is prompted by a report of damage to the fuel transfer line due to wear associated with vibrations and chafing of the fuel transfer line and the air exhaust duct. The actions specified by this proposed AD are intended to detect chafing wear of the air exhaust duct and the fuel transfer line, which could result in a hole in the fuel transfer line, fuel leaking into the engine compartment and creating a fire hazard that could lead to a fire and a subsequent forced landing.

DATES: Comments must be received on or before March 8, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2003-SW-29-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following

address: 9-asw-adcomments@faa.gov. Comments may be inspected at the Office of the Regional Counsel between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Ed Cuevas, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Safety Management Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5355, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments will be considered before taking action on the proposed rule. The proposals contained in this document may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this proposal must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2003-SW-29-AD." The postcard will be date stamped and returned to the commenter.

Discussion

The Direction Generale De L'Aviation Civile (DGAC), the airworthiness authority for France, notified the FAA that an unsafe condition may exist on Eurocopter Model EC 130 B4 and AS 350 B3 helicopters. The DGAC advises of receiving a report of damage to the fuel transfer line due to interference associated with vibrations and chafing of the bleed valve air exhaust duct.

Eurocopter has issued Alert Service Bulletin (ASB) No. 71A001 for Model EC 130 B4 helicopters and ASB No. 71.00.16 for Model AS 350 B3 helicopters, both of which specify checks for interference between the

bleed valve air exhaust duct and the engine fuel line. Both ASBs are dated May 12, 2003. The DGAC classified these ASBs as mandatory and issued ADs No. 2003-208(A) and 2003-209(A), both dated May 28, 2003, to ensure the continued airworthiness of these helicopters in France.

These helicopter models are manufactured in France and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

This previously described unsafe condition is likely to exist or develop on other helicopters of the same type design registered in the United States. Therefore, the proposed AD would require inspecting the fuel transfer line and air exhaust duct for chafing, and if necessary, repositioning the air exhaust duct to achieve at least 20 mm (0.8 in) of clearance in interference Area A and 12 mm (0.5 in) of clearance in interference Area B as depicted in Figure 1 of the Eurocopter Alert Service Bulletin. These are one-time inspections. The actions would be required to be accomplished in accordance with the ASBs described previously.

On July 10, 2002, the FAA issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system. The regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. Because we have now included this material in part 39, we no longer need to include it in each individual AD.

The FAA estimates that this proposed AD would affect 100 helicopters of U.S. registry and the proposed inspection would take approximately 0.5 work hour per helicopter to accomplish and 1 work hour to replace either the fuel transfer line or the air exhaust duct at an average labor rate of \$65 per work hour. Cost of replacement parts, if needed, would be \$817 for the fuel transfer line and \$522 for the air exhaust duct. Based on these figures, we estimate the total cost impact of the proposed AD on U.S. operators to be \$6,188, assuming 2 fuel transfer lines and 2 air exhaust ducts are replaced.

The regulations proposed herein would not have a substantial direct

effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption

ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Eurocopter France: Docket No. 2003-SW-29-AD.

Applicability: Model EC 130 B4 helicopters with an optional engine flushing system installed, and AS 350 B3 helicopters with an optional engine flushing system installed and modified in accordance with MOD 073098, certificated in any category.

Compliance: Required within 10 hours time-in-service, unless accomplished previously.

To detect chafing wear of the air exhaust duct and the fuel transfer line, which could result in a hole in the fuel transfer line, fuel leaking into the engine compartment and creating a fire hazard that could lead to a fire and a subsequent forced landing, accomplish the following:

(a) Inspect the fuel transfer line located between the bleed valve of the engine starting system and the engine fuel filter for chafing

in the interference areas in accordance with the Operational Procedure, paragraph 2.B.1., of Eurocopter Alert Service Bulletin (ASB) No. 71A001, dated May 12, 2003, for Model EC 130 B4 helicopters, or Eurocopter ASB No. 71.00.16, dated May 12, 2003, for Model AS 350 B3 helicopters.

(1) If the depth of the deepest wear mark is less than or equal to 0.05 mm (0.002 in), apply the maintenance procedure stated in the Engine Maintenance Manual.

(2) If the depth of the deepest wear mark is more than 0.05 mm (0.002 in) and less than or equal to 0.2 mm (0.008 in), replace the fuel transfer line within the next 50 hours TIS or within one month, whichever occurs first.

(3) If the depth of the deepest wear mark is more than 0.2 mm (0.008 in), replace the fuel transfer line before further flight.

(b) Inspect the air exhaust duct located between the bleed valve of the engine starting system and the engine fuel filter for a hole in the interference areas in accordance with the Operational Procedure, paragraph 2.B.1., of Eurocopter ASB No. 71A001, dated May 12, 2003, for Model EC 130 B4 helicopters, or Eurocopter ASB No. 71.00.16, dated May 12, 2003, for Model AS 350 B3 helicopters. If there is a hole in the air exhaust duct, replace the air exhaust duct within one month or before performing any engine flushing operation, whichever occurs first.

(c) Measure the clearances between the fuel transfer line and the air exhaust duct located between the bleed valve of the engine starting system and the engine fuel filter in the interference areas in accordance with the Operational Procedure, paragraph 2.B.1., of Eurocopter ASB No. 71A001, dated May 12, 2003, for Model EC 130 B4 helicopters, or Eurocopter ASB No. 71.00.16, dated May 12, 2003, for Model AS 350 B3 helicopters. If the clearance is less than 20 mm (0.8 in) in interference Area A or less than 12 mm (0.5 in) in interference Area B, reposition the air exhaust duct in accordance with the Operational Procedure, paragraph 2.B.2., of Eurocopter ASB No. 71A001, dated May 12, 2003, for Model EC 130 B4 helicopters, or Eurocopter ASB No. 71.00.16, dated May 12, 2003, for Model AS 350 B3 helicopters.

(d) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Safety Management Office, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

Note: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 2003-208(A) and AD 2003-209(A), both dated May 28, 2003.

Issued in Fort Worth, Texas, on December 31, 2003.

Kim Smith,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 04-370 Filed 1-7-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF LABOR

Occupational Safety and Health Administration

29 CFR Part 1926

[Docket No. S-030]

RIN 1218-AC01

Safety Standards for Cranes and Derricks

AGENCY: Occupational Safety and Health Administration (OSHA), U.S. Department of Labor.

ACTION: Notice of Negotiated Rulemaking Committee meetings.

SUMMARY: The Occupational Safety and Health Administration (OSHA) announces the seventh meeting of the Crane and Derrick Negotiated Rulemaking Advisory Committee (C-DAC). The Committee will review summary notes of the prior meeting, review draft regulatory text and continue to address substantive issues. The meeting will be open to the public.

DATES: The meetings will be on February 4th, 5th and 6th, 2004. The meetings will begin each day at 8:30 am. Individuals with disabilities wishing to attend should contact Luz Delacruz by telephone at 202-693-2020 or by fax at 202-693-1689 to obtain appropriate accommodations no later than Friday, January 23, 2003. The C-DAC meeting is expected to last two and a half days.

ADDRESSES: The February meeting will be held at the U.S. Department of Labor, 200 Constitution Avenue, NW., Washington, DC 20210 and will be in conference room N-3437 A, B, C.

Written comments to the Committee may be submitted in any of three ways: by mail, by fax, or by email. Please include "Docket No. S-030" on all submissions.

By mail, submit three (3) copies to: OSHA Docket Office, Docket No. S-030, U.S. Department of Labor, 200 Constitution Avenue, NW., Room N-2625, Washington, DC 20210, telephone (202) 693-2350. Note that receipt of comments submitted by mail may be delayed by several weeks.

By fax, written comments that are 10 pages or fewer may be transmitted to the OSHA Docket Office at fax number (202) 693-1648.

Electronically, comments may be submitted through OSHA's Webpage at <http://ecomments.osha.gov>. Please note that you may not attach materials such as studies or journal articles to your electronic comments. If you wish to include such materials, you must submit three copies to the OSHA Docket

Office at the address listed above. When submitting such materials to the OSHA Docket Office, clearly identify your electronic comments by name, date, subject, and Docket Number, so that we can attach the materials to your electronic comments.

FOR FURTHER INFORMATION CONTACT: Michael Buchet, Office of Construction Standards and Guidance, Occupational Safety and Health Administration, U.S. Department of Labor, Room N-3468, 200 Constitution Avenue, NW., Washington, DC 20210; Telephone: (202) 693-2345.

SUPPLEMENTARY INFORMATION:

I. Background

On July 16, 2002, OSHA published a notice of intent to establish a negotiated rulemaking committee, requesting comments and nominations for membership (Volume 67 of the **Federal Register**, page 46612). In subsequent notices the Department of Labor announced the establishment of the Committee (Volume 68 of the **Federal Register**, page 35172, June 12, 2003), requested comments on a list of proposed members (68 FR 9036, February 27, 2003), published a final membership list (68 FR 39877, July 3, 2003), and announced the first meeting, (68 FR 39880, July 3, 2003), which was held July 30–August 1, 2003. The Agency published notices announcing the subsequent meetings.

II. Agenda

The Committee will review draft materials prepared by the Agency on issues discussed at prior meetings and address additional issues. While the pace of the discussions at the C-DAC meetings varies, C-DAC anticipates discussing the following items at the February meeting:

1. Pile Driving Equipment (Scope)
2. Verification criteria for structural adequacy of crane components
3. Overhead and gantry cranes
4. Floating cranes/cranes on barges.

III. Anticipated Key Issues for Negotiation

OSHA anticipates that key issues to be addressed at future C-DAC meetings will include:

Being Discussed

1. Scope
2. Definitions
3. Assembly & Disassembly (including reeving/rigging)
4. Operation Procedures
5. Signals
6. Operator Qualifications, Training & Testing