

(vii) The avocados must be packed in clean, new boxes, or clean plastic reusable crates. The boxes or crates must be clearly marked with the identity of the grower, packinghouse, and exporter.

(viii) The boxes must be placed in a refrigerated truck or refrigerated container and remain in that truck or container while in transit through Mexico to the port of first arrival in the United States. Prior to leaving the packinghouse, avocados must be packed in insect-proof cartons, loaded in insect-proof containers, or covered with insect-proof mesh or plastic tarpaulin, for transit to the United States. These safeguards must be intact when the avocados arrive at the port of first arrival in the United States.

\* \* \* \* \*

(d) *Certification.* All consignments of avocados must be accompanied by a phytosanitary certificate issued by the Mexican NPPO with an additional declaration certifying that the conditions specified in this section have been met.

(e) *Pest detection.* (1) If any of the avocado seed pests *Heilipus lauri*, *Conotrachelus aguacatae*, *C. perseae*, or *Stenomoma catenifer* are discovered in a municipality during the semiannual pest surveys, orchard surveys, packinghouse inspections, or other monitoring or inspection activity in the municipality, the Mexican NPPO must immediately initiate an investigation and take measures to isolate and eradicate the pests. The Mexican NPPO must also provide APHIS with information regarding the circumstances of the infestation and the pest risk mitigation measures taken. The municipality in which the pests are discovered will lose its pest-free certification and avocado exports from that municipality will be suspended until APHIS and the Mexican NPPO agree that the pest eradication measures taken have been effective and that the pest risk within that municipality has been eliminated.

(2) If the Mexican NPPO discovers the stem weevil *Copturus aguacatae* in an orchard during an orchard survey or other monitoring or inspection activity in the orchard, the Mexican NPPO must provide APHIS with information regarding the circumstances of the infestation and the pest risk mitigation measures taken. The orchard in which the pest was found will lose its export certification immediately and avocado exports from that orchard will be suspended until APHIS and the Mexican NPPO agree that the pest eradication measures taken have been

effective and that the pest risk within that orchard has been eliminated.

(3) If the Mexican NPPO discovers the stem weevil *Copturus aguacatae* in fruit at a packinghouse, the Mexican NPPO must investigate the origin of the infested fruit and provide APHIS with information regarding the circumstances of the infestation and the pest risk mitigation measures taken. The orchard where the infested fruit originated will lose its export certification immediately and avocado exports from that orchard will be suspended until APHIS and the Mexican NPPO agree that the pest eradication measures taken have been effective and that the pest risk within that orchard has been eliminated.

(f) *Inspection.* The avocados are subject to inspection by an inspector at the port of first arrival. At the port of first arrival, an inspector will sample and cut avocados from each consignment to detect pest infestation.

\* \* \* \* \*

Done in Washington, DC, this 19th day of May, 2004.

**Bill Hawks,**

*Under Secretary for Marketing and Regulatory Programs.*

[FR Doc. 04-11709 Filed 5-21-04; 8:45 am]

**BILLING CODE 3410-34-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2003-CE-48-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc. Model DHC-3 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model DHC-3 airplanes modified with A. M. Luton's Supplemental Type Certificate (STC) number SA3777NM. This proposed AD would require you to inspect the wiring for the heating blankets on P<sub>3</sub> and P<sub>Y</sub> pneumatic lines and the push-to-test function lights to ensure that they are wired to the correct schematic; replace the circuit breaker switch as applicable; and replace the flight manual supplement currently in use with Revision G, dated March 28, 2001 (incorporates Revision I of Sheet I of Drawing 20075, "Electrical System

Schematic," dated October 10, 2000). This proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Canada. We are issuing this proposed AD to detect and correct wiring installed in accordance with an incorrect drawing, which shows the pneumatic heating blankets to the P<sub>3</sub> and P<sub>Y</sub> pneumatic lines wired in series with the indicator lights, rather than parallel. This can result in reduced current for the heating blankets and loss of pneumatic line heating, which can lead to loss of engine power or reverse propeller overspeed governing protection and ultimately loss of control of the airplane.

**DATES:** We must receive any comments on this proposed AD by July 15, 2004.

**ADDRESSES:** Use one of the following to submit comments on this proposed AD:

- *By mail:* FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-48-AD, 901 Locust, Room 506, Kansas City, Missouri 64106.
- *By fax:* (816) 329-3771.
- *By e-mail:* 9-ACE-7-Docket@faa.gov.

Comments sent electronically must contain "Docket No. 2003-CE-48-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII.

You may get the service information identified in this proposed AD from A. M. Luton, 3025 Eldridge Ave., Bellingham, WA 98225.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-48-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

#### FOR FURTHER INFORMATION CONTACT:

Richard Simonson, Aerospace Engineer, Special Certification Branch; telephone: 425-917-6507; facsimile: 425-917-6590.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

*How do I comment on this proposed AD?* We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-48-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it. We will date-

stamp your postcard and mail it back to you.

Are there any specific portions of this proposed AD I should pay attention to? We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. If you contact us through a nonwritten communication and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend this proposed AD in light of those comments and contacts.

Discussion

What events have caused this proposed AD? Transport Canada, which is the airworthiness authority for Canada, recently notified FAA that an unsafe condition may exist on all Bombardier, Inc. Model DHC-3 airplanes modified with an A. M. Luton Supplemental Type Certificate (STC) number SA3777NM. Transport Canada reports a drawing error on Revisions G and H of Sheet I of the Electrical System Schematic Drawing 20075, which shows the pneumatic heating blankets to the P<sub>3</sub> and P<sub>Y</sub> pneumatic lines wired in series with the indicator lights, rather than parallel. This can result in severely reduced electrical energy going to the heating blankets with loss of pneumatic line heating, which can lead to loss of engine power or reverse propeller overspeed governing protection.

What are the consequences if the condition is not corrected? Electrical installation using incorrect wiring configurations could result in the electrical energy being absorbed by the light bulbs with insufficient electrical energy for the heating blankets, which would allow ice to form in these lines due to condensation even though the indication lights show the lines being heated. This could result in loss of engine power or reverse propeller overspeed governing protection and lead to loss of control of the airplane.

Is there service information that applies to this subject? A. M. Luton has issued Service Information Letter SIL-00-10-10, Electrical Systems, dated March 22, 2001.

What are the provisions of this service information? The service letter includes procedures for:

—Replacing the flight manual supplement with Revision G, dated March 28, 2001. This flight manual revision corrects the drawing error on Revisions G and H of Sheet I of the Electrical System Schematic Drawing 20075, by incorporating Revision I of Sheet I of Drawing 20075, “Electrical System Schematic,” dated October 10, 2000;

—Inspecting the push-to-test indicator light for correct wiring; and

—Replacing the circuit breaker switch for the P<sub>3</sub> and P<sub>Y</sub> pneumatic heating lines, depending on whether the engine uses one or both heating lines.

What action did Transport Canada take? Transport Canada classified this service bulletin as mandatory and issued Canadian AD Number CF-2002-38, dated August 29, 2002, to ensure the continued airworthiness of these airplanes in Canada.

Did Transport Canada inform the United States per the bilateral airworthiness agreement? These Bombardier, Inc. DHC-3 airplanes are manufactured in Canada and are type-certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement.

Under this bilateral airworthiness agreement, Transport Canada has kept us informed of the situation described above.

FAA’s Determination and Requirements of This Proposed AD

What has FAA decided? We have examined Transport Canada’s findings, reviewed all available information, and determined that AD action is necessary for products of this type design that are

certificated for operation in the United States.

Since the unsafe condition described previously is likely to exist or develop on other Bombardier, Inc. DHC-3 airplanes of the same type design modified with A. M. Luton’s STC number SA3777NM and are registered in the United States, we are proposing AD action to detect and correct incorrect wiring configuration. This can result in the electrical energy being absorbed by the light bulbs with insufficient electrical energy for the heating blankets, which would allow ice to form in these lines due to condensation even though the indication lights show the lines being heated. This could result in loss of engine power or reverse propeller overspeed governing protection and lead to loss of control of the airplane.

What would this proposed AD require? This proposed AD would require you to incorporate the actions in the previously-referenced service information letter.

How does the revision to 14 CFR part 39 affect this proposed AD? On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA’s AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

How many airplanes would this proposed AD impact? We estimate that this proposed AD affects 32 airplanes in the U.S. registry.

What would be the cost impact of this proposed AD on owners/operators of the affected airplanes? We have no way of determining the number of airplanes that may need the proposed rewiring or circuit breaker switch replacement. We estimate the following costs to accomplish this proposed inspection:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
1 workhour est. \$65 per hour = \$65 .....	\$100	\$165	\$5,280

Regulatory Findings

Would this proposed AD impact various entities? We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on

the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

Would this proposed AD involve a significant rule or regulatory action? For

the reasons discussed above, I certify that this proposed AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposed AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-48-AD" in your request.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Bombardier, Inc.:** Docket No. 2003-CE-48-AD

#### When Is the Last Date I Can Submit Comments on This Proposed AD?

(a) We must receive comments on this proposed airworthiness directive (AD) by July 15, 2004.

#### What Other ADs Are Affected by This Action?

(b) None.

#### What Airplanes Are Affected by This AD?

(c) This AD affects the Model DHC-3 airplanes, all serial numbers, that are:

(1) Modified with STC number SA3777NM; and

(2) Certificated in any category.

#### What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of a drawing error on Revisions G and H of Sheet I of Drawing 20075, Electrical System Schematic. The actions specified in this AD are intended to detect and correct wiring installed according to an incorrect drawing, which shows the pneumatic heating blankets to the P<sub>3</sub> and P<sub>Y</sub> pneumatic lines wired in series with the indicator lights, rather than parallel. This can result in insufficient electrical energy for the heating blankets and loss of pneumatic heating, which can lead to loss of engine power or reverse propeller overspeed governing protection and ultimately loss of control of the airplane.

#### What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Action	Compliance	Procedures
(1) Inspect the electrical wiring to the P <sub>3</sub> and P <sub>Y</sub> engine pneumatic line heating blankets and the P <sub>3</sub> heater warning light to determine if they are wired in a parallel configuration. If they are not wired in a parallel configuration, they must be rewired.	Inspect within 4 months after the effective date of this AD or 300 hours time in service (TIS) after the effective date of this AD, whichever occurs first. Rewire prior to further flight after the inspection.	Follow the procedures in the A.M. Luton Service Information Letter SIL-00-10-10, revision dated, March 22, 2001.
(2) Replace Flight Manual Supplement currently in use with Revision G, dated March 28, 2001. This flight manual revision corrects the drawing error on Revisions G and H of Sheet I of the Electrical System Schematic Drawing 20075 by incorporating Revision I of Sheet I of Drawing 20075, "Electrical System Schematic," dated October 10, 2000. (i) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may accomplish the flight manual replacement requirement of this AD. (ii) Make an entry into the aircraft records showing compliance with this portion of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).	Replace within 4 months after the effective date of this AD or 300 hours TIS after the effective date of this AD, whichever occurs first.	Follow the procedures in the A.M. Luton Service Information Letter SIL-00-10-10, revision dated, March 22, 2001.
(3) Inspect circuit breaker switch for heated engine pneumatic lines circuit. If an engine is installed that uses both P <sub>3</sub> and P <sub>Y</sub> heated pneumatic lines, circuit breaker switch, Part Number (P/N) 20075-3 (5 amp), must be replaced with circuit breaker switch P/N 20075-59 (7.5 amp).	Inspect within 4 months after the effective date of this AD or 300 hours TIS after the effective date of this AD, whichever occurs first. Replace prior to further flight after the inspection.	Follow the procedures in the A.M. Luton Service Information Letter SIL-00-10-10, revision dated, March 22, 2001.

#### May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Special Certifications Branch,

Transport Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Richard Simonson, Aerospace Engineer, Special Certifications Branch, Transport Airplane Directorate, 1601 Lind Avenue, SW, Renton, WA 98055; telephone: 425-917-6507; facsimile: 816-917-6590.

#### May I Get Copies of the Documents Referenced in This AD?

(g) You may get copies of the documents referenced in this AD from A.M. Luton, 3025 Eldridge Ave., Bellingham, WA 98225. You may view these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

**Is There Other Information That Relates to This Subject?**

(h) Airworthiness Directive CF-2002-38, dated August 29, 2002, and Service Information Letter SIL-00-10-10, revision dated March 22, 2001, also pertain to the subject of this AD.

Issued in Kansas City, Missouri on May 18, 2004.

**James E. Jackson,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-11644 Filed 5-21-04; 8:45 am]

**BILLING CODE 4910-13-P**

**ENVIRONMENTAL PROTECTION AGENCY****40 CFR Part 52**

[PA208-4215b; FRL-7664-7]

**Approval and Promulgation of Air Quality Implementation Plans; Pennsylvania; VOC and NO<sub>x</sub> RACT Requirements for Two Individual Sources**

**AGENCY:** Environmental Protection Agency (EPA).

**ACTION:** Proposed rule.

**SUMMARY:** EPA proposes to approve revisions to the Commonwealth of Pennsylvania's State Implementation Plan (SIP). The revisions were submitted by the Pennsylvania Department of Environmental Protection (PADEP) to establish and require reasonably available control technology (RACT) for two major sources of volatile organic compounds (VOC) and nitrogen oxides (NO<sub>x</sub>) located in Pennsylvania. In the Final Rules section of this **Federal Register**, EPA is approving the Commonwealth's SIP revisions as a direct final rule without prior proposal because the Agency views this as a noncontroversial submittal and anticipates no adverse comments. The rationale for the approval is set forth in the direct final rule. If no adverse comments are received in response to this action, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed rule. EPA will not institute a second comment period. Any parties interested in commenting on this action should do so at this time.

**DATES:** Comments must be received in writing by June 23, 2004.

**ADDRESSES:** Submit your comments, identified by PA208-4215 by one of the following methods:

A. Federal eRulemaking Portal: <http://www.regulations.gov>. Follow the on-line instructions for submitting comments.

B. E-mail: [morris.makeba@epa.gov](mailto:morris.makeba@epa.gov)

C. Mail: Makeba Morris, Chief, Air Quality Planning Branch, Mailcode 3AP21, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103.

D. Hand Delivery: At the previously-listed EPA Region III address. Such deliveries are only accepted during the Docket's normal hours of operation, and special arrangements should be made for deliveries of boxed information.

**Instructions:** Direct your comments to Docket ID No. PA208-4215. EPA's policy is that all comments received will be included in the public docket without change, including any personal information provided, unless the comment includes information claimed to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Do not submit information that you consider to be CBI or otherwise protected through [regulations.gov](http://www.regulations.gov) or e-mail. The Federal [regulations.gov](http://www.regulations.gov) Web site is an "anonymous access" system, which means EPA will not know your identity or contact information unless you provide it in the body of your comment. If you send an e-mail comment directly to EPA without going through [regulations.gov](http://www.regulations.gov), your e-mail address will be automatically captured and included as part of the comment that is placed in the public docket and made available on the Internet. If you submit an electronic comment, EPA recommends that you include your name and other contact information in the body of your comment and with any disk or CD-ROM you submit. If EPA cannot read your comment due to technical difficulties and cannot contact you for clarification, EPA may not be able to consider your comment. Electronic files should avoid the use of special characters, any form of encryption, and be free of any defects or viruses. Copies of the documents relevant to this action are available for public inspection during normal business hours at the Air Protection Division, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103; and the Pennsylvania Department of Environmental Resources Bureau of Air Quality Control, P.O. Box 8468, 400 Market Street, Harrisburg, Pennsylvania 17105.

**FOR FURTHER INFORMATION CONTACT:**

Betty Harris at (215) 814-2168 or via e-mail at [harris.betty@epa.gov](mailto:harris.betty@epa.gov).

**SUPPLEMENTARY INFORMATION:** For further information, please see the information provided in the direct final action, with the same title, that is located in the "Rules and Regulations" section of this **Federal Register** publication. Please note that if EPA receives adverse comment on an amendment, paragraph, or section of this rule and if that provision may be severed from the remainder of the rule, EPA may adopt as final those provisions of the rule that are not the subject of an adverse comment.

Dated: May 13, 2004.

**Richard J. Kampf,**

*Acting Regional Administrator, Region III.*

[FR Doc. 04-11669 Filed 5-21-04; 8:45 am]

**BILLING CODE 6560-50-P**

**ENVIRONMENTAL PROTECTION AGENCY****40 CFR Part 52**

[II221-1b; FRL-7657-9]

**Approval and Promulgation of Implementation Plans; Illinois**

**AGENCY:** Environmental Protection Agency (EPA).

**ACTION:** Proposed rule.

**SUMMARY:** The EPA is approving a site-specific revision to the Illinois volatile organic compound (VOC) State Implementation Plan (SIP) for the Horween Leather Company (Horween) in Chicago, IL. By its submittal dated May 28, 2003, the Illinois Environmental Protection Agency (Illinois EPA) requested that EPA approve a site-specific rule that would change the VOC control requirements that would apply to a small amount of specialty leathers and allow them to be produced at Horween's leather production facility in Chicago. This request is approvable because it satisfies reasonably available control technology (RACT) and is a more suitable control measure for certain of its specialty leather coating operations than the existing rule which this amends. In the final rules section of this **Federal Register**, we are approving the SIP revision as a direct final rule without prior proposal, because we view this as a noncontroversial revision amendment and anticipate no adverse comments. A detailed rationale for the approval is set forth in the direct final rule. If no adverse comments are received in response to this proposed rule, no further activity is contemplated in relation to this proposed rule. If we receive adverse comments, the direct