

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1078; Directorate Identifier 2008-CE-051-AD]

RIN 2120-AA64

Airworthiness Directives; BURKHART GROB LUFT—UND RAUMFAHRT GmbH & CO KG G103 Series Gliders

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The Luftfahrt-Bundesamt received a report from the Grob Company that a bolt in the airbrake control was found failed during a pre-flight inspection on a G 103C TWIN III ACRO. During an extensive investigation (metallurgical investigation) a double sided fatigue crack was found as root cause. As the bolt is insignificantly stressed by cyclic bending the crack was probably caused by mean stress supported by a bolt torque exceeding the limit.

The actions specified by this airworthiness directive are intended to prevent further bolt cracking which can result in airbrake as well as elevator failure (elevator control is on the same pedestal) and reduced controllability of the power glider.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by November 10, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1078; Directorate Identifier 2008-CE-051-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the aviation authority for the Federal Republic of Germany, has issued AD D-2008-231, dated July 11, 2008; and AD D-2008-232, dated July 11, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

The Luftfahrt-Bundesamt received a report from the Grob Company that a bolt in the airbrake control was found failed during a pre-flight inspection on a G 103C TWIN III ACRO. During an extensive investigation (metallurgical investigation) a double sided fatigue crack was found as root cause. As the bolt is insignificantly stressed by cyclic bending the crack was probably caused by mean stress supported by a bolt torque exceeding the limit.

The actions specified by this airworthiness directive are intended to prevent further bolt cracking which can result in airbrake as well as elevator failure (elevator control is on the same pedestal) and reduced controllability of the power glider.

The MCAI requires:

- Replacement of bolt LN9037-M6x60 from the airbrake bell crank 103B-4437 with a new bolt and a new locking nut and tightening the bolt to a specific torque;
- Check of all parts of the airbrake bell crank and the attachment parts for any damage and replacement of any damaged parts;
- Check of the airbrake locking force of the left-hand and right-hand wing for a specific force value range and that the locking is clearly noticeable; and
- Check of the airbrake locking force at the operating lever in the front cockpit with the wings rigged for a specific force value range.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Grob Aerospace has issued Service Bulletin No. MSB 315-76/1 and 869-27/1 (same document), dated June 23, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA

policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

We estimate that this proposed AD will affect 129 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$15 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$12,255, or \$95 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with

this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Burkhart Grob Luft—Und Raumfahrt GmbH & CO KG: Docket No. FAA-2008-1078; Directorate Identifier 2008-CE-051-AD.

Comments Due Date

- (a) We must receive comments by November 10, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to the following models and serial numbers (SNs) gliders, certificated in any category:

- (1) G103 TWIN II, SNs 3730 through 3878;
- (2) G103A TWIN II ACRO, SNs 3730 through 34078 (K);
- (3) G103C TWIN III ACRO, SNs 34101 through 34203; and
- (4) G 103 C TWIN III SL, SNs 35001 through 35051

Subject

- (d) Air Transport Association of America (ATA) Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

The Luftfahrt-Bundesamt received a report from the Grob Company that a bolt in the airbrake control was found failed during a pre-flight inspection on a G 103C TWIN III ACRO. During an extensive investigation (metallurgical investigation) a double sided fatigue crack was found as root cause. As the bolt is insignificantly stressed by cyclic bending the crack was probably caused by mean stress supported by a bolt torque exceeding the limit. The actions specified by this airworthiness directive are intended to prevent further bolt cracking which can result in airbrake as well as elevator failure (elevator control is on the same pedestal) and reduced controllability of the power glider.

The MCAI requires replacement of bolt LN9037-M6x60 from the airbrake bell crank 103B-4437 with a new bolt with a new locking nut and tightening the bolt to a specific torque; check of all parts of the airbrake bell crank and the attachment parts

for any damage and replacement of any damaged parts; check of the airbrake locking force of the left-hand and right-hand wing for a specific force value range and that the locking is clearly noticeable; and check of the airbrake locking force at the operating lever in the front cockpit with the wings rigged for a specific force value range.

Actions and Compliance

(f) Unless already done, within 60 days after the effective date of this AD, do the following actions following Grob Aerospace Service Bulletin No. MSB 315-76/1 and No. 869-27/1 (same document), dated June 23, 2008:

(1) Remove bolt LN9037-M6x60 from the airbrake bell crank 103B-4437 and install a new bolt LN9037-M6x60 with the new locking nut LN9348-M6 and torque the bolt to 6.4 Nm (4.7 lbs.ft).

(2) Inspect all parts of the airbrake bell crank including the attachment parts for any damage and, before further flight, replace any damaged parts.

(3) Inspect the airbrake locking force of the left-hand (LH) and right-hand (RH) wing using a spring balance. The force must be equal for the LH and RH wing (guidance value: 10±2 daN, (22.5±4.5 lbs)) and the locking must be clearly noticeable.

(4) Inspect the airbrake locking force at the operating lever in the front cockpit with the wings rigged. The guidance value is 10±2 daN, (22.5±4.5 lbs). It must not exceed 15-20 daN (33.7-45.0 lbs).

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Federal Republic of Germany Luftfahrt-Bundesamt AD D-2008-231, dated July 11, 2008; and AD D-2008-232, dated July 11, 2008; and Grob Aerospace Service Bulletin No. MSB 315-76/1 and No. 869-27/1 (same document), dated June 23, 2008, for related information.

Issued in Kansas City, Missouri, on October 2, 2008.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-23973 Filed 10-8-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-1081; Directorate Identifier 2008-NM-143-AD]

RIN 2120-AA64

Airworthiness Directives; ATR Model ATR72 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Incomplete accomplishment instructions in SB [service bulletin] ATR72-27-1059 original issue and Revision 1, failed to mention installation of cotter pins to secure the self locking nuts after re-installation of the modified Pitch Uncoupling Mechanism (PUM), when connecting the elevator control linkage rods to the PUM input levers and the PUM output rods to the elevator bellcranks (on both sides).

Because of the non-installation of these four cotter pins, the fail-safe criteria of the design requirements on the pitch control are no longer met. Such a failure could cause the loss of one self locking nut and would result in the loss of pitch control on one side—Captain or First Officer—or the loss of control of one elevator surface. The symmetrical loss of two concerned self-locking nuts could lead to a complete loss of the pitch control.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by November 10, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2008-1081; Directorate Identifier 2008-NM-143-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Emergency Airworthiness Directive 2008-0137-E, dated July 23, 2008 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Incomplete accomplishment instructions in SB [service bulletin] ATR72-27-1059 original issue and Revision 1, failed to mention installation of cotter pins to secure the self locking nuts after re-installation of the modified Pitch Uncoupling Mechanism (PUM), when connecting the elevator control linkage rods to the PUM input levers and the PUM output rods to the elevator bellcranks (on both sides).

Because of the non-installation of these four cotter pins, the fail-safe criteria of the design requirements on the pitch control are no longer met. Such a failure could cause the loss of one self locking nut and would result in the loss of pitch control on one side—Captain or First Officer—or the loss of control of one elevator surface. The symmetrical loss of two concerned self-locking nuts could lead to a complete loss of the pitch control.

For the reasons stated above, this AD requires you to check [for] the presence of the four cotter pins and [perform] their installation if they are found to be missing.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

ATR has issued Avions de Transport Regional Service Bulletin ATR72-27-1059, Revision 02, dated May 19, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But