

or cracking of the lugs of the forward end clevis of the flap tracks that support the wing trailing edge flaps, according to Part 1 of the Work Instructions in Boeing Service Bulletin 747-57-2307, Revision 1, dated January 17, 2002.

(1) For airplanes inspected before the effective date of this AD according to paragraph (a) of this AD: Do the inspection in paragraph (e) of this AD at the time specified in paragraph (e)(1)(i) or (e)(1)(ii) of this AD, as applicable. Doing this inspection terminates the requirements of paragraph (c) of this AD.

(i) For airplanes listed in Group 1 of Boeing Service Bulletin 747-57-2231, Revision 2: Inspect within 300 flight cycles after the most recent inspection per paragraph (a) or (c) of this AD.

(ii) For airplanes listed in Group 2 or 3 of Boeing Service Bulletin 747-57-2231, Revision 2: Inspect within 1,200 flight cycles after the most recent inspection per paragraph (a) or (c) of this AD.

(2) For airplanes not inspected before the effective date of this AD according to paragraph (a) of this AD: Do the inspection in paragraph (e) of this AD at the time specified in paragraph (e)(2)(i) or (e)(2)(ii) of this AD, whichever occurs later. This terminates the requirement to do paragraph (a) of this AD.

(i) Within 8 years after the earlier of the date of issuance of the original Airworthiness Certificate or the date of issuance of the Export Certificate of Airworthiness, or before the accumulation of 30,000 total flight hours, whichever occurs first.

(ii) Within 300 flight cycles or 120 days after the effective date of this AD, whichever occurs first.

#### *Repetitive Inspections*

(f) If no evidence of migration or rotation of the bushings or cracking of the lugs is found during the inspection required by paragraph (e) of this AD: Repeat the inspections at the applicable repetitive interval specified in Figure 1 of Boeing Service Bulletin 747-57-2307, Revision 1, dated January 17, 2002, until the terminating modification of paragraph (d) or (i) of this AD has been done.

#### *Corrective Actions and Repetitive Inspections*

(g) If evidence of migration or rotation of the bushings is found during any inspection required by paragraph (e) or (f) of this AD, but no cracking is found: Do paragraph (g)(1) or (g)(2) of this AD, as applicable, according to Boeing Service Bulletin 747-57-2307, Revision 1, dated January 17, 2002.

(1) For airplanes listed in Group 1 in the service bulletin and flap track numbers 3 and 6 on airplanes listed in Group 2 of the service bulletin: Before further flight, do the terminating modification in paragraph (i) of this AD, as specified in paragraph (i)(2) of this AD.

(2) For airplanes other than those identified in paragraph (g)(1) of this AD: Before further flight, apply corrosion-inhibiting compound according to the service bulletin, and do paragraphs (g)(2)(i) and (g)(2)(ii) of this AD at the intervals specified in those paragraphs, until paragraph (d) or (i)

of this AD is done. Do paragraph (i) of this AD at the applicable time specified in paragraph (i)(2) of this AD.

(i) Repeat the inspections in paragraph (e) of this AD at the intervals specified in Figure 1 of the service bulletin.

(ii) Apply corrosion-inhibiting compound according to the service bulletin at intervals not to exceed 200 flight cycles.

#### *Replacement of Flap Track*

(h) If any cracking is found during any inspection required by paragraph (d), (e), (f), (g)(2)(i), (i), or (j) of this AD: Before further flight, replace the cracked flap track with a new flap track, according to Boeing Service Bulletin 747-57-2307, Revision 1, dated January 17, 2002. Replacement with a new flap track having a part number listed in the "New Part Number" column of the table under paragraph 2.E. of the service bulletin constitutes terminating action for the requirements of this AD for the replaced track.

#### *Terminating Modification*

(i) At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD: Do all actions (including but not limited to machining, performing magnetic particle inspections, and applying cadmium plating to the clevis bore and bushing) associated with replacing the bushings of the forward end clevis with new bushings with a higher interference fit on flap tracks 1, 2, 3, 4, 5, 6, 7, and 8; as applicable; according to Boeing Service Bulletin 747-57-2307, Revision 1, dated January 17, 2002. This replacement terminates the requirements of this AD.

(1) If no evidence of migration or rotation of the bushings or cracking of the lugs is found during any inspection required by paragraph (e) or (f) of this AD: Do the replacement within 8 years after the effective date of this AD.

(2) If any evidence of bushing migration or rotation is found during any inspection required by paragraph (e) or (f) of this AD: Do the replacement at the applicable time specified in Figure 1 of the service bulletin.

#### *Credit for Actions According to Previous Revision of Service Bulletin*

(j) Inspections, corrective actions, and terminating action done before the effective date of this AD according to Boeing Service Bulletin 747-57-2307, dated July 29, 1999, are considered acceptable for compliance with the corresponding action specified in this AD.

#### *Alternative Methods of Compliance*

(k)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously according to AD 90-24-09, amendment 39-6815, are approved as alternative methods of compliance with paragraphs (a), (b), (c), and (d) of this AD.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### *Special Flight Permits*

(l) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### *Incorporation by Reference*

(m) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Service Bulletin 747-57-2231, Revision 2, dated September 27, 1990; and Boeing Service Bulletin 747-57-2307, Revision 1, dated January 17, 2002; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### **Effective Date**

(n) This amendment becomes effective on August 25, 2003.

Issued in Renton, Washington, on July 8, 2003.

**Ali Bahrami,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 03-17772 Filed 7-18-03; 8:45 am]

**BILLING CODE 4910-13-P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. 2000-NM-326-AD; Amendment 39-13235; AD 2003-14-16]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Lockheed Model 382G Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Lockheed Model 382G series airplanes, that requires repetitive general visual inspections of certain bearings located in the emergency exit door for evidence of excessive wear; and repair of certain bearings, which would terminate the repetitive inspections. This action is necessary to prevent failure of the latch

mechanism, which could result in the inability to open the emergency exit door in an emergency. This action is intended to address the identified unsafe condition.

**DATES:** Effective August 25, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 25, 2003.

**ADDRESSES:** The service information referenced in this AD may be obtained from Lockheed Martin Corporation/ Lockheed Martin Aeronautics Company, Airworthiness Office, Dept. 6A0M, Zone 0252, Column P-58, 86 S. Cobb Drive, Marietta, Georgia 30063. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** William Herderich, Aerospace Engineer, Airframe and Propulsion Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6082; fax (770) 703-6097.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Lockheed Model 382G series airplanes was published in the **Federal Register** on April 29, 2003 (68 FR 22644). That action proposed to require repetitive general visual inspections of certain bearings located in the emergency exit door for evidence of excessive wear; and repair of certain bearings, which would terminate the repetitive inspections.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

#### Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### Changes to 14 CFR Part 39/Effect on the AD

On July 10, 2002, the FAA issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's airworthiness directives system. The regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. However, for clarity and consistency in this final rule, we have retained the language of the NPRM regarding that material.

#### Change in Labor Rate

After the proposed AD was issued, we reviewed the figures we use to calculate the labor rate to do the required actions. To account for various inflationary costs in the airline industry, we find it appropriate to increase the labor rate used in these calculations from \$60 per work hour to \$65 per work hour. The economic impact information, below, has been revised to reflect this increase in the specified hourly labor rate.

#### Cost Impact

There are approximately 10 airplanes of the affected design in the worldwide fleet. The FAA estimates that 1 airplane of U.S. registry will be affected by this AD, that it will take approximately 16 work hours per airplane to accomplish the required actions, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the AD on the single U.S. operator is estimated to be \$1,040.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

#### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a

“significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

**2003-14-16 Lockheed:** Amendment 39-13235. Docket 2000-NM-326-AD.

**Applicability:** Model 382G series airplanes, as listed in Hercules Service Bulletin 382-52-9, dated July 5, 2000; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the latch mechanism located inside the emergency exit door, which could result in the inability to open the door in an emergency, accomplish the following:

### Inspection

(a) Within 30 days after the effective date of this AD: Perform a general visual inspection of bearings having part numbers (P/N) 3326653-1 and 3326653-2 for evidence of a groove greater than 0.060 inch deep. Perform the inspection per paragraph 2.A. of the Accomplishment Instructions specified in Hercules Service Bulletin 382-52-9, dated July 5, 2000.

**Note 2:** For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(1) If evidence of a groove greater than 0.060-inch deep is not found: Repeat the inspection at 30-day intervals until accomplishment of the terminating action required by paragraph (b) of this AD.

(2) If evidence of a groove greater than 0.060-inch deep is found: Before further flight, repair the bearings per paragraph (b) of this AD.

### Repair

(b) Within 90 days after the effective date of this AD: Repair bearings having P/N 3326653-1 and P/N 3326653-2 per paragraph 2.B. of the Accomplishment Instructions specified in Hercules Service Bulletin 382-52-9, dated July 5, 2000. Accomplishment of this repair terminates the requirements of paragraph (a) of this AD.

### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

### Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

### Incorporation by Reference

(e) The actions shall be done in accordance with Hercules Service Bulletin 382-52-9, dated July 5, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C.

552(a) and 1 CFR part 51. Copies may be obtained from Lockheed Martin Corporation/Lockheed Martin Aeronautics Company, Airworthiness Office, Dept. 6A0M, Zone 0252, Column P-58, 86 S. Cobb Drive, Marietta, Georgia 30063. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

### Effective Date

(f) This amendment becomes effective on August 25, 2003.

Issued in Renton, Washington, on July 8, 2003.

### Ali Bahrami,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 03-17771 Filed 7-18-03; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2002-SW-39-AD; Amendment 39-13237; AD 2003-14-18]

RIN 2120-AA64

### Airworthiness Directives; Sikorsky Aircraft Corporation Model S76A, B, and C Helicopters

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) for the specified Sikorsky Aircraft Corporation (Sikorsky) model helicopters that requires removing non-conforming main landing gear brake discs (discs) and replacing them with different part-numbered airworthy discs. It also requires revising the Rotorcraft Flight Manual (RFM) to adjust takeoff and landing distances until the discs are replaced. This amendment is prompted by the manufacture of some discs using inferior materials. The actions specified by this AD are intended to prevent reduced braking performance and subsequent loss of control of the helicopter.

**DATES:** Effective August 25, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 25, 2003.

**ADDRESSES:** The service information referenced in this AD may be obtained

from Sikorsky Aircraft Corporation, Attn: Manager, Commercial Tech Support, 6900 Main Street, Stratford, Connecticut 06614, phone (203) 386-3001, fax (203) 386-5983. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

### FOR FURTHER INFORMATION CONTACT:

Terry Fahr, Aviation Safety Engineer, Boston Aircraft Certification Office, 12 New England Executive Park, Burlington, MA 01803, telephone (781) 238-7155, fax (781) 238-7199.

### SUPPLEMENTARY INFORMATION: A

proposal to amend 14 CFR part 39 to include an AD for Sikorsky Model S76A, B, and C helicopters was published in the **Federal Register** on February 7, 2003 (68 FR 6382). That action proposed to require, within 60 days, determining if discs, part number (P/N) 5014067, are installed. If so, replacing them with discs, P/N 5007672, and re-identifying brake assembly, P/N 5007555 and P/N 5007555-1, as brake assembly P/N 5007555-3, and brake assembly, P/N 5007555-2, as brake assembly, P/N 5007555-4, was proposed to be required within 90 days. The action also proposed to require revising the RFM to adjust the Category A rejected takeoff distance, the Category A landing distance, and the Category B landing distance by multiplying the distance by 1.67 to obtain the corrected distance until the discs are replaced.

Sikorsky has issued Alert Service Bulletin (ASB) No. 76-32-27, dated April 30, 2002, which contains Aircraft Braking Systems Corporation ASB S76-32-A24, dated April 10, 2002; and Sikorsky Aircraft Corporation ASB No. 76-32-28, dated May 17, 2002, which contains Aircraft Braking Systems Corporation ASB S76-32-A25, dated May 15, 2002. The ASBs describe procedures for replacing any non-conforming discs, reidentifying brake assemblies, and revising takeoff and landing distances in the RFM until the discs are replaced.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comment received.

The one commenter, the manufacturer, states that the AD should state that a manufacturer's warranty exists. The commenter states that the service information issued by Aircraft Braking Systems Corporation states that the replacement discs, P/N 5007672, are