

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) For all helicopters, except Model A109S having S/N 22705 or S/N 22706 and Model AW109SP having S/N 22384, before further flight:

(i) Install a placard with the information in Figure 5 of Leonardo Helicopters Emergency Alert Service Bulletin (EASB) No. 109S-079 (EASB 109S-079), or Leonardo Helicopters EASB No. 109SP-120 (EASB 109SP-120), each Revision A, and each dated June 4, 2018, as applicable to your helicopter model, in the baggage compartment on the internal side of the baggage door D8.

(ii) Revise the existing Rotorcraft Flight Manual (RFM) for your helicopter by cutting along the dashed line of Figure 6 of EASB 109S-079 or EASB 109SP-120, as applicable to your model helicopter, and inserting the cutout to replace page 1-28 or 1-3, as applicable to your model helicopter, of the existing RFM for your helicopter.

(2) For all helicopters, except Model A109S having S/N 22705 or S/N 22706 and Model AW109SP having S/N 22384, within 5 hours time-in-service (TIS):

(i) Visually inspect the installation of the terminal lugs to determine whether the installation is consistent with Figure 2 of EASB 109SP-120 or EASB 109S-079, as applicable to your model helicopter. If the installation is not consistent with Figure 2 of EASB 109SP-120 or EASB 109S-079, as applicable to your model helicopter, restore the installation to be consistent with Figure 2 of EASB 109SP-120 or EASB 109S-079, as applicable to your model helicopter.

(ii) Shim the installation of the baggage fairing assembly (fwd up) part number (P/N) 109-0344-31-101 to move it away from the circuit breaker panel, and install a silicon rubber protection over the blind rivets of the hinge in accordance with the Accomplishment Instructions, Part II, steps 3 through 8 of EASB 109S-079 or EASB 109SP-120, as applicable to your model helicopter.

(3) Performing the steps as described in paragraph (e)(2) of this AD allows the RFM revision described in paragraph (e)(1) of this AD to be removed from the existing RFM for your helicopter and the placard described in paragraph (e)(1) of this AD to be removed from the helicopter.

(4) For all helicopters, within 10 hours TIS and thereafter at intervals not to exceed 25 hours TIS, remove the baggage fairing assembly (fwd up) P/N 109-0344-31-101, remove the rubber protections P/N 109-0746-52-105 and P/N 109-0746-52-107, and inspect the cable assemblies routing of both circuit breaker panels for damage. For the purposes of this inspection, damage may be indicated by chafing. If there is any damage, repair or replace the cables in accordance with FAA accepted procedures and protect the cables by installing Nomex sleeve P/N EN6049-006.

(5) For all helicopters, within 200 hours TIS, modify the helicopter's baggage

compartment by adding the protective coverings in accordance with the Accomplishment Instructions, Part II, steps 3 through 14 of Leonardo Helicopters EASB No. 109SP-122, dated July 5, 2018, or Leonardo Helicopters EASB No. 109S-081, dated July 5, 2018, as applicable to your model helicopter. Completion of this modification is a terminating action for the 25 hour TIS repetitive inspections of paragraph (e)(4) of this AD.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of: Kristin Bradley, Aerospace Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD No. 2018-0149-E, dated July 13, 2018. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2020-1139.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 5397, Fuselage Wiring, Baggage Fairings Modification.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Leonardo Helicopters Emergency Alert Service Bulletin (EASB) No. 109S-079, Revision A, dated June 4, 2018.

(ii) Leonardo Helicopters EASB 109SP-120, Revision A, dated June 4, 2018.

(iii) Leonardo Helicopters EASB No. 109SP-122, dated July 5, 2018.

(iv) Leonardo Helicopters EASB No. 109S-081, dated July 5, 2018.

(3) For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>.

(4) You may view this service information at the FAA, Office of the Regional Counsel,

Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 17, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-05147 Filed 3-11-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2020-1132; Project Identifier MCAI-2020-01386-R; Amendment 39-21452; AD 2021-05-09]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2018-15-02, which applied to certain Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters. AD 2018-15-02 required repetitively inspecting the tail rotor (TR) pitch rod for a damaged elastomeric ball joint, and corrective action if necessary. This AD continues to require the repetitive inspections and allows the repetitive inspection interval to be extended under certain conditions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. This AD was prompted by a report of several cases of damaged TR pitch rod ball joints. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 16, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 16, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3,

50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1132.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1132; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Katherine Venegas, Aviation Safety Engineer, Cabin Safety, Mechanical and Environmental Systems Section, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5353; fax: 562-627-5210; email: Katherine.Venegas@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the

European Union, has issued EASA AD 2017-0020R1, dated May 22, 2019 (EASA AD 2017-0020R1) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Airbus Helicopters Model AS350B, AS350BA, AS350BB, AS350B1, AS350B2, AS350B3, AS355E, AS355F, AS355F1, AS355F2, AS355N and AS355NP helicopters. Model AS350BB helicopters are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those helicopters in the applicability.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2018-15-02, Amendment 39-19334 (83 FR 34029, July 19, 2018) (AD 2018-15-02). AD 2018-15-02 applied to certain Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters. The NPRM published in the **Federal Register** on December 16, 2020 (85 FR 81427). The NPRM was prompted by a report of several cases of damaged TR pitch rod ball joints. The NPRM proposed to continue to require the repetitive inspections of the TR pitch rod for a damaged elastomeric ball joint, as specified in an EASA AD. The NPRM also proposed to allow the repetitive inspection intervals specified in AD 2018-15-02 to be extended to correspond with the intervals for the inspection of the TR pitch rod specified in the airworthiness limitation section of the applicable helicopter maintenance manual, as specified in an EASA AD. The FAA is issuing this AD to address damage to the elastomeric ball joint on the TR pitch change rod.

This condition could result in failure of the TR pitch change rod and subsequent loss of control of the helicopter.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2017-0020R1 describes procedures for repetitively inspecting the TR pitch rod for a damaged (debonding, extrusion, or cracking) elastomeric ball joint and corrective action. The corrective action includes replacing an affected TR pitch rod with a serviceable TR pitch rod. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 955 helicopters of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2018-15-02	0.5 work-hour × \$85 per hour = \$42.50	\$0	\$42.50	\$40,587.50

This new AD adds no new costs to affected operators.

The FAA estimates the following costs to do any necessary on-condition

actions that would be required based on the results of any required actions. The FAA has no way of determining the

number of helicopters that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
1 work-hour × \$85 per hour = \$85	\$3,358	\$3,443

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:

- a. removing Airworthiness Directive (AD) 2018–15–02, Amendment 39–19334 (83 FR 34029, July 19, 2018); and
- b. adding the following new AD:

2021–05–09 Airbus Helicopters:

Amendment 39–21452; Docket No. FAA–2020–1132; Project Identifier MCAI–2020–01386–R.

(a) Effective Date

This airworthiness directive (AD) is effective April 16, 2021.

(b) Affected ADs

This AD replaces AD 2018–15–02, Amendment 39–19334 (83 FR 34029, July 19, 2018) (AD 2018–15–02).

(c) Applicability

This AD applies to Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2017–0020R1, dated May 22, 2019 (EASA AD 2017–0020R1).

(d) Subject

Joint Aircraft System Component (JASC) Code 6720, Tail Rotor Control System.

(e) Reason

This AD was prompted by a report of several cases of damaged tail rotor (TR) pitch rod ball joints. The FAA is issuing this AD to address damage to the elastomeric ball joint on the TR pitch change rod. This condition could result in failure of the TR pitch change rod and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) New Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2017–0020R1.

(h) Exceptions to EASA AD 2017–0020R1

(1) Where EASA AD 2017–0020R1 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2017–0020R1 refers to February 9, 2017 (the effective date of EASA AD 2017–0020–E, dated February 9, 2017), this AD requires using August 3, 2018 (the effective date of AD 2018–15–02).

(3) The "Remarks" section of EASA AD 2017–0020R1 does not apply to this AD.

(4) Although the service information referenced in EASA AD 2017–0020R1 specifies to discard certain parts, this AD does not include that requirement.

(5) Where EASA AD 2017–0020R1 refers to flight hours (FH), this AD requires using hours time-in-service (TIS).

(6) Where paragraph (1) of EASA AD 2017–0020R1 specifies an initial compliance time of "Before exceeding 50 FH [flight hours] since the last inspection per ALS [airworthiness limitations] chapter 04–20–00,

or within 10 FH or 7 days, whichever occurs first," for this AD, the initial compliance time is within 10 hours TIS.

(7) For the inspections specified in paragraph (1) of EASA AD 2017–0020R1: Accomplishing the actions specified in paragraphs (h)(7)(i) and (ii) of this AD before the effective date of this AD are acceptable for compliance with the inspections specified in paragraph (1) of EASA AD 2017–0020R1. On or after the effective date of this AD, comply with the inspections as specified in paragraph (1) of EASA AD 2017–0020R1.

(i) Manually induce a flapping movement in the TR blade until the pitch change rod rotates a minimum of 10 degrees.

(ii) Inspect both faces of the blade side of the ball joint elastomer for debonding, extrusion, and cracks.

(8) Although the service information referenced in EASA AD 2017–0020R1 permits certain actions to be performed by a mechanical engineering technician or pilot, this AD requires that the actions be performed by a qualified mechanic.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Katherine Venegas, Aviation Safety Engineer, Cabin Safety, Mechanical and Environmental Systems Section, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5353; fax: 562–627–5210; email: Katherine.Venegas@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2017–0020R1, dated May 22, 2019.

(ii) [Reserved]

(3) For EASA AD 2017–0020R1, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1132.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 19, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-05145 Filed 3-11-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2020-0664; Airspace Docket No. 20-ACE-15]

RIN 2120-AA66

Revocation and Amendment of Class E Airspace; Orange City and Le Mars, IA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action removes the Class E airspace extending upward from 700 feet above the surface at Orange City Municipal Airport, Orange City, IA and amends the Class E airspace extending upward from 700 feet above the surface at the Le Mars Municipal Airport, Le Mars, IA. This action is the result of an airspace review caused by the decommissioning of Orange City (ORC) non-directional beacon (NDB), and the Automated Weather Observing System (AWOS) navigation aids, and the closure of the Orange City Municipal Airport. Additionally, the geographical coordinates for the Le Mars Municipal Airport, Le Mars, IA, have been updated to coincide with the FAA's aeronautical database.

DATES: Effective 0901 UTC, June 17, 2021. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11E, Airspace Designations and Reporting

Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email: fedreg.legal@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT:

Rebecca Shelby, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5857.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it revokes the Class E airspace extending upward from 700 feet above the surface at Orange City Municipal, Orange City, IA and amends the Class E airspace at Le Mars Municipal Airport, Le Mars, IA, to support instrument flight rule operations at this airport.

History

The FAA published a notice of proposed rulemaking in the **Federal Register** (85 FR 62269; October 2, 2020) for Docket No. FAA-2020-0664 to remove the Class E airspace extending upward from 700 feet above the surface at Orange City Municipal Airport, Orange City, IA, and amend the Class E airspace extending upward from 700 feet above the surface at Le Mars Municipal Airport, Le Mars, IA. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. One comment received supporting the proposed action. No response is provided.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.11E, dated July 21, 2020, and effective September 15, 2020, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11E, Airspace Designations and Reporting Points, dated July 21, 2020, and effective September 15, 2020. FAA Order 7400.11E is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11E lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This amendment to 14 CFR part 71 revokes the Class E airspace extending upward from 700 feet above the surface at Orange City Municipal Airport, Orange City, IA, as the instrument procedures at this airport have been cancelled and the airport closed, so the airspace is no longer required.

Amends the Class E airspace extending upward from 700 feet above the surface to within 6.4-mile (decreased from 7.5-mile) radius of Le Mars Municipal Airport, Le Mars, IA and removes the Orange City Municipal Airport; exclusionary language from the Le Mars Municipal Airport, Le Mars, IA, airspace legal description; and updates the geographic coordinates of the airport to coincide with the FAA's aeronautical database.

This action is due to an airspace review caused by the decommissioning of the Orange City NDB, and the Automated Weather Observing System (AWOS) navigation aids which provided navigational information to the instrument procedures at this airport.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT