

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2022-0602; Project Identifier MCAI-2020-01211-A; Amendment 39-22143; AD 2022-17-05]

RIN 2120-AA64

**Airworthiness Directives; Viking Air Limited (Type Certificate Previously Held by Bombardier Inc. and de Havilland Inc.) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2002-14-28, which applied to all de Havilland Inc. (type certificate currently held by Viking Air Limited) Model DHC-2 Mk. I, DHC-2 Mk. II, and DHC-2 Mk. III airplanes. AD 2002-14-28 established a life limit for the front fuselage struts and required repetitively replacing the front fuselage struts every 15 years or repetitively inspecting the struts for corrosion or fatigue damage and replacing when the damage exceeded a certain level. Since the FAA issued AD 2002-14-28, Transport Canada superseded its mandatory continuing airworthiness information (MCAI) to correct this unsafe condition on these products. This AD requires either doing recurring visual inspections, borescope inspections, and non-destructive inspections (NDIs) of the struts and airframe lugs with corrective action as necessary or replacing the struts every 15 years and doing recurring NDIs of the airframe lugs with corrective action as necessary. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective September 30, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of September 30, 2022.

**ADDRESSES:** For service information identified in this final rule, contact Viking Air Limited Technical Support, 1959 de Havilland Way, Sidney, British Columbia, Canada, V8L 5V5; phone: (800) 663-8444; fax: (250) 656-0673; email: [technical.support@vikingair.com](mailto:technical.support@vikingair.com); website: [www.vikingair.com/support/service-bulletins](http://www.vikingair.com/support/service-bulletins). You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the

FAA, call (817) 222-5110. It is also available at [www.regulations.gov](http://www.regulations.gov) under Docket No. FAA-2022-0602.

**Examining the AD Docket**

You may examine the AD docket at [www.regulations.gov](http://www.regulations.gov) under Docket No. FAA-2022-0602; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Aziz Ahmed, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7329; email: [aziz.ahmed@faa.gov](mailto:aziz.ahmed@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2002-14-28, Amendment 39-12828 (67 FR 47684, July 22, 2002) (AD 2002-14-28). AD 2002-14-28 applied to all de Havilland Inc. (type certificate currently held by Viking Air Limited) Model DHC-2 Mk. I, DHC-2 Mk. II, and DHC-2 Mk. III airplanes. AD 2002-14-28 established a life limit for the front fuselage struts and required repetitively replacing the front fuselage struts every 15 years or repetitively inspecting the struts for corrosion or fatigue damage and replacing when the damage exceeded a certain level. The FAA issued AD 2002-14-28 to prevent structural failure of the front fuselage caused by corrosion or fatigue damage to the struts that develops over time, which could result in reduced or loss of airplane control.

The NPRM published in the **Federal Register** on June 7, 2022 (87 FR 34591). The NPRM was prompted by AD CF-2020-22, dated June 5, 2020 (referred to after this as “the MCAI”), issued by Transport Canada, which is the aviation authority for Canada, which superseded its prior AD on this unsafe condition, AD CF-98-37R1, dated August 20, 1999. Transport Canada issued the MCAI to introduce a revised inspection schedule for the front fuselage struts from previously published schedules to alleviate the burden of mandatory replacement every 15 years or ultrasonic inspections every 5 years. The MCAI states:

Operators have reported incidents of corrosion of the DHC-2 front fuselage struts which are installed on each side of the flight compartment windshield. Deterioration of the airframe lugs to which the struts are attached has also been reported. The actions specified by this [Transport Canada] AD are intended to prevent structural failure of the front fuselage caused by damage to the fuselage struts and airframe lugs that develops over time, which could result in the loss of airframe structural integrity.

AD CF-98-37 issued 29 September 1998 mandated a 15-year life limit on the strut. It also prohibited installation of part numbers (P/Ns) C2FS209 and C2FS210.

Revision 1, CF-98-37R1, introduced repetitive inspection as an alternative to replacement of the strut. Detailed visual inspection was required to begin within 12 months from the effective date of the [Transport Canada] AD and be repeated every 12 months regardless of the age of the strut. Ultrasonic thickness measurements were required to begin within 24 months from the effective date of the [Transport Canada] AD and be repeated every 5 years regardless of the age of the strut.

After AD CF-98-37R1 was issued, it was determined that the repetitive inspections are not required to be started until the strut has accumulated 15 years since installation. As a result, Transport Canada (TC) approved several AMOCs [alternative methods of compliance] to authorize starting the inspections at that time.

Since the issuance of AD CF-98-37R1, TC has received several Service Difficulty Reports (SDRs) indicating that the corrective actions of that [Transport Canada] AD have not been effective at controlling damage of the fuselage struts to an acceptable level.

Viking Air Ltd. (Viking) has determined that a modified program of recurring visual inspection, borescope inspection and non-destructive inspection (NDI) of the struts and airframe lugs would be more effective than the existing inspection program. This program modifies affected parts by introducing a hole to permit a borescope inspection if that hole does not already exist in the parts.

To implement the modified inspection program, Viking has published Service Bulletin (SB) V2/0010 and Technical Bulletin (TB) V2/00002 that provide specific instructions for performing the modification, inspections and measurements required by this [Transport Canada] AD. The SB and TB also define the follow-on actions associated with those inspections and measurements.

Viking has also developed a version of the front fuselage strut with improved resistance to corrosion and with provisions for borescope inspection. The improved struts have been assigned P/Ns C2FS3281A-9 (left strut) and C2FS3282A-9 (right strut).

The corrective actions of this [Transport Canada] AD differ from those of AD CF-98-37R1 in the following ways:

- AD CF-98-37R1 included the details for all of the corrective actions, it did not require reference to other documents. For this [Transport Canada] AD, the details of the corrective actions are now specified in a SB and a TB.

- AD CF-98-37R1 required repetitive detailed visual inspection (DVI) of the airframe lugs. This [Transport Canada] AD requires repetitive DVI and NDI of the airframe lugs.
- AD CF-98-37R1 only permitted installation of P/Ns C2FS3281A and C2FS3282A. This [Transport Canada] AD permits installation of those parts, the superseding Viking P/Ns, parts installed by TC-issued or -accepted Supplemental Type Certificate (STC) or Part Manufacturing Approval (PMA) and Part Design Approval (PDA) parts that are approved for installation in DHC-2 as replacements for P/Ns C2FS3281A and C2FS3282A. Those are all approved parts.
- AD CF-98-37R1 did not specify to remove parts from the aeroplane to perform inspections. This [Transport Canada] AD requires repetitive removal of the struts from the aeroplane followed by a NDI of the airframe lugs. This requirement applies to DHC-2 where the struts are being replaced when they reach 15 years since installation. It also applies to DHC-2 where the struts are kept in service and inspected as required by the SB and TB.
- AD CF-98-37R1 required the visual inspection to start within 12 months from the [Transport Canada] AD effective date and the NDI to start within 24 months from the [Transport Canada] AD effective date. This [Transport Canada] AD requires the repetitive inspections to start no later than when the struts have accumulated 15 years since initial installation.
- AD CF-98-37R1 required repetitive ultrasonic thickness measurement for all parts. This [Transport Canada] AD only requires that measurement if corrosion is detected during an inspection.
- AD CF-98-37R1 required visual inspection of the exterior surfaces of the strut with the strut installed in the aeroplane. For struts that have accumulated more than 15 years since first installation, this [Transport Canada] AD continues to require visual inspection of the accessible exterior surfaces of the strut with the strut installed. This [Transport Canada] AD also includes repetitive requirements for:

- Inspection of the fillet sealant;
- Borescope inspection of the interior of the strut; and
- Removal of the strut from the aeroplane followed by visual inspection of the entire strut and NDI of the strut end fittings.

All TC-issued or -accepted AMOCs with AD CF-98-37R1 are cancelled on the effective date of this [Transport Canada] AD. Parts in service must be replaced or modified, inspected and maintained in accordance with the requirements of this [Transport Canada] AD unless TC approves AMOCs with the requirements of this [Transport Canada] AD.

You may examine the MCAI in the AD docket at [www.regulations.gov](http://www.regulations.gov) under Docket No. FAA-2022-0602.

In the NPRM, the FAA proposed to require either doing recurring visual inspections, borescope inspections, and NDIs of the struts and airframe lugs with corrective action as necessary or replacing the struts every 15 years and doing recurring NDIs of the airframe lugs with corrective action as necessary. The FAA is issuing this AD to address the unsafe condition on these products.

#### Discussion of Final Airworthiness Directive

##### Comments

The FAA received no comments on the NPRM or on the determination of the costs.

##### Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety

requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

#### Related Service Information Under 1 CFR Part 51

The FAA reviewed Viking DHC-2 Beaver Technical Bulletin No. V2/00002, Revision 'A,' dated June 20, 2019. The service information specifies procedures for a detailed visual, borescope, and non-destructive testing (NDT) inspection of the front fuselage struts and airframe lugs.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

#### Other Related Service Information

The FAA reviewed Viking DHC-2 Beaver Service Bulletin No. V2/0010, Revision 'NC,' dated April 3, 2020. The service information contains a detailed and revised schedule for a detailed visual inspection of the forward-lower and aft-upper strut attachment points on the fuselage (mating airframe lugs) every 12 months, borescope inspection of the strut interior surfaces every 5 years, NDT inspection of the fuselage strut fork ends and lugs every 15 years, replacement of each fuselage strut every 15 years, and replacement of the 5-year ultrasonic thickness measurement as an option to the 15-year life limit.

#### Costs of Compliance

The FAA estimates that this AD affects 143 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

#### ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per airplane	Cost on U.S. operators
Visual, borescope, and NDT inspections of the front fuselage struts and airframe lugs.	80 work-hours × \$85 per hour = \$6,800 per inspection cycle.	Not applicable .....	\$6,800 per inspection cycle.	\$972,400 per inspection cycle.
Detailed visual inspection .....	4 work-hours × \$85 per hour = \$340 per inspection cycle.	Not applicable .....	\$340 per inspection cycle.	\$48,620 per inspection cycle.
Borescope and detailed visual inspection.	6 work-hours × \$85 per hour = \$510 per inspection cycle.	Not applicable .....	\$510 per inspection cycle.	\$72,930 per inspection cycle.
Replace left-hand fuselage strut .....	54 work-hours × \$85 per hour = \$4,590.	\$2,331.40 .....	\$6,921.40 .....	\$989,760.20.
Replace right-hand fuselage strut ....	54 work-hours × \$85 per hour = \$4,590.	\$2,331.40 .....	\$6,921.40 .....	\$989,760.20.

The extent of damage found during the required inspections could vary significantly from airplane to airplane. The FAA has no way of determining

how much damage may be found on each airplane, the cost to repair damaged parts on each airplane, or the

number of airplanes that may require repair.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

The FAA has determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by:

- a. Removing Airworthiness Directive 2002–14–28, Amendment 39–12828 (67 FR 47684, July 22, 2002); and
- b. Adding the following new airworthiness directive:

**2022–17–05 Viking Air Limited (type certificate previously held by Bombardier Inc. and de Havilland Inc.):**  
Amendment 39–22143; Docket No. FAA–2022–0602; Project Identifier MCAI–2020–01211–A.

### (a) Effective Date

This airworthiness directive (AD) is effective September 30, 2022.

### (b) Affected ADs

This AD replaces AD 2002–14–28, Amendment 39–12828 (67 FR 47684, July 22, 2002) (AD 2002–14–28).

### (c) Applicability

This AD applies to Viking Air Limited (type certificate previously held by Bombardier Inc. and de Havilland Inc.) Model DHC–2 Mk. I, DHC–2 Mk. II, and DHC–2 Mk. III airplanes, all serial numbers, certificated in any category.

### (d) Subject

Joint Aircraft System Component (JASC) Code 5300, Fuselage Structure (General).

### (e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as the development of damage to the front fuselage struts and airframe lugs over time. The FAA is issuing this AD to address this condition. The unsafe condition, if not addressed, could result in failure of the front fuselage struts, which could lead to failure of the airframe and loss of airplane control.

### (f) Definition of Serviceable Part

For purposes of this AD, a "serviceable part" is a front fuselage strut that has a part number (P/N) other than P/N C2FS209 and C2FS210 and meets the conditions in either paragraph (f)(1) or (2) of this AD:

- (1) Has accumulated less than 15 years since first installation on an airplane; or
- (2) Has accumulated 15 or more years since first installation on an airplane and has been inspected in accordance with the requirements of this AD.

### (g) Compliance

Comply with the initial actions in paragraph (h) of this AD at the applicable compliance time in paragraph (g)(1), (2), or (3) of this AD, unless already done.

- (1) For airplanes with a front fuselage strut that has been installed for less than 15 years as of the effective date of this AD: Before each front fuselage strut accumulates 15 years since first installation on an airplane.
- (2) For airplanes with a front fuselage strut that has been installed for more than 15 years as of the effective date of this AD or with a front fuselage strut where the date of first installation on an airplane is unknown and

the ultrasonic inspection required by paragraph (d)(2) of AD 2002–14–28 has not been done within the last 5 years: Before further flight.

(3) For airplanes with a front fuselage strut that has been installed for more than 15 years as of the effective date of this AD or with a front fuselage strut where the date of first installation on an airplane is unknown and the ultrasonic inspection required by paragraph (d)(2) of AD 2002–14–28 has been done within the last 5 years: Within 5 years from the date of the last ultrasonic inspection done in accordance with paragraph (d)(2) of AD 2002–14–28.

### (h) Initial Actions

(1) Do the actions in paragraph (h)(1)(i) or (ii) of this AD:

(i) Remove the front fuselage struts from service and install and seal serviceable parts in accordance with steps w. and y. through ii. of Section II.B.1. or II.B.2., as applicable to your airplane, of Viking DHC–2 Beaver Technical Bulletin No. V2/00002, Revision A, dated June 20, 2019 (Viking TB V2/00002); or

(ii) Do visual and borescope inspections of the front fuselage struts and non-destructive testing (NDT) inspections of the fuselage strut fork ends for corrosion and cracks in accordance with steps m. through p. of Section II.B.1. or II.B.2., as applicable to your airplane, of Viking TB V2/00002, except you are not required to contact the manufacturer. Instead, do the actions in paragraph (h)(3) of this AD.

(2) Do visual and NDT inspections of the mating airframe lug surfaces and bolt holes for corrosion and cracks and replace if necessary in accordance with steps q., r., t., and u. of Section II.B.1. or II.B.2., as applicable to your airplane, of Viking TB V2/00002, except you are not required to contact the manufacturer.

(3) If, during any inspection required by paragraph (h)(1)(ii) of this AD, any crack or corrosion is found, before further flight, do one of the following:

- (i) Remove the part from service and install and seal a serviceable part in accordance with steps w. and y. through ii. of Section II.B.1. or II.B.2., as applicable to your airplane, of Viking TB V2/00002; or
- (ii) If the wall thickness of the part is 0.030 inch or more, repair in accordance with step s.(2) of Section II.B.1. or II.B.2., as applicable to your airplane, of Viking TB V2/00002; or
- (iii) Repair using a method approved by the Manager, New York ACO Branch, FAA; Transport Canada; or Viking Air Limited's Transport Canada Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

### (i) Repetitive Actions

(1) After completing the actions in paragraphs (h)(1)(ii) and (2) of this AD, unless already done, do the following:

(i) At intervals not to exceed 12 months, except when complying with paragraph (i)(1)(ii) or (2) of this AD, clean and visually inspect the front fuselage struts and airframe lugs for corrosion and cracking in accordance with steps n., p., and q. of Section II.B.1. or

II.B.2., as applicable to your airplane, of Viking TB V2/00002. If there is a crack or any corrosion, before further flight, comply with the actions in paragraph (h)(3)(i), (ii), or (iii) of this AD.

(ii) At intervals not to exceed 5 years, except when complying with paragraph (i)(2) of this AD, do visual and borescope inspections of the front fuselage struts and a visual inspection of the airframe lugs for corrosion and cracking in accordance with steps m. through q. and t. of Section II.B.1. or II.B.2., as applicable to your airplane, of Viking TB V2/00002, except you are not required to contact the manufacturer. If there is a crack or any corrosion, before further flight, comply with the actions in paragraph (h)(3)(i), (ii), or (iii) of this AD.

(2) At intervals not to exceed 15 years, repeat the actions required by paragraph (h) of this AD.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Related Information

(1) For more information about this AD, contact Aziz Ahmed, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7329; email: [aziz.ahmed@faa.gov](mailto:aziz.ahmed@faa.gov).

(2) Refer to Transport Canada AD CF-2020-22, dated June 5, 2020, for more information. You may examine the Transport Canada AD in the AD docket at [www.regulations.gov](http://www.regulations.gov) by searching for and locating Docket No. FAA-2022-0602.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Viking DHC-2 Beaver Technical Bulletin No. V2/00002, Revision 'A,' dated June 20, 2019.

(ii) [Reserved]

(3) For Viking Air Ltd service information identified in this AD, contact Viking Air Limited Technical Support, 1959 de Havilland Way, Sidney, British Columbia, Canada, V8L 5V5; phone: (800) 663-8444; fax: (250) 656-0673; email: [technical.support@vikingair.com](mailto:technical.support@vikingair.com); website: [www.vikingair.com/support/service-bulletins](http://www.vikingair.com/support/service-bulletins).

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on August 4, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022-18383 Filed 8-25-22; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2022-0715; **Airspace**  
Docket No. 22-ASW-13]

**RIN 2120-AA66**

#### Revocation of Class E Airspace; Coalgate, OK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action removes the Class E airspace at Coalgate, OK. The FAA is taking this action due to the cancellation of the instrument procedures at the associated airport, and the airspace no longer being required.

**DATES:** Effective 0901 UTC, November 3, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [www.faa.gov/air-traffic/publications/](http://www.faa.gov/air-traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

**FOR FURTHER INFORMATION CONTACT:** Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

**SUPPLEMENTARY INFORMATION:**

#### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it removes the Class E airspace extending upward from 700 feet above the surface at Mary Hurley Hospital Heliport, Coalgate, OK, due to the cancellation of the instrument procedures at this airport, and the airspace no longer being required.

#### History

The FAA published a notice of proposed rulemaking in the **Federal Register** (87 FR 35469; June 10, 2022) for Docket No. FAA-2022-0715 to remove the Class E airspace at Coalgate, OK. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. Two comments were received supporting this action.

Class E airspace designations are published in paragraph 6005 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11F.

#### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

#### The Rule

This amendment to 14 CFR 71 removes the Class E airspace extending upward from 700 feet above the surface at Mary Hurley Hospital Heliport, Coalgate, OK.

This action is the result of the instrument procedures at this airport