

List of Subjects in 9 CFR Part 202

Administrative practice and procedure, Stockyards.

■ For the reasons set forth in the preamble, GIPSA amends 9 CFR part 202 as follows:

PART 202—RULES OF PRACTICE GOVERNING PROCEEDINGS UNDER THE PACKERS AND STOCKYARDS ACT

■ 1. Revise the authority citation for part 202 to read as follows:

Authority: 7 U.S.C. 228(a); 7 CFR 2.22 and 2.81.

■ 2. Immediately following § 202.123 add a new undesignated center heading and §§ 202.200 and 202.210 to read as set forth below:

Rules of Practice Applicable to All Other Proceedings**§ 202.200 Scope and applicability of rules of practice.**

The Uniform Rules of Practice for the Department of Agriculture promulgated in Subpart H of Part 1, Subtitle A, Title 7, Code of Federal Regulations, are the Rules of Practice applicable to adjudicatory, administrative proceedings under the Packers and Stockyards Act, as amended (7 U.S.C. 181 *et seq.*). In addition, the Supplemental Rules of Practice set forth in this part shall be applicable to such proceedings.

§ 202.210 Stipulations.

(a) The Administrator may enter into a stipulation with any person operating subject to the Packers and Stockyards Act, as amended (P&S Act), prior to issuing a complaint that seeks a civil penalty against that person.

(1) The Administrator will give the person notice of an alleged violation of the P&S Act or regulations and provide an opportunity for a hearing;

(2) The person has the option to expressly waive the opportunity for a hearing and agree to pay a specified civil penalty within a designated time;

(3) The Administrator will agree to settle the matter by accepting payment of the specified civil penalty within a designated time;

(4) If the person does not agree to the stipulation, or does not pay the penalty within the specified time, the Administrator may issue an administrative complaint citing the alleged violation; and

(5) The civil penalty that the Administrator proposed in a stipulation agreement has no bearing on the civil penalty amount that may be sought in a formal administrative proceeding

against the same person for the same alleged violation.

(b) [Reserved].

James E. Link,

Administrator, Grain Inspection, Packers and Stockyards Administration.

[FR Doc. E7-7041 Filed 4-16-07; 8:45 am]

BILLING CODE 3410-KD-P

NUCLEAR REGULATORY COMMISSION**10 CFR Part 72**

RIN 3150-AI03

List of Approved Fuel Storage Casks: Standardized NUHOMS® System, Revision 9, Confirmation of Effective Date

AGENCY: Nuclear Regulatory Commission

ACTION: Direct final rule: Confirmation of effective date.

SUMMARY: The Nuclear Regulatory Commission (NRC) is confirming the effective date of April 17, 2007, for the direct final rule that was published in the **Federal Register** on February 1, 2007 (72 FR 4615). This direct final rule amended the NRC's regulations to revise the Transnuclear, Inc., Standardized NUHOMS® System listing to include Amendment No. 9 to Certificate of Compliance (CoC) No. 1004.

DATES: *Effective Date:* The effective date of April 17, 2007, is confirmed for this direct final rule.

ADDRESSES: Documents related to this rulemaking, including comments received, may be examined at the NRC Public Document Room, located at One White Flint North, 11555 Rockville Pike, Rockville, MD 20852. These same documents may also be viewed and downloaded electronically via the rulemaking Web site (<http://ruleforum.llnl.gov>). For information about the interactive rulemaking Web site, contact Ms. Carol Gallagher (301) 415-5905; e-mail CAG@nrc.gov.

FOR FURTHER INFORMATION CONTACT:

Jayne M. McCausland, Office of Federal and State Materials and Environmental Management Programs, U.S. Nuclear Regulatory Commission, Washington, DC 20555, telephone (301) 415-6219, e-mail jmm2@nrc.gov.

SUPPLEMENTARY INFORMATION: On February 1, 2007 (72 FR 4615), the NRC published a direct final rule amending its regulations in 10 CFR part 72 to revise the Transnuclear, Inc., Standardized NUHOMS® System listing within the "List of Approved Spent Fuel

Storage Casks" to include Amendment No. 9 to CoC No. 1004. This amendment revises Technical Specifications 1.2.1 and 1.2.14 to add the Framatome-ANP, Version 9x9-2 fuel assemblies as approved contents for storage in the NUHOMS-61BT dry shielded canister. In the direct final rule, NRC stated that if no significant adverse comments were received, the direct final rule would become final on April 17, 2007. The NRC did not receive any comments that warranted withdrawal of the direct final rule. Therefore, this rule will become effective as scheduled.

Dated at Rockville, Maryland, this 11th day of April, 2007.

For the Nuclear Regulatory Commission.

Michael T. Lesar,

Chief, Rulemaking, Directives and Editing Branch, Division of Administrative Services, Office of Administration.

[FR Doc. E7-7262 Filed 4-16-07; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF THE TREASURY**Office of Thrift Supervision****12 CFR Part 563e**

[No. 2007-16]

RIN 1550-AC08

Community Reinvestment Act Rule—Interagency Uniformity; Correction

AGENCY: Office of Thrift Supervision, Treasury (OTS).

ACTION: Final rule; correction.

SUMMARY: OTS is correcting an inadvertent omission and incorrect word in a final rule that appeared in the **Federal Register** of March 22, 2007 (72 FR 13429). That final rule reestablishes uniformity between OTS's Community Reinvestment Act (CRA) regulations and those of the other federal banking agencies.

DATES: Effective July 1, 2007.

FOR FURTHER INFORMATION CONTACT:

Celeste Anderson, Senior Project Manager, Compliance and Consumer Protection, (202) 906-7990; Richard Bennett, Counsel, Regulations and Legislation Division, (202) 906-7409, Office of Thrift Supervision, 1700 G Street, NW., Washington, DC 20552.

SUPPLEMENTARY INFORMATION: In the final rule FR Doc. E7-5188 appearing on page 13429 in the **Federal Register** of Thursday, March 22, 2007, the following corrections are made:

§ 563.28 [Corrected]

■ 1. On page 13435, in the third column, in § 563e.28 Assigned ratings, in paragraph (c)(1), in the first sentence, “or any affiliate” is corrected to read “or in any assessment area by any affiliate”.

Appendix A to Part 563e—Ratings [Corrected]

■ 2. On page 13436, in the second column, in Appendix A to Part 563e—Ratings, in paragraph (d)(3)(ii)(B), in the second sentence, “a bank’s performance” is corrected to read “a savings association’s performance”.

Dated: April 11, 2007.

By the Office of Thrift Supervision.

Deborah Dakin,

Senior Deputy Chief Counsel.

[FR Doc. E7-7226 Filed 4-16-07; 8:45 am]

BILLING CODE 6720-01-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2005-21624; Directorate Identifier 2005-NE-17-AD; Amendment 39-15028; AD 2005-13-25R1]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Arriel 2B Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is revising an existing airworthiness directive (AD) for Turbomeca S.A. Arriel 2B turboshaft engines with Modification TU62A incorporated. That AD currently requires initial and repetitive inspections, cleaning, lubrication, and checks for proper operation of the HMU acceleration controller axle. This AD requires the same actions, but removes engines incorporating TU132 from the applicability and adds an optional terminating action for the repetitive actions required in AD 2005-13-25. This AD results from the engine manufacturer releasing a service bulletin to introduce modification TU132. We are issuing this AD to prevent loss of control of engine fuel flow in manual control mode or mixed control mode, which can lead to engine overspeed, and in-flight engine shutdown resulting in a forced autorotation landing or accident.

DATES: Effective May 22, 2007. The Director of the Federal Register

previously approved the incorporation by reference of Alert Mandatory Service Bulletin (ASB) No. A292 73 2814, Update No. 1, dated January 11, 2005, on July 11, 2005 (70 FR 36480, June 24, 2005). The Director of the Federal Register approved the incorporation by reference of ASB No. A292 73 2814, Update No. 2, dated December 15, 2006, as of May 22, 2007.

We must receive any comments on this AD by June 18, 2007.

ADDRESSES: Use one of the following addresses to comment on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Turbomeca S.A., 40220 Tarnos, France; telephone 33 05 59 74 40 00, fax 33 05 59 74 45 15, for the service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7175; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: On June 16, 2005, the FAA issued AD 2005-13-25, Amendment 39-14162 (70 FR 36480, June 24, 2005). That AD requires initial and repetitive inspections, cleaning, lubrication, and checks for proper operation of the hydromechanical unit (HMU) acceleration controller axle on engines that incorporate modification TU62A. That AD was the result of several reports of the HMU acceleration controller axle sticking that resulted in engine overspeed and in-flight engine shutdown or uncommanded in-flight engine shutdown. That condition, if not corrected, could result in loss of control of engine fuel flow in manual control mode or mixed control mode, which can lead to engine overspeed, and in-flight engine shutdown resulting in a forced autorotation landing or accident.

Actions Since We Issued AD 2005-13-25

Since we issued that AD, the manufacturer introduced modification TU132, which includes a new P3 cover with a self-lubricating coating and a reduced centering length in the P3 cover. The European Aviation Safety Authority (EASA) which is the airworthiness authority for the European Union, recently notified us that Turbomeca S.A. has introduced modification TU132 to eliminate the cause of an unsafe condition on Turbomeca S.A. Arriel 2B turboshaft engines. This AD requires inspecting and lubricating the P3 cover and HMU acceleration control axle on HMUs that are not modified to TU132. We are issuing this AD to prevent loss of control of engine fuel flow in the manual control mode or mixed control mode, which can lead to engine overspeed, and in-flight engine shutdown resulting in a forced autorotation landing or accident.

Relevant Service Information

We have reviewed and approved the technical contents of Turbomeca Alert Mandatory Service Bulletin (ASB) No. A292 73 2814, Update No. 2, dated December 15, 2006. That ASB describes procedures for inspecting, lubricating, and checking for proper operation of the HMU acceleration controller axle. The EASA issued AD 2007-0026, dated February 1, 2007, in order to ensure the airworthiness of these Arriel 2B turboshaft engines in the European Union.

Bilateral Airworthiness Agreement

This engine model is manufactured in France, and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Under this bilateral airworthiness agreement, the EASA has kept the FAA informed of the situation described above. We have examined the findings of the EASA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

FAA's Determination and Requirements of This AD

The unsafe condition described previously is likely to exist or develop on other Turbomeca S.A. Arriel 2B turboshaft engines of the same type design. We are issuing this AD to prevent loss of control of engine fuel flow in the manual control mode or