

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Empresa Brasileira De Aeronautica S.A. (EMBRAER); Docket No. FAA-2008-0668; Directorate Identifier 2008-NM-088-AD.

Comments Due Date

- (a) We must receive comments by July 24, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to EMBRAER Model ERJ 190-100 STD, -100 LR, -100 IGW, -100ECJ, -200 STD, -200 LR, and -200 IGW airplanes, certificated in any category, serial numbers 19000004, 19000006 through 19000028 inclusive, and 19000030 through 19000039 inclusive.

Subject

(d) Air Transport Association (ATA) of America Code 57: Wings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

During aircraft structure fatigue tests, cracks were found in the wing lower skin stringers between ribs 7 and 10 on both wings. In order to prevent fatigue cracks in the wing lower skin stringers, which could result in fuel leakage and reduced structural integrity of the wing, the referred stringers must be reworked.

The corrective actions include spot-facing the lower wing stringers between ribs 7 and 10, doing a dye-penetrant inspection of the reworked stringers, shot-peening if no cracking is found, contacting Agência Nacional de Aviação Civil (ANAC) if any crack is found, and repairing.

Actions and Compliance

(f) Unless already done: Prior to the accumulation of 5,000 total flight cycles, or within 500 flight cycles after the effective date of this AD, whichever occurs later, do the following actions.

(1) Spot-face the lower wing stringers between ribs 7 and 10 on both wings by changing their run out in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 190-57-0005, Revision 01, dated October 27, 2006.

(2) Do a dye-penetrant inspection for cracking of the reworked stringers in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 190-57-0005, Revision 01, dated October 27, 2006.

(i) If no cracking is detected: Before further flight, shot-peen the stringer reworked area following the parameters indicated in the Accomplishment Instructions of EMBRAER Service Bulletin 190-57-0005, Revision 01, dated October 27, 2006.

(ii) If any cracking is detected: Before further flight, contact the ANAC for repair instructions and repair.

(3) Actions done before the effective date of this AD in accordance with EMBRAER Service Bulletin 190-57-0005, dated October 10, 2006, are acceptable for compliance with the requirements of paragraph (f) of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane

Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Kenny Kaulia, Aerospace Engineer, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2848; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Brazilian Airworthiness Directive 2008-01-02, effective February 25, 2008, and EMBRAER Service Bulletin 190-57-0005, Revision 01, dated October 27, 2006, for related information.

Issued in Renton, Washington, on June 9, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-14187 Filed 6-23-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0671; Directorate Identifier 2008-NM-017-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-300, -400, and -500 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 737-300, -400, and -500 series airplanes. This proposed AD would require repetitive high frequency eddy current (HFEC) inspections for cracking of the 1.04-inch nominal diameter wire penetration hole in the

frame and frame reinforcement, between stringers S-20 and S-21, on both the left and right sides of the airplane, and related investigative/corrective actions if necessary. This proposed AD results from reports of cracking in the frame, or in the frame and frame reinforcement, common to the 1.04-inch nominal diameter wire penetration hole intended for wire routing. We are proposing this AD to detect and correct cracking in the fuselage frames and frame reinforcements, which could reduce the structural capability of the frames to sustain limit loads, and result in cracking in the fuselage skin and subsequent rapid depressurization of the airplane.

DATES: We must receive comments on this proposed AD by August 8, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6447; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0671; Directorate Identifier 2008-NM-017-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports of cracking in the frame, or in the frame and frame reinforcement, common to the 1.04-inch nominal diameter wire penetration hole intended for wire routing, between stringers S-20 and S-21, on both the left and right sides of the airplane. The cracked frames are located between station (STA) 500B and STA 520 on Model 737-300 and -400 series airplanes and between STA 482 and STA 520 on Model 737-500 series airplanes. The cracks at the 1.04-inch nominal diameter wire penetration hole are due to the effect of operating loads in combination with the stress concentration at the 1.04-inch nominal hole. The cracking initiated at the 1.04-inch nominal diameter wire penetration hole and grew towards the inner chord.

We have since received reports of more than fifty cracked frames at the 1.04-inch nominal diameter wire penetration hole on more than 20 airplanes, all either Model 737-300 or 737-500 series airplanes. The airplanes had accumulated between 35,832 and 66,694 total flight cycles.

This type of cracking has occurred at three frame stations on Model 737-300 series airplanes, at one frame station on Model 737-400 series airplanes, and at four stations on Model 737-500 series airplanes. Sixteen airplanes had cracking at multiple frames, and 10 frames had cracking at adjacent frames. Forty-three frames had cracking only at the inboard side of the 1.04-inch nominal diameter wire penetration hole in the frame inner chord or in the frames and frame reinforcement inner chord. Three of the frames had cracking in the outboard side of the 1.04-inch

nominal diameter wire penetration hole in the frame and the frame reinforcement. Two of the frames were severed. Some of the frames had additional cracking at either the standoff/tooling holes or at the 0.50-inch diameter hole positioned below the 1.04-inch nominal diameter wire penetration hole.

Cracking in the fuselage frames at the wire penetration hole intended for wire routing will reduce the structural capability of the frames to sustain limit loads. Cracking in the frames could result in cracking in the fuselage skin and subsequent rapid depressurization of the airplane.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 737-53A1279, dated December 18, 2007. The service bulletin describes procedures for doing either a high frequency eddy current (HFEC) surface inspection or HFEC hole/edge inspection for cracking of the 1.04-inch nominal diameter wire penetration hole in the frame and frame reinforcement, between stringers S-20 and S-21, on both the left and right sides of the airplane. If cracking is found, the service bulletin also describes procedures for related investigative and corrective actions. The related investigative action is doing an HFEC inspection for cracking in the 0.50-inch diameter hole and all standoff/tooling holes in the frame and frame reinforcement, between stringers S-19 and S-22. The corrective action is repairing any cracking found and repeating the HFEC inspections. If additional cracking is found, the service bulletin specifies contacting Boeing for repair instructions. The service bulletin further describes procedures for a preventative modification for frames on which either the initial or repetitive inspections have been done. The preventative modification terminates the repetitive inspections.

The initial compliance time for the initial inspection is either within 3,000 or 6,000 (but not to exceed 53,000 total flight cycles) flight cycles after release of the service bulletin, depending on the number of total flight cycles on the airplane. The repetitive interval for the HFEC inspection is 14,000 flight cycles. Corrective actions must be done before further flight.

FAA's Determination and Requirements of this Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the(se)

same type design(s). This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under “Differences Between the Proposed AD and the Service Bulletin.”

Differences Between the Proposed AD and the Service Bulletin

The service bulletin specifies to contact the manufacturer for

instructions on how to remove damage and repair certain conditions, but this proposed AD would require removing damage and repairing those conditions in one of the following ways:

- Using a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by an Authorized Representative for the Boeing Commercial Airplanes

Delegation Option Authorization Organization whom we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD would affect 616 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD. The average labor rate is \$80 per work hour.

ESTIMATED COSTS

Action	Work hours	Parts	Cost per product	Number of U.S.-registered airplanes	Fleet cost
Inspection	Between 6 and 8 (depending on airplane configuration), per inspection cycle.	\$0	Between \$480 and \$640, per inspection cycle.	616	Between \$295,680 and \$394,240, per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866,
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Boeing: Docket No. FAA–2008–0671; Directorate Identifier 2008–NM–017–AD.

Comments Due Date

- (a) We must receive comments by August 8, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Boeing Model 737–300, –400, and –500 series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 737–53A1279, dated December 18, 2007.

Unsafe Condition

- (d) This AD results from reports of cracking in the frame, or in the frame and frame reinforcement, common to the 1.04-inch

nominal diameter wire penetration hole intended for wire routing. We are issuing this AD to detect and correct cracking in the fuselage frames and frame reinforcements, which could reduce the structural capability of the frames to sustain limit loads, and result in cracking in the fuselage skin and subsequent rapid depressurization of the airplane.

Compliance

- (e) Comply with this AD within the compliance times specified, unless already done.

Service Bulletin Reference Paragraph

(f) The term “service bulletin,” as used in this AD, means the Accomplishment Instructions of Boeing Alert Service Bulletin 737–53A1279, dated December 18, 2007.

(1) Where the service bulletin specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where the service bulletin specifies to contact Boeing for instructions for removing damage and repairing cracking: Before further flight, remove the damage or repair the cracking using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(3) Although the service bulletin referenced in this AD specifies to submit information to the manufacturer, this AD does not include that requirement.

Inspections, Related Investigative and Corrective Actions

- (g) At the applicable time specified in paragraph 1.E., “Compliance,” of the service bulletin, except as specified by paragraph (f)(1) of this AD: Do a high frequency eddy current (HFEC) surface inspection or an HFEC hole/edge inspection for cracking of the 1.04-inch nominal diameter wire penetration hole in the frame and frame reinforcement, between stringer S–20 and S–21; and do all applicable related investigative and corrective actions; by accomplishing all

the actions specified in the Accomplishment Instructions of the service bulletin, except as specified by paragraphs (f)(2) and (f)(3) of this AD. Do all applicable related investigative and corrective actions before further flight. Thereafter, repeat the inspections at the applicable intervals specified in paragraph 1.E. of the service bulletin.

Terminating Action

(h) Doing the repair in Part 3 or the preventative modification in Part 4 of the service bulletin terminates the repetitive inspection requirements of this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6447; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on June 8, 2008.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-14183 Filed 6-23-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0670; Directorate Identifier 2007-NM-339-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Damage to the lower lateral fittings of the 80VU rack * * * [and] damage to the lower central support fitting * * *.

In the worst case scenario a complete failure of the 80VU fittings in combination with a high load factor or strong vibration could lead to failure of the rack structure and/or computers or rupture/disconnection of the cable harnesses to one or more computers located in the 80VU. This rack contains computers for Flight Controls, Communication and Radio-navigation. These functions are duplicated across other racks but during critical phases of flight the multiple system failures/re-configuration may constitute an unsafe condition.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by July 24, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM-116,

Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include "Docket No. FAA-2008-0670; Directorate Identifier 2007-NM-339-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2007-0276, dated October 26, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Damage to the lower lateral fittings of the 80VU rack, typically elongated holes, migrated bushes [bushings], and/or missing bolts have been reported in-service. In addition damage to the lower central support fitting (including cracking) has been reported.

In the worst case scenario a complete failure of the 80VU fittings in combination with a high load factor or strong vibration could lead to failure of the rack structure and/or computers or rupture/disconnection of the cable harnesses to one or more computers located in the 80VU. This rack contains computers for Flight Controls, Communication and Radio-navigation. These functions are duplicated across other racks but during critical phases of flight the multiple system failures/re-configuration may constitute an unsafe condition.

This Airworthiness Directive (AD) mandates the repetitive inspection of the lower lateral 80VU fittings for damage and the inspection of the lower central 80VU support for damage and cracking, and the associated corrective actions as necessary with more restrictive actions than defined in Airbus Service Bulletin (SB) A320-25A1555 at its original issue.

The new requirements defined in this AD will be introduced in revision 1 of SB A320-25A1555.