

necessary and which the Committee shall specify in its request.

(b) * * *

(2) * * *

(i) The total net weight of the standard raisins acquired during the reporting period; and

(ii) The cumulative totals of such acquisitions from the beginning of the then current crop year.

* * * * *

(c) * * *

(1) Each month each handler who is not a processor shall furnish to the Committee, on an appropriate form provided by the Committee and so that it is received by the Committee not later than the seventh day of the month, a report showing the aggregate quantity of each varietal type of packed raisins and standard natural condition raisins which were shipped or otherwise disposed of by such handler during the preceding month (exclusive of transfers within the State of California between plants of any such handler and from such handler to other handlers): *Provided*, That, for the Other Seedless varietal type, handlers shall report such information for the different types of Other Seedless raisins. Such required information shall be segregated as to:

* * * * *

(d) * * *

(1) Any handler who transfers raisins to another handler within the State of California shall submit to the Committee not later than five calendar days following such transfer a report showing:

* * * * *

(v) If packed, the transferring handler shall certify that such handler is transferring only acquired raisins that meet all applicable marketing order requirements, including reporting, incoming inspection, and assessments.

* * * * *

(f) * * *

(1) * * *

(i) The quantity of raisins, segregated as to locations where they are stored and whether they are natural condition or packed;

(ii) * * *

(2) * * *

(i) The total net weight of the standard raisins acquired during the reporting period; and

* * * * *

(3) *Disposition report of organically-produced raisins.* No later than the seventh day of each month, handlers who are not processors shall submit to the Committee, on an appropriate form provided by the Committee, a report showing the aggregate quantity of packed raisins and standard natural condition raisins which were shipped or otherwise disposed of by such handler during the preceding month (exclusive of transfer within the State of California between the plants of any such handler and from such handler to other handlers). Such information shall include:

* * * * *

■ 29. In § 989.210:

■ a. Remove paragraphs (b), (c) and (e);

■ b. Redesignate paragraph (d) as (b), paragraph (f) as (c), and paragraph (g) as (d); and

■ c. Revise newly redesignated paragraph (b).

The revisions read as follows:

§ 989.210 Handling of varietal types of raisins acquired pursuant to a weight dockage system.

* * * * *

(b) *Assessments.* Assessments on any lot of raisins of the varietal types specified in paragraph (a) of this section acquired by a handler pursuant to a weight dockage system shall be applicable to the creditable weight of such lot.

* * * * *

■ 30. Sections 989.221 and 989.257 are removed.

■ 31. The subpart heading “Subpart-Schedule of Payments” prior to § 989.401 is removed.

■ 32. Section 989.401 is removed.

■ 33. In part 989 all references of “offgrade” are revised to read “off-grade”.

■ 34. In part 989 all references to “nonnormal” are revised to read “non-normal”.

■ 35. In part 989 all references to “committee” are revised to read “Committee”.

■ 36. In the list below, for each section indicated in the left column, remove the title indicated in the middle column from wherever it appears in the section, and add the title indicated in the right column:

Section	Remove	Add
989.58(d)	Processed Products Standardization and Inspection Branch.	Specialty Crops Inspection Division.
989.59(d)	Processed Products Standardization and Inspection Branch.	Specialty Crops Inspection Division.
989.102	Processed Products Branch, Fruit and Vegetable Division.	Specialty Crops Inspection Division.

Dated: May 3, 2017.

Bruce Summers,

Acting Administrator, Agricultural Marketing Service.

[FR Doc. 2017-09242 Filed 5-30-17; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0495; Directorate Identifier 2017-NM-017-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), and Model CL-600-2D24 (Regional Jet Series 900) airplanes. This proposed AD was prompted by development of a modification to prevent uncommanded rudder movement during flight. This proposed AD would require modifying the wiring harness of the yaw damper control system. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 17, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; Internet: <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0495; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about

this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0495; Directorate Identifier 2017-NM-017-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2017-06, effective February 14, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440), Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), and Model CL-600-2D24 (Regional Jet Series 900) airplanes. The MCAI states:

[Canadian] AD CF-2013-13 was issued on 28 May 2013 [related to FAA AD 2013-14-11, Amendment 39-17516 (78 FR 44781, July 25, 2013) (“AD 2013-14-11”)] to mandate the introduction of an emergency procedure to the Aeroplane Flight Manual to address the uncommanded rudder movement.

Since the original issue of [Canadian] AD CF-2013-13, Bombardier Aerospace has developed a wiring modification for the yaw damper control system to prevent uncommanded movement of the rudder [and consequent loss of the ability to control the airplane].

This [Canadian] AD mandates the wiring modification for the yaw damper control system * * *.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0495.

Related Rulemaking

On July 11, 2013, we issued AD 2013-14-11, applicable to all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440), Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), and Model CL-600-2D24

(Regional Jet Series 900) airplanes. That AD requires revising the airplane flight manual by incorporating an emergency procedure for uncommanded yaw motion. That AD was prompted by reports of airplanes experiencing uncommanded rudder movements while in flight. That AD was issued to advise the flightcrew of procedures to address a possible failure of the voltage regulator inside the yaw damper actuator that could lead to uncommanded rudder movement and consequent loss of the ability to control the airplane.

Since issuance of AD 2013-14-11, a wiring modification for the yaw damper control system has been developed to prevent uncommanded rudder movement.

Related Service Information Under 1 CFR Part 51

We reviewed Bombardier Service Bulletin 601R-22-017, Revision C, dated May 11, 2016; and Bombardier Service Bulletin 670BA-22-007, Revision A, dated February 16, 2016. This service information describes procedures for modifying the wiring harness of the yaw damper control system. These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 1,006 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Wiring modification	5 work-hours × \$85 per hour = \$425	Up to \$39	Up to \$464	Up to \$466,784.

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national

Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2017-0495; Directorate Identifier 2017-NM-017-AD.

(a) Comments Due Date

We must receive comments by July 17, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), and Model CL-600-2D24 (Regional Jet Series 900) airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto Flight.

(e) Reason

This AD was prompted by development of a modification to prevent uncommanded rudder movement during flight. We are issuing this AD to prevent uncommanded rudder movement and consequent loss of the ability to control the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 6,600 flight hours or 36 months after the effective date of this AD, whichever occurs first: Modify the wiring harness of the yaw damper control system, in accordance with the applicable service information specified in table 1 to paragraph (g) of this AD.

TABLE 1 TO PARAGRAPH (g) OF THIS AD

Airplane model	Airplane serial numbers	Applicable Service Bulletin
CL-600-2B19	7002 through 8999 inclusive	Bombardier Service Bulletin 601R-22-017, Revision C, dated May 11, 2016.
CL-600-2C10	10002 through 10344 inclusive	Bombardier Service Bulletin 670BA-22-007, Revision A, dated February 16, 2016.
CL-600-2D15 and CL-600-2D24	15001 through 15400 inclusive.	

(h) Credit for Previous Actions

(1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the service information specified in paragraph (h)(1)(i), (h)(1)(ii), or (h)(1)(iii) of this AD, which is applicable to Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes.

(i) Bombardier Service Bulletin 601R-22-017, dated September 24, 2014, in conjunction with Bombardier Service Non-Incorporated Engineering Order (SNIEO) K601R50211 S02, dated October 31, 2014.

(ii) Bombardier Service Bulletin 601R-22-017, Revision A, dated February 26, 2015, in conjunction with Bombardier SNIEO K601R50211 S03, dated April 21, 2015; or S04, dated April 24, 2015.

(iii) Bombardier Service Bulletin 601R-22-017, Revision B, dated July 16, 2015.

(2) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 670BA-22-007, dated October 15, 2014, which is applicable to Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet

Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes.

(i) Parts Installation Limitations

As of 24 months after the effective date of this AD, no person may install, on any airplane, a yaw damper actuator having part number 622-9968-001, unless it has been modified in accordance with the applicable service information specified in table 1 to paragraph (g) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2017-06, effective February 14, 2017, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0495.

(2) For more information about this AD, contact Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; Internet: <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on May 15, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-10544 Filed 5-30-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0513; Directorate Identifier 2016-NM-152-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Dassault Aviation Model FALCON 2000EX airplanes. This proposed AD was prompted by a quality review of delivered airplanes, which identified a manufacturing deficiency of some engine air inlet anti-ice “piccolo” tubes. This proposed AD would require inspecting each anti-ice “piccolo” tube assembly of certain engine air inlets for discrepancies, and doing corrective actions if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 17, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax*: 202-493-2251.
- *Mail*: U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue

SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0513; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0513; Directorate Identifier 2016-NM-152-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2016-0168, dated August 17, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Dassault Aviation Model FALCON 2000EX airplanes. The MCAI states:

A quality review of recently delivered aeroplanes identified a manufacturing deficiency of some engine air inlet anti-ice “piccolo” tubes.