

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-0369; Directorate Identifier 2007-NM-258-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 50 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Some occurrences have been reported where life rafts were difficult to remove from inside divan compartment. Investigations revealed that:

- Life raft was incorrectly stowed, with deployment straps inboard;
- Life raft had not been repacked to specified dimensions.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by January 22, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the

regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2007-0369; Directorate Identifier 2007-NM-258-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2006-0366, dated December 11, 2006 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Some occurrences have been reported where life rafts were difficult to remove from inside divan compartment. Investigations revealed that:

- Life raft was incorrectly stowed, with deployment straps inboard;
- Life raft had not been repacked to specified dimensions

The purpose of this Airworthiness Directive (AD) is to verify that all life rafts are stowed correctly with deployment straps outboard, and are repacked to specified dimensions.

Corrective actions include correctly reinstalling an incorrectly stowed life raft, installing a properly repacked life raft, and installing placards. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Dassault has issued Service Bulletin F50-480, dated December 5, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 25 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$68 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$3,700, or \$148 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Dassault Aviation: Docket No. FAA-2007-0369; Directorate Identifier 2007-NM-258-AD.

Comments Due Date

- (a) We must receive comments by January 22, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Dassault Model Mystere-Falcon 50 airplanes, certificated in any category, serial numbers 294, 299, 301 through 304, 306, 307, 310, 313, 314, 316 through 320, 322 through 331, 334 through 337 and 339.

Subject

- (d) Air Transport Association (ATA) of America Code 25: Equipment/Furnishings.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

Some occurrences have been reported where life rafts were difficult to remove from inside divan compartment. Investigations revealed that:

- Life raft was incorrectly stowed, with deployment straps inboard;
- Life raft had not been repacked to specified dimensions

The purpose of this Airworthiness Directive (AD) is to verify that all life rafts are stowed correctly with deployment straps outboard, and are repacked to specified dimensions.

Corrective actions include correctly reinstalling an incorrectly stowed life raft, installing a properly repacked life raft, and installing placards.

Actions and Compliance

- (f) Unless already done, do the following actions.

- (1) Within 10 flight cycles after the effective date of this AD: Verify that the life rafts are stowed correctly, with deployment straps outboard, in accordance with the instructions specified in Dassault Service Bulletin F50-480, dated December 5, 2006, and verify that the overall dimensions of the life raft hard pack do not exceed nominal values, as indicated in Part F50-480-1 of the service bulletin.

- (i) If a life raft is found incorrectly stowed, before next flight, reinstall it in accordance with the instructions specified in Part F50-480-1 of the service bulletin.

- (ii) If nominal values of the overall dimensions of the life raft hard pack are exceeded, within 3 months after the effective date of this AD, install a properly repacked life raft as instructed in Part F50-480-2 of the service bulletin.

Note 1: Notice that with no life raft aboard, local national operating regulations may not allow some extended overwater flights.

- (2) Within 3 months after the effective date of this AD: Install placards on the sofa in

accordance with the instructions specified in Part F50-480-2 of Dassault Service Bulletin F50-480, dated December 5, 2006.

FAA AD Differences

- Note 2:** This AD differs from the MCAI and/or service information as follows:
- No differences.

Other FAA AD Provisions

- (g) The following provisions also apply to this AD:

- (1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *ATTN:* Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

- (2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

- (3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

- (h) Refer to MCAI EASA Airworthiness Directive 2006-0366, dated December 11, 2006, and Dassault Service Bulletin F50-480, dated December 5, 2006, for related information.

Issued in Renton, Washington, on December 12, 2007.

Michael J. Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-24698 Filed 12-19-07; 8:45 am]

BILLING CODE 4910-13-P

SECURITIES AND EXCHANGE COMMISSION

17 CFR PART 239

[Release No. 33-8871; File No. S7-30-07]

RIN 3235-AK02

Revisions to Form S-11 To Permit Historical Incorporation by Reference

AGENCY: Securities and Exchange Commission.