

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by:

- a. Removing Airworthiness Directive (AD) 2022–11–01, Amendment 39–22051 (87 FR 32292, May 31, 2022); and
- b. Adding the following new AD:

2025–01–07 Airbus SAS: Amendment 39–22931; Docket No. FAA–2024–2141; Project Identifier MCAI–2024–00421–T.

(a) Effective Date

This airworthiness directive (AD) is effective March 11, 2025.

(b) Affected ADs

This AD replaces AD 2022–11–01, Amendment 39–22051 (87 FR 32292, May 31, 2022).

(c) Applicability

This AD applies to Airbus SAS airplanes identified in paragraphs (c)(1) through (5) of this AD, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2024–0145, dated July 23, 2024 (EASA AD 2024–0145).

(1) Model A300 B4–2C, B4–103, and B4–203 airplanes.

(2) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.

(3) Model A300 B4–605R and B4–622R airplanes.

(4) Model A300 C4–605R Variant F airplanes.

(5) Model A300 F4–605R and F4–622R airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of cracking in the main landing gear (MLG) support rib 5 lower flange, inboard and outboard of rib 5, on the right-hand and left-hand sides, and the determination that additional airplanes are affected by the unsafe condition. The FAA is issuing this AD to address cracking of the MLG support rib 5 lower flange. This condition, if not detected and corrected, could affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2024–0145.

(h) Exceptions to EASA AD 2024–0145

(1) Where EASA AD 2024–0145 refers to August 31, 2021 (the effective date of EASA AD 2021–0190), this AD requires using July 5, 2022 (the effective date of AD 2022–11–01, Amendment 39–22051 (87 FR 32292, May 31, 2022)).

(2) Where EASA AD 2024–0145 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (3) of EASA AD 2024–0145 specifies to “accomplish those instructions accordingly” if any crack is detected, for this AD if any crack is detected, the crack must be repaired before further flight using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(4) This AD does not adopt the “Remarks” section of EASA AD 2024–0145.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) Airbus Statement of Airworthiness Compliance (ASAC) 80955386/006/2021, Issue 1, dated August 25, 2021; and ASAC 80955386/024/2022, Issue 1, dated February 25, 2022, are approved as AMOCs for the corresponding provisions of this AD for the airplanes identified in those ASACs only.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (i)(2) of this AD, if any material referenced in EASA AD 2024–0145 contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an

AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Dan Rodina, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206–231–3225; email: Dan.Rodina@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0145, dated July 23, 2024.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 6, 2025.

Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025–02145 Filed 2–3–25; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2025–0018; Project Identifier MCAI–2024–00749–R; Amendment 39–22952; AD 2025–03–04]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all

Airbus Helicopters Model AS332L, AS332L1, AS 365 N3, SA-365C1, SA-365C2, SA-365N, and SA-365N1 helicopters. This AD was prompted by a report that certain rescue hoist cable assemblies may be equipped with a defective ball end. This AD requires inspecting certain rescue hoist cable assemblies and, depending on the results, replacing the rescue hoist cable assembly. This AD also allows installing certain rescue hoist cable assemblies and certain rescue hoists provided its requirements are met. These actions are specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 19, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 19, 2025.

The FAA must receive comments on this AD by March 21, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0018; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX

76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0018.

FOR FURTHER INFORMATION CONTACT: Eric Rivera, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (847) 294-7166; email: eric.rivera01@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2025-0018; Project Identifier MCAI-2024-00749-R” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Eric Rivera, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (847) 294-7166; email: eric.rivera01@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0244, dated December 13, 2024 (EASA AD 2024-0244) (also referred to as the MCAI), to correct an unsafe condition on Airbus Helicopters Model AS 332 L, AS 332 L1, SA 365 N, SA 365 N1, AS 365 N3, SA 365 C1, SA 365 C2, and SA 365 C3 helicopters. The MCAI states the manufacturer reported that a defective testing tool was used during production, repair, and overhaul of certain rescue hoist cable assemblies resulting in assemblies equipped with a defective ball end.

The FAA is issuing this AD to detect and address defective rescue hoist cable assembly ball ends. This unsafe condition, if not addressed, could lead to failure of the rescue hoist cable assembly, possibly resulting in injuries to a human load, or to persons on ground.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0018.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2024-0244, which requires, for helicopters with certain rescue hoists installed, a one-time inspection of the rescue hoist cable assembly and, depending on the results, replacing the rescue hoist cable assembly. EASA AD 2024-0244 also allows installing certain rescue hoist cable assemblies on any helicopter provided it is new (never previously installed on a rescue hoist) and allows installing certain rescue hoists on any helicopter provided it passes its required inspection.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA about the unsafe condition described in the MCAI. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of these same type designs.

AD Requirements

This AD requires accomplishing the actions specified in EASA AD 2024-

0244, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD and except as discussed under “Differences Between This AD and the MCAI.”

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2024–0244 is incorporated by reference in this AD. This AD requires compliance with EASA AD 2024–0244 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024–0244 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2024–0244. Material required by EASA AD 2024–0244 for compliance will be available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–0018 after this AD is published.

Differences Between This AD and the MCAI

The MCAI applies to Model SA 365 C3 helicopters, whereas this AD does not because that model is not FAA type-certificated.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption.

The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because the rescue hoist assembly is essential during rescue operations and failure of this assembly could result in a failed rescue attempt and injury to a person being lifted or persons on the ground. Additionally, the FAA has no information pertaining to the extent of the defect in the rescue hoist assembly that may currently exist in helicopters or how quickly the condition may propagate to failure, therefore, the initial actions required by this AD must be accomplished before next rescue hoist operation. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects up to 227 helicopters of U.S. registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates that operators may incur the following costs to comply with this AD.

Inspecting a rescue hoist cable assembly will take 2 work-hours for an estimated cost of \$170 per helicopter and up to \$38,590 for the U.S. fleet. If required, replacing a rescue hoist cable assembly will take 1 work-hours and parts will cost \$10,218 for an estimated cost of \$10,303 per helicopter.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more

detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–03–04 Airbus Helicopters:

Amendment 39–22952; Docket No. FAA–2025–0018; Project Identifier MCAI–2024–00749–R.

(a) Effective Date

This airworthiness directive (AD) is effective February 19, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model AS332L, AS332L1, AS 365 N3, SA-365C1, SA-365C2, SA-365N, and SA-365N1 helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2500, Cabin Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by a report that certain rescue hoist cable assemblies may be equipped with a defective ball end. The FAA is issuing this AD to detect and address defective rescue hoist cable assembly ball ends. This unsafe condition, if not addressed, could result in failure of the rescue hoist cable assembly, in-flight failure of the rescue hoist, and subsequent injury to a person being lifted or to persons on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency AD 2024-0244, dated December 13, 2024 (EASA AD 2024-0244).

(h) Exceptions to EASA AD 2024-0244

(1) Where EASA AD 2024-0244 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2024-0244 defines the “affected rescue hoist,” this AD requires replacing that definition with “Any rescue hoist, as identified in Table 2 of EASA AD 2024-0244, either manufactured, repaired, or overhauled by Breeze-Eastern’s main facility in Whippany, New Jersey before April 8, 2024 and which has not had the rescue hoist cable replaced since then, and any rescue hoist, as identified in Table 2 of EASA AD 2024-0244, if the date of manufacture, repair, or overhaul cannot be determined.”

(3) Where paragraph (2) of EASA AD 2024-0244 states “any discrepancy is detected, as defined in the ASB,” this AD requires replacing that text with “there is any gouging.”

Note 1 to paragraph (h)(3): The material referenced in EASA AD 2024-0244 provides an illustration of gouging.

(4) This AD does not adopt the “Remarks” section of EASA AD 2024-0244.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2024-0244 specifies to submit certain information to the manufacturer, this AD does not require that action.

(j) Special Flight Permit

Special flight permits may be issued under 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished provided that the rescue hoist is not used.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Eric Rivera, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (847) 294-7166; email: eric.rivera01@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024-0244, dated December 13, 2024.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 30, 2025.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025-02248 Filed 1-31-25; 4:15 pm]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2024-1483; Project Identifier MCAI-2023-01094-T; Amendment 39-22924; AD 2024-26-09]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2021-10-02, which applied to all Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. AD 2021-10-02 required repetitive general visual inspections of the left- and right-hand elevator torque tube bearings for any sand, dust, or corrosion; repetitive functional tests of the elevator control system; and replacement of the elevator torque tube bearings if necessary. This AD continues to require certain actions in AD 2021-10-02 and requires revising the existing maintenance or inspection program, as applicable, to incorporate a new airworthiness limitation. This AD was prompted by a determination that a new airworthiness limitation is necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 11, 2025.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 11, 2025.

The Director of the Federal Register approved the incorporation by reference of certain other publications listed in this AD as of July 29, 2021 (86 FR 33088, June 24, 2021).

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2024-1483; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Bombardier material identified in this AD, contact Bombardier Business