

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Cindy Lorenzen, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, GA 30349; telephone: (770) 703-6078; facsimile, (770) 703-6097.

(g) *What if I need to fly the airplane to another location to comply with this AD?* FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* You must accomplish the actions required by this AD in accordance with Maule Mandatory Service Bulletin No. 20, dated December 27, 1999. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Maule Aerospace Technology, Inc., 2099 Georgia Hwy. 133 South, Moultrie, GA 31768. You can look at copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, MO, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on May 30, 2000.

Issued in Kansas City, Missouri, on April 27, 2000.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-11176 Filed 5-8-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-244-AD; Amendment 39-11704; AD 2000-08-18]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-9 Series Airplanes, and Model MD-88 and MD-90-30 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-9 series airplanes, and Model MD-88 and MD-90-30 airplanes, that requires replacement of the lanyard assembly pins of the evacuation slides with solid corrosion-resistant pins. This amendment is prompted by a report that, due to stress

corrosion on the lanyard pins, the arms of the lanyard assembly of the evacuation slide were found to be frozen. The actions specified by this AD are intended to prevent the improper deployment of the evacuation slide due to stress corrosion, which could delay or impede evacuation of passengers during an emergency.

DATES: Effective June 13, 2000. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 13, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, CA 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60).

This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, WA; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Alan Sinclair, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; telephone (562) 627-5338; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-9 series airplanes, and Model MD-88 and MD-90-30 airplanes was published as a supplemental notice of proposed rulemaking (NPRM) in the **Federal Register** on November 26, 1999 (64 FR 66417). That action proposed to require replacement of the lanyard assembly pins of the evacuation slides with solid corrosion-resistant pins.

Comments Received

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Support for Proposed AD

One commenter supports the proposed AD. Another commenter states

that the proposed AD does not affect its fleet.

Requests To Revise Applicability Statement of Proposed AD

Two commenters request that the applicability statement of the proposed AD be revised to exclude freighter airplanes on which emergency evacuation slides have not been installed. The commenters state that such a revision would eliminate alternative method of compliance (AMOC) requests. The commenters did not provide any data to substantiate their request.

The FAA does not concur. The FAA is unable to verify that all freighter airplanes are not equipped with evacuation slides. Therefore, all affected freighter airplanes must be included in the applicability statement of the final rule. However, under the provisions of paragraph (c) of the final rule, the FAA may consider requests for approval of an AMOC if sufficient data are submitted to substantiate that replacement of the lanyard pins with solid corrosion-resistant pin are not necessary.

One commenter questions whether Boeing latch assembly, part number (P/N) 69-70843-1, should be included in the applicability statement of the proposed AD. The commenter states that the roll pin, P/N MS39086-140, which resulted in the corrosion problem, is present in the Boeing latch assembly, as well as the Douglas latch assembly, P/N's 3961899-1 and 3956939-501.

The FAA has determined that the subject Boeing latch assemblies are not susceptible to stress corrosion, and therefore, are not subject to the identified unsafe condition of this AD. Therefore, no change to the final rule is necessary.

Requests for Alternative Method of Compliance (AMOC)

One commenter requests that the FAA approve lanyard assembly pin, P/N MS16555-627, as an AMOC for the pin required by the AD (reference McDonnell Douglas Alert Service Bulletin DC9-25A357, dated February 11, 1997). The commenter states that this pin is shorter and would not require any machining. If the FAA does not approve the pin having P/N MS16555-627, the commenter requests that the FAA approve the installation of an unmodified pin, P/N MS16555-628, which would protrude from the latch assembly. The commenter states that both of these alternatives would not interfere with the operation of the lanyard or deployment of the slide and

would provide the same level of safety as the pin required by the AD.

The FAA does not concur. The FAA finds that the shorter pin would not provide an equivalent level of safety to that of the pin required by the AD, because the taper on the end of the shorter pin would not provide the same level of pin retention. The shorter pin could become loose and fall out of the latch, thus causing the latch to fail. The FAA also finds that a pin that extends past the surface of the latch could cause the latch to hang up and fail. Therefore, no change to the final rule is necessary.

One commenter requests that the proposed AD be revised to include an AMOC, which was approved by the airplane manufacturer, to eliminate the need of each airline making a request to the FAA on an individual basis. The commenter states that the AMOC involves a program to accomplish, among other things, an initial check of the lanyard and then to periodically check, clean, and refurbish the subject lanyards with new roll pins of the same P/N.

The FAA does not concur. Because Airplane Maintenance Programs vary from operator to operator, there are no assurances that each operator's Airplane Maintenance Program contains the identical actions required by this AD. However, under the provisions of paragraph (c) of the final rule, the FAA may consider requests for approval of an AMOC if sufficient data are submitted to substantiate that such an AMOC would provide an acceptable level of safety.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 2,167 McDonnell Douglas Model DC-9 series airplanes, and Model MD-88 and MD-90-30 airplanes of the affected design in the worldwide fleet. The FAA estimates that 1,200 airplanes of U.S. registry will be affected by this AD, that it will take approximately 2 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$144,000, or \$120 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish

those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-08-18 McDonnell Douglas:

Amendment 39-11704. Docket 97-NM-244-AD.

Applicability: Model DC-9 series airplanes, and Model MD-88 airplanes, as listed in McDonnell Douglas Alert Service Bulletin DC9-25A357, Revision 02, dated May 28, 1998; and Model MD-90-30 airplanes, as listed in McDonnell Douglas Alert Service Bulletin MD90-25A019, dated February 11, 1997; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been

modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the improper deployment of the evacuation slide, which could delay or impede evacuation of passengers during an emergency, accomplish the following:

Replacement

(a) Within 180 days after the effective date of this AD, replace the lanyard assembly pins of the evacuation slides with solid corrosion-resistant pins, in accordance with McDonnell Douglas Alert Service Bulletin MD80-25A357, dated February 11, 1997, Revision 01, dated March 16, 1998, or Revision 02, dated May 28, 1998 (for Model DC-9 series airplanes and Model MD-88 airplanes); or McDonnell Douglas Alert Service Bulletin MD90-25A019, dated February 11, 1997 (for Model MD-90-30 airplanes); as applicable.

Spares

(b) As of the effective date of this AD, no lanyard assembly, part number (P/N) 3961899-1 or P/N 3956939-501, shall be installed on any airplane unless that assembly has been modified in accordance with the requirements of paragraph (a) of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The replacement shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD80-25A357, dated February 11, 1997; McDonnell Douglas Alert Service Bulletin DC9-25A357, Revision 01, dated March 16, 1998; McDonnell Douglas Alert Service Bulletin DC9-25A357, Revision

02, dated May 28, 1998; or McDonnell Douglas Alert Service Bulletin MD90-25A019, dated February 11, 1997; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on June 13, 2000.

Issued in Renton, Washington, on April 19, 2000.

Donald L. Riffin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-10288 Filed 5-8-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 95

[Docket No. 30029; Amdt. No. 422]

IFR Altitudes; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts miscellaneous amendments to the required IFR (instrument flight rules) altitudes and changeover points for certain Federal airways, jet routes, or direct routes for which a minimum or maximum en route authorized IFR altitude is prescribed. This regulatory action is needed because of changes occurring in the National Airspace

System. These changes are designed to provide for the safe and efficient use of the navigable airspace under instrument conditions in the affected areas.

EFFECTIVE DATE: 0901 UTC, June 10, 2000.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 95 of the Federal Aviation Regulations (14 CFR part 95) amends, suspends, or revokes IFR altitudes governing the operation of all aircraft in flight over a specified route or any portion of that route, as well as the changeover points (COPs) for Federal airways, jet routes, or direct routes as prescribed in part 95.

The Rule

The specified IFR altitudes, when used in conjunction with the prescribed changeover points for those routes, ensure navigation aid coverage that is adequate for safe flight operations and free of frequency interference. The reasons and circumstances that create the need for this amendment involve matters of flight safety and operational efficiency in the National Airspace System, are related to published aeronautical charts that are essential to the user, and provide for the safe and efficient use of the navigable airspace. In addition, those various reasons or circumstances require making this amendment effective before the next scheduled charting and publication date of the flight information to assure its timely availability to the user. The effective date of this amendment reflects those considerations. In view of the close and immediate relationship between these regulatory changes and

safety in air commerce, I find that notice and public procedure before adopting this amendment are impracticable and contrary to the public interest and that good cause exists for making the amendment effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 95

Airspace Navigation (air).

Issued in Washington, D.C. on May 3, 2000.

L. Nicholas Lacey,

Director, Flight Standards Service.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, part 95 of the Federal Aviation Regulations (14 CFR part 95) is amended as follows effective at 0901 UTC.

PART 95—[AMENDED]

1. The authority citation for part 95 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44719, 44721.

2. Part 95 is amended to read as follows:

REVISIONS TO IFR ALTITUDES AND CHANGEOVER POINTS

[Amendment 422 Effective Date: June 15, 2000]

From	To	MEA
Color Routes		
§ 95.10 Amber Federal Airway 7 Is Added To Read		
Campbell Lake, AK NDB	Mineral Creek AK NDB	12,100
Color Routes		
§ 95.60 Blue Federal Airway 2 Is Added to Read		
Point Lay, AK NDB	Cape Lisburne, AK NDB/DME	4,000
Cape Lisburne, AK NDB/DME	Hotham, AK NDB	*8,000