

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2000–NM–382–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 767–200 Series Airplanes**AGENCY:** Federal Aviation Administration, DOT.**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 767–200 series airplanes. This proposal would require repetitive inspections of the side panels of the nose wheel well for broken rivets and replacement of any broken rivets with bolts. This proposal would also require follow-on inspections of adjacent areas for cracks or broken rivets, whenever two or more adjacent broken rivets are found; repair of any cracks; and replacement of any broken rivets with bolts. Finally, this proposal provides for the optional replacement of all rivets in the affected area with bolts, which would terminate the repetitive inspections. This action is necessary to detect and correct broken rivets in the nose wheel well side panels and top panel, which could impair the function of the nose landing gear and cause fatigue cracks in the side panel and top panel webs of the nose wheel well, which could result in rapid cabin depressurization during flight. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by February 11, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket Number 2000–NM–382–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain “Docket No. 2000–NM–382–AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must

be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124–2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: John Craycraft, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2782; fax (425) 227–1181.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket Number 2000–NM–382–AD.” The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM–114, Attention: Rules Docket Number 2000–NM–382–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.

Discussion

The FAA has received a report indicating that 155 broken rivets were found in the side and top panels of the nose wheel well on a Boeing Model 767–200 airplane. Analysis indicates that pressurization loads on the side panel and top panel webs results in high prying loads on these rivets. Broken rivets in the side and top panels of the nose wheel well, if not corrected, could impair the function of the nose landing gear and cause fatigue cracks in the side and top panel webs of the nose wheel well, which could result in rapid cabin depressurization during flight.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Service Bulletin 767–53A0090, Revision 1, dated September 14, 2000, which describes procedures for repetitive inspections of the nose wheel well side panels for broken rivets and replacement of any broken rivets with bolts. The service bulletin also describes procedures for follow-up inspections of adjacent areas for broken rivets and cracks, whenever two or more adjacent broken rivets are found; repair of any cracks; and replacement of any broken rivets with bolts. Finally, the service bulletin describes procedures for the optional replacement of all rivets in the affected area with bolts, which eliminates the need for repetitive inspections.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed rule would require accomplishment of the actions specified in the service bulletin described previously, except as described below.

Differences Between Service Bulletin and Proposed Rule

Operators should note that the service bulletin specifies that if broken rivets are found during a secondary inspection, they must be repaired, and that repair data should be requested from the Boeing Company. However, this proposed rule would require the repair to be accomplished per a method

approved by the FAA, or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle Aircraft Certification Office, to make such findings.

Cost Impact

There are approximately 62 airplanes of the affected design in the worldwide fleet. The FAA estimates that 46 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 2 work hours per airplane to accomplish the proposed inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$5,520, or \$120 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2000–NM–382–AD.

Applicability: Model 767 series airplanes, line numbers 1 through 62; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct broken rivets in the nose wheel well side panels and top panel, which could impair the function of the nose landing gear and cause fatigue cracks in the nose wheel well side panel and top panel webs, which could result in rapid cabin depressurization during flight, accomplish the following:

Initial and Repetitive Inspections

(a) Within 18 months or 3,000 flight cycles after the effective date of this AD, whichever occurs first: Perform a detailed visual inspection of the nose wheel well side panels for broken rivets, in accordance with Boeing Service Bulletin 767–53A0090, Revision 1, dated September 14, 2000.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface

cleaning and elaborate access procedures may be required."

Note 3: Inspections, replacement, and repairs performed prior to the effective date of this AD in accordance with Boeing Service Bulletin 767–53A0090, dated August 3, 2000, are considered acceptable for compliance with the applicable actions specified in this amendment.

(1) If no broken rivets are detected: No further action is required as part of the initial inspection. Repeat the inspection at intervals not to exceed 18 months or 3,000 flight cycles, whichever occurs first.

(2) If broken rivets are detected, but they do not include two or more adjacent rivets: Prior to further flight, replace the broken rivets with bolts in accordance with the service bulletin. Repeat the inspection at intervals not to exceed 18 months or 3,000 flight cycles, whichever occurs first.

(3) If two or more adjacent broken rivets are detected: Prior to further flight, perform a secondary inspection as specified in paragraph (c) of this AD.

Optional Terminating Action

(b) Replacement of all the rivets with bolts in accordance with Figure 5 of Boeing Service Bulletin 767–53A0090, Revision 1, dated September 14, 2000, terminates the repetitive inspection required by paragraph (a) of this AD.

Secondary Inspections

(c) If two or more adjacent broken rivets are found during any inspection required by paragraph (a) of this AD: Prior to further flight, perform a detailed visual inspection of the side panels and the top panel of the nose wheel well for cracks or broken rivets, in accordance with Boeing Service Bulletin 767–53A0090, Revision 1, dated September 14, 2000.

(1) If no cracks or additional broken rivets are found: Prior to further flight replace all of the rivets with bolts in accordance with Figure 5 of the service bulletin. This terminates the repetitive inspections required by paragraph (a) of this AD.

(2) If any cracks or additional broken rivets are found: Prior to further flight, repair the cracks and replace all of the rivets, per a method approved by the Manager, Seattle Aircraft Certification Office, or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD. This terminates the repetitive inspections required by paragraph (a) of this AD.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on December 17, 2001.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-31558 Filed 12-21-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-112991-01]

RIN 1545-AY82

Credit for Increasing Research Activities

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of proposed rulemaking and notice of public hearing.

SUMMARY: This document contains proposed regulations relating to the computation of the research credit under section 41(c) and the definition of qualified research under section 41(d). In addition, this document contains proposed regulations describing when computer software that is developed by (or for the benefit of) a taxpayer primarily for the taxpayer's internal use is excepted from the internal-use software exclusion contained in section 41(d)(4)(E). These proposed regulations reflect changes to section 41 made by the Tax Reform Act of 1986, the Revenue Reconciliation Act of 1989, the Small Business Job Protection Act of 1996, the Taxpayer Relief Act of 1997, the Tax and Trade Relief Extension Act of 1998, and the Tax Relief Extension Act of 1999. This document also provides notice of a public hearing on these proposed regulations.

DATES: Written and electronic comments and requests to speak (with outlines of oral comments) at the public hearing scheduled for March 27, 2002 must be received no later than March 6, 2002.

ADDRESSES: Send submissions to: CC:IT&A:RU (REG-112991-01), room 5226, Internal Revenue Service, POB

7604, Ben Franklin Station, Washington, DC 20044. Submissions may also be hand delivered Monday through Friday between the hours of 8 a.m. and 5 p.m. to: CC:IT&A:RU (REG-112991-01), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue NW., Washington, DC. Alternatively, taxpayers may submit comments electronically via the Internet by selecting the "Tax Regs" option of the IRS Home Page, or by submitting comments directly to the IRS Internet site at: http://www.irs.gov/tax_regs/reglist.html. The public hearing will be held in the IRS Auditorium (7th Floor), Internal Revenue Building, 1111 Constitution Avenue, NW., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Concerning the regulations, Lisa J. Shuman, 202-622-3120; concerning submissions of comments and the hearing, LaNita VanDyke, 202-622-7180 (not toll-free numbers).

SUPPLEMENTARY INFORMATION:

Paperwork Reduction Act

The collections of information contained in this proposed regulation have been previously reviewed and approved by the Office of Management and Budget (OMB) in accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3507(d)) and assigned OMB Control Number 1545-1625. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a valid control number assigned by OMB.

Books or records relating to a collection of information must be retained as long as their contents may become material in the administration of any internal revenue law. Generally, tax returns and tax return information are confidential, as required by 26 U.S.C. 6103.

Background

On January 3, 2001, Treasury and the IRS published in the **Federal Register** (66 FR 280) final regulations (TD 8930) relating to the computation of the credit for increasing research activities (the research credit) under section 41(c) and the definition of qualified research under section 41(d). In response to taxpayer concerns regarding TD 8930, on January 31, 2001, Treasury and the IRS published Notice 2001-19 (2001-10 I.R.B. 784), announcing that Treasury and the IRS would review TD 8930 and reconsider comments previously submitted in connection with the finalization of TD 8930. Comments were requested on all aspects of TD 8930 with

specific comments requested on whether modifications should be made to the documentation requirement contained in § 1.41-4(d).

Notice 2001-19 also provided that, upon the completion of this review, Treasury and the IRS would announce changes to the regulations, if any, in the form of proposed regulations. Notice 2001-19 stated that TD 8930 would be revised so that the provisions of the regulations, including any changes to TD 8930, would be effective no earlier than the date when the completion of this review was announced, except that the provisions relating to internal-use computer software (including any revisions) generally would be applicable for taxable years beginning after December 31, 1985.

Explanation of Provisions

This document amends 26 CFR part 1 to provide additional rules under section 41. Section 41 contains the rules for the research credit. After consideration of the statute and legislative history, the court decisions, TD 8930 and the comments previously submitted in connection with the finalization of TD 8930, and the comments submitted in response to Notice 2001-19, Treasury and the IRS have revised TD 8930 to provide rules regarding:

(i) The requirement in section 41(d)(1)(B)(i) that qualified research be "undertaken for the purpose of discovering information which is technological in nature";

(ii) The requirement in section 41(d)(1)(C) that qualified research be research "substantially all of the activities of which constitute elements of a process of experimentation";

(iii) The type of computer software constituting software "which is developed by (or for the benefit of) the taxpayer primarily for internal use by the taxpayer" for purposes of section 41(d)(4)(E); and

(iv) the documentation required to substantiate the research credit. These and other changes to TD 8930 are discussed below.

I. Research That Is Undertaken for the Purpose of Discovering Information Which Is Technological in Nature

Section 41(d)(1)(B)(i) requires that qualified research must be "undertaken for the purpose of discovering information which is technological in nature." TD 8930 provided that "research is undertaken for the purpose of discovering information only if it is undertaken to obtain knowledge that exceeds, expands, or refines the common knowledge of skilled