

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2017–0032, dated February 17, 2017; corrected February 20, 2017.

(ii) [Reserved]

(3) For EASA AD 2017–0032, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1131.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 17, 2021.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2021–05151 Filed 3–11–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2020–1107; Project Identifier 2019–SW–049–AD; Amendment 39–21444; AD 2021–05–01]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Model SA330J helicopters. This AD was prompted by report of failure of a second stage planet gear of the main gear box (MGB). This AD requires replacement of the MGB

particle detector assembly with an improved, elongated MGB particle detector assembly, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 16, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 16, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1107.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1107; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Mahmood G. Shah, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: 817–222–5538; email: mahmood.g.shah@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0108, dated May 17, 2019 (EASA AD 2019–0108) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an

unsafe condition for all Airbus Helicopters Model SA330J helicopters.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Helicopters Model SA330J helicopters. The NPRM published in the **Federal Register** on December 4, 2020 (85 FR 78277). The NPRM was prompted by a report of failure of a second stage planet gear of the MGB on a Model EC225 helicopter. Following a review of design similarities, it was determined that such an event might also occur on Model SA330J helicopters. The NPRM proposed to require replacement of the MGB particle detector assembly with an improved, elongated MGB particle detector assembly, as specified in an EASA AD.

The FAA is issuing this AD to address failure of a second stage planet gear of the MGB, which could lead to loss of control of the helicopter. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

EASA AD 2019–0108 describes procedures for replacement of the MGB particle detector assembly with an improved, elongated MGB particle detector assembly. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 15 helicopters of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
4 work-hours × \$85 per hour = \$340	\$6,795	\$7,135	\$107,025

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-05-01 Airbus Helicopters:

Amendment 39-21444; Docket No. FAA-2020-1107; Project Identifier 2019-SW-049-AD.

(a) Effective Date

This airworthiness directive (AD) is effective April 16, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model SA330J helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 6320, Main rotor gearbox.

(e) Reason

This AD was prompted by a report of failure of a second stage planet gear of the main gear box (MGB). The FAA is issuing this AD to address failure of a second stage planet gear of the MGB, which could lead to loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019-0108, dated May 17, 2019 (EASA AD 2019-0108).

(h) Exceptions to EASA AD 2019-0108

(1) Where EASA AD 2019-0108 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2019-0108 does not apply to this AD.

(3) Where EASA AD 2019-0108 refers to flight hours (FH), this AD requires using hours time-in-service.

(4) Although the service information referenced in EASA 2019-0108 specifies to discard certain parts, this AD does not include that requirement.

(i) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the helicopter can be modified (if the operator elects to do so), provided that no passengers are onboard.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Strategic Policy Rotorcraft Section, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Strategic Policy Rotorcraft Section, send it to: Manager, Strategic Policy Rotorcraft Section, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110. Information may be emailed to: 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Mahmood G. Shah, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: 817-222-5538; email: mahmood.g.shah@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0108, dated May 17, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0108, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1107.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 17, 2021.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2021-05143 Filed 3-11-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1139; Product Identifier 2018-SW-056-AD; Amendment 39-21447; AD 2021-05-04]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain serial-numbered Leonardo S.p.a. (Leonardo) Model A109S and AW109SP helicopters. This AD requires installing a placard in the baggage compartment, revising the existing Rotorcraft Flight Manual (RFM) for your helicopter, and inspecting the installation of the terminal lugs. Depending on the outcome of the inspection, this AD requires restoring the installation of the terminal lugs. This AD would also require modifying the helicopter to shim the baggage fairing assy (fwd up) away from the circuit breaker panel and incorporating protective coverings. This AD was prompted by reports of several occurrences of fire ignition and smoke in the baggage compartment. The actions of this AD are intended to address an unsafe condition on these products.

DATES: This AD is effective April 16, 2021.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of April 16, 2021.

ADDRESSES: For service information identified in this final rule, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074;

fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1139.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1139; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The street address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Kristin Bradley, Aerospace Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email Kristin.Bradley@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Leonardo Model A109S helicopters, serial number (S/N) 22702, 22703, 22705, and 22706 and AW109SP helicopters with S/N up to 22386 inclusive, except S/N 22375 and S/N 22376. The NPRM published in the **Federal Register** on December 21, 2020 (85 FR 82972). The NPRM proposed to require, before further flight, for certain serial-numbered helicopters, installing a placard and revising the existing RFM for your helicopter. The NPRM also proposed to require within 5 hours time-in-service (TIS), for certain model helicopters, inspecting the installation of the terminal lugs, shimming the installation of the baggage fairing assembly (fwd up), and installing a silicon rubber protection over the blind rivets of the hinge in accordance with certain applicable service information. The NPRM also proposed to require within 10 hours TIS and thereafter at

intervals not to exceed 25 hours TIS until protective coverings are installed, removing the baggage fairing assembly (fwd up), removing the rubber protections, and inspecting the cable assembly routing of both circuit breaker panels for damage. Depending on the outcome of these inspections, the NPRM proposed to require repairing or replacing certain parts. The NPRM also proposed to require, within 200 hours TIS, modifying the helicopter to incorporate a certain protective coverings, which would provide a terminating action for the repetitive inspections. The proposed requirements were intended to prevent fire in the baggage department.

The NPRM was prompted by EASA Emergency AD No. 2018-0120-E, dated May 29, 2018 (EASA AD 2018-0120-E), issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition for Leonardo S.p.a. (formerly Finmeccanica S.p.A., AgustaWestland S.p.A., Agusta S.p.A.) Model A109S and AW109SP helicopters. EASA advises that an occurrence was reported on an AW109SP helicopter experiencing fire ignition and smoke in the baggage compartment. The investigation determined the event was due to chafing of electrical wiring and further analysis indicated that due to similarity of design, this event could also occur on A109S helicopters. Accordingly, the EASA AD requires modification of the affected baggage fairing assembly (fwd up) part number (P/N) 109-0344-31-101 and temporarily amending the existing RFM and installing a placard prohibiting carrying any loads in the baggage compartment.

After EASA AD 2018-0120-E was issued, a second occurrence was reported of fire ignition and smoke in the baggage compartment, and as a precautionary measure, Leonardo Helicopters issued a series of emergency alert service bulletins providing instructions to prevent damage of electrical assemblies in the baggage compartment. Accordingly, EASA issued EASA Emergency No. 2018-0149-E, dated July 13, 2018 (EASA AD 2018-0149-E), which retains the requirements of EASA AD 2018-0120-E, and also requires repetitive inspections of the baggage compartment electrical assemblies and depending on the inspection outcomes, repairing or replacing certain parts. Also, EASA AD 2018-0149-E expands the applicability to include three additional serial-numbered helicopters, and requires a modification, which acts as a terminating action for the repetitive inspections.