

In the incorrect formula, an “×” (multiplication) has been replaced with a “+” (addition) when the data was converted in the system and if this formula is followed, you may receive a result outside of the allowed tolerance.

Incorrect balance, outside the tolerance of the aileron control surface, may lead to vibrations that in [the] worst case can result in flutter.

The hard copy of the manual, SAAB 2000 SRM, is correct.

The CD/DVD dated Oct 01/05, marked “Reissue”, includes a correct SAAB SRM revision 22.

The corrective action includes identifying ailerons that have been balanced after July 4, 2005, until the effective date of this AD. If balanced incorrectly, they must be rebalanced.

Actions and Compliance

(f) Within one month after the effective date of this AD, unless already done, do the following actions.

(1) Identify ailerons that have been balanced after July 4, 2005. If balanced incorrectly, they must be rebalanced before further flight in accordance with Saab Service Bulletin 2000–57–040, dated February 23, 2006.

(2) As of the effective date of this AD, the aileron balancing procedure contained in the CD/DVD “Issue Date: Apr 01/05” including the Saab SAAB 2000 SRM at Revision 21 and the CD/DVD “Issue Date: Oct 01/05” including SRM at Revision 22 may not be used.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Borfitz, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone 227–2677; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB)

has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Emergency Airworthiness Directive 2006–0053–E, dated February 22, 2006, and Saab Service Bulletin 2000–57–040, dated February 23, 2006.

Material Incorporated by Reference

(i) You must use Saab Service Bulletin 2000–57–040, dated February 23, 2006, including Attachment 1, dated April 1, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Saab Aircraft AB, SAAB Aircraft Product Support, S–581.88, Linköping, Sweden.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 21, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–19199 Filed 10–2–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–27010; Directorate Identifier 2006–NM–259–AD; Amendment 39–15214; AD 2007–20–04]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A300 Airplanes and Model A310 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) that applies to all Airbus Model A300 and A310 airplanes, and certain Model A300–600 series airplanes. That AD currently requires an inspection of the wing and center fuel tanks to determine if certain P-clips are installed and corrective action if necessary. That AD also requires an inspection of electrical

bonding points of certain equipment in the center fuel tank for the presence of a blue coat and related investigative and corrective actions if necessary. That AD also requires installation of new bonding leads and electrical bonding points on certain equipment in the wing, center, and trim fuel tanks, as necessary. This new AD requires, for certain airplanes, installation of bonding on an additional bracket and modification of the fuel/defuel valves on the left-hand wing. This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to ensure continuous electrical bonding protection of equipment in the wing, center, and trim fuel tanks and to prevent damage to wiring in the wing and center fuel tanks, due to failed P-clips used for retaining the wiring and pipes, which could result in a possible fuel ignition source in the fuel tanks.

DATES: This AD becomes effective November 7, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of November 7, 2007.

On August 29, 2006 (71 FR 42026, July 25, 2006), the Director of the Federal Register approved the incorporation by reference of certain other publications listed in the AD.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1622; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647–5527) is located on the ground floor of the West Building at the DOT street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a supplemental notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2006-15-09, amendment 39-14689 (71 FR 42026, July 25, 2006). The existing AD applies to all Airbus Model A300, and Model A310 airplanes; and Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model C4-605R Variant F airplanes (collectively called A300-600 series airplanes). The supplemental NPRM was published in the **Federal Register** on June 20, 2007 (72 FR 33929). The supplemental NPRM proposed to require an inspection of the wing and center fuel tanks to determine if certain P-clips are installed and corrective action if necessary; an inspection of electrical bonding points of certain equipment in the center fuel tank for the presence of a blue coat and related investigative and corrective actions if necessary; and installation of new bonding leads and electrical bonding points on certain equipment in the wing, center, and trim fuel tanks, as necessary. That supplemental NPRM also proposed to require, for certain airplanes, installation of bonding on an additional bracket; and for certain other airplanes, modification of the fuel/defuel valves on the left-hand wing.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

Request To Revise Compliance Times and To Put New Actions in a Separate Rule

Air Transport Association (ATA), on behalf of its member American Airlines (AA), is concerned with the administrative burden of the supplemental NPRM. The commenters point out that the supplemental NPRM contains multiple compliance periods for the required actions. The commenters believe that the multiple compliance periods should be

consolidated into one compliance period. AA states that the scope of the existing AD along with the work added by the supplemental NPRM makes the proposed AD unwieldy to implement. AA states that considerable planning and procurement schedules must be accommodated for each additional AD, which disrupts planning that is already in place. The commenters state that the scope change described in the supplemental NPRM would have been more appropriately mandated as a separate rule.

We do not agree that the compliance times should be consolidated into one compliance period. In developing the compliance time for this AD action, we considered not only the safety implications of the identified unsafe condition, but the average utilization rate of the affected fleet, the practical aspects of an orderly inspection or modification to the fleet during regular maintenance periods, the availability of required parts, and the time necessary for the rulemaking process. We also considered the compliance periods specified by the European Aviation Safety Agency (EASA) and the airplane manufacturer. We have determined that the proposed compliance times following the effective date of the AD are appropriate. We have not revised the AD in this regard.

However, we do agree that the scope change in the supplemental NPRM is better mandated as a separate rule for reasons the commenters stated. Since we issued the supplemental NPRM, the EASA has revised its airworthiness directive to 2006-0325 R1, dated July 25, 2007. (We cited the original issue of EASA airworthiness directive 2006-0325, dated October 23, 2006, as the parallel airworthiness directive in the supplemental NPRM.) Revision 1 of the EASA airworthiness directive removes the procedures in Airbus Service Bulletin A300-28-6064 from its stated actions. Airbus Service Bulletin A300-28-6064 includes procedures for Model A300-600 series airplanes. That service bulletin contains the scope change to

which the commenters referred. R1 of the EASA airworthiness directive also removes Model A300-600 series airplanes from its applicability. As a result, we have revised the AD to do the following:

- Remove paragraph (k) of the supplemental NPRM. That paragraph contains the scope change cited by the commenters. We have re-identified subsequent paragraphs accordingly.
- Remove Model A300-600 series airplanes from the applicability. EASA is considering additional rulemaking regarding the unsafe condition for Model A300-600 series airplanes. Once the EASA airworthiness directive is approved, we will consider additional rulemaking for Model A300-600 series airplanes.
- Remove Model A300-600 service bulletins from Table 1 of the supplemental NPRM.
- Remove the costs information for Model A300-600 series airplanes from the Costs of Compliance section.
- Revise the Related Information (paragraph (n) of the supplemental NPRM) to refer to Revision 1 of the EASA airworthiness directive.

Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

There are about 92 Model A300 and A310 airplanes of the affected design in the U.S. fleet. The following table provides the estimated costs, at an average labor rate of \$80 per hour, for U.S. operators to comply with this AD. For some actions, the estimated work hours and cost of parts in the following table depend on the airplane configuration.

ESTIMATED COSTS

Model	Action	Work hours	Cost of parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
A300 airplanes ..	Inspect wing and center fuel tanks for P-clips (required by AD 2006-15-09).	40	None	\$3,200	29	\$92,800.
	Install bonding leads/points in wing and center fuel tank (required by AD 2006-15-09).	Between 136 and 155.	Between \$3,800 and \$5,200.	Between \$14,680 and \$17,600.	29	Between \$425,720 and \$510,400.
A310 airplanes ..	Inspect wing and center fuel tanks for P-clips (required by AD 2006-15-09).	40	None	\$3,200	63	\$201,600.

ESTIMATED COSTS—Continued

Model	Action	Work hours	Cost of parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
	Install bonding leads/points in wing and center fuel tank (required by AD 2006–15–09).	Between 248 and 285.	Between \$8,840 and \$9,190.	Between \$28,680 and \$31,990.	63	Between \$1,806,840 and \$2,015,370.
	Inspect and install bonding leads/points in the trim fuel tank (required by AD 2006–15–09).	Between 53 and 61.	Between \$50 and \$70.	Between \$4,290 and \$4,950.	63	Between \$270,270 and \$311,850.
	Install bonding for slat track 11 canister bracket (new action).	2	\$30	\$190	63	\$11,970.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39–14689 (71 FR 42026, July 25, 2006) and by adding

the following new airworthiness directive (AD):

2007–20–04 Airbus: Amendment 39–15214. Docket No. FAA–2007–27010; Directorate Identifier 2006–NM–259–AD.

Effective Date

(a) This AD becomes effective November 7, 2007.

Affected ADs

(b) This AD supersedes AD 2006–15–09.

Applicability

(c) This AD applies to all Model A300 and A310 airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to ensure continuous electrical bonding protection of equipment in the wing, center, and trim fuel tanks and to prevent damage to wiring in the wing and center fuel tanks, due to failed P-clips used for retaining the wiring and pipes, which could result in a possible fuel ignition source in the fuel tanks.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of the Requirements of AD 2006–15–09

Service Bulletin References

(f) The term “service bulletin,” as used in this AD, means the Accomplishment Instructions of the service bulletins identified in Table 1 of this AD, as applicable.

TABLE 1.—SERVICE BULLETIN REFERENCES

For Airbus—	And the actions specified in—	Use Airbus Service Bulletin—	Dated—
Model A300 airplanes	paragraph (g) of this AD ... paragraph (h) of this AD ...	A300–28–0081 A300–28–0079	July 20, 2005. September 29, 2005; or Revision 01, dated June 6, 2006. After the effective date of this AD, only Revision 01 may be used.
Model A310 airplanes	paragraph (g) of this AD ... paragraph (h) of this AD ...	A310–28–2143 A310–28–2142	July 20, 2005. August 26, 2005; or Revision 01, dated July 17, 2006. After the effective date of this AD, only Revision 01 may be used.

TABLE 1.—SERVICE BULLETIN REFERENCES—Continued

For Airbus—	And the actions specified in—	Use Airbus Service Bulletin—	Dated—
	paragraph (j) of this AD	A310–28–2153	July 20, 2005.

Inspection and Corrective Actions

(g) Within 59 months after August 29, 2006 (the effective date of AD 2006–15–09): Do a general visual inspection of the right and left wing fuel tanks and center fuel tank, if applicable, to determine if any NSA5516–XXND– and NSA5516–XXNJ–type P-clips are installed for retaining wiring and pipes in any tank, and do all applicable corrective actions before further flight after the inspection, by accomplishing all the actions specified in the service bulletin.

Note 1: For the purposes of this AD, a general visual inspection is: “A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked.”

Installation of Bonding Leads and Points for Wing and Center Fuel Tanks

(h) Within 59 months after August 29, 2006: Do the actions specified in paragraphs (h)(1) and (h)(2) of this AD, by accomplishing all the actions specified in the service bulletin.

(1) In the center fuel tank, if applicable, do a general visual inspection of the electrical

bonding points of the equipment identified in the service bulletin for the presence of a blue coat, and do all related investigative and corrective actions before further flight after the inspection.

(2) In the left and right wing fuel tanks and center fuel tank, if applicable, install bonding leads and electrical bonding points on the equipment identified in the service bulletin.

Installation of Bonding Leads and Points for the Trim Fuel Tank

(i) For Model A310 airplanes equipped with a trim fuel tank: Within 59 months after August 29, 2006, install a new bonding lead(s) on the water drain system of the trim fuel tank and install electrical bonding points on the equipment identified in the service bulletin in the trim fuel tank, by accomplishing all the actions specified in the service bulletin, as applicable.

New Requirements of This AD

Installation of Bonding for Slat Track Canister 11 Bracket

(j) For all Model A310 airplanes on which the actions specified in Airbus Service Bulletin A310–28–2142, dated August 26, 2005, have been done before the effective date of this AD: Within 50 months after the effective date of this AD, install bonding for the slat track canister 11 bracket, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310–28–2142, Revision 01, dated July 17, 2006.

Parts Installation

(k) As of August 29, 2006, no person may install any NSA5516–XXND–or NSA5516–XXNJ–type P-clip for retaining wiring and pipes in any wing, center, or trim fuel tank, on any airplane.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2006–15–09 are approved as AMOCs for the corresponding provisions of this AD.

Related Information

(m) European Aviation Safety Agency airworthiness directive 2006–0325 R1, dated July 25, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(n) You must use the service information listed in Table 2 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

TABLE 2.—ALL MATERIAL INCORPORATED BY REFERENCE

Airbus Service Bulletin—	Revision level—	Date—
A300–28–0079	Original	September 29, 2005.
A300–28–0079	01	June 6, 2006.
A300–28–0081	Original	July 20, 2005.
A310–28–2142	Original	August 26, 2005.
A310–28–2142	01	July 17, 2006.
A310–28–2143	Original	July 20, 2005.
A310–28–2153	Original	July 20, 2005.

(1) The Director of the Federal Register approved the incorporation by reference of the service bulletins listed in Table 3 of this

AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

TABLE 3.—NEW MATERIAL INCORPORATED BY REFERENCE

Airbus Service Bulletin—	Revision level—	Date—
A300–28–0079	01	June 6, 2006.
A310–28–2142	01	July 17, 2006.

(2) On August 29, 2006 (71 FR 42026, July 25, 2006), the Director of the Federal Register approved the incorporation by reference of the service bulletins listed in Table 4 of this AD.

TABLE 4.—MATERIAL PREVIOUSLY INCORPORATED BY REFERENCE

Airbus Service Bulletin—	Dated—
A300–28–0079	September 29, 2005.
A300–28–0081	July 20, 2005.
A310–28–2142	August 26, 2005.
A310–28–2143	July 20, 2005.
A310–28–2153	July 20, 2005.

(3) Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 21, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–19206 Filed 10–2–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–27015; Directorate Identifier 2006–NM–169–AD; Amendment 39–15215; AD 2007–20–05]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A318–111 and A318–112 Airplanes and Model A319, A320, and A321 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding two existing airworthiness directives (ADs). One AD applies to all Airbus Model A319 and A320 airplanes and currently requires repetitive ultrasonic inspections to detect fatigue cracking in the wing/fuselage joint cruciform fittings, and corrective actions if necessary. The other AD applies to all Airbus Model A319, A320, and A321 airplanes and currently requires a revision to the Airworthiness Limitations section (ALS) of the Instructions for Continued

Airworthiness (ICA). This new AD requires new revisions to the ALS of the ICA to incorporate service life limits for certain items and inspections to detect fatigue cracking, accidental damage, or corrosion in certain structures; and accomplishment of the repetitive ultrasonic inspections of the wing/fuselage joint cruciform fittings in accordance with the revised ALS of the ICA. This AD also adds airplanes to the applicability. This AD results from issuance of new and more restrictive service life limits and structural inspections based on fatigue testing and in-service findings. We are issuing this AD to detect and correct fatigue cracking, accidental damage, or corrosion in principal structural elements and to prevent failure of certain life limited parts, which could result in reduced structural integrity of the airplane.

DATES: This AD becomes effective November 7, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of November 7, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–2141; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647–5527) is located on the ground floor of the West Building at the DOT street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2004–03–06, amendment 39–13450 (69 FR 5909, February 9,

2004) and AD 2005–02–09, amendment 39–13954 (70 FR 3871, January 27, 2005). AD 2004–03–06 applies to all Airbus Model A319 and A320 airplanes, and AD 2005–02–09 applies to all Airbus Model A319, A320, and A321 airplanes. That NPRM was published in the **Federal Register** on January 26, 2007 (72 FR 3768). That NPRM proposed to require new revisions to the Airworthiness Limitations section (ALS) of the Instructions for Continued Airworthiness (ICA) to incorporate service life limits for certain items and inspections to detect fatigue cracking, accidental damage, or corrosion in certain structures; and accomplishment of the repetitive ultrasonic inspections of the wing/fuselage joint cruciform fittings in accordance with the revised ALS of the ICA. That NPRM also proposed to add airplanes to the applicability.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments that have been received on the NPRM.

Support for the NPRM

Airbus supports the NPRM. Northwest Airlines and United Airlines agree with the intent of the NPRM.

Request To Incorporate Certain Service Information

The Air Transport Association (ATA), on behalf of its member U.S. Airways, requests that we incorporate the following documents into this AD: Airbus Operator Information Telex (OIT) 999.0049/06, dated April 14, 2006; Airbus OIT 999.0055/06/CL, dated May 4, 2006; and the Airbus A318/A319/A320/A321 Scheduled Maintenance Data (SMD). The commenters further request that we revise this AD to allow operators to use later revisions of Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE–M4/95A.0252/96 (hereafter referred to as the “Airbus ALI”), as acceptable for compliance with the requirements of this AD. As justification for its request, US Airways states that Airbus will be revising the SMD and ALI on a regular basis.

We agree to refer to Airbus ALI, Issue 08, dated March 2006 (approved by the European Aviation Safety Agency (EASA) on January 4, 2007); and Issue 09, dated November 2006 (approved by the EASA on May 21, 2007); as appropriate sources of service information for accomplishing the actions required by paragraph (i) of this AD. We have also revised paragraph (j)