

this AD or within 400 hours time-in-service (TIS) after the last inspection required by AD 89-24-06 R1, whichever occurs later, and thereafter at intervals not to exceed 400 hours TIS; or

(ii) For Model DHC-6-400 airplanes, before further flight after the effective date of this AD and thereafter at intervals not to exceed 400 hours TIS.

Note 1 to paragraph (g)(1): The elevator quadrant may be identified as part number (P/N) C6CFM1138-27 (Pre Mod 6/1394), P/N C6CFM1450-27 (Post Mod 6/1394 or production cut-in (PCI) serial number (S/N) 331, Pre Mod 6/1678), or P/N C6CFM1450-29 (Post Mod 6/1678 or PCI S/N 602), and is referred to as assembly P/N C6CF1137-1, -3, -5, or -7.

(2) If any indication of distortion is found on the elevator quadrant during any inspection required by paragraph (g)(1) of this AD, before further flight, replace the elevator quadrant with a serviceable part and inspect the elevator quadrant support bracket assembly for cracks by following paragraphs III.B.1. through III.B.4.(b) of the Accomplishment Instructions in DHC-6 SB 6-511, Revision A. This AD requires that you do a fluorescent penetrant inspection as the type of required dye penetrant inspection. If a crack is found in the elevator quadrant support bracket, before further flight, replace with a serviceable part by following paragraphs III.B.5 through III.B.12 of the Accomplishment Instructions in DHC-6 SB 6-511, Revision A.

(3) For Model DHC-6-1, DHC-6-100, DHC-6-200, and DHC-6-300 airplanes: Within 400 hours TIS after the effective date of this AD, unless already done within the preceding 12 months before the effective date of this AD, inspect the elevator quadrant support bracket assembly for cracks by following paragraphs III.B.1. through III.B.4.(b) of the Accomplishment Instructions in DHC-6 SB 6-511, Revision A. This AD requires that you do a fluorescent penetrant inspection as the type of required dye penetrant inspection. If a crack is found in the elevator quadrant support bracket, before further flight, replace with a serviceable part by following paragraphs III.B.5 through III.B.12 of the Accomplishment Instructions in DHC-6 SB 6-511, Revision A.

(h) Credit for Previous Actions

(1) For Model DHC-6-1, DHC-6-100, DHC-6-200, and DHC-6-300 airplanes: This paragraph provides credit for the inspection required by paragraph (g)(1) of this AD if you performed the inspection before the effective date of this AD using paragraph (a)(1) of AD 89-24-06 R1.

(2) For Model DHC-6-1, DHC-6-100, DHC-6-200, and DHC-6-300 airplanes: This paragraph provides credit for the fluorescent penetrant inspection and subsequent replacement of the elevator quadrant support bracket due to a crack found from the fluorescent penetrant inspection required by paragraph (g)(2) of this AD if performed before the effective date of this AD using paragraphs (a)(3) and (4) of AD 89-24-06 R1.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Darren Gassetto, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7323; email: 9-avs-nyaco-cos@faa.gov.

(2) Refer to Transport Canada AD CF-1972-06R5, dated June 22, 2018, for more information. You may examine the Transport Canada AD at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0099.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Viking DHC-6 (Twin Otter) Service Bulletin 6-511, Revision A, dated June 22, 1990.

(ii) [Reserved]

(3) For service information identified in this AD, contact Viking Air Ltd., 1959 de Havilland Way, Sidney British Columbia, Canada V8L 5V5; phone: (800) 663-8444; email: continuing.airworthiness@vikingair.com; website: <https://www.vikingair.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 5, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-10758 Filed 5-18-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0217; Project Identifier MCAI-2020-01486-A; Amendment 39-22041; AD 2022-10-03]

RIN 2120-AA64

Airworthiness Directives; Viking Air Limited (Type Certificate Previously Held by Bombardier, Inc. and de Havilland, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Viking Air Limited (type certificate previously held by Bombardier, Inc. and de Havilland, Inc.) Model DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 airplanes. This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as loose quadrants on the rudder pedal torque tube and signs of loose rivets or rivet joint wear due to inadequate manufacturing tolerances. This AD requires inspecting the rudder pedal torque tube quadrant for looseness and taking corrective action as necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 23, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 23, 2022.

ADDRESSES: For service information identified in this final rule, contact Viking Air Ltd., 1959 de Havilland Way, Sidney British Columbia, Canada V8L 5V5; phone: (800) 663-8444; email: continuing.airworthiness@vikingair.com; website: <https://www.vikingair.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0217.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov>

searching for and locating Docket No. FAA–2021–0217; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Deep Gaurav, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228–7300; email: deep.gaurav@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain serial-numbered Viking Air Limited Model DHC–6–1, DHC–6–100, DHC–6–200, DHC–6–300, and DHC–6–400 airplanes. The NPRM published in the **Federal Register** on February 7, 2022 (87 FR 6802). The NPRM was prompted by MCAI originated by Transport Canada, which is the aviation authority for Canada. Transport Canada has issued AD CF–2020–45R1, dated April 16, 2021 (referred to after this as “the MCAI”), to correct an unsafe condition on Viking Air Limited Model DHC–6 series 1, DHC–6 series 100, DHC–6 series 110, DHC–6 series 200, DHC–6 series 210, DHC–6 series 300, DHC–6 series 310, DHC–6 series 320, and DHC–6 series 400 airplanes, serial numbers 001 through 987. The MCAI states:

There have been in-service reports of loose quadrants on the rudder pedal torque tube and signs of loose rivets or rivet joint wear, such as dark areas or streaks around the rivet heads and quadrant to torque tube interface. Viking Air Ltd. has determined that inadequate manufacturing tolerances may result in this condition. This defect, if not

detected and corrected, could result in the affected parts deteriorating until the rivets fail, leading to loss of control of the rudder and possible loss of control of the aeroplane.

To detect and correct this condition, [Transport Canada] AD CF–2020–45 mandated a one-time detailed inspection of the rudder pedal torque tube quadrant assembly, and rectification, as required, of the affected parts.

Viking Air Ltd. had published Service Bulletin (SB) V6/0067, Revision NC, dated 16 July 2020, providing Accomplishment Instructions for the one-time detailed inspection for looseness of the affected parts. Since [Transport Canada] AD CF–2020–45 was issued, Viking Air Ltd. has introduced a new rudder pedal torque tube assembly in production that is not subject to the unsafe condition of this [Transport Canada] AD. As a result, Viking Air Ltd. has revised the SB V6/0067 at Revision A, dated 26 January 2021 (referred to as “the SB” in this [Transport Canada] AD) to update the aeroplane serial number applicability.

This [Transport Canada] AD revision, CF–2020–45R1, is issued to modify the aeroplane serial number applicability in accordance with the SB.

You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0217.

In the NPRM, the FAA proposed to require inspecting the rudder pedal torque tube quadrant for looseness and taking corrective action as necessary. The FAA is issuing this AD to address the unsafe condition on these products.

Discussion of Final Airworthiness Directive

Comments

The FAA received one comment from the Airline Pilots Association, International (ALPA). ALPA supported the NPRM without change.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD

to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Viking DHC–6 Twin Otter Service Bulletin V6/0067, Revision A, dated January 26, 2021. This service information specifies procedures for inspecting the rudder pedal torque tube quadrant for looseness and performing a detailed visual inspection of the rudder torque tube assembly for signs of loose rivets or rivet joint wear. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA also reviewed Viking DHC–6 Twin Otter Service Bulletin V6/0067, Revision NC, dated July 16, 2020. This service information specifies procedures for inspecting the rudder pedal torque tube quadrant for looseness and visually inspecting for signs of loose or smoking rivets.

Differences Between This AD and the MCAI

The MCAI applies to Viking Air Limited Model DHC–6 series 110, DHC–6 series 210, DHC–6 series 310, and DHC–6 series 320 airplanes, and this AD would not because these models do not have an FAA type certificate. Transport Canada Models DHC–6 series 1, DHC–6 series 100, DHC–6 series 200, DHC–6 series 300, and DHC–6 series 400 airplanes correspond to FAA Model DHC–6–1, DHC–6–100, DHC–6–200, DHC–6–300, and DHC–6–400 airplanes, respectively.

Costs of Compliance

The FAA estimates that this AD affects 33 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per airplane	Cost on U.S. operators
Inspection	1 work-hour × \$85 per hour = \$85	Not Applicable	\$85	\$2,805

The FAA estimates the following costs to replace the rudder pedal torque tube quadrant assembly based on the

results of the inspection. The agency has no way of determining the number of

airplanes that might need this replacement:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per airplane
Rudder pedal torque tube quadrant assembly replacement.	10 work-hours × \$85 per hour = \$850	\$9,256	\$10,106

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022-10-03 Viking Air Limited (Type Certificate Previously Held by Bombardier, Inc. and de Havilland, Inc.): Amendment 39-22041; Docket No. FAA-2021-0217; Project Identifier MCAI-2020-01486-A.

(a) Effective Date

This airworthiness directive (AD) is effective June 23, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Viking Air Limited (type certificate previously held by Bombardier, Inc. and de Havilland, Inc.) Model DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 airplanes, serial numbers 001 through 987, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2700, Flight Control System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as loose quadrants on the rudder pedal torque tube and signs of loose rivets or rivet joint wear due to inadequate manufacturing tolerances. The FAA is issuing this AD to detect and correct loose rivets or rivet joint wear and signs of loose or smoking rivets. The unsafe condition, if not addressed, could result in the rudder pedal torque tube quadrant assembly deteriorating until the rivets fail, leading to loss of rudder control with consequent loss of airplane control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Action

Within 3 months after the effective date of this AD, inspect the rudder pedal torque tube

quadrant assembly for looseness and, if there is any looseness of the rudder pedal torque tube quadrant assembly, a loose rivet, any rivet joint wear, or a smoking rivet, before further flight, repair or replace the rudder pedal torque tube or quadrant assembly. Do these actions by following the Accomplishment Instructions, steps A.1. through A.9., in Viking DHC-6 Twin Otter Service Bulletin No. V6/0067, Revision A, dated January 26, 2021, except for any requirement to obtain repair instructions from Viking Customer Support, the repair must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; Transport Canada; or Viking Air Limited's Transport Canada Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(h) Credit for Previous Actions

You may take credit for the actions required by paragraph (g) of this AD if you performed those actions before the effective date of this AD using Viking DHC-6 Twin Otter Service Bulletin V6/0067, Revision NC, dated July 16, 2020.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the address identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Deep Gaurav, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7300; email: deep.gaurav@faa.gov.

(2) Refer to Transport Canada AD CF-2020-45R1, dated April 16, 2021, for related information. You may examine the Transport Canada AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0217.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Viking DHC-6 Twin Otter Service Bulletin V6/0067, Revision A, dated January 26, 2021.

(ii) [Reserved]

(3) For service information identified in this AD, contact Viking Air Ltd., 1959 de Havilland Way, Sidney British Columbia, Canada V8L 5V5; phone: (800) 663-8444; email: continuing.airworthiness@vikingair.com; website: <https://www.vikingair.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 30, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-10760 Filed 5-18-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2021-1004; Project Identifier MCAI-2021-00480-E; Amendment 39-22030; AD 2022-09-10]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG (Type Certificate Previously Held by Rolls-Royce plc) Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Rolls-Royce Deutschland Ltd & Co KG (RRD) RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 model turbofan engines. This AD was prompted by findings during engine overhaul of corrosion on the low-pressure compressor (LPC) front case

assembly. This AD requires inspection of the LPC front case assembly and, depending on the result of the inspection, accomplishment of the applicable corrective action(s), as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 23, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 23, 2022.

ADDRESSES: For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1004. For RRD service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: +44 (0)1332 242424 fax: +44 (0)1332 249936; website: <https://www.rolls-royce.com/contact-us.aspx>.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1004; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Nicholas Paine, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7116; email: nicholas.j.paine@faa.gov.

SUPPLEMENTARY INFORMATION:**Background**

EASA, which is the Technical Agent for the Member States of the European

Union, has issued EASA AD 2021-0114, dated April 23, 2021 (EASA AD 2021-0114), to address an unsafe condition for certain RRD RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 model turbofan engines.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to RRD RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 model turbofan engines. The NPRM published in the **Federal Register** on November 16, 2021 (86 FR 63319). The NPRM was prompted by findings during engine overhaul of corrosion on the LPC front case assembly caused by excessive movement between the Kevlar wrap and the fan case, which resulted in the anti-corrosion paint fretting away. In the NPRM, the FAA proposed to require the performance of all required actions within the compliance times specified in, and in accordance with EASA AD 2021-0114, except for any differences identified as exceptions in the regulatory text of this AD and except as discussed under “Differences Between this Proposed AD and the EASA AD.” The FAA is issuing this AD to address the unsafe condition on these products. See EASA AD 2021-0114 for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from three commenters. The commenters were American Airlines (American), The Boeing Company (Boeing), and Rolls-Royce plc (RR). The following presents the comments received on the NPRM and the FAA’s response to each comment.

Request To Revise Applicability

American requested that the FAA revise paragraph (c), Applicability, of this AD to replace “as identified in EASA AD 2021-0114” with “RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17 and 895-17 engines with Low Pressure (LP) Compressor front (fan) case assemblies having Part Number (P/N) FK33097, P/N FK26850, P/N FK26853, P/N FK26915, P/N FK26692 or P/N FK28577.” American stated that certain engines identified in the EASA AD applicability section have already performed rework on the LPC front case assembly to provide additional corrosion protection using RR RB211 Trent 800 Series Propulsion Systems Service Bulletin (SB) RB.211-72-G634